

From: Beggs, Tauren R - DNR
Sent: Thursday, April 12, 2018 10:43 AM
To: 'Henderson, Dave'; Maletzke, Jeff
Cc: GravelPit (GravelPit@manitowoc.org); Kasdorf, James H Jr - DNR
Subject: RE: Newton Pit - replacement well water quality discussion

Hi Dave and Jeff,

This is the information I received from Dave Johnson:

With the deep casing it will take a while (6-12 months) for the casing to settle in and so the iron will be higher than the ground water itself. Prefilters and iron curtain should help a lot. As for the hardness that too should settle down with some time. When you drill you expose a lot of fresh surface and that will react for some time but generally not as long as it takes for the casing to settle. We could explore treating the wells with acid to speed the process of "weathering" along.

We are committed to service excellence.

Visit our survey at <http://dnr.wi.gov/customersurvey> to evaluate how I did.

Tauren R. Beggs

Phone: (920) 662-5178

Tauren.Beggs@wisconsin.gov

From: Henderson, Dave [<mailto:Dave.Henderson@aecom.com>]
Sent: Thursday, March 8, 2018 8:36 AM
To: Beggs, Tauren R - DNR <Tauren.Beggs@wisconsin.gov>; Kasdorf, James H Jr - DNR <James.KasdorfJr@wisconsin.gov>; Johnson, Dave M - DNR <Dave.Johnson@wisconsin.gov>; Maletzke, Jeff <Jeff.Maletzke@aecom.com>
Cc: GravelPit (GravelPit@manitowoc.org) <GravelPit@manitowoc.org>
Subject: Newton Pit - replacement well water quality discussion

Tauren, et al:

The last three replacement portable wells we've installed have produced some water quality complaints from the home owners (e.g. Fe issues, taste, white residue, etc.). As such, we've been working to review the situation and find solutions.

As those complaints relate to TDS - we are in continuing discussions with the well driller, the plumber, and Jim directed us to Glen Schleuter at DSPS. We've also taken a new round of laboratory water quality samples w/ speciation for Fe and TDS. Jeff Maletzke, AECOM, has also taken a look at the depth of well install as it relates to the bedrock unit we're in and if a change in unit can affect water quality.

Dave Johnson – I think this question is more directed to you? Please see the attached documents:

- Replacement Potable Well Summary – an excel spreadsheet with specific well data.
- Manitowoc County preliminary bedrock map.
- Zoomed in bedrock map with the wells penciled in.

There are two dolostone units we're open borehole in:

Se – Engadine formation.
Sm – Manistique formation.

It appears most of our wells are open borehole in the Se unit (knowing/understanding that the x-section is approximate for our location).

It also appears that our recent wells penetrated the Sm unit – this is a change. The Manistique unit is noted as being “... very cherty...”

Taking a look at the summary data table, our most recent wells have TDS that is approx. 1/3 higher than the previous wells, which may be the root of our TDS complaints.

Dave – can you please provide technical support about the Se and Sm units and how they may relate to water quality?

Please give Jeff a call with any questions. We look forward to your input.



Thanks
dsh

David Henderson, P.E.
Senior Project Manager/Director, Environment
D 414-944-6190
M 414-429-8304
dave.henderson@aecom.com

AECOM
1555 N. RiverCenter Drive, Suite 214
Milwaukee, WI 53212, USA
T 414-944-6080
aecom.com

Built to deliver a better world

[LinkedIn](#) [Twitter](#) [Facebook](#) [Instagram](#)



1/6.2

1 in = 400

1 - 1.5 miles south of A - A'



DRAFT - Table x
 Replacement Potable Wells
 Well Depth and Water Quality Summary
 Former Newton Pit, Manitowoc Wisconsin

| Address | Replacement Well Data From Driller's Well Construction Reports (all measurements approximate ± a foot or two) | | | | | | | | Water Quality Information From Laboratory Reports | | |
|-------------------------|--|---------------------------|--------------------------------------|----------------------|--------------------------|---------------------------|--------------------------------|---|---|------------|-----------------|
| | Ground Surface Elevation (ft MSL) | Depth to Bedrock (ft BGS) | Elevation of Top of Bedrock (ft MSL) | Cased Depth (ft BGS) | Cased Elevation (ft MSL) | Total Well Depth (ft BGS) | Well Bottom Elevation (ft MSL) | Length of Open Borehole in Bedrock (ft) | Fe (mg/L) | TDS (mg/L) | Hardness (mg/L) |
| 3303 Hecker Road | 691 | 118 | 573 | 280 | 411 | 303 | 388 | 23 | 28.9 | 2,003 | 1,374 |
| 3515 Hecker Road | 691 | 110 | 581 | 277 | 414 | 300 | 391 | 23 | 1.22 | 2,156 | 1,504 |
| 3518 Hecker Road | 697 | 115 | 582 | 250 | 447 | 282 | 415 | 32 | 7.01 | 2,064 | 1,448 |
| 3609 Hecker Road | 696 | 131 | 565 | 290 | 406 | 300 | 396 | 10 | 5.08 | 2,264 | 1,591 |
| 3023 CTH CR | 667 | 133 | 534 | 275 | 392 | 308 | 359 | 33 | 5.17 | 2,164 | 1,545 |
| 3120 CTH CR | 683 | 121 | 562 | 279 | 404 | 305 | 378 | 26 | 4.82 | 1,966 | 1,309 |
| 3403 CTH CR | 667 | 150 | 517 | 275 | 392 | 307 | 360 | 32 | 0.32 J | 2,349 | 1,688 |
| 3504 CTH CR | 680 | 168 | 512 | 278 | 402 | 320 | 360 | 42 | 12.9 | 2,330 | 1,380 |
| 4002 Thunder Ridge Road | 686 | 171 | 515 | 319 | 367 | 420 | 266 | 101 | 14.5 | 2,450 | 1,753 |
| 4005 Thunder Ridge Road | 688 | 180 | 508 | 320 | 368 | 420 | 268 | 100 | 9.83 | 2,706 | 1,873 |
| 4010 Thunder Ridge Road | 687 | 178 | 509 | 320 | 367 | 400 | 287 | 80 | 9.77 | 2,658 | 1,588 |
| 2918 S 26th Street | 654 | 125 | 529 | 300 | 354 | 400 | 254 | 100 | 14.5 | 3,007 | 1,898 |

| Location | Avg Top of Bedrock Elev | Delta from Hecker - (ft) Lower | Approx Dist. From Hecker (ft) |
|----------------|-------------------------|--------------------------------|-------------------------------|
| At Hecker Rd | 575 | 0 | 0 |
| At CTH CR | 531 | 44 | 2,500 |
| At Thunder Rdg | 511 | 65 | 3,500 |
| At S 26th | 529 | 46 | 8,000 |