

**SUBSURFACE INVESTIGATION  
AND REMEDIAL ACTION  
CHRYSLER CORPORATION  
KENOSHA ENGINE PLANT  
KENOSHA, WISCONSIN**

PREPARED FOR:

**CHRYSLER CORPORATION  
FEATHERSTONE ROAD ENGINEERING CENTER  
2301 FEATHERSTONE ROAD, CIMS 429-02-04  
AUBURN HILLS, MICHIGAN 48326**

TRIAD ENGINEERING PROJECT NO. W943163.005

JANUARY 1994



**TRIAD ENGINEERING INCORPORATED**

---

325 East Chicago Street  
Milwaukee, Wisconsin 53202  
414-291-8840 Fax 414-291-8841

4410 Executive Boulevard  
Fort Wayne, Indiana 46808  
219-471-3388 Fax 219-471-3565

**SUBSURFACE INVESTIGATION  
AND REMEDIAL ACTION  
CHRYSLER CORPORATION  
KENOSHA ENGINE PLANT  
KENOSHA, WISCONSIN**

PREPARED FOR:

**CHRYSLER CORPORATION  
FEATHERSTONE ROAD ENGINEERING CENTER  
2301 FEATHERSTONE ROAD, CIMS 429-02-04  
AUBURN HILLS, MICHIGAN 48326**

PREPARED BY:

**TRIAD ENGINEERING INCORPORATED  
325 EAST CHICAGO STREET  
MILWAUKEE, WISCONSIN 53202**

TRIAD ENGINEERING PROJECT NO. W943163-005

JANUARY 1994



*Thomas L. Meinholz*  
Thomas L. Meinholz, P.E.  
President



David S. Voight, CPG  
Senior Project Manager

*Richard J. Binder*  
Richard J. Binder, P.G.  
Project Manager

*Jeanne M. Ramponi*  
Jeanne M. Ramponi  
Hydrogeologist

## TABLE OF CONTENTS

	PAGE
EXECUTIVE SUMMARY .....	1
1.0 INTRODUCTION .....	2
1.1 Introduction .....	2
1.2 Background and Scope of Work .....	2
2.0 SUBSURFACE INVESTIGATION .....	3
2.1 Investigation Procedures. ....	3
2.2 Investigation Results. ....	3
2.2.1 Site Geology. ....	3
2.2.2 Field Observations and Analytical Results .....	3
3.0 REMEDIAL ACTION RESULTS .....	5
4.0 SUMMARY AND CONCLUSIONS. ....	6

---

### LIST OF FIGURES

FIGURE 1	COOLANT TANKS AND BORING LOCATION
FIGURE 2	COOLANT CONCENTRATION IN STORM SEWER WATER SAMPLES
FIGURE 3	CROSS SECTION
FIGURE 4	FLOW VOLUME IN STORM SEWER

### LIST OF APPENDICES

APPENDIX A	RELEASE LETTER REPORT AND MATERIAL SAFETY DATA SHEET
APPENDIX B	METHODS OF INVESTIGATION
APPENDIX C	BOREHOLE LOG AND ABANDONMENT FORM
APPENDIX D	LABORATORY RESULTS
APPENDIX E	VOLUME RECEIVED LIQUID DATA, STORM SEWER

## **EXECUTIVE SUMMARY**

Triad Engineering Incorporated (Triad) was contracted by Chrysler Corporation (Chrysler) to conduct a limited subsurface investigation at Chrysler's, Kenosha Engine Plant, located at 5555 30th Avenue, Kenosha, Wisconsin. The purpose of the investigation was to evaluate the extent of an apparent release from a machining coolant tank (Coolant System #1). Based on conversations with the Wisconsin Department of Natural Resources (WDNR), the investigation was conducted in conjunction with remedial actions performed by Chrysler, which included tank replacement (complete with secondary containment) and recovery of coolant from an isolated storm sewer.

Field observations and laboratory analytical results indicate that the release of machining coolant is confined to the immediate vicinity of the coolant tank and the nearby storm sewer. The concentration of coolant observed in water samples collected from the storm sewer has decreased to below detectable levels following the installation of the new tank system indicating that the remedial action undertaken by Chrysler has been effective. Current conditions suggest further action is not warranted.

## 1.0 INTRODUCTION.

### 1.1 Introduction.

Triad Engineering Incorporated (Triad) was contracted by Chrysler Corporation (Chrysler) to conduct a subsurface investigation in the area of a subgrade machining coolant tank (Coolant System #1) at Chrysler's, Kenosha Engine Plant, located at 5555 30th Avenue, Kenosha, Wisconsin. The purpose of the investigation was to evaluate the extent of an apparent release of machining coolant from the tank. Based on conversations with the Wisconsin Department of Natural Resources (WDNR), the investigation was conducted in conjunction with remedial actions undertaken by Chrysler which included tank replacement (complete with secondary containment) and recovery of coolant from an isolated storm sewer.

### 1.2 Background and Scope of Work.

An apparent release of machining coolant to a storm sewer at Chrysler's Kenosha Engine Plant was discovered on July 19, 1993. A section of the storm sewer was plugged and pumps were installed in both the storm sewer, and within the concrete containment surrounding the coolant tank. These actions facilitated the capture of the release. Notification was also made to the WDNR's Industrial Waste Water Section - Emergency Response Coordinator (Appendix A).

Information provided by the manufacturer concerning the nature of the coolant (Bencyn Lubricants Inc., Articool 51) is provided in Material Safety Data Sheet (MSDS) included in Appendix A. This information indicates that the coolant is nonhazardous.

A television camera was inserted in the storm sewer to assess their condition on July 21, 1993. Coolant was observed entering the line at a piping joint near the coolant system, approximately 10 feet east of the coolant tank. On August 23, 1993, a dye was added to the coolant tank to trace the release. The dye tracing confirmed the coolant source.

Triad performed a limited subsurface investigation on December 4, 1993, to assess local soil and groundwater conditions, and to evaluate the potential for coolant to occur hydraulically downgradient of the coolant tank. On December 9 and 10, 1993, the coolant tank was drained and removed. A new tank, complete with secondary containment (and allowing for visual observation of the interstitial space), was installed during the latter half of December 1993.

The results of the investigation and remedial actions are documented in the following sections of this report.

## 2.0 SUBSURFACE INVESTIGATION.

### 2.1 Investigation Procedures.

On December 4, 1993, soil boring EP-1 was installed approximately 80 feet east of the coolant tank (Figure 1). This boring was placed hydraulically downgradient of the source area (Figure 1). The boring was advanced by using standard penetration test drilling methods to a depth of 9 feet. Soil samples were collected continuously at the boring location by using standard penetration test drilling methods. Visual and olfactory observations were made by the on-site geologist during drilling and sampling activities. One soil sample collected from just above the apparent water table depth was submitted for laboratory analysis. As discussed with the WDNR, this sample was submitted under chain-of-custody to Chrysler's laboratory for analysis of coolant concentration, using an alkaline titration method.

Representative groundwater samples were collected from the water table depth from EP-1 using a HydroPunch II™ sampler. These samples were also submitted to Chrysler's laboratory for analysis of coolant concentration (alkaline titration method). Further discussion of the investigation methods used are provided in Appendix B. The completed borehole log and abandonment form for EP-1 are contained in Appendix C.

### 2.2 Investigation Results.

#### 2.2.1 Site Geology.

Subsurface boring information indicates that the investigation area is generally paved by one foot of concrete. The concrete is underlain by approximately four feet of fine to medium grained sand, which is in turn underlain by silty clay. Saturated conditions were observed within a silty sand seam at a depth of approximately 8 to 9 feet. The depth to groundwater measured in the HydroPunch II™ sampler approximately 20 minutes after sampling was 9.35 feet below surface grade.

A cross section depicting the depth of the coolant tank and storm sewer relative to groundwater is provided (Figure 3). As shown, the base of the coolant tank is at or just above the water table. The release point into the sewer appears to be below the water table.

#### 2.2.2 Field Observations and Analytical Results.

Laboratory analytical reports and summary of results are contained in Appendix D. Field and laboratory results for soil, groundwater and storm sewer samples are discussed below:

- Soil. No staining or coolant-like odor was observed in soil samples collected at boring EP-1. No coolant was detected in the soil sample submitted for laboratory analysis.
- Groundwater. The groundwater sample collected for analysis was clear and exhibited no odor. No coolant was detected in the groundwater sample submitted for laboratory analysis.

Investigation results, indicate that there has been no occurrence of a release of machining coolant into the soil and groundwater at the location of boring EP-1.

### **3.0 REMEDIAL ACTION RESULTS.**

Laboratory results provided by Chrysler indicate that the coolant concentration in sample collected from the storm sewer samples has decreased from approximately 4 percent coolant (typical full strength coolant concentrations are 4 to 5 percent), to below detectable levels following draining of the coolant tank and installation of the new tank (Figure 2; Appendix D). The volume of water/coolant recovered from the storm sewer has also decreased over time (Figure 4; Appendix E). No coolant was observed by Chrysler personnel within the concrete containment structure housing the coolant tank following installation of the new tank.




#### 4.0 SUMMARY AND CONCLUSIONS.

Investigation results indicate that the release of machining coolant at Chrysler's Kenosha Engine Plant facility appears to have been confined to the vicinity of the coolant tank and nearby storm sewer. Since the installation of a new tank system, the concentration of coolant observed in water samples collected from the storm sewer collection system has decreased to below detectable levels. Available information indicates that further action is not warranted. Storm sewer sampling at the site will continue per the facility storm water permit.

## FIGURES


---





**FIGURE 1**  
CHRYSLER KENOSHA ENGINE PLANT  
COOLANT TANKS AND BORING LOCATIONS

Figure 2  
Coolant Concentration in Storm Sewer Water Samples







FIGURE 3  
CHRYSLER KENOSHA ENGINE PLANT  
CROSS-SECTION

FIGURE 4

VOLUME OF LIQUID RECOVERED IN ISOLATED STORM SEWER



Volume Data is Contained in Appendix E.

W943163.c-2/2/94

**APPENDIX A**

---

**RELEASE LETTER REPORT  
MATERIAL SAFETY DATA SHEET**

Chrysler Corporation  
Kenosha Engine Plant

July 23, 1993

Industrial Waste Water Section  
Southeast District Office  
Department of Natural Resources  
4041 North Richard Street  
P.O. Box 12436  
Milwaukee, Wisconsin 53212  
Attn: Mr. J. Williams  
Emergency Response Coordinator

Subject: Storm Sewer Event of 7/19/93 - Synthetic Oil Release to  
Pike Creek. National Response Center Report #187468.

Dear Mr. Williams:

The State of Wisconsin experienced heavy rains the weekend of 7/18/93. On Monday morning, 7/19/93, a tour of the plant revealed no environmental problems. The same morning the Environmental Engineer also inspected the plate separator on 50th Street. The water was clear, but a film was detected and the discharge was milky. Continuing to the floatation basin, a muddy condition was detected coming from the City.

After 12:30 P.M., the plate separator still showed milky and the basin and Pike Creek looked the same. At this time all indications pointed to a plant generated soluble oil release. Initial notification of a problem was given to the writer at 1:30 P.M. At this time, both plate separator and basin were reinspected by Plant Engineering and it was confirmed that a problem existed. Engineering immediately called in assistance from Triad Engineering and Bane Nelson, Inc. to assist in locating the source. At 4:00 P.M. the source generator was found to be located in Bldg. 53 near Hydromation #1 which utilizes synthetic oil. It was estimated, due to the very slow flow, that only a small amount of coolant was released. We estimated approximately 20 to 22 gallons of the diluted 4% material by volume was released. The material identified was ARTICOOOL 51.

By 6:00 P.M. the same day, the 18" storm line was bulkheaded downstream to isolate this contamination to the local main.

Further inspection of the system downstream confirmed that the leak had been contained, as the plate separator and basin were clear by 6:00 A.M. Tuesday.

The plant also immediately requested the services of a camera to inspect this 18" line early on 7/20/93.

On 7/21/93, Visu-Sewer Clean & Seal, Inc. was contracted and on site to document, via VCR tape, the underground conditions. They confirmed what was suspected, that a leak in the hydromation tank found its way to the storm sewer below and was bleeding into the storm at a hub connection.



STORM SEWER EVENT OF 7/19/93 -  
SYNTHETIC OIL RELEASE TO PIKE CREEK.  
NATIONAL RESPONSE CENTER REPORT #187468  
Page 2


On 7/20/93, Corporate Environmental was notified of the problem at 8:15 A.M. The Episode Plan "Exhibit B" was put into effect and the following parties were contacted:

Emergency Government (J. Ashmore) 8:55 A.M. 7/20/93  
Department of Natural Resources (B. Smith) 10:15 A.M. 7/20/93  
City of Kenosha (J. Prijic) 11:50 A.M. 7/20/93  
Natural Response Center (Afternoon) 7/20/93

Corrective Actions:

As of 7/19/93 6:00 P.M., the 18" line was isolated from the storm system and it was confirmed no flow is going downstream. The suspect leak area by the hydromation tank is scheduled for repairs on September 4, 5, 6, Labor Day weekend. In the meantime, any oil which is entering the isolated 18" line is being sumped into a mobile tank and returned to the hydromation system on a daily basis. The plant is aware of the seriousness of this repair and is providing daily reports and observations on all activities. You will be advised of when final repairs are completed. When they are completed, the plant will verify by visual observation that these repairs were completed satisfactorily.

Any further questions, please contact the writer, L. Fasano, (414) 658-6061.  
Thank you.

  
E. Jensen  
Environmental Administrator  
Plant Engineering  
Kenosha Engine Plant

  
L. Fasano  
Supervisor  
Plant Engineering  
Kenosha Engine Plant

RJ/jf  
0721.RJ

CC: J. Bugno  
L. Jurca  
D. King  
N. McKay  
B. Rabe  
D. Remboski

SECTION I - PRODUCT INFORMATION

MFG: BENCYN LUBRICANTS, INC. EMERGENCY PHONE: 313-227-5953  
185 RAILROAD STREET NORTHVILLE MI 48167 AFTER HOURS: 313-227-5953  
DISTRIBUTED BY: BENCYN LUBRICANTS, INC. EMERGENCY PHONE: 313-227-5953  
185 RAILROAD STREET NORTHVILLE MI 48167 AFTER HOURS: 313-227-5953  
BRAND NAME: SYNTHETIC COOLANT ARTICOOOL 51 CHRY IND HYGIEN: 313-956-5478  
MFG ID : ARTICOOOL 51 AFTER HOURS: 313-956-5557  
DESCRIPTION: CUTTING OIL BENCYN LUBRICANTS ARTICOOOL 51 SYNTH. FOR FERROUS

SECTION II - INGREDIENTS

HAZARDOUS INGREDIENTS:	PERCENT					
COMMON NAME / CAS-NO AND CHEMICAL NAME:	BY WEIGHT	OSHA	ACGIH	CHRY	UNITS	NOTATIONS
CAUSTIC POTASH	1-5	W	N/AP	N/AP	N/AP	MG/M3
001310-58-3 POTASSIUM HYDROXIDE (2019CI)	C		2	2		2

GENERIC DESCRIPTION: AN AQUEOUS LUBRICANT CONTAINING FATTY ACIDS, SALTS, AMIDES, ACIDS AND CAUSTIC.

FOR EXPLANATION OF 'NOTATIONS'. SEE THE HAZARD COMMUNICATION SHEET EXPLANATIONS PAGE.

W = TWA VALUES; L = STEL VALUES; C = CEILING VALUES.

SECTION III - PHYSICAL DATA

BOILING POINT : N/AV	SOLUBILITY IN WATER: COMPLETE ( IN ALL PROPORTIONS )
VAPOR PRESSURE: N/AV	EVAPORATION RATE : 1.000 REF=: WATER = 1
VAPOR DENSITY : N/AV	SPECIFIC GRAVITY : N/AV
PH AT FULL STRENGTH: 9.8	PH AT REC. DILUTION: 9.5
EVOLATILE BY VOL: N/AV	VOLATILE ORGANIC COMPOUNDS: N/AV N/AV
ODOR THRESHOLD: N/AV PPM FOR	% POPULATION
FREEZING POINT: 32.0 F	COEFFICIENT OF WATER/OIL DISTRIBUTION: N/AV
APPEARANCE & ODOR: AMBER LIQUID. SOAP ODOR.	

SECTION IV - FIRE AND EXPLOSION DATA

FLASH POINT: N/AP N/AP IGNITION TEMP: N/AP LEL: N/AP UEL: N/AP  
SPECIAL FIRE & EXPLOSION HAZARDS: MATERIAL DOES NOT BURN. MAY PRODUCE TOXIC THERMAL DECOMPOSITION PRODUCTS. REACTS VIOLENTLY WITH OXIDIZERS. REACTS VIOLENTLY WITH STRONG ACIDS. SPONTANEOUS HEATING MAY OCCUR IN RAGS, INSULATION, OR TRASH SOAKED WITH THIS MATERIAL AND EXPOSED TO AIR.  
EXTINGUISHING MEDIA: NON-FLAMMABLE. USE MEDIA APPROPRIATE FOR MATERIALS ACTUALLY INVOLVED IN FIRE.  
SPECIAL FIREFIGHTING PROCEDURES: USE SELF-CONTAINED BREATHING APPARATUS. USE WATER TO COOL FIRE EXPOSED CONTAINERS. REMOVE CONTAINERS FROM FIRE AREA IF POSSIBLE.  
SENSITIVE TO MECHANICAL IMPACT?: NO SENSITIVE TO STATIC DISCHARGE?: NO  
HAZARDOUS COMBUSTION PRODS: CARBON DIOXIDE, CARBON MONOXIDE. OXIDES OF NITROGEN.  
FLAME PROJECTION: N/AP

SECTION V - HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE-ACUTE & CHRONIC: ((---INHALATION---)) MIST MAY PRODUCE IRRITATION OF UPPER RESPIRATORY TRACT. ((---SKIN CONTACT---)) PROLONGED CONTACT MAY PRODUCE IRRITATION. ((---EYE CONTACT---)) DIRECT CONTACT MAY PRODUCE DAMAGE TO EYE TISSUE AND SEVERE IRRITATIO ((---INGESTION---)) MAY BE HARMFUL IF SWALLOWED.

PREPARATION DATE: 04/18/90

PAGE 2

STANDARD: H/AV

OSHA HAZARDOUS: YES

CONSUMER PRODUCT: ?

HAZWOPER HAZARDOUS: YES

EMERGENCY FIRST AID PROCEDURES: <<---INHALATION--->> REMOVE TO FRESH AIR AT ONCE. IF CONDITION PERSISTS. CONSULT A PHYSICIAN. <<---SKIN CONTACT--->> IMMEDIATELY FLUSH CONTAMINATED AREA WITH LARGE AMOUNTS OF WATER. IF CONDITION PERSISTS. CONSULT A PHYSICIAN. <<---EYE CONTACT--->> RINSE EYES IMMEDIATELY WITH LARGE AMOUNTS OF WATER. OCCASIONALLY LIFTING BOTH UPPER AND LOWER LIDS. CONTINUE FOR 15 MINUTES. CONTACT A PHYSICIAN. <<---INGESTION--->> DO NOT INDUCE VOMITING-CALL PHYSICIAN IMMEDIATELY.

---

**SECTION VI - REACTIVITY DATA**

---

STABILITY: STABLE

CONDITIONS TO AVOID: FREEZING.

MATERIALS TO AVOID : STRONG OXIDIZING AGENTS, STRONG ACID.

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

POLYMERIZATION CONDITIONS TO AVOID: POLYMERIZATION WILL NOT OCCUR.

HAZARDOUS DECOMPOSITION PRODUCTS: THERMAL DECOMPOSITION MAY PRODUCE CARBON MONOXIDE, CARBON DIOXIDE AND OXIDES OF NITROGEN.

---

**SECTION VII - SPILL OR LEAK PROCEDURES**

---

STEPS TO BE TAKEN IF MATERIAL IS RELEASED OR SPILLED: WEAR PROTECTIVE CLOTHING. STOP SPILL AT SOURCE. CONTAIN WITH DIKE. ABSORB ON AN INERT MATERIAL. DISCARD INTO SEALED CONTAINERS FOR DISPOSAL. FLUSH AREA WITH WATER.

WASTE DISPOSAL METHODS: DISPOSE OF IN A MANNER CONSISTENT WITH STATE, PROVINCIAL, LOCAL, AND FEDERAL DISPOSAL REGULATIONS. FOR FURTHER INFORMATION CALL CORPORATE PURCHASING AT TIE LINE 859-7969 (OUTSIDE OF CHRYSLER CALL 313/855-7969). FLUSH WITH WATER TO WASTE TREATMENT.

---

**SECTION VIII - SPECIAL PROTECTION**

---

RESPIRATORY PROTECTION: NO SPECIAL PROTECTION NEEDED UNDER NORMAL CONDITIONS.

VENTILATION TYPE : GENERAL VENTILATION IS USUALLY ADEQUATE.

PROTECTIVE GLOVES : RECOMMENDED. RUBBER GLOVES OR NEOPRENE GLOVES.

EYE PROTECTION : RECOMMENDED. CHEMICAL GOGGLES.

OTHER PROTECTIVE EQUIP: APRON-SAME MATERIAL AS GLOVES IF NEEDED.

---

**SECTION IX - SPECIAL PRECAUTIONS**

---

PRECAUTIONS TO BE TAKEN IN HANDLING & STORAGE: DO NOT FREEZE. KEEP CONTAINER TIGHTLY CLOSED WHEN NOT IN USE.

OTHER PRECAUTIONARY MEASURES: AVOID PROLONGED OR REPEATED SKIN CONTACT. AVOID EYE CONTACT. AVOID INGESTION. DO NOT SMOKE OR EAT WHEN HANDLING THIS SUBSTANCE; WASH THOROUGHLY AFTER USING. MAINTAIN GOOD HOUSEKEEPING AND HYGIENIC PRACTICES.

---

**SECTION X - WASTE LABELING INFORMATION**

---

DOT LABELING INFORMATION (49 CFR 100-199) EMERGENCY RESPONSE GUIDE NO =  
NOT HAZARDOUS PER DOT REGULATIONS

RCRA INFORMATION (40 CFR 122-124, 260-265)

HAZARDOUS WASTE NUMBERS: N/AP

HAZARD CODES: N/AP

MICHIGAN WASTE NUMBERS: N/AP

THE ABOVE INFORMATION IS BASED ON DATA PROVIDED BY SUPPLIERS. TESTING IS NOT NEEDED.

---

**SECTION XI - PREPARATION INFORMATION**

---

PREPARATION DATE: 04/18/90

DATA EFFECTIVE DATE: 02/28/90

70482

HAZARD COMMUNICATION SHEET  
PAGE 3

PART/COMMTY CD: 47-050-T204  
STANDARD: N/AV  
CONSUMER PRODUCT: ?

PREPARATION DATE: 04/18/90  
OSHA HAZARDOUS: YES  
HAZWOPER HAZARDOUS: YES

DATA SHEET PREPARED BY: INDUSTRIAL HYGIENE DEPARTMENT  
CHRYSLER CORPORATION  
PHONE: 313/956-5478

PREPARED BY: STAFF  
REVIEWED BY: STAFF  
REVISED BY:

HAZARD COMMUNICATION LABEL

PART/COMMODITY CD: 47050T204

SUPPLIER: 64781 MFG:

BRANDNAME: SYNTHETIC COOLANT ARTICOL 51

MATL ID-NO: ARTICOL 51

MFG: N/AV

EMERGENCY PHONE: 313-227-5953

N/AV

AFTER HOURS: 313-227-5953

CHRY IND HYGIEN: 313-956-5478

AFTER HOURS: 313-956-5557

HAZARDOUS INGREDIENTS: CAUSTIC POTASH

PHYSICAL HAZARD WARNING: N/AP

STABILITY: STABLE

HEALTH HAZARD DATA-EFFECTS OF OVEREXPOSURE: (<---INHALATION--->) MIST MAY PRODUCE IRRITATION OF UPPER RESPIRATORY TRACT. (<---SKIN CONTACT--->) PROLONGED CONTACT MAY PRODUCE IRRITATION. (<---EYE CONTACT--->) DIRECT CONTACT MAY PRODUCE DAMAGE TO EYE TISSUE AND SEVERE IRRITATION. (<---INGESTION--->) MAY BE HARMFUL IF SWALLOWED.

SPECIAL FIRE & EXPLOSION HAZARDS: MATERIAL DOES NOT BURN. MAY PRODUCE TOXIC THERMAL DECOMPOSITION PRODUCTS. REACTS VIOLENTLY WITH OXIDIZERS. REACTS VIOLENTLY WITH STRONG ACIDS. SPONTANEOUS HEATING MAY OCCUR IN RAGS, INSULATION, OR TRASH SOAKED WITH THIS MATERIAL AND EXPOSED TO AIR.

CONSULT CORRESPONDING HCS (MSDS)  
FOR FURTHER INFORMATION

**APPENDIX B**

---

**METHODS OF INVESTIGATION**

## METHODS OF INVESTIGATION

The boring was installed using hollow stem auger techniques. Utility clearances and access to the drilling site was confirmed with Chrysler Corporation prior to any site activities. All boring tools were steam cleaned off site prior to site drilling. All soil cuttings were drummed and labeled in the field

Soil samples were collected continuously using split-spoon sampling in accordance with ASTM Method D1586-84 in order to characterize subsurface conditions. The boring was logged and soil described in the field via ASTM Method D-2488-90.

One groundwater sample was collected from laboratory analysis using Hydropunch II techniques. The Hydropunch was driven to the estimated depth of groundwater (9 feet). Groundwater was then pumped using a peristaltic pump and tubing.




Soil and groundwater samples collected for laboratory analysis were submitted to Chrysler laboratory. All samples collected for laboratory analysis were placed in laboratory-supplied sample containers, preserved with laboratory-supplied preservative, as appropriate, and immediately placed on ice for delivery under chain-of-custody to the laboratory.

**APPENDIX C**


**BOREHOLE LOG AND ABANDONMENT FORM  
EP-1**



Facility/Project Name <b>Chrysler Corporation</b>			License/Permit/Monitoring Number		Boring Number <b>EP-1</b>	
Boring Drilled By (Firm name and name of crew chief) <b>Midwest Engineering Services, Inc. Ed Weiberg, Jeff Turczyn</b>			Date Drilling Started <b>12/4/93</b>		Date Drilling Completed <b>12/4/93</b>	Drilling Method <b>HSA 3.25" ID</b>
DNR Facility Well No.	WI Unique Well No.	Common Well Name	Final Static Water Level Feet MSL		Surface Elevation Feet MSL	Borehole Diameter <b>7.0</b> Inches
Boring Location State Plane <b>SW 1/4 of SE 1/4 of Section 36 T 2 N,R 22 E</b>			Lat <b>0 1 "</b>	Local Grid Location (If applicable)		E <input type="checkbox"/>
			Long <b>0 1 "</b>	Feet <input type="checkbox"/> S	Feet <input type="checkbox"/> W	
County <b>Kenosha</b>			DNR County Code <b>30</b>	Civil Town/City/ or Village <b>City of Kenosha</b>		

Sample Number	Length (in) Recovered	Blow Counts	Depth In Feet	Soil/Rock Description And Geologic Origin For Each Major Unit	U S C S	Graphic Log	Well Diagram	PID/FID	Soil Properties					RQD/ Comments	
									Standard Penetration	Moisture Content	Liquid Limit	Plastic Limit	P 200		
			0-1.0	CONCRETE.											
1	20	11 14 9 15	1.0 1.5 2.0 2.5	1.0-5.0 feet SAND, trace gravel, fine to medium grained, dark yellowish brown (10 YR 3/6), to very dark brown (10 YR 2/2), to black (10 YR 2/1), loose, no odor, dry.	SW				23						
2	20	13 10 8 6	3.0 3.5 4.0 4.5						18						
3	18	3 3 4 4	5.0 5.5 6.0	5.0-7.0 feet CLAYEY SILT, grading to SILTY CLAY, medium plastic, very dark grayish brown (2.5 YR 3/2), to grayish brown (2.5 YR 5/2), loose, slight sulfuric odor, damp to	CL ML				7						

I hereby certify that the information on this form is true and correct to the best of my knowledge.

Signature 	Firm <b>TRIAD ENGINEERING INCORPORATED</b> Milwaukee, Wisconsin Tel: 414 291 8840, Fax: 414 291 8841
--	---

This form is authorized by Chapters 144, 147 and 162, Wis. Stats. Completion of this report is mandatory. Penalties: Forfeit not less than \$10 nor more than \$5,000 for each violation. Fined not less than \$10 or more than \$100 or imprisoned not less than 30 days, or both for each violation. Each day of continued violation is a separate offense, pursuant to ss 144.99 and 162.06, Wis. Stats.



All abandonment work shall be performed in accordance with the provisions of Chapters NR 111, NR 112 or NR 141, Wis. Admin. Code, whichever is applicable. Also, see instructions on back.

<b>(1) GENERAL INFORMATION</b>		<b>(2) FACILITY NAME</b>	
Well/Drillhole/Borehole Location	County <b>KENOSHA</b>	Original Well Owner (If Known)	
SW 1/4 of SE 1/4 of Sec. <b>36</b> ; T. <b>2</b> N. R. <b>22</b> <input checked="" type="checkbox"/> E. <input type="checkbox"/> W. (If applicable)		Present Well Owner <b>Chrysler Corporation</b>	
Gov't Lot	Grid Number	Street or Route <b>5555 30th Avenue</b>	
Grid Location _____ ft. <input type="checkbox"/> N. <input type="checkbox"/> S., _____ ft. <input type="checkbox"/> E. <input type="checkbox"/> W.		City, State, Zip Code <b>Kenosha, Wisconsin, 53144</b>	
Civil Town Name		Facility Well No. and/or Name (If Applicable)   WI Unique Well No. <b>EP-1</b>   _____	
Street Address of Well <b>5555 30th Avenue</b>		Reason For Abandonment <b>Completed sampling</b>	
City, Village <b>Kenosha</b>		Date of Abandonment <b>12/4/93</b>	

<b>WELL/DRILLHOLE/BOREHOLE INFORMATION</b>		<b>(4) Depth to Water (Feet)</b> <u>9.35</u>	
<b>(3) Original Well/Drillhole/Borehole Construction Completed On</b> (Date) <u>12/4/93</u>		<input type="checkbox"/> Pump & Piping Removed? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Applicable <input type="checkbox"/> Liner(s) Removed? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Applicable <input type="checkbox"/> Screen Removed? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Applicable <input type="checkbox"/> Casing Left in Place? <input type="checkbox"/> Yes <input type="checkbox"/> No If No, Explain _____	
<input type="checkbox"/> Monitoring Well <input type="checkbox"/> Water Well <input type="checkbox"/> Drillhole Borehole	Construction Report Available? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Was Casing Cut Off Below Surface? <input type="checkbox"/> Yes <input type="checkbox"/> No Did Sealing Material Rise to Surface? <input type="checkbox"/> Yes <input type="checkbox"/> No Did Material Settle After 24 Hours? <input type="checkbox"/> Yes <input type="checkbox"/> No If Yes, Was Hole Retopped? <input type="checkbox"/> Yes <input type="checkbox"/> No	
Construction Type: <input checked="" type="checkbox"/> Drilled <input type="checkbox"/> Driven (Sandpoint) <input type="checkbox"/> Dug <input type="checkbox"/> Other (Specify) _____	Formation Type: <input type="checkbox"/> Unconsolidated Formation <input type="checkbox"/> Bedrock	<b>(5) Required Method of Placing Sealing Material</b>	
Total Well Depth (ft.) <u>10</u> Casing Diameter (ins.) <u>NA</u> (From ground surface)	Casing Depth (ft.) _____	<input checked="" type="checkbox"/> Conductor Pipe-Gravity <input type="checkbox"/> Conductor Pipe-Pumped <input type="checkbox"/> Dump Bailer <input type="checkbox"/> Other (Explain) _____	
Was Well Annular Space Grouted? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown If Yes, To What Depth? _____ Feet		<b>(6) Sealing Materials</b> For monitoring wells and monitoring well boreholes only	
		<input type="checkbox"/> Neat Cement Grout <input type="checkbox"/> Sand-Cement (Concrete) Grout <input type="checkbox"/> Concrete <input type="checkbox"/> Bentonite Pellets <input type="checkbox"/> Clay-Sand Slurry <input type="checkbox"/> Granular Bentonite <input type="checkbox"/> Bentonite-Sand Slurry <input type="checkbox"/> Bentonite - Cement Grout <input checked="" type="checkbox"/> Chipped Bentonite	

(7) Sealing Material Used	From (Ft.)	To (Ft.)	No. Yards, Sacks Sealant or Volume	(Circle One)	Mix Ratio or Mud Weight
<b>QUICK SET CONCRETE</b>	Surface	0.67	0.25		
<b>BENTONITE CHIPS</b>	0.67	10.	3.0		

(8) Comments: \_\_\_\_\_

**(9) Name of Person or Firm Doing Sealing Work**  
**Ed Weiberg, Midwest Engineering Services, Inc.**  
 Signature of Person Doing Work \_\_\_\_\_ Date Signed \_\_\_\_\_  
 Street or Route \_\_\_\_\_ Telephone Number \_\_\_\_\_  
**205 Wilmont Drive** (414) 521-0125  
 City, State, Zip Code \_\_\_\_\_  
**Kenosha, WI 53101**

**(10) FOR DNR OR COUNTY USE ONLY**

Date Received/Inspected	District/County
Reviewer/Inspector	<input type="checkbox"/> Complying Work <input type="checkbox"/> Noncomplying Work
Follow-up Necessary	

**APPENDIX D**  
**LABORATORY RESULTS**

To: L. Fasano

January 18 ,1994

From: R.C. Eberhardt

Laboratory

6416

Subject: Coolant Concentration Checks  
Dept 816 Storm Sewer Samples

Below are the results of BenCyn's coolant concentration checks of the pump discharge from the dead-headed Dept 816 storm sewer.

<u>Date</u>	<u>Concentration</u>
08/18/93	2.1%
08/19/93	1 %
08/24/93	4.0%
08/26/93	4.1%
08/27/93	3.5%
08/30/93	2.0%
12/01/93	3.2%
12/03/93	3.2%
12/07/93	2.0%
12/09/93	2.0%
12/14/93	3.8%

Since 12/20

0 Samples have been "clear,"  
and shown no evidence of  
coolant.

*R.C. Eberhardt*

R.C. Eberhardt

To: L. Fasano

January 18, 1994

From: R.C. Eberhardt

Laboratory

6416

Subject: Dept 816 Storm Sewer  
Sample of 01/13/94

Introduction:

At your request, on January 13, 1994, Einar Jensen and I took a sample of the water in the dead-headed storm sewer running through Dept 816. We got the sample out of the hose end of the pump discharge after allowing the pump to run for approximately one minute. (The pump was off when we got there.)

The sample was hazy, but basically transparent, and had a pale, light green color.

Conclusion:

Based on the physical appearance of the sample and the lab tests run, it does not appear that the storm sewer sample taken contains coolant from System #1.

Procedure:

The sample was analyzed by running the following lab coolant concentration type tests :

1. pH
2. Refractive Index
3. Alkaline titration with 0.1N NaOH to a methyl orange end point.

Results:

The test results are summarized below:

<u>Sample</u>	<u>pH</u>	<u>Refractive Index</u>	<u>Titration ml NaOH</u>
Sewer Sample	7.8	0.2	0.4
0.4% Articool 51, Lab solution*	9.1	0.4	1.1

\* Articool 51 is the coolant in Sys #1 and is normally run at 5%. 0.4% was the reference for the ground water sample

*R. C. Eberhardt*  
R.C. Eberhardt

## WATER SAMPLING FIELD DATA SUMMARY

Project Name: Chrysler Corporation—Engine Plant	Project Number:	W943163.005
Location: Kenosha, Wisconsin		
Field Equipment:	pH:	Schott Model 819, Serial # 9002—0728
	Conductivity:	Hanna Instruments H18733
	Temperature:	Thermometer
	Alkalinity:	—
	Other:	—

### Sampling and Field Measurement/Observation

Sample Location Identification:	Outfall 001		
Water Type	Storm Water		
Date	1/13/94 9:31 a.m.		
Sampled by	L. Stanton		
Reference Elevation (Top of riser etc.)	—		
Measured Depth to Water (ft.)	—		
Measured Well Depth (ft.)	—		
Purging/Sampling Device(s)	—		
Well Casing Volumes/Gallons Purged	—		
Well Purged Dry? (Y/N)	—		
Time Purging Completed (Military)	—		
Time Sample Withdrawn (Military)	—		
Field Temperature (degrees C)	22° C		
Field Conductivity: Measured (u mhos/cm)	319		
Field Conductivity @25 degrees C (u mhos/cm)	—		
pH (std. units)	7.52		
Alkalinity (mg/l)	—		
Color	Yellowish milky—like color		
Odor	Same as plant		
Turbidity	—		
Other	Small amount of oil floating on top of samples		

### Sampling Container and Presentation Information

Sample Parameter(s)	Alkalinity		
# Of Containers & Volume	—	Note: Sampled off bottom of manhole. Pumped dry when sampled.	
Container Type (amber glass, clear glass, plastic etc.)	—		
Filtered/Unfiltered	Unfiltered		
Preserved/Unpreserved/Type	Unpreserved		
Refrigerated/on Ice	On ice		

### Shipping Information

Laboratory	Chrysler Lab		
Date Submitted	1/13/94		
Chain of Custody Number	—		
Courier Shipping Number/Hand Delivered etc.	H.D.		

To: J. Bugno

December 20, 1993

From: R.C. Eberhardt

Laboratory

6416

Subject: Ground Water and Soil  
Sample Analysis

### Introduction:

On December 6, 1993, Triad Engineering submitted a soil sample and two ground water samples for analysis to determine if either type showed contamination by Articool 51 synthetic coolant. The samples had been taken on December 4, 1993 and were stored in an ice filled insulated container.

The two ground water samples were both clear and colorless with some sediment on the bottom of the bottles; the soil sample was dark in color, had a mostly sandy texture, and contained small, smooth stones.

### Conclusion:

The lab test results do not indicate that either the ground water or soil sample is contaminated with Articool 51 coolant. While the ground water sample showed some response to the methyl orange titration, there are many natural sources that could be responsible.

### Procedure:

#### Water Extraction of Soil Sample -

A water extraction of the soil sample was performed in the following manner -

1. 110 g of well mixed soil was put into a 600 ml beaker.
2. 400 ml of deionized water was added.
3. Covered beaker placed on hot plate and contents heated, with regular stirring, to 60 - 65 C and held there for 1 1/2 hour.
4. Beaker removed from hot plate and contents allowed to cool to room temperature, stirred occasionally.



Analysis of All Water Samples -

The following standard lab coolant concentration type tests were run on the ground water sample and water extract of the soil sample:

1. pH
2. Refractive index
3. Titration of a 10 ml aliquot with 0.1 N NaOH to a methyl orange end point.

In addition, a standard freon oil and grease gravimetric extraction was also performed on the samples. If there were significant coolant contamination of the samples, the isolated residues could be analyzed by infrared spectroscopy to confirm identity.

Results:

<u>Sample</u>	<u>pH</u>	<u>Refractive Index</u>	<u>Methyl Orange Titration</u>	<u>Freon Oil &amp; Grease Extraction</u>
Ground water	7.2	0.3	1.1 ml	2 mg/l
Soil Extract	7.4	0.2	0.15 ml	--
Tap Water	7.5	0.2	0.25 ml	0 mg/l
0.4% Articool 51 Solution - lab prepared	9.1	0.4	1.1 ml	40 mg/l

The freon oil and grease residue isolated from the 0.4% Articool 51 sample was analyzed by infrared spectroscopy. The ground water sample gave a trace response, but there was insufficient for an infrared analysis.

*R. C. Eberhardt*

R.C. Eberhardt

Copy to: ~~Triad~~ Engineering  
L. Fasano  
L. Jurca

# WATER SAMPLING FIELD DATA SUMMARY

Project Name: Chrysler Corporation—Engine Plant	Project Number:	W943163.005
Location: Kenosha, Wisconsin		
Field Equipment:	pH:	Schott Model 819, Serial # 9002—0728
	Conductivity:	Hanna Instruments H18733
	Temperature:	Thermometer
	Alkalinity:	—
	Other:	—

## Sampling and Field Measurement/Observation

Sample Location Identification:	EP—1	EP—1		
Water Type	Groundwater	Groundwater		
Date	12/04/93	12/04/93		
Sampled by	R. Binder	R. Binder		
Reference Elevation (Top of riser etc.)	Ground	Ground		
Measured Depth to Water (ft.)	9.35	9.35		
Measured Well Depth (ft.)	10.0	10.0		
Purging/Sampling Device(s)	Hydropunch II	Hydropunch II		
Well Casing Volumes/Gallons Purged	—	—		
Well Purged Dry? (Y/N)	N	N		
Time Purging Completed (Military)	—	—		
Time Sample Withdrawn (Military)	1100	1100		
Field Temperature (degrees C)	22 degrees	22 degrees		
Field Conductivity: Measured (u mhos/cm)	1259	1184		
Field Conductivity @25 degrees C (u mhos/cm)	—	—		
pH (std. units)	7.07	6.86		
Alkalinity (mg/l)	—	—		
Color	light brown	clear		
Odor	none	none		
Turbidity	Turbid	clear		
Other	Silt/sand sdmt	—		

## Sampling Container and Presentation Information

Sample Parameter(s)	Alkalinity	Alkalinity		
# Of Containers & Volume	1—500 mls	1—500 mls		
Container Type (amber glass, clear glass, plastic etc.)	plastic	plastic		
Filtered/Unfiltered	unfiltered	unfiltered		
Preserved/Unpreserved/Type	unpreserved	unpreserved		
Refrigerated/on Ice	on ice	on ice		

## Shipping Information

Laboratory	Chrysler Lab	Chrysler Lab		
Date Submitted	12/06/93	12/06/93		
Chain of Custody Number	—	—		
Courier Shipping Number/Hand Delivered etc.	Hand Delivered	Hand Delivered		

**TRIAL ENGINEERING INCORPORATED  
CHAIN OF CUSTODY RECORD**

N/A

Project Name: Triad project no. W943143  
 Project Manager: Rick Binder  
 Samplers: Rick Binder  
Jeanne Rampone  
 Date Needed: \_\_\_\_\_

Field Filtered (y/n)	✓					
Preservative	✓					
Refrigerated (y/n)						

Sample Type  
(Soil, Groundwater, Wastewater, Solid Waste)

Sample ID	Date	Time	Comp	Grab	Location/Description	No. of Containers	Analysis For Coolant (Alkaline)	Titration Method												
EP-1	12/4/93	1100		✓	EP-1	2													groundwater	
EP-2	12/4/93	1002		✓	EP-2, 3-5 feet	1													soil	

Sample Condition : \* Coolant Manufacture I.D. - Articool 51  
 description: cutting oil Benzyn Lubricant Articool 51 synth. for ferrous (MSDS)

**Triad Engineering Incorporated**  
 325 E. Chicago Street  
 Milwaukee, Wisconsin 53202  
 Telephone: (414) 291-8840  
 FAX: (414) 291-8841

RELINQUISHED BY: <i>Jeanne Rampone</i>	Date 12/6/93	Time	RECEIVED BY: <i>R. Eberhardt</i>	Date 12/6/93	Time 2:30p
RELINQUISHED BY:	Date	Time	RECEIVED BY:	Date	Time
RELINQUISHED BY:	Date	Time	RECEIVED BY:	Date	Time

DEC 6 '93 15:48 MIL MFG ENGDLING LF PAGE.02

**APPENDIX E**

**VOLUME OF RECOVERED LIQUID  
DATA, STORM SEWER**

**VOLUME OF LIQUID RECOVERED  
FROM STORM SEWER**

Date	Gallons
7/22	1,000
7/23	1,400
7/24	1,000
7/25	6,000
7/26	2,500
7/27	1,900
7/28	1,500
7/29	1,000
7/30	1,500
7/31	1,000
8/1	2,000
8/2	1,500
8/3	1,500
8/4	1,500
8/5	1,000
8/6	1,000
8/7	1,000
8/8	1,500
8/9	1,500
8/10	1,500
8/11	1,000
8/12	1,000
8/13	1,000
8/14	500
8/15	500
8/16	2,000
8/17	1,500
8/18	1,500
8/19	1,900
8/20	1,500
8/21	500
8/22	500
8/23	2,000

Date	Gallons
8/24	500
8/25	500
8/26	1,000
8/27	1,000
8/28	500
8/29	1,500
8/30	1,500
8/31	2,000
9/1	1,750
9/2	1,500
9/3	1,750
9/4	1,500
9/5	500
9/8	500
9/9	500
9/10	1,000
9/11	500
9/12	500
9/13	500
9/14	1,000
9/15	2,100
9/16	1,500
9/17	1,000
9/18	1,500
9/19	500
9/20	500
9/21	500
9/24	1,000
9/25	500
9/26	500
9/28	500
9/29	1,000
9/30	1,000

Date	Gallons
10/1	500
10/2	500
10/3	500
10/5	500
10/18	500
10/19	500
12/1	500
12/2	1,500
12/3	100
12/4	500
12/5	1,500
12/6	1,500
12/7	100
12/8	500
12/9	1,000
12/10	500
12/11	500
12/12	500
12/16	500
12/18	500
12/19	500
12/20	1,000
12/22	500
12/23	500
12/27	500
12/29	500
1/3	500
1/4	500
1/5	500
1/6	1,000
1/7	500
1/8	500
1/11	500