

4/1/86

RCRA PRELIMINARY ASSESSMENT
NARRATIVE SUMMARY

SITE NAME: Freeman Chemical Company

EPA ID. NO.: WID 980615439

LOCATION: Railroad Street
Saukville, Ozaukee County, Wisconsin

OVERVIEW: Freeman Chemical Company ^{manufactures} alkyd, polyester, and urethane synthetic resin at the Saukville Plant. The resins are used in paints and varnishes, in molded polyester parts, and for insulation ^{and sealing} materials ^{recycling}. The plant has been operating since 1948, and has periodically been expanded. Attachment 1 is a general location map of the facility.

From 1952-65, waste reaction acid water was discharged to ^a shallow seepage pit. Upon closure, the pit was filled and is currently covered with asphalt. No chemical analysis of the reaction water is available ^{from years} for the ^{time of} waste water discharge to the seepage pit. Sampling of the reaction water performed in 1981 showed the waste water contained 27 ppm ethyl benzene, 110 ppm toluene, and 55 ppm phenol. ^{Evaporation} ~~Incineration~~ of this waste ^{in an incinerator} began in 1965.

Freeman Chemical has submitted several different RCRA Part B permit applications, ^S because of changes in hazardous waste storage and incineration proposals. The most recent Part B application was received by the Wisconsin

Department of Natural Resources (WDNR) on January 15, 1986. This Part B proposes storage and incineration of 625,000 gallons of F003 wastes and ~~one~~ ^(spent non-halogenated solvents, including xylene and ethyl benzene) million of D001 wastes ^(ignitable) per year. The Part B application will not be reviewed by WDNR because Wisconsin has received final authorization for its hazardous waste management program. A Feasibility Report and Plan of Operation for hazardous waste incineration and a Feasibility Report for hazardous waste storage were called in by WDNR on December 12, 1985, and are due by June 30, 1986. Freeman Chemical has been operating under a WDNR interim license since December 6, 1985. The license ^{and} allows storage of hazardous waste in 200 drums, one-40 ^{cu. yd.} ~~cu. yd.~~ ^{box} lugger, one-7,200 gallon tank, and one-12,000 gallon tank, and permits incineration of F003 and D001 wastes.

Freeman Chemical was notified of its corrective action responsibilities under HSWA by EPA in a letter dated April 22, 1985. ^{EPA received} ^{Chemical} A response from Freeman ~~was~~ ^{reported} received ~~by EPA~~ on June 20, 1985. The response ~~indicated~~ the presence of the previously mentioned seepage pit and associated releases of reaction water and spent solvents from this pit. An initial screening by WDNR found that Freeman Chemical was environmentally significant. WDNR prepared a facility management plan for Freeman ^{Chemical}. The initial screening and facility management plan were transmitted to EPA on July 26, 1985.

Five different waste streams are generated on site:

1. Solvents: Rinse solvent, consisting of xylene and other hydrocarbons, and process solvents, including xylene and toluene. These waste solvents are blended and incinerated (F003 and D001).
2. Reaction Water: This waste is generated during resin production and includes the solvents toluene ^{ethyl benzene,} and xylene (D001).
3. Clean up Wastes (U-listed waste): Produced by small spills of U-listed

waste throughout the plant. These hazardous wastes are disposed of off site.

and filter cake

4. Waste Resins (F001): Test samples ~~and~~ rejected resins.
5. Incinerator Ash: The ash from the present incinerator is disposed of off site. The proposed incinerator will burn only liquids and will not generate ash.

Groundwater contamination has been documented that this facility and in the Village of Saukville. In 1979, municipal well #2 was disconnected from the public water supply, because organic compounds such as benzene, toluene, trichloroethylene, and xylene were detected. Freeman Chemical is believed to be one of the sources of this contamination. Another source of the contamination, particularly the trichloroethylene, is believed to be from spills at the Laubenstein property, west of Freeman Chemical. A 1985 hydrogeologic study by Hatcher Incorporated details the extent of contamination and provides recommendations for remedial action. Specific conclusions and recommendations of the report are discussed later in this narrative.

UNIT DESCRIPTION :

Incineration: Two separate incinerators are currently in use for solid incineration and solvent-acid water incineration. A new liquid injection incinerator was proposed in the most recent Part B application. This incinerator will only burn waste solvents and reaction water. Reaction water has occasionally been spilled at the current incinerator location. The amount of waste released is unknown.

Tank Storage: Several tanks currently store reaction water and waste solvent

prior to incineration. The tanks are above ground and are located inside a building. Three underground tanks have been used for storage of gasoline, diesel fuel, and caustics (see attached^{ment} 2 for location of tanks). The

proposed incinerator will use six storage tanks, each with an 8,500 gallon capacity ~~for waste management~~. Releases from tanks or during loading and unloading ~~may have occurred, but have not been documented~~. ^{probably}

Container Storage: Barrel storage historically has been scattered throughout the facility. However, it is not known if all of the barrel storage areas stored hazardous waste. Small releases have been reported from these areas in the Hatcher investigation. Containerized hazardous wastes currently are stored adjacent to the present incinerator. The most recent Part B proposes to store hazardous waste for less than 90 days in a warehouse separated from the incinerator.

Seepage Pit: From 1948 to 1952, waste reaction water was charged directly to the Milwaukee River. Beginning in 1952, and continuing until 1965, reaction water was discharged to a seepage pit located on the west end of the facility (see attachment 2). The exact location of this pit has not been determined and the site is presently covered by asphalt. The pit may have extended down to the top of the dolomite, which is about 15 feet ^{below the surface} thick in this area.

POLLUTANT DISPERSAL: The primary pollutant dispersal pathway is via movement of water in the subsurface through the unsaturated zone and below the water table. Detailed information on hydrogeology ^{is} presented in the February 1986 Hatcher report. Bedrock at the site consists of the Niagara dolomite, which also serves as a local aquifer. Surficial glacial deposits covering the dolomite average about 15 feet thick (see attachment 3) and consists of soil or ~~fill~~, silty sand, dense clay, and glacial till.

Attachment 4 shows a water table map for summer 1985. Groundwater flow was

generally to the south ^{toward the Milwaukee River}. However, along the west property boundary ^x groundwater flow was westward. Attachment 5 is a map showing groundwater head values within the dolomite aquifer. A local groundwater high is present ~~at~~ ^{below} the facility ^{in the dolomite, with} causing radial groundwater flow away from ^{the high} this facility. Attachment 6 shows a difference in head between the water table and the dolomite aquifer. The difference is smallest in the area of the groundwater mound. However, at all locations the head in the dolomite is less than in the glacial deposits, indicated that downward movement of groundwater is occurring and that the area serves as a recharge zone.

KNOWN OR SUSPECTED RELEASES: ^P Accidental spillage of waste streams, resins, and raw materials have occurred at Freeman Chemical throughout the life of the facility. Attachment 2 shows the facility layout and the potential sources of groundwater contamination.

The seepage pit that operated from 1952-65 is a source of known releases of reaction water. This pit may have provided a direct conduit for hazardous constituents to reach the dolomite. Other known releases include spills of reaction water at the incinerator site, at least one underground pipeline leak, ^{and} product and raw materials ^{spills} at the railroad siding. It is suspected that releases have occurred in numerous barrel storage areas and at the tank sites. The Interim Remedial Investigation Report by Hatcher Incorporated notes that at least one of the buildings has a sump that is constructed at or close to the top of the dolomite, which could provide a pathway for contamination. In addition, at least two tanker spills have occurred at the tanker parking areas. These spills resulted in overland flow of Freeman property and onto a school yard to the north. Freeman responded by removing sod and excavating soil.

Groundwater contamination has been well documented at the Freeman Chemical site. Attachment 7 shows the location of monitoring wells at the facility.

An odor survey of the glacial deposits performed during augering and coring yielded the results displayed in Attachment 8. The five areas of strongest odor are located near the (1) tank farm; (2) off site in school yard area ^(associated with tanker spills); (3) near several buried tanks; (4) at the site of the seepage pit; (5) and in the extreme southwest corner of the property, near the train tracks and ~~in~~ ^a container storage area.

Chemical analyses of groundwater samples taken in November 1985, showed that contamination in the glacial deposits is greatest west of the line connecting shallow piezometers ~~5, 6, 7, 8, and 16.~~ ^{4a} 7, 8, and 16. These piezometers showed either no contamination or trace amounts of ~~methy~~ ^{methylene} chloride. Within the zone of high contamination, shallow piezometer 6a showed high levels of toluene, ethyl benzene, benzene, trans-~~one,~~ ^{1, 2} dichloroethylene, and shallow piezometer 14a had high levels of xylene and ethyl benzene. To the west of the site, near the Laubenstein warehouse, high concentrations of trichloroethylene ~~were~~ ^{found} detected in shallow wells, in addition to ~~some of the organics detected on-site~~ ^{detects of} some of the organics ~~detected on-site~~ ^{found}.

organic chemicals present

at Freeman ^{chemical} The trichloroethylene is not believed to originate from Freeman, because ~~the use of the solvent is reported not to have occurred at Freeman.~~ ^{Freeman Chemical reports that trichloroethylene has never been used at its facility} ~~at its facility~~ ^{at its facility}

However, reports indicate that trichloroethylene has been previously used at the Laubenstein property ^{during operation of the Northern Signal Co.}

Contamination is present in all the upper dolomite piezometers, except Well 22. the highest level of contamination is found in Well 21, which showed high levels of benzene, toluene, and ethyl benzene, and private Well 8, which has a very high level of trichloroethylene (2000 ug/l) and lesser amounts of other volatile organics.

A pump test on private Well 8, which extends into the deep dolomite aquifer, indicated that trichloroethylene is present in the deep aquifer in this area. Trichloroethylene was continuously detected over the entire five ^{day} ~~to eight~~ test period.

→ Operator: Please add ① - attached

RECOMMENDATIONS: WDNR believes that corrective action needs to be taken at Freeman Chemical. Several preliminary recommendations for remedial action have been proposed in the Hatcher report. The three goals proposed are: control of present contamination sources; decontamination of soil and groundwater through in-situ treatment; and limiting the off site migration of contaminated groundwater. To control present contaminations sources, Hatcher proposes the following action: removal of unused buried tanks; excavation of ^{the} seepage pit; modification of all ~~forest slumps~~ ^{floor sumps} to protect against spills, removal of the existing tank farm and removal ^{or} of flushing of all buried raw material pipes; paving of all locations at the site where spills are likely to occur ^{and} appropriate collection ^{and} analysis of run/off (a WPDES plan review is in progress for this proposal); construction of a new tank farm with spill control; and sealing of an old on-site well.

For prevention of pollutant migration in the glacial deposits, Hatcher proposed that the sediments be dewatered using three PVC Ranny drains (see attachment 9). Attachment 10 shows the proposed location of these drains. The collected water will be air stripped of volatiles and discharged to the local POTW. It is estimated that eight ^{gpm} ~~gpm~~ will be collected with this design.

To control pollutant migration in the dolomite aquifer, Hatcher proposes to pump water from wells in the upper dolomite and air strip the extracted water before using it as cooling water. In addition, to reverse groundwater flow away from the municipal wells, Hatcher recommends that municipal wells #1 and #2 be removed from service indefinitely and that one or more deep dolomite wells on or near the site be pumped. This water will be used as cooling water and will replace water currently taken from municipal well #2.

Municipal well #3, which is currently shut down due to ~~reason~~ faulty well casing, should be recased and returned to service to replace the loss of well #1. WDNR tentatively supports the recommendations for remedial action proposed by of well #1.

Hatcher Incorporated, subject to completion of the Department's review. WDNR also recommends that a RCRA consent agreement be drafted and signed to insure that the appropriate remedial action is carried out.

62700

4/1/86

CONTACTS:

Freeman Chemical Co.

Russell L. Cerk
(414) 284-5541

Lee W. Barwick, Plant Manager
(414) 284-5541

Roger Hatcher, Ph.D., Consultant
(804) 320-0193

CONTACTS:

Wisconsin Department of Natural Resources

Theresa Evanson, Hydrogeologist
Bureau of Solid Waste Management
(608) 266-0941

Gary Edelstein, Environmental Engineer
Bureau of Solid Waste Management
(608) 267-7563


Catherine Hoy
Southeast District
(414) 562-9640

John Krahlung, Hydrogeologist
Southeast District
(414) 562-9677


① TARGET POPULATION:

Freeman Chemical is located within the Village of Souleville. The 1985 population estimate by the Wisconsin Department of Administration is 3631. Souleville takes all of its water from the Niagara dolomite aquifer. The wells extend down to about 500 feet of depth. Municipal well #2 has not been used for drinking water since 1979, due to ^{the} volatile organic contamination discussed previously. Wells #1 and #4 are currently supplying the village with drinking water. See attachment 1 for the location of the municipal wells.


Attachment 1
 Location Map showing
 Freeman Chemical Co.
 and Municipal wells.



SCALE 1:24,000




CONTOUR INTERVAL 10 FEET
 NATIONAL GEODETIC VERTICAL DATUM OF 1929



UTM GRID AND 1976 MAGNETIC NORTH
 DEFINITION AT CENTER OF SHEET

Attachment 2



- 1 BARREL STORAGE AREAS
- 2 BURIED INCINIRATOR LOCATION (?)
- 3A OLD FARM WATER WELL
- 3B OLD DRY WELL (*Seepage Pit*)
- 4A BURIED CAUSTIC TANK
- 4B BURIED DIESEL TANK (?)
- 4C BURIED TANK (?)
- 5 TANK FARM
- 6 BASEMENT SUMP
- 7 PRESENT INCINERATOR
- 8 LOCATION OF FORMER TANKS
- 9 UNDERGROUND ROUTE OF "ACID H₂O" LINE
- 10 BROKEN LINSEED (?) OIL LINE
- 11 PIT FOR TANK SCALES
- 12 TRUCK WASHING AREA
- 13 ACID WATER & OTHER PRODUCT SPILL AREAS
- 14 STORM SEWER
- 15 TANKER PARKING AREAS

FIGURE 17
SOME POTENTIAL SOURCES OF
GROUNDWATER CONTAMINATION

1" = ± 145'

Attachment 3





FIGURE 10
THICKNESS OF
GLACIAL OVERBURDEN
ISOPLETH MAP
1" = ±130


Attachment 4



Arrows added by WDNR

Job No.: 0001-003	Hatcher Incorporated	Date: February 1986	Water Table Map	
		Scale: 1" = ±182'	Drawing No.:	Figure No.: 13
	RICHMOND, VIRGINIA			

Attachment 5



LEGEND


- WATER LEVEL CONTOUR
- - - GROUNDWATER DIVIDE
- DATA POINT

Direction of groundwater flow

Arrows added by WDNR

Job No.: 0001-003	Hatcher Incorporated RICHMOND, VIRGINIA	Date: February 1986	DOLOMITE CONSOLIDATED WATER LEVEL MAP—SUMMER 1985	
		Scale: 1" = ± 182'	Drawing No.:	Figure No.: 15

Attachment 6



Job No.: 0001-003

Hatcher Incorporated

RICHMOND, VIRGINIA

Date: February 1986


Scale: 1" = ±130'

Difference in Head Between Water Table And Dolomite Aquifer

Drawing No.:

Figure No.: 16

Attachment 7



- LEGEND**
- PIEZOMETER ELIMINATED
 - ORIGINAL SHALLOW PIEZOMETER (PRIOR TO 7-1-85)
 - ▲ NEW DOLOMITE PIEZOMETER
 - NEW SHALLOW PIEZOMETER
 - MUNICIPAL WELL
 - ▲ PRIVATE WELL
 - NEW DEEP PIEZOMETER

Job No.: 0001-003

Hatcher Incorporated
RICHMOND, VIRGINIA

Date: February 1986
Scale: 1" = 200'

Location Of Decommissioned And Other Monitoring Wells
Drawing No.: _____ Figure No.: 1




FIGURE 18
ODOR CONCENTRATION, GLACIAL
SEDIMENT, PLAN VIEW

1" = ±152'

Attachment 9





FIGURE 20
PILOT FRENCH DRAIN



Attachment 10



LEGEND

- ⊗ DEEP DOLOMITE WELL
- ⊙ RANNY COLLECTOR SYSTEM
- ⊙ UPPER DOLOMITE AQUIFER SCAVAGING WELL
- LARGE DIAMETER WELL

FIGURE 23

**LOCATION OF RECOMMENDED
REMEDIAL INSTALLATIONS**

1" = ± 165'