## Royal Scott S.D.

## New Franken, Wisconsin

The Royal Scott S. D. STP discharges through a polishing pond to a man-made pond located on the adjacent golf course. Except for wet periods during the year the golf course pond does not have a discharge. When a discharge does occur, the effluent from the pond enters a man-made drainage ditch which flows into Vincent Point Creek. The Creek is also dry for most of the year. Any flow in the Creek that reaches the area near the center of Section 8 disappears in a crevice in the limestone bedrock. We do not know if the crevice is capable of handling volumes encountered during spring runoff.

## Recommendations

The ditch from the golf course pond to Vincent Point Creek should be classified as a drainage ditch. Vincent Point Creek should be classified as non-continuous/marginal.


Dan Uhl


District Engineer

Dennis Weisensel District Biologist

DU:DW:sh

## ROYAL SCOTT S. D. - NEW FRANKEN







#2 Royal Scatt A.D.,

1 1 mile below STP

looking downstream



#1 Rayal Scott S.D.

a & mile above STP

looking upstream.

Butfall discharges to

pand an galf cause.

Pictice is taken at

pond autfall - no discharg

from pand.



# 3 Royal Scott S.D.

2 ½ mile below STP

looking downstream