for Flambeau Crowley Hydroelectric Project FERC Project #2473 Flambeau Hydro, LLC Price County, Wisconsin

Submitted by:



429 River Lane, P.O. Box 27 Amasa, Michigan 49903 Phone: 906-822-7889

Summary of Purple Loosestrife Inventory for Flambeau Crowley Hydroelectric Project, FERC #2473

On August 12, 2020, White Water Associates, Inc. performed an inventory of purple loosestrife at the Flambeau Crowley Project. The method of inventory approved and modified by a Federal Energy Regulatory Commission (FERC) Order (June 18, 2003) was defined as follows:

While purple loosestrife is blooming in mid-July to early August, the inventory should be conducted using a boat to survey the impoundment above the dam within the Project Boundary and on foot or by boat below the dam within the Project Boundary. County wetland maps may be used to determine other areas where Purple Loosestrife could be found on lands owned by Flambeau Hydro, LLC (FHLLC) within the Project Boundary. Lands owned by FHLLC within the Project Boundary will be surveyed on foot. A pair of binoculars should be used to search for the purple flowered spikes of the plant. When plants are located, the person(s) inventorying should get close enough to make a positive identification without disturbing the plants or the immediate area around the plants as this could cause them to spread. A GPS will be used to establish a GPS coordinate for the location of the plants. If it is not possible to get close enough to establish an accurate location, an approximate location will be established with reference to an established GPS coordinate. The plants should be inventoried by marking and numbering the location on a project map along with notes approximating size of plants, stand area, percent cover, stem density, plant density, and location with reference to established GPS coordinates. Photos and/or videotape will be taken of the largest occurrences.

2020 Observations

The Flambeau Crowley Project boundary was divided into three different areas; *the impoundment* (from approximately 500 feet downstream of the Pixley Dam to the Crowley Dam), *FHLLC-owned property within the project boundary* (FHLLC-owned property adjacent to the dam and powerhouse), and *the tailrace* (from the dam and powerhouse to approximately 500 feet downstream of the dam).

The impoundment was surveyed by boat and one purple loosestrife plant was found. On the south side of HWY 70 at 6 Mile Creek there were five sites that had purple loosestrife plants (Table 1). These sites were observed on foot.

The FHLLC-owned property within the project boundary was surveyed on foot and no purple loosestrife plants were found.

The tailrace was surveyed by boat and no purple loosestrife plants were observed.

Site FLCRPL008, FLCRPL010, and FLCRPL011 had 20+ plants with no treatment. FLCRPL009 had two plants that were removed. Site FLCRPL013 had one multi-stem plant. No treatment because it was


on private property. Site FLCR014 had 20+ plants across the highway past the wetland area and no plants were removed due to the location.

Maps of purple loosestrife locations observed in 2020 is available in Appendix A. Appendix B provides tables of historical purple loosestrife data as well as observations made in 2020. Appendix C provides scans of field data sheets. Appendix D provides photos taken at the project area.

Appendix A Maps



Map 1. Locations of purple loosestrife at Flambeau Crowley in 2020.



Map 2. Locations of purple loosestrife at Flambeau Crowley in 2020.



Map 3. Locations of purple loosestrife at Flambeau Crowley in 2020.

Appendix B Tables

Table 1. GPS points for purple loosestrife inventory at Flambeau Crowley, FERC#2473.								
GPS Point	Latitude	Longitude	Plant Height	Stand Area	Comments			
FLCRPL001	45.86360	-90.54765	1'-4'	~180'x25'	2002-first observed. 11 plants observed. 2003-2008-treated with herbicide. 2009-are of purple loosestrife had declined by 50% 2010-area of purple loosestrife similar, but number of plants increased. Treated with herbicide. 2011-number of plants decreased. Treated with herbicide. 2012-number of plants increased. Treated with herbicide. 2013, 2014, & 2015-plants were hand pulled. 2016-14 plants observed and pulled. 2017-1 plant observed no treatment. 2018- Multi-stem out of reach no treatment.			
FLCRPL002	45.86417	-90.54643	1'-3'	~180'x25'	2002-first observed. 11 plants observed. 2003-2008-treated with herbicide. 2009-are of purple loosestrife had declined by 50% 2010-area of purple loosestrife similar, but number of plants increased. Treated with herbicide. 2011-number of plants decreased. Treated with herbicide. 2012-number of plants increased. Treated with herbicide. 2013, 2014, & 2015-plants were hand pulled. 2016-14 plants observed and pulled.			
FLCRPL003	45.86429	-90.54673	N/A	N/A	2002-first observed. Flowering heads clipped 2003-treated with herbicide. 2004-no plants observed. 2005-1 plant observed and pulled. 2006-some plants observed. Treated with herbicide. 2007, 2008, & 2009-no plants observed. 2010-1 plant observed. Treated with herbicide. 2011-1 plant observed and pulled. 2012, 2013, 2014, & 2015-no plants observed. 2016-no plants observed.			

GPS Point	Latitude	Longitude	Plant Height	Stand Area	Comments
FLCRPL004	45.86421	-90.54690	N/A	N/A	2002-first observed. Flowering heads clipped 2003-treated with herbicide. 2004-no plants observed. 2005-1 plant observed and pulled. 2006-some plants observed. Treated with herbicide. 2007, 2008, & 2009-no plants observed. 2010-1 plant observed. Treated with herbicide. 2011-1 plant observed and pulled. 2012, 2013, 2014, & 2015-no plants observed. 2016-no plants observed.
FLCRPL005	45.86544	-90.54646	N/A	N/A	2002-first observed. Flowering heads clipped. 2003-2015-no plants observed. 2016-no plants observed
FLCRPL006	45.86356	-90.54909	N/A	N/A	2008-first observed. Plants pulled. 2009-plants observed. Plants pulled. 2010-2015-No plants observed. 2016-no plants observed.
FLCRPL007	45.86385	-90.54592	1'-3'	2'x2'	2015-first observed. No treatment. 2016-no plants observed. 2018- no treatment.
FLCRPL008 (CR PLA)	45.86396	-90.54697	3'	1'x1'	2016-first observed. 55 plants observed. No treatment. 2017-4 plants observed. No treatment. 2018-ten plants observed and pulled. 2020- 20 + no treatment.
FLCRPL009	45.86377	-90.54746	3'	1'x1'	2017-first observed. Three plants observed. No treatment. 2018- Multi-stemmed plant three by edge pulled – two plants across water no treatment. 2020- 2 plants pulled.
FLCRPL010	45.86410	-90.54667	3'	2'x2'	2017-first observed. Ten plants observed. No treatment. 2018- ~ 12 plants pulled. 2020-+15 no treatment.
FLCRPL011	45.86431	-90.54614	3'	1'x1'	2017-first observed. Three plants observed. No treatment. 2018- two plants pulled. 2020-no treatment.
FLCRPL013	45.87027	-90.54172	4'	2'x2'	First observed 2020-private property by a dock. No treatment.
FLCRPL014	45.86364	-90.54777	4'	20'x10'	First observed in 2020 – 20+ no treatment wetland area.

Appendix C Scans of Datasheets

Purple Loosestrife Survey											
Cocoley	Hydroe	electric Proje	ct – FERC # <u>ネタ</u>	73	Page 1 of 2						
Date 8-12 40 Co		/\			James						
HWL 1977 22 TWL 1407,0 CFS 1/26 Equipment Used: 13 moular camera, 6/5											
Air Temp: 62 ° Wind Speed: 55w Barometer: 30,07 Sky Conditions: 90 Clard S											
All Temp. Very Conditions. The Conditions of											
Time Survey Started 3. Time Survey Ended 5. Boat (14ft or Canoe) and/or Foot											
Latitude Start Longitude End											
Location of Survey Area: TailraceBypass ReachImpoundment FHLLC Property											
Description of Location											
Historic Info:											
	/ /		1								
Purple Loosestrife Found. Yes or No											
Information (A)											
Site Crowley A	12 013	CKPL14	# CKPUX09	FLCK 140							
Time <i>J</i>	1	1529'	1930	(160)							
Photo ID	455	436	Silve Reet	737-76	2						
Location Single or Multi-stem	Persons 1 and	wellend	Mast	JULA ROGA							
# of Plants	multi	Trans-	77101333	201							
Acreage est.	*	4 40	a,								
Stand Area Density	272'	20X 10'	272'	100 x 10°							
Size Colony			-Milan	2 0							
S=0-5, M=6-50, L=>50~	2	N.	3	W							
Plant Height ~ Ft	lef	4/2	W.	4.							
Flowering %	100%	100%	, w/o	1000							
Beetle Feeding?			<u>a</u>	#							
Plant Vigor (Very poor to	Good	Cood	Lord	Cool							
good) Plant Removed (explain)	W V	1000	1	20							
	M W	- vve	L Geo		1/						
	rund preparty	Ad duck	0	Tooman	<i>§</i>						
Information	y Joole Osles Fra	777 52.01.46									
Site											
Time											
Photo ID											
Location				· · · · · · · · · · · · · · · · · · ·							
Single or Multi-stem											
# of Plants	S. S. S.										
Acreage est.	<i>98</i>		,								
Stand Area Density											
Size Colony					•						
S=0-5, M=6-50, L=>50~											
Plant Height ~ Ft											
Flowering % Beetle Feeding?											
Plant Vigor (Very poor to											
good)											
Plant Removed (explain)											
	Other Species Observed:										

Purple Loosestrife Survey Latitude Start _____ Longitude End ______ Location of Survey Area: Tailrace ____ Bypass Reach __ Impoundment ____ FHLLC Property ____ Description of Location Historic Info: Purple Loosestrife Found: Yes or No. Information Site Time Photo ID Location Single or Multi-stem # of Plants Acreage est. Stand Area Density Size Colony S=0-5, M=6-50, L=>50~ Plant Height ~ Ft Flowering % Beetle Feeding? Plant Vigor (Very poor to good) Plant Removed (explain) Information Site Time Photo ID Location Single or Multi-stem # of Plants Acreage est. Stand Area Density Size Colony S=0-5, M=6-50, L=>50~ Plant Height ~ Ft Flowering % Beetle Feeding? Plant Vigor (Very poor to

Other Species Observed:

Plant Removed (explain)

Appendix D Photos



Photo 1. Purple loosestrife growing along roadside.



Photo 2. Purple loosestrife growing on wooded bank.



Photo 3. Purple loosestrife growing along roadside.