

## **Attachment B/Maps and Figures**

### **B.1 Location Maps**

#### **B.1.a Location Map**

#### **B.1.b Detailed Site Map**

#### **B.1.c RR Site Map**

### **B.2 Soil Figures**

#### **B.2.a Soil Contamination**

#### **B.2.b Residual Soil Contamination**

### **B.3 Groundwater Figures**

#### **B.3.a.1 Geologic Cross-Section Map**

#### **B.3.a.2 Geologic Cross-Section Map (Close Up)**

#### **B.3.a.3 Geologic Cross-Section Figure**

#### **B.3.b Groundwater Isoconcentration**

#### **B.3.c Groundwater Flow Direction**

#### **B.3.d Monitoring Wells**

### **B.4 Vapor Maps and Other Media**

#### **B.4.a Vapor Intrusion Map**

B.4.b Other media of concern - No surface waters or sediments were assessed as part of the site investigation.

B.4.c Other – Not applicable.

B.5 Structural Impediment Photos – There were no structural impediments to the completion of the investigation.