Mason, John M - DNR

| From: | Mason, John M - DNR |
|----------|--|
| Sent: | Wednesday, April 29, 2020 1:54 PM |
| То: | 'mfryman@chorus.net ' |
| Subject: | RE: Excavation Report Comments - Frei Oil Co - Horicon (BRRTS #02-14-287206) |

Hello Mark, Please submit an updated (Revised) report. Thanks. -John

We are committed to service excellence. Visit our survey at <u>http://dnr.wi.gov/customersurvey</u> to evaluate how I did.

John Mason Phone: (608) 275-3222 for voicemail Temporary cell: (608) 212-7701 john.mason@wisconsin.gov

From: mfryman@chorus.net <mfryman@chorus.net>
Sent: Tuesday, April 28, 2020 2:24 PM
To: Mason, John M - DNR <John.Mason@wisconsin.gov>
Subject: Re: Excavation Report Comments - Frei Oil Co - Horicon (BRRTS #02-14-287206)

John, Thanks for looking at the report so fast.

Regarding your comments:

Do you want an updated version of the report with the new forms/figures included or should I just send them under a separate cover?

I have the utilities/borings on my CAD basemap, I just did not turn on the layer because I thought it cluttered the figure. These will be shown on the appropriate figures in the closure request. I can remake the excavation map for the Excavation Report if you would like.

When you get a chance send me an email or just call (608-220-4847) to tell me how you would like this stuff to be addressed.

Thanks, Mark Fryman Seymour Environmental

From: "John M Mason - DNR" <<u>John.Mason@wisconsin.gov</u>> To: "Mark Fryman (<u>mfryman@chorus.net</u>)" <<u>mfryman@chorus.net</u>> Sent: Monday, April 27, 2020 12:14:37 PM Subject: Excavation Report Comments - Frei Oil Co - Horicon (BRRTS #02-14-287206) Hello Mark,

I reviewed the Soil Excavation Report and Post Remedial Groundwater Report for the Frei Oil site that was received on April 20, 2020.

Here some comments:

The boring log for MW-2R should be prepared using WDNR form 4400-122.

The completed well development form (4400-113b) for MW-2R was not included.

Buried utilities should be shown on the maps.

For example, the bulk fuel storage area excavation was stopped in the area of residual soil contamination due to a storm sewer, but the storm sewer was not shown on the map.

A soil excavation map should also show locations of all soil sample locations/borings.

Let me know if you have any questions. Thanks.

-John

We are committed to service excellence. Visit our survey at <u>http://dnr.wi.gov/customersurvey</u> to evaluate how I did.

John Mason

Hydrogeologist, Remediation and Redevelopment Program, Environmental Management Division

Wisconsin Department of Natural Resources

3911 Fish Hatchery Road, Fitchburg, WI 53711 Phone: (608) 275-3222 for Voicemail

Temporary Cell: (608) 212-7701 john.mason@wisconsin.gov

