38-052604 TOXIC AND HAZARDOUS SPILL REPORT State of Wisconsin Form 4400-91 Department of Natural Resources State Div. Emergency Gov't. (608) 266-3232 Spill ID Number U.S. Nat'l. Response Center (800) 424-8802 (800) 424-9300 Chemtrec/Pesticides/Chlorine Y Y M M D D 0-99 A.M. Telephone Number Date of Incident Day of Week Time of Incident Reported By (Name) 17151735-9033 12-25-95 3:00 P.M. A.M. Date Reported Day of Week Time Reported Agency or Firm Reporting Reported thru Div. Emergen. Yes 8:22 Specialty CI ☐ P.M. Person or Firm Responsible Substance Involved Quantity Units 551 gallons Telephone Number Substance Involved Units Contact Name Quantity Phillip (7/5) Address, - Street or Route Physical Characteristics Stonton of ☑ Liquid Solid Color. City, State, Zip Code ☐ Semisolid ☐ Gas Marinet Odor Cause of Incident Action Taken By Spiller Derator CITOI No Action Exact Location Description (intersection, mileage, etc.) Notification Investigate Taken City of Marinette Containment; Type County Location 1/41/4, 1/4, Section, Town, Range Cleanup; Method armette Maria Amount Recovered Monitor Groundwaters Affected MAK Contractor Hired; Name No No Yes Surface Waters Affected Name of Surface Water Other Action No No Potential ☐ Yes Spill Location Date District Day of Week Time District Notified Industrial Facility/Paper Mill/Chem. Co. Notified ☐ A.M. Gas/Service Station/Garage, Auto Dealer, Repair Shop 12-25-95 Mon. ☐ P.M. ☐ Ag Coop/Facility/Cheese Factory/Creamery District Person Notified Telephone Number Other Small Business (bank, grocery, insurance co., etc.) Kandall V. Otark (115)130 Public Property (city, county, state, church, school, etc.) Day of Week Date Investigated Time Investigated A.M. Utility Co., Power Generating/Transfer Facility ☐ P.M. Private Property (home/farm) Person Investigating Telephone Number Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler Kandoll J. Transportation Accident, Fuel Supply Tank Spill

Action Taken By DNR Transportation Accident, Load Spill No Action Supervise/Conduct Construction, Excavation, Wrecking, Quarry, Mine Investigation Taken Cleanup Other Spiller Required To Spilled Substance Destination Take Action; Type ☐ Air Contractor Hired Soil By DNR; Name Groundwater ☐ Amount Recovered Surface Water 29.29 Enforcement Storm Sewer Spills Coordinator Other Agencies on Scene Sanitary Sewer M Contained/Recovered Local Person Filing This Report (print name) Stork Kandal Signature Date Signed Federal Additional Comments: erator was transterring C.

A Bayer (1) Company

December 29, 1995

Two Stanton Street Marinette, WI 54143 Phone: 715 735-9033 Fax: 715 735-5304

Mr. Randy Stark State of Wisconsin Department of Natural Resources 1636 Industrial Parkway, Box 16 Marinette, WI 54143 CONFIDENTIAL

Dear Randy:

Regarding the inadvertent discharge of vinyl acetate to one of our dikes on December 25, 1995, we have taken the following actions in the hope of avoiding this situation in the future.

- 1) Retrain all operators in the importance of following procedures as written and in monitoring day tank filling.
- 2) Disciplinary action against the operator responsible consisting of six (6) twelve (12) hour days off without pay. This is equal to nearly one-half month off. The operator violated both personal safety and operating procedure requirements.

During your visit to the site you met with the following people, Mr. J. Harris, Mr. G. Kandow, Mr. J. Lloyd (Building 52 Supervisor) and myself. I am enclosing business cards for everyone but Mr. Lloyd as he does not have business cards for his position.

I continued to pursue the issue of why there was water in the dike, when we were led to believe it should be dry. The water we saw was a final wash after a propylene glycol decontamination. It hadn't frozen due to residual propylene glycol (anti-freeze), the reason for the wash. Analysis of this water showed no vinyl acetate and a small amount of propylene glycol with the remaining water. I estimate we were just above the water's freezing point at the time of our review.

If you have any additional questions, please don't hesitate to contact me.

Sincerely,

Philip R. Everhart, C.S.P.

Safety & Training Manager

CASE ACTIVITY REPORT

Form 4100-160

1-89

State of Wisconsin
Department of Natural Resources
Law Enforcement

Case Number	Case Title		
95238050.A	Specialty Chem Vinyl Acetate Spill		
Activity		Date of Activity	
Investigation of Spill		12-27-95	
Narrative	A CONTRACTOR OF THE PROPERTY O		

On Monday, 12-25-95 at approximately 8:22 a.m. Conservation Warden Supervisor Randall J. Stark was informed by telephone at his residence by Phillip Everhart of Specialty Chem in Marinette that a 557 gallon vinyl acetate spill had occurred at that facility. Mr. Everhart stated that the spill was contained in a secondary containment structure and that the vinyl acetate had been completely recovered and posed no threat to the environment.

On Wednesday, 12-27-95 Warden Stark went to Specialty Chem located at 2 Stanton Street, Marinette, Wisconsin and met with Phillip Everhart to complete a spill report. At this time Everhart informed Warden Stark that the spill had occurred at approximately 3:00 a.m. on 12-25-95 and involved 557 gallons of vinyl acetate. Mr. Everhart stated that the cause of the spill was operator error. Mr. Everhart stated that the operator was transferring vinyl acetate from a bulk tank into a day tank and had apparently left the area and failed to monitor the transfer of the chemical, as a result the prolonged absence from the monitoring station, the day tank overfilled and approximately 557 gallons of vinyl acetate spilled. Warden Stark inquired of the pump rate of the pump that is used to transfer the chemical from the bulk tank to the day tank. Mr. Everhart stated the pump rate is approximately 35 gallons per minute. Given the fact that 557 gallons of product had spilled at a 35 gallon pump rate, this translates to approximately 16 minutes time having elapsed without the operator present after the tank been completely filled to capacity which is 500 gallons. Warden Stark informed Mr. Everhart that he had recalled investigating a similar situation approximately 2 or 3 years ago. Warden Stark recalled that operator error was the cause in that particular accident also. Warden Stark recalled meeting with company President and General Manager Joseph Acker as well as Environmentalist Affairs President Leonard Moore concerning that spill. Warden Stark asked Mr. Everhart whether there was any procedure in place requiring an employee to stay at the pump station and monitor the transfer of chemicals from a bulk tank to the day tank. Mr. Everhart conferred with other individuals at the plant and came to the consensus that there is no policy per se requiring and employee to physically be present to continually monitor chemicals being transferred from the bulk tank to a day tank. Mr. Everhart did state however, that it is implied that the employee stay at the station. Warden Stark inquired as to whether or not Specialty Chem plant would take any disciplinary action against the employee. Mr. Everhart stated that Specialty Chem was going to call the employee in and in all likelihood would take disciplinary action. Warden Stark requested that the name of the employee and well as the outcome of the disciplinary process be forwarded to him as part of the spill investigation. At this time Warden Stark went out along with Mr. Everhart and two other employees to containment structure where the vinyl acetate had spilled. Mr. Everhart had previously told Warden Stark that the secondary containment structure was dry and had been completely cleaned out, however, upon arrival at the secondary containment structure Warden Stark observed a yellow liquid in the containment structure. Warden Stark

Warden Reporting:
Randall I Stark

WARDEN SUPERVISOR
P.O. BOX 16

MARINETTE, WI 54143

RANDY STARK

WARDEN SUPERVISOR
12-27-95

This document was produced as a result of an official Law Enforcement investigation. Contents, in whole or part, are privileged by s. 905.09, Wis. Stats., and may not be used without express permission of the Wisconsin Warden service or appropriate prosecutor.

inquired of Mr. Everhart what this material was, and Mr. Everhart was unable to answer Warden Stark's question. Warden Stark had expected it to be completely dried out as Everhart had indicated earlier. Upon investigating the situation Mr. Everhart determined that the yellowish liquid in the containment structure was a combination of water and snow and some salt from having washed out the structure. Mr. Everhart stated that this material would be recovered and run through the Specialty Chem waste water treatment facility.

On December 30, 1995 Warden Stark received a memo from Everhart concerning the disciplinary action that Specialty Chem had taken against the employee responsible for the spill. The memo stated the employee was to receive (6) twelve hour days off without pay. It should be noted that Warden Stark also had a discussion with Everhart concerning the five hour delay in initially reporting the spill. Mr. Everhart accepted responsibility for the delay citing confusion on his part as to what constituted a spill. Warden Stark explained the spill reporting requirements to Everhart who stated he now understands the reporting requirements. Other individuals contacted by Warden Stark during the investigation of this spill were Gordon Kandow - Director of Fine Chemical Manufacturing, John Harris - Director of Regulatory Affairs and J. Lloyd - Building 52 Supervisor

State of Wisconsin Substance Release Notification Form 24-Hour Emergency Hotline Number: 1-800-943-0003 Form 4400-91 Rev. 11-95

Date and Mil. Time of Incident 12.25.9.5 0330 Date and Mil. Time Reported 12.25.95 0829					
Person Reporting Phillip Everhart			Telephone # (7/5) 7.32 · 2442)		
Representing Agency, Firm, or Citizen Speciality Chem Products					
Responsible Party SQME					
Contact Name Same			Telephone # (). Same		
Address 2 STANTON	<i>S</i> 7.		ic, Zip Code		
Substance Involved VINYL ACETATE	Amount & Units Release 600 Gals	Amt. Recovered dentis a 304 (Trollege USC) sphire			
Solid Semisolid Maquid	□ Gas Color		Odor		
Exact Location (inc. address, facility name, mileage, bldg. #, etc.) OUT SIDE DOG TROOK DYKE					
City Marmette	Soluty Marine	17e	The state of the s		
DNR Region					
Cause_of Incident Over full					
☐ ☐ Local Law Enforcement ☐ ☐ ☐ LEPC or Local Emer. Gov. ☐ ☐	☐ Transportation Accided Industrial Facility ☐ Ag Coop/Facility/Poox ☐ Gas/Service Station/Ga ☐ Pipeline, Terminal, Ta ☐ Public Property (city, ☐ Utility Co., Power Ge ☐ Private Property (hom ☐ Construction, Excavati ☐ Airport Pacility ☐ Other ☐ Has an extension ☐ Construction ☐ Construction ☐ Construction ☐ Construction ☐ Construction ☐ Excavati ☐ Airport Pacility ☐ Other ☐ Has an extension ☐ Construction ☐ Has an extension ☐ Div.	Paper Mill	Containment Contractor Hired Name: Other: No Potential? D Yes D No Incarced Commander know 1888		
5275 Dec					
Prepared By: (Print) Elgin flunter (Sign) Co-Limits Date: Steet to DATCP? Clycs CNo Person Notified: Ranky Space By Soller Region Notified: Marchet Time: 0840 Date: 12-25-95					
Invstgtd By:(Print)	(Sign)	Date:	Site Closed? Yes No		
Spill Coordinator Signoff:	Daie:	Transferred to ERP? UN			
		□Yes; Case #	Spill Packet Sent? 'Yes No		
	The state of the s		☐ Additional Comments on Reverse		