BERTS #

Code 188

July 23, 2017

Dear Nancy,

Enclosed is the annual reporting for One Hour Martinizing Butler.

Nothing has changed, including my ability to sell the building.

Tom Grimm

ARCADIS

02-68-539238 Rec'd 8/1/17 Code 188

Date:

Date:

Sub-Slab Depressurization Systems - Annual O&M Inspection Form	Sub-Slab I	Depressurization	Systems 😴	Annual	<b>O&amp;M Ins</b>	pection Form
--	------------	------------------	-----------	--------	--------------------	--------------

Property Identification Number:		Ter	nperature (Ambient	t):			°F
Tenant's Name: Tom Comm	127	Ten	perature (House):	· .			°F
Owner's Name:		Bar	ometric Pressure:		<u></u>		"Hg
Owners Address (If Different from/Property):	Of Men	Fells al	ather Conditions:				
Inspector Name: Torn Crimm		52100					
Date: 5 3-14							
Time: 1:30 20141.					A tot		
<i>'</i>			,		- 20/4		
System Inspection		State and "	)			L.	
Is Fan Operating?		Yes	NO NA		3012 01	K	
Any Unusual Fan Noises?		Yes	~Nø		Ones	11	
Are Vent Piping and Piping Joints Intact?		Yes	No		2016 D	K	
Any Caulking Required Around Piping Penetra		( <u>Yes</u>	No No		JUIU .		
Is System Padlock Intact (System ON/OFF Sw	ntch)?	Yes	No NA		0A17 0	K	
Is O&M Manual Present?		Yes	No		DII	•	
Any Areas In Need of Additional Sealing?		Yes	CNO /				
List Areas to be Sealed:			/				
List Any Necessary System Repairs:			/				
Tenant/Owner Observations			/		5.		
Any Change in Fan Noise or Vibration?		Yes	No		N.	、 、	
Have you Turned the Fan OFF for Any Period	of Time?	Yes	No NA			$\mathbf{A}$	
Reason?			0			$\lambda$	
Is Differential Pressure in the Manometer Outs	ide of Norma	Operating R	ande?		Yes	NO/ NA	
Is the System Manometer Steady?	Yes No					and the second se	
Have You or the Owner Made any Changes to	and the second	nt or Other Fe	oundation?		Yes	Na	
If So, What Were the Changes:						in a f	
	┍╌┼┼⋽╍₩ <b>⋧</b> ₩ <del>╺</del> ⋰⋺₽ <sub>₽</sub> ┟╴╶╶╌┈	27. A					
Quarterly Manometer Measurements							
Minimum		Inspectio	n		Post R	epair (If Neces	ssary)
Vacuum			Pressure				Pressure

ivinimum inspection						Post Repair (II Necessary)			
	Vacuum			Pressure	Γ			Pressure	
Sample Point ID	(in w.c.)	Date	Time	(in w.c.)		Date	Time	(in w.c.)	
Manometer – Q1	0.50		″		[				
Manometer – Q2	0.50	5 99.14	1:50	. 75					
Manometer – Q3	0.50	5-20-15	11:35	:70					
Manometer – Q4	0.50	6-1-16	11:00	.71					
Comments (Any Re	pairs Made While Visitin	g. etc.). 2 - 16	1:30	× 14				· · · · · · · · · · · · · · · · · · ·	
	· · · · · · · · · · · · · · · · · · ·	101-2-1	7 11:00						
	l	1-3-1 1-10-17	1 12:45	177					
Repairs		5717	JiW	. 80					
Additional Sealing C	omplotod	SI PII	<u> </u>	-			Date:		

Additional Sealing Completed: System Repairs Completed:

X

Annual Maintenance/Inspection of engineered barrier at 12523 West Hampton Avenue property has been completed and documented by property owner. Date of inspection:

Note: The active mitigation system design is based on the sub-slab depressurization system (SSDS), sub-membrane depressurization system (SMDS), and crawlspace depressurization system (CSDS) design criteria found in American Society for Testing and Materials (ASTM) Designation: E2121-03, Standard Practice for Installing Radon Mitigation Systems in Existing Low-Rise Residential Buildings (ASTM, 2008), United States Environmental Protection Agency (U.S. EPA) Region 5, Vapor Intrusion Guidebook (U.S. EPA, 2010), and U.S. EPA 625, Radon Reduction Techniques for Existing Detached Houses (U.S. EPA, 1993), and U.S. EPA, Indoor Air Vapor Intrusion Mitigation Approaches (U.S. EPA, 2008).

		Insp	pection Report	
Inspection Date	Inspector	Condition of Cap	Recommendations	Have Recommendations from previous inspection been implemented?
4-23-14	TON Gormin	C.K.	None	N/B.
5-30-15-		OR	Pare	SULA.
6-1-16	10	OK	Marco	NIA.
7-13-16	11	dt	Chelle .	CN/A
10-1-16	/ 5	OR	Al anger	ME
1-3-17	<i>t</i> 4	OM	Nane	NIC
1-10-17	/`	OK.	Mare	NIC
5-1-17		8K	None	NIC
	· · · · · · · · · · · · · · · · · · ·		/	······································
	·····		والمراجعة والمراجعة والمنافية المتعادية والمتعين والمعادين والمعادية والمتعادية والمتعادية والمتعادية	
	·····			
	·····			
	·		······································	
	· · · · · · · · · · · · · · · · · · ·			
	· · · · · · · · · · · · · · · · · · ·			

## **Cap Maintenance**