

**From:** Donald Johnson <donaldjohnson715@msn.com>  
**Sent:** Thursday, February 4, 2021 9:01 AM  
**To:** Flietner, Barbara J - DNR; Saari, Christopher A - DNR  
**Cc:** Deborah Wickham-Keller  
**Subject:** Lee's Dry Cleaners vapor mitigation  
**Attachments:** Power Switch\_North System\_Lees Cleaners.pdf; Power Switch\_South System\_Lees Cleaners.pdf; Subslab Inspection\_North System\_Lees Cleaners.pdf; Subslab Inspection\_South System\_Lees Cleaners.pdf; Utube\_North System\_Lees Cleaners.pdf; Utube\_South System\_Lees Cleaners.pdf

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Good morning,

Attached are the Subslab inspection reports, as well as photos of the North and South U-tubes and power switches.

Please let us know if you require anything further to bring us into compliance.

I've cc'd our manager and POC, Deborah Wickham-Keller, who handles the inspections and documentation, as well as daily operations.

To ensure a more timely response, please use the business mailing address for future correspondence via USPS:

1727 S Main St  
Rice Lake, WI 54868  
(715) 234-9315  
[leescleaners.rl.wi@outlook.com](mailto:leescleaners.rl.wi@outlook.com)  
[donaldjohnson715@msn.com](mailto:donaldjohnson715@msn.com)

Thank you,

Respectfully,

Donald W Johnson  
(715) 205-8039  
[donaldjohnson715@msn.com](mailto:donaldjohnson715@msn.com)

Sent from [Mail](#) for Windows 10











**Subslab Depressurization System Inspection Log NORTH SYSTEM**

Site Name Lees Cleaners  
 Address 1727 S. Main Street  
 Rice Lake, WI  
 BRRTS# 02-03-552055

Contacts: Ken Ebbott or Mark Gibeault - Fehr Graham  
 920-892-2444 (Environmental Consultant)

Date	Time	Location	Reading (inches H2O )	Method	Comments
11/17/2014	1:00 PM	North Wall	1.8"	U-Tube	
1/24/2020	4:00 PM	North Wall	1.2"	U-Tube	
2/27/2020	3:00 PM	North Wall	1.1"	U-Tube	
3/25/2020	10: AM	North Wall	1.2"	U-Tube	
4/20/2020	11: AM	North Wall	2.1"	U-Tube	
5/24/2020	3:00 pm	North Wall	1.2"	U-Tube	
6/20/2020	4:30 PM	North Wall	1.2"	U-Tube	
7/28/2020	11:33 AM	North Wall	1.2"	U-Tube	
9/11/2020	9:02 AM	North Wall	1.1"	U-Tube	
9/30/2020	5:11 PM	North Wall	1.2"	U-Tube	
11/7/20	12:11 PM	North Wall	1.2"	U-Tube	
12/4/20	1:01: PM	North Wall	1.1"	U-Tube	
1/15/21	12:32 PM	North Wall	1.3"	U-Tube	
		North Wall			
		North Wall			
		North Wall			
		North Wall			
		North Wall			
		North Wall			
		North Wall			




**Subslab Depressurization System Inspection Log SOUTH SYSTEM**


Site Name Lees Cleaners  
 Address 1727 S. Main Street  
 Rice Lake, WI  
 BRRTS# 02-03-552055

Contacts: Ken Ebbott or Mark Gibeault - Fehr Graham  
 920-892-2444 (Environmental Consultant)

Date	Time	Location	Reading (inches H2O )	Method	Comments
11/17/2014	8:00 AM	South Wall	3.6"	U-Tube	
1/24/2020	4:00 PM	South Wall	2.7"	U-Tube	
2/27/2020	3:00 PM	South Wall	2.7"	U-Tube	
3/25/2020	10:00 AM	South Wall	2.6"	U-Tube	
4/20/2020	11:00 AM	South Wall	2.7"	U-Tube	
5/24/2020	3:00 PM	South Wall	2.6"	U-Tube	
6/20/2020	4:30 PM	South Wall	2.6"	U-Tube	
7/28/2020	11:36 AM	South Wall	2.6"	U-Tube	
9/1/20	9:01 AM	South Wall	2.6"	U-Tube	
9/30/20	5:11 PM	South Wall	2.7"	U-Tube	
11/7/20	12:70 PM	South Wall	2.7"	U-Tube	
12/4/20	1:00 PM	South Wall	2.7"	U-Tube	
1/15/21	12:31 PM	South Wall	2.8"	U-Tube	
		South Wall			
		South Wall			
		South Wall			
		South Wall			
		South Wall			
		South Wall			
		South Wall			





 **RAD SPEC**  
OF W  
**866-55**  
1072 Rock Lake  
This device does not measure radon  
**← Vacuum**  
Please call for more information  
 Active  
 Passive  
EPA recommended  
Install Date \_\_\_\_\_  
Initial Pressure \_\_\_\_\_  
Installed By \_\_\_\_\_



ION  
SPECIALISTS  
INC.  
7236  
Lane, Neenah  
Do not measure  
levels.  
Indicator  
Service if levels  
RP145  
GP501  
every 2 years

