Real Estate Bayfield County Tax Record

Today's Date: 3/30/2023

2019 2005 2016 2002 Tax Records: 2022 <u>2021</u> <u>2020</u> <u> 2018</u> <u>2017</u> 2015 2014 2013 <u>2012</u> 2011 2009 2006 2004 2003 2010

	Pro	perty	Iden	tifica	tion
		PCILY	Lucii	CITICA	CIOII

Tax ID:	26860
PIN:	04-038-2-48-09-17-3 03-000-20000
Legacy PIN:	038103405000
Map ID:	

2022 Ownership	Billing Address		
STANLEY A EVAVOLD	STANLEY A EVAVOLD		
STANLET A EVAVOLD	ATTN: NORDIC AUCTIONS		
	2713 COURTLAND ST		
	DULUTH MN 55806		

2022 Property Values

A NATIONAL PROPERTY OF THE PRO	Market Street,
Total Land Value:	600
Total Improved Value:	400
Total Forestry Land Value:	0
Total Value:	1,000
Estimated Fair Market - Land:	600
Estimated Fair Market - Improved:	400
Estimated Fair Market - Forest Land:	0
Total Estimated Fair Market:	1,000

2022 Levy & Tax Information

Aggregate Ratio:	1.00302
Mill Rate:	0.014902131
School Credit:	1.52

Special	S

ı	W/	н
-	_	_

2022 Tax Bill		Status:	Delinquen
	B	D-:-I	N - I i

LISTING FOR TAX YEAR: 2022

6.21

*	Due	Paid	Balance
Gross Real Estate	14.91		1
First Dollar Credit	- 8.82		
Lottery Credit	- 0.00		
Real Estate	6.09	0.00	6.09
Special Assessments	0.00	0.00	0.00
Special Charges	0.00	0.00	0.00
Delinquent Utilities	0.00	0.00	0.00
Private Forest	0.00	0.00	0.00
Managed Forest Open	0.00	0.00	0.00
Managed Forest Closed	0.00	0.00	0.00
Interest			0.12

Amount Due If Paid By 3/31/2023:

Installments

Installment #	Due	Payable To	Amount
Installment 1	1/31/2023	Municipality	6.09
Installment 2	7/31/2023	County	0.00
		Total ->	6.00

Payments

Receipt #	Posted	Paid By	Amount
-----------	---------------	---------	--------

TOWN OF OULU TREASURER

MARJORIE LAHTI

4060 EASTVIEW RD

IRON RIVER WI 54847 Phone: (715) 372-8870 E-Mail: marjoulu@cheqnet.net

> **STANLEY A EVAVOLD** ATTN: NORDIC AUCTIONS 2713 COURTLAND ST

DULUTH MN 55806

REAL ESTATE PROPERTY TAX BILL FOR 2022

STATE OF WISCONSIN - BAYFIELD COUNTY

PAYMENTS should reference: Tax ID: 26860

DOCUMENT RECORDING, or anything Else should reference:

04-038-2-48-09-17-3 03-000-20000

Alternate/Legacy ID: 038-1034-05 000

Ownership: STANLEY A EVAVOLD

Important: Be sure this covers your property. Note that this description is for tax bills only and may not be a full legal description. See reverse side for important information.

Property Description / Location of Property

Site Address:

73010 COUNTY HWY B

Description: Sec 17 Tn 48 Rg 09 PAR IN SW SW IN V.462 P.191, 301

Please include self-addressed, stamped envelope for return receipt.

Acreage: 1.750

14.91

8.82

0.00

6.09

25.74

0.00

15.38

-63.7

-65.7

-60.4

0.0

Please inform your	treasure	r of any bi	Iling address o	hanges. D	ocument: 83
Assessed Value				Average	Net Assessed Value
<u> </u>	<u>Land</u>	<u>Improved</u>	<u>Total</u>	Assessment Ratio	Rate
					(Does NOT reflect lottery
	\$600	\$400	\$1,000	1.00302	or first dollar credit)
					0.014902131
Estimated Fair Market Value				An "X" means unpaid	School taxes reduced by
	<u>_and</u>	<u>Improved</u>	<u>Total</u>	prior year taxes.	school levy tax credit.
					\$1.52
	600	\$400	\$1,000		
V.			Estimated St	ate Aids	% Tax
1.0			Allocated Tax	x District No.	et Tax <u>Change</u>

V.	Estimated St Allocated Tax	Net Tax		% Tax Change	
Taxing Jurisdiction	2021	2022	2021	2022	
COUNTY	15,637	17,263	10.12	3.91	-61.4
TOWN OF OULU	219,299	222,009	9.77	3.36	-65.6
SCHL-SOUTHSHORE	51,276	63,996	20.43	7.37	-63.9
TECHNICAL COLLEGE	32,071	34,242	0.80	0.27	-66.3

-	Total Due:	6.09
	Total Duce	 6.00
	Net Real Estate Tax:	 6.09
	Lottery Credit:	 -0.00
	First Dollar Credit:	-8.82
	Real Estate Tax:	14.91
	3-284;115-59;462-191	

For full payment pay to TOWN OF OULU treasurer

January 31, 2023

Warning

If not paid by due dates, installment option is lost and total tax is delinquent and subject to interest and if applicable, penalty. (See reverse)

For	Pav	vment	In	Full

First Dollar Credit

Net Property Tax

Lottery & Gaming Credit

Totals

6.09

318,283

337,510

by January 31, 2023

Amount enclosed:

STANLEY A EVAVOLD Tax ID: 26860 (038) Make payment payable and mail to: **TOWN OF OULU TREASURER**

MARJORIE LAHTI 4060 EASTVIEW RD **IRON RIVER WI 54847**

Include this stub with your payment

CORRESPONDENCE/MEMORANDUM ·

DATE:

August 24, 2018

FILE REF:

TO:

Ralph Smith - RR/5

FROM:

Chris Saari – Ashland

SUBJECT: Transfer/Status Memo – Iron River Co-op – Oulu (#03-04-559467)

This case involves USTs removed from a former general store in July 2012. The TSSA was funded by DSPS, and a lien was recorded on the property deed to cover the costs. The original responsible party was identified as the Iron River Co-op Association. However, the Iron River Co-op Association sold the to Stanley Evavold in 1987, and in the sale documents, Mr. Evavold had accepted responsibility for the USTs and the product contained within.

RP letters have been sent to the both the Iron River Co-op Association and Mr. Evavold. The former indicated that they transferred all liability for the property to the latter as part of the 1987 property sale.

Based on subsequent communications with Mr. Evavold's daughter, he is (was?) living in a nursing home in poor health. It does not appear that Mr. Evavold would have the capacity, financially or otherwise, to undertake a site investigation.

The site has been listed as a possible state-lead candidate by NOR staff. The relatively high contaminant concentrations detected during the TSSA, coupled with the existence of private wells in the area, indicates that this site should be evaluated more fully for a state funded site investigation.



Saari, Christopher A - DNR

From:

Patrick Dooley <igacoop@cheqnet.net>

Sent:

Tuesday, April 21, 2015 1:33 PM

To:

Saari, Christopher A - DNR

Subject:

FW: Stanley Evavold

From: Patrick Dooley [mailto:igacoop@cheqnet.net]

Sent: Tuesday, April 21, 2015 9:43 AM

To: 'Christopher.'

Subject: Stanley Evavold

Hello Chris,

FYI I came across an ad for Nordic Auctions in the Evergreen Shopper with Stanley Evavolds address In Duluth, MN. I thought you might be interested. Col. Forrest S. Evavold 2713 Courtland ST. Duluth, MN 55806.

Patrick Dooley
General Manager
Iron River Cooperatives, Inc.

Saari, Christopher A - DNR

From:

Heather O. <flexworkho@yahoo.com>

Sent:

Thursday, February 05, 2015 3:14 PM

To:

Saari, Christopher A - DNR

Subject: **Attachments:** Re: Former Iron River Co-op - Oulu Stanley Evavold Oulo Property.docx

Thank you very much!

I quickly typed up something so that I did not forget the details (attached).

Please let me know how else I can be of assistance.

Heather Opsahl

From: "Saari, Christopher A - DNR" < Christopher Saari@wisconsin.gov>

To: "flexworkho@yahoo.com" <flexworkho@yahoo.com>

Sent: Thursday, February 5, 2015 2:43 PM Subject: Former Iron River Co-op - Oulu

Hi Heather:

Attached are copies of the liens recorded on your father's property by the Wisconsin Department of Safety and Professional Services. There must've been a mistake in the first document so they needed to record a second lien. I have also included a copy of Bayfield County's tax records for the property; I was unable to create an internet link to the records, but you might be able to follow the web address on the bottom of the page to get at it. It looks like the property is 1.75 acres.

Feel free to contact me if you have further questions.

We are committed to service excellence.

Visit our survey at http://dnr.wi.gov/customersurvey to evaluate how I did.

Chris Saari

Hydrogeologist - Remediation and Redevelopment Program Wisconsin Department of Natural Resources

Phone: (715) 685-2920 Fax: (715) 685-2909 Christopher.Saari@Wi.gov



February 5, 2015

Chris Saari
Hydrogeologist – Remediation and Redevelopment Program
Wisconsin Department of Natural Resources

Dear Mr. Saari:

Per our discussion today, I would like to report on the circumstances of my father, Stanley Evavold.

On October 20, 2012, my mother, Mardelle Evavold, passed away. She was a Registered Nurse and was married to my father for 50 years. After she passed, Stanley was not taking care of himself properly and did not take his diabetes medication correctly. Two months after Mardelle passed, my father had a major Cerebral Vascular Accident (CVA) or stroke. He went to rehab for 2 weeks, but was unable to return home. Stanley was admitted to Aftenro Nursing Home, and has resided there since. He has no assets, and receives Medical Assistance and Medicare to provide for his care.

Please send mail to my address: 3338 West Beech Street, Duluth, MN 55804, for my father is unable to fully understand the mail he receives.

If you have any further questions, please contact me at 218-348-6019.

Thank you for your assistance with this issue.

Sincerely,

Heather Opsahl Stanley Evavold's Daughter

Saari, Christopher A - DNR

From:

Cochart, Lacey L - DNR

Sent:

Tuesday, February 03, 2015 10:43 AM

To:

Saari, Christopher A - DNR

Subject:

FW: Tank Pull Lien?

Attachments:

Evavold recorded lien.pdf; Modified Recorded Lien.pdf

I received the attached liens related to the Iron River Coop property.

We are committed to service excellence.

Department clients visit our survey at http://intranet.dnr.state.wi.us/int/legal/ to evaluate how I did.

Lacey Cochart
Phone: (608) 267-0846
Lacey.cochart@wisconsin.gov

CONFIDENTIALITY: This message may contain information which, by law, is privileged, confidential or exempt from disclosure. Contact the sender for permission prior to disclosing the contents of this message to any other person.

This message is intended solely for the use of the addressee. If you are not the addressee, you are hereby notified that any use, distribution or copying of this message is strictly prohibited. If you received this message in error, please notify us by reply e-mail or by telephone and immediately delete this message and any/all of its attachments.

From: Moser, James E - DNR

Sent: Thursday, January 22, 2015 9:55 AM

To: Cochart, Lacey L - DNR **Subject:** RE: Tank Pull Lien?

There is a recorded lien and a modified recorded lien – both attached

We are committed to service excellence.

Wisit our survey at http://dnr.wi.gov/customersurvey to evaluate how I did.

JAMES E MOSER

Phone:

(608) 267-7533

E-mail:

.

ij.,

james.moser@wisconsin.gov

From: Cochart, Lacey L - DNR

Sent: Thursday, January 22, 2015 9:20 AM

To: Moser, James E - DNR **Subject:** Tank Pull Lien?

Hi James,

Will you check if DSPS filed a lien on a property in Bayfield County? The address is 73010 County Hwy B in Oulu. The tanks were pulled under Order in 2012. The case was State v. Evavold. The property owner Stanley A. Evavold.

Any information you have would be helpful.

Thanks.

Lacey

We are committed to service excellence.

Department clients visit our survey at http://intranet.dnr.state.wi.us/int/legal/ to evaluate how I did.

Lacey Cochart
Attorney – Bureau of Legal Services

Wisconsin Department of Natural Resources

Phone: (608) 267-0846 Cell: (608) 358-5179 Fax: (608) 266-6983

Lacey.cochart@wisconsin.gov



CONFIDENTIALITY: This message may contain information which, by law, is privileged, confidential or exempt from disclosure. Contact the sender for permission prior to disclosing the contents of this message to any other person.

This message is intended solely for the use of the addressee. If you are not the addressee, you are hereby notified that any use, distribution or copying of this message is strictly prohibited. If you received this message in error, please notify us by reply e-mail or by telephone and immediately delete this message and any/all of its attachments.

NOTICE OF LIEN

§101.1435(3), Stats.

Document Number

Title of Document

As provided by §101.1435(3), Stats., the Department of Safety and Professional Services (department) has incurred costs in the amount of \$4,100.00 for a removal of an abandoned underground petroleum storage tank. On behalf of Stanley A. Evavold, a married man owner of record of the following property:

The Southwest Quarter of the Southwest Quarter (SW 1/4 of SW 1/4), Section Seventeen (17), Township forty-eight (48) North, Range Nine (9) West, described as follows: Beginning at the Southwest corner of said Southwest Quarter of the Southwest Quarter (SW 1/4 of SW 1/4); thence North along the Section Line 416 feet; thence East 104 feet; thence South 208 feet; thence East 156 feet; thence South 208 feet to the South Line of said Southwest Quarter of the Southwest Quarter (SW ¼ of SW ¼); thence West along the South Line 260 feet to the point of beginning; Bayfield County, Wisconsin.

PATRICIA A OLSON BAYFIELD COUNTY, WI REGISTER OF DEEDS

2012R-545114

08/08/2012 09:15AM TF EXEMPT #: RECORDING FEE: 30.00 PAGES: 1

Record this record with the Register of Deeds. Name and return address:

Tanya Herranz

PECFA Program Specialist

Division of Environmental and Regulatory Services

PO Box 7838

Madison WI 53707-7838

Phone (608) 266-6796

Tax Parcel: #

The property remains subject to this lien until the deductible is paid in full to the Department. No interest is recoverable on this lien.

The department makes and files this claim for the interest held by the Owner(s) in this property under §101.1435(3), Stats. The department certifies that to the best of its knowledge and belief, all information contained in this Notice of Lien is correct, and this lien represents a legal encumbrance upon the property. Based on the above information, the department claims a lien on all the interest, which the Owner(s) have in the above-described property.



Department of Safety and Professional Services

By:

Tanya Herranz, PECFA Program Specialist

Division of Environmental and Regulatory Services

AUTHENTICATION OF ACKNOWLEDGMENT

The above named person was sworn to before me this 9th day of July, 2012.

Christine A. Severson, Notary Public

State of Wisconsin, County of Dane

My Commission expires October 12th, 2014.

This document was drafted & approved

State of Wisconsin

Department of Safety and Professional

Services

PO Box 7970

Madison WI 53707-7970

V1088 P48

MODIFIED NOTICE OF LIEN

§101.1435(3), Stats.

Document Number

Title of Document

As provided by §101.1435(3), Stats., the Department of Safety and Professional Services (department) has incurred costs in the amount of \$9,066.00 for a removal of an abandoned underground petroleum storage tank. On behalf of Stanley A. Evavold owner of record of the following property:

The Southwest Quarter of the Southwest Quarter (SW ¼ of SW ¼), Section Seventeen (17), Township forty-eight (48) North, Range Nine (9) West, described as follows: Beginning at the Southwest corner of said Southwest Quarter of the Southwest Quarter (SW ¼ of SW ¼); thence North along the Section Line 416 feet; thence East 104 feet; thence South 208 feet; thence East 156 feet; thence South 208 feet to the South Line of said Southwest Quarter of the Southwest Quarter (SW ¼ of SW ¼); thence West along the South Line 260 feet to the point of beginning; Bayfield County, Wisconsin.

PATRICIA A OLSON BAYFIELD COUNTY, WI REGISTER OF DEEDS

2013R-547834

Record this record with the Register of Deeds.

Name and return address:
Tanya Herranz
PECFA Program Specialist
Division of Industry Services
PO Box 7838
Madison WI 53707-7838
Phone (608) 266-6796

This modified lien replaces the previously filed lien recorded on 08/08/2012. Document number 2012R-545114, Volume 1088 Page 48. The property remains subject to this lien until the deductible is paid in full to the department. No Interest is recoverable on this lien.

The department makes and files this claim for the interest held by the Owner(s) in this property under §101.1435(3), Stats. The department certifies that to the best of its knowledge and belief, all information contained in this Notice of Lien is correct, and this lien represents a legal encumbrance upon the property. Based on the above information, the department claims a lien on all the interest, which the Owner(s) have in the above-described property.



Department of Safety and Professional Services By:

Tanya Kerranz, PECFA Program Specialist

Division of Industry Services

AUTHENTICATION OF ACKNOWLEDGMENT

The above named person was sworn to before me this 17th day of December, 2012.

Christine A. Severson, Notary Public State of Wisconsin, County of Dane

My Commission expires October 12th, 2014.

This document was drafted &approved by:
Department of Safety and Professional
Services
PO Box 7970

Madison WI 53707-7970 Bar #1015480

V1099 P733



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Scott Walker, Governor Cathy Stepp, Secretary John Gozdzialski, Regional Director

February 2, 2015

FILE COPY

MR STANLEY EVAVOLD 3338 W BEECH ST DULUTH MN 55804-2600

Subject: Petroleum Contamination at the Former Iron River Cooperative – Oulu Branch 73010 County Highway B, Town of Oulu, Bayfield County, Wisconsin WDNR BRRTS #03-04-599467

Dear Mr. Evavold:

I am writing today in regard to the status of petroleum contamination at the above referenced site. On October 15, 2012, the Wisconsin Department of Natural Resources (DNR) was notified by Mike Kohn of IC Environmental Corporation of gasoline contamination at the site. The contamination was identified during the removal of three underground storage tanks (USTs) from the site on July 17, 2012. The UST removal assessment was completed on behalf of the Wisconsin Department of Safety and Professional Services (DSPS).

Based on the information that has been submitted to the DNR regarding this site, we believe you are responsible for investigating and restoring the environment at the above-described site under Section 292.11, Wisconsin Statutes, known as the hazardous substances spill law. As you might remember, I sent a similar letter to the Iron River Co-op Association on October 7, 2014, because that party was listed as the owner of the USTs on the Tank System Service and Closure Assessment Report. I pointed out at that time that you also could be considered responsible for the contamination, as being in "possession and control" of the discharge. Based on information supplied by Iron River Cooperatives, Inc., it appears that you were fully aware of the USTs at the time of purchase of the property. Therefore, the DNR believes that you have responsibility to investigate and remediate the contamination.

This letter describes the legal responsibilities of a person who is responsible under section 292.11, Wis. Stats., explains what you need to do to investigate and clean up the contamination, and provides you with information about cleanups, environmental consultants, possible financial assistance, and working cooperatively with the DNR.

Legal Responsibilities:

Your legal responsibilities are defined both in statute and in administrative codes. The hazardous substances spill law, Section 292.11(3), Wisconsin Statutes, states:

• RESPONSIBILITY. A person who possesses or controls a hazardous substance which is discharged or who causes the discharge of a hazardous substance shall take the actions necessary to restore the environment to the extent practicable and minimize the harmful effects from the discharge to the air, lands, or waters of the state.

Mr. Stanley Evavold – February 2, 2015 Page 2

In addition to the statutory requirements, Wisconsin Administrative Code chapters NR 700 through NR 754 establish requirements for emergency and interim actions, public information, site investigations, design and operation of remedial action systems, and case closure. Wisconsin Administrative Code chapter NR 140 establishes groundwater standards for contaminants that reach groundwater.

Steps to Take:

The longer contamination is left in the environment, the farther it can spread and the more it may cost to clean up. Quick action may lessen damage to your property and neighboring properties and reduce your costs in investigating and cleaning up the contamination. To ensure that your cleanup complies with Wisconsin's laws and administrative codes, you should hire a professional environmental consultant who understands what needs to be done. The following information provides the timeframes and required steps to take. Unless otherwise approved by DNR in writing you must complete the work by the timeframes specified.

- Within the next 45 days, by March 19, 2015, you should submit written verification (such as a letter from the consultant) that you have hired an environmental consultant. If you do not take action within this time frame, the DNR may initiate enforcement action against you.
- 2. Within 60 days, by April 3, 2015, you must submit a work plan for completing the investigation. The work plan must comply with the requirements in the NR 700 Wis. Adm. Code rule series and should adhere to current DNR technical guidance documents.
- 3. You must initiate the site investigation within 90 days of submitting the site investigation work plan. You may proceed with the field investigation upon DNR notification to proceed. If the DNR has not responded within 30 days from submittal of the work plan, you are required to proceed with the field investigation. If a fee for DNR review has been submitted, the field investigation must begin within 60 days after receiving DNR approval.
- 4. Within 60 days after completion of the field investigation and receipt of the laboratory data, you must submit a Site Investigation Report to the DNR or other agency with administrative authority.
- 5. Within 60 days after submitting the Site Investigation Report, you must submit a remedial actions options report.

Sites where discharges to the environment have been reported are entered into the Bureau for Remediation and Redevelopment Tracking System ("BRRTS"), a version of which appears on the DNR's internet site. You may go to http://dnr.wi.gov/botw/SetUpBasicSearchForm.do and view the information related to your site at any time and use the feedback system to alert us to any errors in the data.

If you want a formal written response from the department on a specific submittal, please be aware that a review fee is required in accordance with ch. NR 749, Wis. Adm. Code. If a fee is not submitted with your reports, you must complete the site investigation and cleanup to maintain your compliance with the spills law and chapters NR 700 through NR 754. The timeframes specified above are required by

Mr. Stanley Evavold – February 2, 2015 Page 3

rule, so do not delay the investigation of your site. We have provided detailed technical guidance to environmental consultants. Your consultant is expected to know our technical procedures and administrative rules and should be able to answer your questions on meeting cleanup requirements.

All correspondence regarding this site should be sent to me at the above address. Unless otherwise directed, submit one paper copy and one electronic copy of plans and reports. To speed processing, correspondence should reference the BRRTS number shown at the top of this letter.

Site Investigation and Vapor Pathway Analysis

As you develop the site investigation work plan, we want to remind you to include an assessment of the vapor intrusion pathway. Chapter NR 716, Wis. Adm. Code, outlines the requirements for investigation of contamination in the environment. Specifically, s. NR 716.11(3) (a) requires that the field investigation determine the "nature, degree and extent, both areal and vertical, of the hazardous substances or environmental pollution in all affected media". In addition, ss. NR 716.11(5) (g) and (h) contain the specific requirements for evaluating the presence of vapors in the sub-surface as well as in indoor air.

You will need to include documentation with the Site Investigation Report that explains how the assessment was done. If the vapor pathway is being ruled out, then the report needs to provide the appropriate justification for reaching this conclusion. If the pathway cannot be ruled out, then investigation and, if appropriate, remedial action must be taken to address the risk presented prior to submitting the site for closure. The DNR has developed guidance to help responsible parties and their consultants comply with the requirements described above. The guidance includes a detailed explanation of how to assess the vapor intrusion pathway and provides criteria which identify when an investigation is necessary. The guidance is available at: http://dnr.wi.gov/files/PDF/pubs/rr/RR800.pdf.

Additional Information for Petroleum Site Owners:

We encourage you to visit our website at http://dnr.wi.gov/topic/Brownfields/, where you can find information on selecting a consultant, financial assistance and understanding the cleanup process. You will also find information there about liability clarification letters, post-cleanup liability and more.

It appears that this case might be eligible for participation in the DNR's Petroleum Environmental Cleanup Fund Award (PECFA) program. PECFA funds can be used to reimburse responsible parties for their costs to investigate and clean up contamination from eligible petroleum tank systems. More information about the PECFA program can be obtained by calling (608) 261-7715 or through the DNR's web site at http://dnr.wi.gov/topic/Brownfields/PECFA.html. However, because PECFA operates as a reimbursement program, responsible parties generally have to have an initial source of funding (e.g., a line of credit from a bank) available to pay the investigation and cleanup costs, and then seek reimbursement of those costs. In situations where the responsible party cannot come up with the initial funding needed to begin the investigation and cleanup, PECFA does offer a second alternative, the PECFA agent.

Mr. Stanley Evavold – February 2, 2015 Page 4

An agent means a person or organization (i.e., environmental consulting firm) designated by the responsible party to act on behalf of the responsible party in conducting the investigation and cleanup. The agent is responsible for paying for the cleanup and submitting the claims for PECFA reimbursement. The reimbursement checks are then issued in the name of the responsible party and the agent, and mailed to the agent. This alternative eliminates the need for a responsible party to secure a line of credit from a bank to pay the investigation and cleanup costs. More information about the PECFA agent process can be found at http://dnr.wi.gov/topic/Brownfields/PECFA.html under the Consultant/Agent tab, or by calling (608) 261-7715.

If you have any questions concerning this letter or the project in general, please do not hesitate to write or call me at 715-685-2920. I can also be reached by e-mail at Christopher.Saari@Wisconsin.gov.

Thank you for your cooperation.

Sincerely,

Christopher A. Saari

Hydrogeologist

cc: Patrick Dooley – Iron River Cooperatives, Inc.



State of Wisconsin

Department of Natural Resources 2501 Golf Course Road Ashland, WI 54806 ST PALE MN 550 27 JAN 15 PM 2 L





X 553 N7E 100911410001/27/15
FORWARD TIME EXP RTN TO SEND
EVAVOLD
3338 W BEECH ST
DULUTH MN 55804-7500

RETURN TO SENDER



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Scott Walker, Governor Cathy Stepp, Secretary John Gozdzialski, Regional Director

January 27, 2015

MR STANLEY EVAVOLD 14 ROYALTON RD SUPERIOR WI 54880

Subject: Petroleum Contamination at the Former Iron River Cooperative – Oulu Branch 73010 County Highway B, Town of Oulu, Bayfield County, Wisconsin WDNR BRRTS #03-04-599467

Dear Mr. Evavold:

I am writing today in regard to the status of petroleum contamination at the above referenced site. On October 15, 2012, the Wisconsin Department of Natural Resources (DNR) was notified by Mike Kohn of IC Environmental Corporation of gasoline contamination at the site. The contamination was identified during the removal of three underground storage tanks (USTs) from the site on July 17, 2012. The UST removal assessment was completed on behalf of the Wisconsin Department of Safety and Professional Services (DSPS).

Based on the information that has been submitted to the DNR regarding this site, we believe you are responsible for investigating and restoring the environment at the above-described site under Section 292.11, Wisconsin Statutes, known as the hazardous substances spill law. As you might remember, I sent a similar letter to the Iron River Co-op Association on October 7, 2014, because that party was listed as the owner of the USTs on the Tank System Service and Closure Assessment Report. I pointed out at that time that you also could be considered responsible for the contamination, as being in "possession and control" of the discharge. Based on information supplied by Iron River Cooperatives, Inc., it appears that you were fully aware of the USTs at the time of purchase of the property. Therefore, the DNR believes that you have responsibility to investigate and remediate the contamination.

This letter describes the legal responsibilities of a person who is responsible under section 292.11, Wis. Stats., explains what you need to do to investigate and clean up the contamination, and provides you with information about cleanups, environmental consultants, possible financial assistance, and working cooperatively with the DNR.

Legal Responsibilities:

Your legal responsibilities are defined both in statute and in administrative codes. The hazardous substances spill law, Section 292.11(3), Wisconsin Statutes, states:

RESPONSIBILITY. A person who possesses or controls a hazardous substance which is
discharged or who causes the discharge of a hazardous substance shall take the actions
necessary to restore the environment to the extent practicable and minimize the harmful
effects from the discharge to the air, lands, or waters of the state.

In addition to the statutory requirements, Wisconsin Administrative Code chapters NR 700 through NR 754 establish requirements for emergency and interim actions, public information, site investigations, design and operation of remedial action systems, and case closure. Wisconsin Administrative Code chapter NR 140 establishes groundwater standards for contaminants that reach groundwater.

Steps to Take:

The longer contamination is left in the environment, the farther it can spread and the more it may cost to clean up. Quick action may lessen damage to your property and neighboring properties and reduce your costs in investigating and cleaning up the contamination. To ensure that your cleanup complies with Wisconsin's laws and administrative codes, you should hire a professional environmental consultant who understands what needs to be done. The following information provides the timeframes and required steps to take. Unless otherwise approved by DNR in writing you must complete the work by the timeframes specified.

- 1. Within the next **45 days**, by March 13, 2015, you should submit <u>written</u> verification (such as a letter from the consultant) that you have hired an environmental consultant. If you do not take action within this time frame, the DNR may initiate enforcement action against you.
- 2. Within **60 days**, by March 28, 2015, you must submit a work plan for completing the investigation. The work plan must comply with the requirements in the NR 700 Wis. Adm. Code rule series and should adhere to current DNR technical guidance documents.
- 3. You must initiate the site investigation within 90 days of submitting the site investigation work plan. You may proceed with the field investigation upon DNR notification to proceed. If the DNR has not responded within 30 days from submittal of the work plan, you are required to proceed with the field investigation. If a fee for DNR review has been submitted, the field investigation must begin within 60 days after receiving DNR approval.
- 4. Within 60 days after completion of the field investigation and receipt of the laboratory data, you must submit a Site Investigation Report to the DNR or other agency with administrative authority. For sites with agrichemicals contamination, your case will be transferred to the Department of Agriculture, Trade and Consumer Protection for oversight.
- 5. Within 60 days after submitting the Site Investigation Report, you must submit a remedial actions options report.

Sites where discharges to the environment have been reported are entered into the Bureau for Remediation and Redevelopment Tracking System ("BRRTS"), a version of which appears on the DNR's internet site. You may go to http://dnr.wi.gov/botw/SetUpBasicSearchForm.do and view the information related to your site at any time and use the feedback system to alert us to any errors in the data.

If you want a formal written response from the department on a specific submittal, please be aware that a review fee is required in accordance with ch. NR 749, Wis. Adm. Code. If a fee is not submitted with your reports, you must complete the site investigation and cleanup to maintain your compliance with the spills law and chapters NR 700 through NR 754. The timeframes specified above are required by

rule, so do not delay the investigation of your site. We have provided detailed technical guidance to environmental consultants. Your consultant is expected to know our technical procedures and administrative rules and should be able to answer your questions on meeting cleanup requirements.

All correspondence regarding this site should be sent to me at the above address. Unless otherwise directed, submit one paper copy and one electronic copy of plans and reports. To speed processing, correspondence should reference the BRRTS number shown at the top of this letter.

Site Investigation and Vapor Pathway Analysis

As you develop the site investigation work plan, we want to remind you to include an assessment of the vapor intrusion pathway. Chapter NR 716, Wis. Adm. Code, outlines the requirements for investigation of contamination in the environment. Specifically, s. NR 716.11(3) (a) requires that the field investigation determine the "nature, degree and extent, both areal and vertical, of the hazardous substances or environmental pollution in all affected media". In addition, ss. NR 716.11(5) (g) and (h) contain the specific requirements for evaluating the presence of vapors in the sub-surface as well as in indoor air.

You will need to include documentation with the Site Investigation Report that explains how the assessment was done. If the vapor pathway is being ruled out, then the report needs to provide the appropriate justification for reaching this conclusion. If the pathway cannot be ruled out, then investigation and, if appropriate, remedial action must be taken to address the risk presented prior to submitting the site for closure. The DNR has developed guidance to help responsible parties and their consultants comply with the requirements described above. The guidance includes a detailed explanation of how to assess the vapor intrusion pathway and provides criteria which identify when an investigation is necessary. The guidance is available at: http://dnr.wi.gov/files/PDF/pubs/rr/RR800.pdf.

Additional Information for Petroleum Site Owners:

We encourage you to visit our website at http://dnr.wi.gov/topic/Brownfields/, where you can find information on selecting a consultant, financial assistance and understanding the cleanup process. You will also find information there about liability clarification letters, post-cleanup liability and more.

It appears that this case might be eligible for participation in the DNR's Petroleum Environmental Cleanup Fund Award (PECFA) program. PECFA funds can be used to reimburse responsible parties for their costs to investigate and clean up contamination from eligible petroleum tank systems. More information about the PECFA program can be obtained by calling (608) 261-7715 or through the DNR's web site at http://dnr.wi.gov/topic/Brownfields/PECFA.html. However, because PECFA operates as a reimbursement program, responsible parties generally have to have an initial source of funding (e.g., a line of credit from a bank) available to pay the investigation and cleanup costs, and then seek reimbursement of those costs. In situations where the responsible party cannot come up with the initial funding needed to begin the investigation and cleanup, PECFA does offer a second alternative, the PECFA agent.

Mr. Stanley Evavold – January 27, 2015 Page 4

An agent means a person or organization (i.e., environmental consulting firm) designated by the responsible party to act on behalf of the responsible party in conducting the investigation and cleanup. The agent is responsible for paying for the cleanup and submitting the claims for PECFA reimbursement. The reimbursement checks are then issued in the name of the responsible party and the agent, and mailed to the agent. This alternative eliminates the need for a responsible party to secure a line of credit from a bank to pay the investigation and cleanup costs. More information about the PECFA agent process can be found at http://dnr.wi.gov/topic/Brownfields/PECFA.html under the Consultant/Agent tab, or by calling (608) 261-7715.

If you have any questions concerning this letter or the project in general, please do not hesitate to write or call me at 715-685-2920. I can also be reached by e-mail at Christopher.Saari@Wisconsin.gov.

Thank you for your cooperation.

Sincerely,

cc:

Christopher A. Saari Hydrogeologist

Patrick Dooley - Iron River Cooperatives, Inc.

- Did we record a lien as part of fack removal? Maybe DSPS did, not us. - Could Italk to Co-go a bout being agent, get loen on for deductible? Sure Or I could just try to get Evavold to act as ayent since they traly are broke It Evovold denics access, will probably have to get in great warmst - I'll contact Evavold (and loop) ask it he can be agent lacey is checking w/J. Moser about lien issue.

Real Estate Bayfield County Property Listing Today's Date: 1/26/2015

Property Status: Current Created On: 3/15/2006 1:15:54 PM

IRON RIVER 54847

Description	Updated: 9/28/2004
parent la company of the company of	
Tax ID:	26860
PIN:	04-038-2-48-09-17-3 03-000-20000
Legacy PIN:	038103405000
Map ID:	
Municipality:	(038) TOWN OF OULU
STR:	S17 T48N R09W
Description:	PAR IN SW SW IN V.462 P.191, 301
Recorded Acres:	1.750
Calculated Acres:	1.738
Lottery Claims:	0
First Dollar:	Yes
Coning:	(C) Commercial
ESN:	125
1.11	

Tax Districts	Updated: 3/15/2006		
	STATE		
<u> </u>	COUNTY		
038	TOWN OF OULU		
044522	SCHL-SOUTHSHORE		
201700	TECHNICAL COLLEGE		
Recorded Documents	Undated: 3/15/2006		

4	SINIL
ું જેવાર -	COUNTY
038.	TOWN OF OULU
044522	SCHL-SOUTHSHORE
୍ରୀ 700 <u> </u>	TECHNICAL COLLEGE
Recorded Documents	Updated: 3/15/2006
ONVERSION	
**************************************	83-284;115-59;462-191

Ownership	Updated: 3/15/20			
STANLEY A EVAVOLD	SUPERIOR WI			
Billing Address:	Mailing Address:			
STANLEY A EVAVOLD	STANLEY A EVAVOLD			
14 ROYALTON RD	14 ROYALTON RD			
SUPERIOR WI 54880	SUPERIOR WI 54880			

Property Assessment		- Opuateu:	3/15/2006
2014 Assessment Detail			
Code	Acres	Land	Imp.
G2-COMMERCIAL	1.750	600	2,100
2-Year Comparison	2013	2014	Change
Land:	600	600	0.0%
Improved:	2,100	2,100	0.0%
Total:	2,700	2,700	0.0%

73010 CO HWY B

Property History	
N/A	

IRON RIVER COOPERATIVES, INC.

P.O. Box 8

IRON RIVER, WI 54847

IRON RIVER FOODS 715-372-4264 FAX 715-372-4199

Established in 1914

HARDWARE HANK 715-372-4200 Fax 715-372-5333

December 8, 2014

Wisconsin Department of Natural resources Christopher A. Saari Ashland Service Center 2501 Golf Course Road Ashland, WI 54806



Subject: Petroleum Contamination at 73010 County HWY B Town of Oulu, Bayfield County, Wisconsin WDNR BRRTS #03-04-559467

Dear Mr. Saari

After an investigation of our records and the records at the Bayfield County Clerk of Courts, the Iron River Cooperatives, Inc. is taking the position that we The Iron River Cooperatives, Inc. are not the responsible party in your communication on October 7, 2014. We believe this to be true for the following reasons:

- 1. The Iron River Cooperatives, Inc. sold the property in question to Mr. Stanley Evavold in 1987 including fuel oil which was still in one of the tanks at the time. See closing statement enclosed. The Cooperative has not possessed or had control over these tanks including the substances in them for the last 27 years.
- 2. The Cooperative made no warranties or promises to Mr. Evavold about any future liability or potential clean up in the transfer of the property in question.
- 3. Enclosed is the most recent court order for Mr. Evavold holding him in contempt for not complying with the State of Wisconsin order to clean up the site in question. Further examination of his file 01-CV -0095 shows that the State of Wisconsin filed a lawsuit in 2002 against Mr. Evavold and later a judgment that he Mr. Evavold was considered to be the responsible party and ordered to have the tanks removed, the site assessed and any contamination that was found to be to be cleaned up.

I have enclosed a copy of the warranty deed and the closing statement for the property in question as well as a copy of the contempt order against Mr. Stanley Evavold. I am also enclosing DSPS tank detail which incorrectly lists the Iron River Cooperatives, Inc. as the owner of this property. I do not know how to go about correcting this or if this is something your office can correct but it needs to be corrected. I would be willing to discuss this further with you if you have any questions or require additional information.

Sincerely,

General Manager

Iron River Cooperatives, Inc.



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Scott Walker, Governor Cathy Stepp, Secretary

Ashland Service Center 2501 Golf Course Road Ashland, Wisconsin 54806 Telephone 715-685-2900 FAX 715-685-2909

October 7, 2014

IRON RIVER CO-OP ASSOCIATION PO BOX 8 IRON RIVER WI 54847

Subject: Petroleum Contamination at the Former Iron River Co-op – Oulu Branch 73010 County Highway B, Town of Oulu, Bayfield County, Wisconsin WDNR BRRTS #03-04-559467

Dear Sir or Madam:

On October 15, 2012, the Wisconsin Department of Natural Resources (DNR) was notified by Mike Kohn of IC Environmental Corporation of gasoline contamination at the above referenced site. The contamination was identified during the removal of three underground storage tanks (USTs) from the site on July 17, 2012. The UST removal assessment was reportedly completed on behalf of the Wisconsin Department of Safety and Professional Services (DSPS). The DNR was waiting for ownership information from the DSPS before sending a letter to the responsible party/parties; that information was recently submitted to us.

Based on the information that has been submitted to the DNR regarding this site, we believe you are responsible for investigating and restoring the environment at the above-described site under Section 292.11, Wisconsin Statutes, known as the hazardous substances spill law.

This letter describes the legal responsibilities of a person who is responsible under section 292.11, Wis. Stats., explains what you need to do to investigate and clean up the contamination, and provides you with information about cleanups, environmental consultants, possible financial assistance, and working cooperatively with the DNR.

Legal Responsibilities:

Your legal responsibilities are defined both in statute and in administrative codes. The hazardous substances spill law, Section 292.11 (3) Wisconsin Statutes, states:

• RESPONSIBILITY. A person who possesses or controls a hazardous substance which is discharged or who causes the discharge of a hazardous substance shall take the actions necessary to restore the environment to the extent practicable and minimize the harmful effects from the discharge to the air, lands, or waters of the state.

I have addressed this letter to the Iron River Co-op Association because that party is listed on the attached Tank System Service and Closure Assessment Report as the owner of the USTs. I have also sent a copy of this letter to Mr. Stanley Evavold because, according to Bayfield County's property ownership records, he is listed as the owner of the property. Under the hazardous substances spill law, both the Iron River Co-op Association and Mr. Evavold could potentially be considered responsible for the contamination, as the "causer" or being in "possession and control" of the discharge, respectively. However, in this case it would appear that the Iron River Co-op Association would be the primary responsible party through their ownership of the former USTs.

In addition to the statutory requirements, Wisconsin Administrative Code chapters NR 700 through NR 754 establish requirements for emergency and interim actions, public information, site investigations, design and operation of remedial action systems, and case closure. Wisconsin Administrative Code chapter NR 140 establishes groundwater standards for contaminants that reach groundwater.

Steps to Take:

The longer contamination is left in the environment, the farther it can spread and the more it may cost to clean up. Quick action may lessen damage to your property and neighboring properties and reduce your costs in investigating and cleaning up the contamination. To ensure that your cleanup complies with Wisconsin's laws and administrative codes, you should hire a professional environmental consultant who understands what needs to be done. The following information provides the timeframes and required steps to take. Unless otherwise approved by DNR in writing you must complete the work by the timeframes specified.

- 1. Within the next 45 days, by November 21, 2014, you should submit written verification (such as a letter from the consultant) that you have hired an environmental consultant. If you do not take action within this time frame, the DNR may initiate enforcement action against you.
- 2. Within **60 days**, by December 6, 2014, you must submit a work plan for completing the investigation. The work plan must comply with the requirements in the NR 700 Wis. Adm. Code rule series and should adhere to current DNR technical guidance documents.
- 3. You must initiate the site investigation within 90 days of submitting the site investigation work plan. You may proceed with the field investigation upon DNR notification to proceed. If the DNR has not responded within 30 days from submittal of the work plan, you are required to proceed with the field investigation. If a fee for DNR review has been submitted, the field investigation must begin within 60 days after receiving DNR approval.
- 4. Within 60 days after completion of the field investigation and receipt of the laboratory data, you must submit a Site Investigation Report to the DNR or other agency with administrative authority. For sites with agrichemicals contamination, your case will be transferred to the Department of Agriculture, Trade and Consumer Protection for oversight.
- 5. Within 60 days after submitting the Site Investigation Report, you must submit a remedial actions options report.

Sites where discharges to the environment have been reported are entered into the Bureau for Remediation and Redevelopment Tracking System ("BRRTS"), a version of which appears on the DNR's internet site. You may go to http://dnr.wi.gov/botw/SetUpBasicSearchForm.do and view the information related to your site at any time and use the feedback system to alert us to any errors in the data.

If you want a formal written response from the department on a specific submittal, please be aware that a review fee is required in accordance with ch. NR 749, Wis. Adm. Code. If a fee is not submitted with your reports, you must complete the site investigation and cleanup to maintain your compliance with the spills law and chapters NR 700 through NR 754. The timeframes specified above are required by rule, so do not delay the investigation of your site. We have provided detailed technical guidance to environmental consultants. Your consultant is expected to know our technical procedures and administrative rules and should be able to answer your questions on meeting cleanup requirements.

All correspondence regarding this site should be sent to me at the above address. Unless otherwise directed, submit one paper copy and one electronic copy of plans and reports. To speed processing, correspondence should reference the BRRTS number shown at the top of this letter.

Site Investigation and Vapor Pathway Analysis

As you develop the site investigation work plan, we want to remind you to include an assessment of the vapor intrusion pathway. Chapter NR 716, Wis. Adm. Code, outlines the requirements for investigation of contamination in the environment. Specifically, s. NR 716.11(3) (a) requires that the field investigation determine the "nature, degree and extent, both areal and vertical, of the hazardous substances or environmental pollution in all affected media". In addition, ss. NR 716.11(5) (g) and (h) contain the specific requirements for evaluating the presence of vapors in the sub-surface as well as in indoor air.

You will need to include documentation with the Site Investigation Report that explains how the assessment was done. If the vapor pathway is being ruled out, then the report needs to provide the appropriate justification for reaching this conclusion. If the pathway cannot be ruled out, then investigation and, if appropriate, remedial action must be taken to address the risk presented prior to submitting the site for closure. The DNR has developed guidance to help responsible parties and their consultants comply with the requirements described above. The guidance includes a detailed explanation of how to assess the vapor intrusion pathway and provides criteria which identify when an investigation is necessary. The guidance is available at: http://dnr.wi.gov/files/PDF/pubs/rr/RR800.pdf.

Additional Information for Site Owners:

asan

We encourage you to visit our website at http://dnr.wi.gov/topic/Brownfields/, where you can find information on selecting a consultant, financial assistance and understanding the cleanup process. You will also find information there about liability clarification letters, post-cleanup liability and more.

If you have any questions concerning this letter or the project in general, please do not hesitate to write or call me at 715-685-2920. I can also be reached by e-mail at Christopher.Saari@Wisconsin.gov.

Thank you for your cooperation.

Sincerely,

Christopher A. Saari Hydrogeologist

Enclosures:

Tank System Service and Closure Assessment Report

Selecting a Consultant – RR-502 http://dnr.wi.gov/files/PDF/pubs/rr/RR502.pdf

Environmental Services Contractor List – RR-024 http://dnr.wi.gov/files/PDF/pubs/rr/RR024.pdf

Petroleum Environmental Cleanup Fund Award, Information about PECFA Reimbursement, DNR Publication RR-942 http://dnr.wi.gov/topic/brownfields/pecfa.html

cc: Stanley Evavold, 14 Royalton Rd., Superior, WI 54880 (w/o attachments)
Mike Kohn – ICECOR

STATE OF WISCONSIN,

Plaintiff,

v

Case No. 01-CV-0095

FILED

Iffice of Clerk of Courts
BAYFIELD COUNTY

STANLEY A. EVAVOLD,

Defendant.

MAY 2 1 2012

Kay of Coderley

ORDER FOR CONTEMPT

On May 14, 2012, the Court heard the plaintiff's motion for remedial sanctions, brought pursuant to Wis. Stat. §§ 785.03(1)(a) and 785.04(1), which sought an order finding Mr. Evavold in contempt of court and imposing appropriate and purgeable remedial sanctions for his alleged failure to fully comply with the Court's Order for Judgment dated October 21, 2002. The October 21, 2002 Order had required Mr. Evavold to remove unused and noncompliant underground storage tanks that had been used to store gasoline, and to have the excavation site properly assessed.

The plaintiff State of Wisconsin appeared at the hearing by Assistant Attorney General Diane L. Milligan. After being given proper notice, the defendant Stanley A. Evavold appeared in person.

Based on the record, the evidence presented, and arguments of the parties, and for the reasons stated at the hearing, the Court made findings and issued orders as follows.

THE COURT FINDS:

- 1. Defendant Stanley A. Evavold is in contempt of court for failing to comply with the deadlines set by the Court's October 21, 2002 Order.
- 2. Mr. Evavold is unable to pay for the removal of the abandoned underground petroleum storage tank(s) on his property, and removal by the State of Wisconsin Department of Safety and Professional Services (DSPS), pursuant to Wis. Stat. § 101.1435, is in the interest of justice.
- 3. It is fair and reasonable to impose monetary forfeitures of \$50.00 per day as remedial sanctions; to stay those sanctions; and to purge the sanctions if Mr. Evavold cooperates with the DSPS when it has the underground petroleum storage tank(s) on his property removed pursuant to its authority under Wis. Stat. § 101.1435.

IT IS ORDERED:

1. Defendant Stanley A. Evavold shall pay \$50.00 per day in forfeitures to the Bayfield County Clerk of Courts, as a remedial sanction pursuant to Wis. Stat. § 785.04(1)(c).

IT IS FURTHER ORDERED:

- 2. The foregoing order imposing forfeitures is stayed.
- 3. The order imposing forfeitures will be purged in its entirety if Mr. Evavold cooperates with the DSPS, if he works in conjunction with that agency to apply for any and all programs that may be available to assist with payment of removal costs, and if Mr. Evavold signs any and all necessary paperwork to facilitate the removal of the tank(s) and the assessment and backfilling of his property.

4. The DSPS and its contracted agents shall be granted access to the property described in the Complaint for the purpose of removing the underground storage tanks, pursuant to Wis. Stat. § 101.1435(2). DSPS may then file a lien on the property for the amount of the costs incurred for the removal of the tank systems, the assessment of the site, and the backfilling of the excavation, pursuant to Wis. Stat. § 101.1435(3).

Dated this 2 day of Meux

, 2012.

BY THE COURT

THE HONORABLE JOHN P. ANDERSON

Bayfield County Circuit Court

Search by Site, Owner, or Tank Search by Tank ID Search Instructions **Characteristics** Tank Detail Site and Owner **County & Municipality** Owner Site Info Facility ID: 89958 IRON RIVER COOP - OULU BRANCH 04 - BAYFIELD ID: 325560 IRON RIVER COOP 73010 COUNTY HWY B Town of OULU Fire Dept ID: 0412 - Iron River 307 MAIN ST **BRULE** Landowner Type: Private PO Box 8 **IRON RIVER WI 54847** Site Anniversary Date: Dispensers have Sumps: Unknown Underground Storage Tank - ID: 254150, Wang ID: 041200027, Closed/Removed as of 11/15/1990 Capacity in Gallons: 500 Contents: Fuel Oil Install Date: **CAS Number:** Tank Occupancy: Mercantile/Commercial Marketer: Required Required **Overfill Protection:** - Not - Not **Spill Protection:** Federally Regulated: Installed Installed Containment Sump Installed: Unknown Overfill Prot Type: null **Lining Inspected Date: Corrosion Protect Type:** Date of Lining: **Cath Expire Date: Cath Test Date:** Leak Detection: Unknown Leak Expire Date: **Leak Test Date:** Leak Test Meth: Underground Piping: Y Construction Material: **Coated Steel** Wall Size: Single **Close Order Date:** Close Order By: Piping - Closed/Removed Related Tank ID: Flex Connectors: **UST** mainfolded: **Aboveground Piping: Aboveground Pipe Construction:** Type: Unknown **Leak Detection: Construction Material:** Unknown Corrosion Protect Type:

Cath Test Date:

Cath Expire Date:

Leak Test Meth:

Leak Test Date:

Leak Expire Date:

Pipe Wall Size:

Single

Catastrophic Leak Detection:

Cat Leak Test Date:

Piping System Type:

Unknown

Inspections

Click here for login page

Trans ID

Type

Status

Date Fiscal Yr

** No inspections for this tank **

Close this response window

Wisconsin Department of Safety and Professional Services

Search In	structions	Search	by Site, Owr Characterist	er, or Tank tics	Search by	Tank ID	
Annual Control of the							
Tank Detail							

Site and Owner

Site Info **County & Municipality**

Facility ID: 89958 IRON RIVER COOP - OULU BRANCH 04 - BAYFIELD

ID: 325560

Owner

73010 COUNTY HWY B

Landowner Type: Private

Town of OULU

IRON RIVER COOP

IRON RIVER WI 54847

Fire Dept ID: 0412 - Iron River 307 MAIN ST

PO Box 8

Site Anniversary Date:

Dispensers have Sumps: Unknown

Underground Storage Tank - ID: 254221, Wang ID: 041200099, Closed/Removed as of 07/17/2012

Install Date:

BRULE

Capacity in Gallons:

750

Contents:

Leaded Gasoline

Tank Occupancy:

Retail

Fuel Sales Marketer:

Υ

CAS Number:

Federally Regulated:

Spill Protection:

Required -

Required -

Υ

Not Installed **Overfill Protection:**

Not Installed

Overfill Prot Type:

null

Containment Sump Installed: Unknown Date of Lining:

Lining Inspected Date:

Corrosion Protect Type: Leak Detection:

Unknown Cath Test Date:

Cath Expire Date:

Leak Test Meth:

Leak Expire Date:

Leak Test Date:

Construction Material: Bare Steel Wall Size:

Single

Underground Piping: Y

Close Order Date:

Close Order By:

Piping - Abandoned without Product

Flex Connectors:

UST mainfolded:

Related Tank ID:

Type:

Aboveground Piping:

Construction Material:

Unknown Corrosion Protect Type:

Aboveground Pipe Construction:

Unknown

Leak Detection:

Cath Test Date:

Cath Expire Date:

Leak Test Meth:

Single

Leak Test Date: Catastrophic Leak Detection: **Leak Expire Date:** Cat Leak Test Date: Pipe Wall Size: **Piping System Type:**

Unknown

Inspections

Click here for login page

Trans ID

Type

Status

Date Fiscal Yr

916321

AN

2004

CLNI

Close this response window

Wisconsin Department of Safety and Professional Services

Appell to was the Value of the construction of		
Search Instructions	Search by Site, Owner, or Tank Characteristics	Search by Tank ID

Tank Detail

Site and Owner

Site Info **County & Municipality** Owner ID: 325560

Facility ID: 89958 IRON RIVER COOP - OULU BRANCH 04 - BAYFIELD 73010 COUNTY HWY B

Town of OULU IRON RIVER COOP

Leak Test Date:

BRULE Fire Dept ID: 0412 - Iron River 307 MAIN ST

Landowner Type: Private PO Box 8

IRON RIVER WI 54847

Required

Site Anniversary Date: Dispensers have Sumps: Unknown

Underground Storage Tank - ID: 254222, Wang ID: 041200100, Closed/Removed as of 07/17/2012

Unleaded 500 Contents: Install Date: Capacity in Gallons: Gasoline

Retail

CAS Number: Fuel Marketer: **Tank Occupancy:**

Sales

Required - Not **Overfill Protection:** - Not Federally Regulated: Υ **Spill Protection:** Installed

Installed

Overfill Prot Type: null Containment Sump Installed: Unknown

Corrosion Protect Type: Date of Lining: Lining Inspected Date: **Cath Expire Date: Leak Detection:** Unknown Cath Test Date:

Leak Test Meth: Leak Expire Date:

Bare Underground Piping: Y Wall Size: Single **Construction Material:**

Steel

Close Order Date: Close Order By: Piping - Closed/Removed

Related Tank ID: **UST** mainfolded: Flex Connectors:

Aboveground Pipe Construction: Aboveground Piping: Type:

Steel Corrosion Protect Type: Unknown Leak Detection: **Construction Material:**

Leak Test Meth: Cath Expire Date: Cath Test Date:

Single Pipe Wall Size: Leak Expire Date: **Leak Test Date:** Unknown **Piping System Type:** Cat Leak Test Date: **Catastrophic Leak Detection:**

Inspections Click here for login page

Date Fiscal Yr Type Status Trans ID 2004 **CLNI** AN 916321

Close this response window

Search by Site, Owner, or Tank **Search Instructions** Search by Tank ID **Characteristics**

Tank Detail

Site and Owner

Site Info County & Municipality

Facility ID: 89958 IRON RIVER COOP - OULU **BRANCH**

73010 COUNTY HWY B

BRULE

Landowner Type: Private

04 - BAYFIELD Town of OULU

Fire Dept ID: 0412 - Iron

River

Owner ID: 325560

IRON RIVER COOP

307 MAIN ST PO Box 8

IRON RIVER WI

54847

Site Anniversary Date: Dispensers have Sumps: Unknown

Underground Storage Tank - ID: 1398299, Wang ID: null, Closed/Removed as of 07/17/2012

Install Date:

Capacity in Gallons:

550

Y

Contents:

Leaded

Gasoline

Retail

null

Tank Occupancy:

Fuel Marketer: Sales

Required

CAS Number:

Required

- Not

Federally Regulated:

Corrosion Protect Type:

Υ **Spill Protection:** - Not

Overfill Protection:

Installed

Installed

Overfill Prot Type:

Date of Lining:

Containment Sump Installed: Unknown

Lining Inspected Date: Cath Expire Date:

Leak Detection: Leak Test Meth: null

Cath Test Date: Leak Expire Date:

Leak Test Date:

Construction Material:

Bare

Wall Size: Steel

Underground Piping:

Close Order Date:

Close Order By:

Piping - Closed/Removed

Flex Connectors:

UST mainfolded:

Related Tank ID:

Type:

Aboveground Piping:

Aboveground Pipe Construction:

Construction Material:

Corrosion Protect Type:

Leak Detection:

null

Cath Test Date:

Steel

Cath Expire Date:

Leak Test Meth:

Leak Test Date:

Leak Expire Date:

Pipe Wall Size:

Catastrophic Leak Detection:

Cat Leak Test Date:

Piping System Type:

Inspections

Click here for login page

Trans ID

Type Status

Date Fiscal Yr

** No inspections for this tank **

Close this response window

CLOSING STATEMENT IRON RIVER COOP/EVAVOLD

		rice:			\$6,500.00
Fue1	Oil -	550 ga.	L @ \$.75/gal.:		412.50
	Total	Price:			\$6,912.50

Credits to Buyer:

Rent applied to purchase	Ψ 300.00		
price - 3 Mo. @ \$200:	600.00		
Real Estate tax prorate:	<u>361.21</u>		
Total Credits:	\$1,461.21		
		\$6,912	

\$6,912.50 -1,461.21 TOTAL DUE SELLER: \$5,451.29

\$ 500.00

Seller will issue to buyer a check in the amount of \$19.50 as transfer fee.

ACCEPTED ;

Starley A avoid 9-15-87

James A Loward

DOCUMENT NO. THIS SPACE RESERVED FOR RECORDING DATA STATE BAR OF WISCONSIN FORM 2-1982 372447 REGISTER'S OFFICE } s.s. Bayfield County, Wis. RECORDED AT Iron River Cooperative, Inc. formerly ON NOV 2 4 1987 The Farmer's Co-operative Mercantible Vol. 46 2 of RGC Page 191 ys and warrants to Stanley A. Evavold, a married man remeter of denos Stanlex A. Evavold, 14 Royalton Road TA.19-50Pd.) Superior, WI. 54880 the following described real estate in ... Bayfield ... County, State of Wisconsin:
The Southwest Quarter of the Southwest Quarter The Southwest Quarter of the Southwest Quarter Tax Parcel No:

(SW% of SW%), Section Seventeen (17), Township forty-eight (48) North,
Range Nine (9) West, described as follows: Beginning at the Southwest corner
of said Southwest Quarter of the Southwest Quarter (SW% of SW%); thence
North along the Section Line 416 feet; thence East 104 feet; thence South
208 feet; thence East 156 feet; thence South 208 feet to the South Line
of said Southwest Quarter of the Southwest Quarter (SW% of SW%); thence
West along the South Line 260 feet to the point of beginning; Bayfield
County Wisconsin County, Wisconsin. FEE EXEMPT TRANSFER FEE RENTAL WEATHERIZATION CODE is not homestead property. Exception to warranties: day of SEPTEMBER Dated this ... • Robert C. Johnson, President by: ___((SEAL) AUTHENTICATION ACKNOWLEDGMENT STATE OF WISCONSIN Signature(s) Bayfield County. Personally came before me this ... 2nd day of September 19.87 the above named Robert C Johnson and James R Swaab Thomas T. Lindsey TITLE: MEMBER STATE BAR OF WISCONSIN

Notary Public Bayfield County, Wis.
My Commission is permanent (If not, state expiration (Signatures may be authenticated or acknowledged. Both are not necessary.) date: 8-14-88 , 19 88) 462 Page 191

authorized by § 706.06, Wis. Stats.)

THIS INSTRUMENT WAS DRAFTED BY

Thomas T. Lindsey

Volume 462

.....524£...

to me known to be the person .S who executed the foregoing instrument and acknowledge the same.

Sande & Horacia

* Sandra Kovacic



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Scott Walker, Governor Cathy Stepp, Secretary

Ashland Service Center 2501 Golf Course Road Ashland, Wisconsin 54806 Telephone 715-685-2900 FAX 715-685-2909

October 7, 2014

IRON RIVER CO-OP ASSOCIATION PO BOX 8
IRON RIVER WI 54847

FILE COPY

Subject: Petroleum Contamination at the Former Iron River Co-op – Oulu Branch 73010 County Highway B, Town of Oulu, Bayfield County, Wisconsin WDNR BRRTS #03-04-559467

Dear Sir or Madam:

On October 15, 2012, the Wisconsin Department of Natural Resources (DNR) was notified by Mike Kohn of IC Environmental Corporation of gasoline contamination at the above referenced site. The contamination was identified during the removal of three underground storage tanks (USTs) from the site on July 17, 2012. The UST removal assessment was reportedly completed on behalf of the Wisconsin Department of Safety and Professional Services (DSPS). The DNR was waiting for ownership information from the DSPS before sending a letter to the responsible party/parties; that information was recently submitted to us.

Based on the information that has been submitted to the DNR regarding this site, we believe you are responsible for investigating and restoring the environment at the above-described site under Section 292.11, Wisconsin Statutes, known as the hazardous substances spill law.

This letter describes the legal responsibilities of a person who is responsible under section 292.11, Wis. Stats., explains what you need to do to investigate and clean up the contamination, and provides you with information about cleanups, environmental consultants, possible financial assistance, and working cooperatively with the DNR.

Legal Responsibilities:

Your legal responsibilities are defined both in statute and in administrative codes. The hazardous substances spill law, Section 292.11 (3) Wisconsin Statutes, states:

• RESPONSIBILITY. A person who possesses or controls a hazardous substance which is discharged or who causes the discharge of a hazardous substance shall take the actions necessary to restore the environment to the extent practicable and minimize the harmful effects from the discharge to the air, lands, or waters of the state.

I have addressed this letter to the Iron River Co-op Association because that party is listed on the attached Tank System Service and Closure Assessment Report as the owner of the USTs. I have also sent a copy of this letter to Mr. Stanley Evavold because, according to Bayfield County's property ownership records, he is listed as the owner of the property. Under the hazardous substances spill law, both the Iron River Co-op Association and Mr. Evavold could potentially be considered responsible for the contamination, as the "causer" or being in "possession and control" of the discharge, respectively. However, in this case it would appear that the Iron River Co-op Association would be the primary responsible party through their ownership of the former USTs.

In addition to the statutory requirements, Wisconsin Administrative Code chapters NR 700 through NR 754 establish requirements for emergency and interim actions, public information, site investigations, design and operation of remedial action systems, and case closure. Wisconsin Administrative Code chapter NR 140 establishes groundwater standards for contaminants that reach groundwater.

Steps to Take:

The longer contamination is left in the environment, the farther it can spread and the more it may cost to clean up. Quick action may lessen damage to your property and neighboring properties and reduce your costs in investigating and cleaning up the contamination. To ensure that your cleanup complies with Wisconsin's laws and administrative codes, you should hire a professional environmental consultant who understands what needs to be done. The following information provides the timeframes and required steps to take. Unless otherwise approved by DNR in writing you must complete the work by the timeframes specified.

- 1. Within the next **45 days**, by November 21, 2014, you should submit <u>written</u> verification (such as a letter from the consultant) that you have hired an environmental consultant. If you do not take action within this time frame, the DNR may initiate enforcement action against you.
- 2. Within 60 days, by December 6, 2014, you must submit a work plan for completing the investigation. The work plan must comply with the requirements in the NR 700 Wis. Adm. Code rule series and should adhere to current DNR technical guidance documents.
- 3. You must initiate the site investigation within 90 days of submitting the site investigation work plan. You may proceed with the field investigation upon DNR notification to proceed. If the DNR has not responded within 30 days from submittal of the work plan, you are required to proceed with the field investigation. If a fee for DNR review has been submitted, the field investigation must begin within 60 days after receiving DNR approval.
- 4. Within 60 days after completion of the field investigation and receipt of the laboratory data, you must submit a Site Investigation Report to the DNR or other agency with administrative authority. For sites with agrichemicals contamination, your case will be transferred to the Department of Agriculture, Trade and Consumer Protection for oversight.
- 5. Within 60 days after submitting the Site Investigation Report, you must submit a remedial actions options report.

Sites where discharges to the environment have been reported are entered into the Bureau for Remediation and Redevelopment Tracking System ("BRRTS"), a version of which appears on the DNR's internet site. You may go to http://dnr.wi.gov/botw/SetUpBasicSearchForm.do and view the information related to your site at any time and use the feedback system to alert us to any errors in the data.

Enclosures:

Tank System Service and Closure Assessment Report

Selecting a Consultant – RR-502 http://dnr.wi.gov/files/PDF/pubs/rr/RR502.pdf

Environmental Services Contractor List – RR-024 http://dnr.wi.gov/files/PDF/pubs/rr/RR024.pdf

Petroleum Environmental Cleanup Fund Award, Information about PECFA Reimbursement, DNR Publication RR-942 http://dnr.wi.gov/topic/brownfields/pecfa.html

cc: Stanley Evavold, 14 Royalton Rd., Superior, WI 54880 (w/o attachments)
Mike Kohn – ICECOR

If you want a formal written response from the department on a specific submittal, please be aware that a review fee is required in accordance with ch. NR 749, Wis. Adm. Code. If a fee is not submitted with your reports, you must complete the site investigation and cleanup to maintain your compliance with the spills law and chapters NR 700 through NR 754. The timeframes specified above are required by rule, so do not delay the investigation of your site. We have provided detailed technical guidance to environmental consultants. Your consultant is expected to know our technical procedures and administrative rules and should be able to answer your questions on meeting cleanup requirements.

All correspondence regarding this site should be sent to me at the above address. Unless otherwise directed, submit one paper copy and one electronic copy of plans and reports. To speed processing, correspondence should reference the BRRTS number shown at the top of this letter.

Site Investigation and Vapor Pathway Analysis

As you develop the site investigation work plan, we want to remind you to include an assessment of the vapor intrusion pathway. Chapter NR 716, Wis. Adm. Code, outlines the requirements for investigation of contamination in the environment. Specifically, s. NR 716.11(3) (a) requires that the field investigation determine the "nature, degree and extent, both areal and vertical, of the hazardous substances or environmental pollution in all affected media". In addition, ss. NR 716.11(5) (g) and (h) contain the specific requirements for evaluating the presence of vapors in the sub-surface as well as in indoor air.

You will need to include documentation with the Site Investigation Report that explains how the assessment was done. If the vapor pathway is being ruled out, then the report needs to provide the appropriate justification for reaching this conclusion. If the pathway cannot be ruled out, then investigation and, if appropriate, remedial action must be taken to address the risk presented prior to submitting the site for closure. The DNR has developed guidance to help responsible parties and their consultants comply with the requirements described above. The guidance includes a detailed explanation of how to assess the vapor intrusion pathway and provides criteria which identify when an investigation is necessary. The guidance is available at: http://dnr.wi.gov/files/PDF/pubs/rr/RR800.pdf.

Additional Information for Site Owners:

nd as an

We encourage you to visit our website at http://dnr.wi.gov/topic/Brownfields/, where you can find information on selecting a consultant, financial assistance and understanding the cleanup process. You will also find information there about liability clarification letters, post-cleanup liability and more.

If you have any questions concerning this letter or the project in general, please do not hesitate to write or call me at 715-685-2920. I can also be reached by e-mail at Christopher.Saari@Wisconsin.gov.

Thank you for your cooperation.

Sincerely,

Christopher A. Saari Hydrogeologist

Saari, Christopher A - DNR

From:

Moser, James E - DNR

Sent:

Tuesday, October 07, 2014 3:28 PM

To:

Saari, Christopher A - DNR

Subject:

RE: Iron River Co-op - Oulu UST Removal, Town of Oulu, Bayfield County

Attachments:

Order for Contempt filed 5-21-12.pdf

Read the attached document.

We are committed to service excellence.

Visit our survey at http://dnr.wi.gov/customersurvey to evaluate how I did.

JAMES E MOSER

Phone:

(608) 267-7533

E-mail:

3

ζ.

3

1

james.moser@wisconsin.gov

From: Saari, Christopher A - DNR

Sent: Tuesday, October 07, 2014 3:23 PM

To: Moser, James E - DNR

Subject: RE: Iron River Co-op - Oulu UST Removal, Town of Oulu, Bayfield County

Excellent, thanks James! Did the State pay for this because the tank owner could not (or would not), or is there more to this?

We are committed to service excellence.

Visit our survey at http://dnr.wi.gov/customersurvey to evaluate how I did.

Chris Saari

Phone: (715) 685-2920 Christopher.Saari@Wi.gov

From: Moser, James E - DNR

Sent: Tuesday, October 07, 2014 3:21 PM

To: Saari, Christopher A - DNR

Subject: RE: Iron River Co-op - Oulu UST Removal, Town of Oulu, Bayfield County

Hi Chris, the PIFF Abandoned petroleum underground storage tank system removal State funds were used to remove the tank system from this site. This funding program moved over to the DNR when I was transferred from DATCP. I guess you could say I am Sheldon's successor, I managed this program while at DATCP and I continue to do so here at DNR.

Do not hesitate to contact me if you have questions about sites that have had their tank systems removed. I have all the files.

Cordially

We are committed to service excellence.

Visit our survey at http://dnr.wi.gov/customersurvey to evaluate how I did.

JAMES E MOSER

Phone: (608) 267-7533

E-mail:

james.moser@wisconsin.gov

From: Saari, Christopher A - DNR

Sent: Tuesday, October 07, 2014 3:05 PM

To: Moser, James E - DNR

Subject: Iron River Co-op - Oulu UST Removal, Town of Oulu, Bayfield County

Hi James:

As you can see below, Greg Bareta at DATCP suggested that I run my question by you. I was trying to determine if the USTs removed from the above site in July 2012 were done so using state or federal funds. I was lead to believe that from the site assessment contractor. No hurry, I was just curious to see how this happened.

We are committed to service excellence.

Visit our survey at http://dnr.wi.gov/customersurvey to evaluate how I did.

Chris Saari

Phone: (715) 685-2920 Christopher.Saari@Wi.gov

From: Bareta, Greg P - DATCP

Sent: Tuesday, October 07, 2014 2:44 PM

To: Saari, Christopher A - DNR

Subject: RE: Sheldon Schall's Old Job

Most likely state funds or maybe brownfield funds (fed?). See if James Moser in your department has the information, otherwise I can pull the file from the records center and see if it's in there.

Let me know.

Greg

From: Saari, Christopher A - DNR

Sent: Monday, October 06, 2014 2:28 PM

To: Bareta, Greg P - DATCP

Subject: RE: Sheldon Schall's Old Job

Greg, were these tanks pulled using state and/or federal funds? That's what I was lead to believe by the site assessment contractor.

We are committed to service excellence.

Visit our survey at http://dnr.wi.gov/customersurvey to evaluate how I did.

Chris Saari

Phone: (715) 685-2920 Christopher.Saari@Wi.gov

From: Bareta, Greg P - DATCP

Sent: Monday, October 06, 2014 2:10 PM

To: Saari, Christopher A - DNR

Subject: RE: Sheldon Schall's Old Job

Chris.

The RP (owner) was/is listed as:

Iron River Coop 307 Main St Iron River, WI 54847 (715) 372-4264

Hope this is what you were looking for.

Greg

Greg Bareta P.E.

Section Chief
Storage Tank Regulation
Bureau of Weights & Measures
Wisconsin Department of Agriculture, Trade and Consumer Protection (DATCP)
2811 Agriculture Dr.
Madison, WI 53708
Ph: (608) 224-5150

Fax: (608) 221-6592

greg.bareta@wisconsin.gov

From: Saari, Christopher A - DNR

Sent: Monday, October 06, 2014 10:09 AM

To: Smith, Ralph N - DNR **Cc:** Bareta, Greg P - DATCP

Subject: RE: Sheldon Schall's Old Job

Thanks Ralph.

Greg, the property in question is the Iron River Co-op — Oulu Branch, at 73010 County Highway B in Iron River (Bayfield County). The USTs were removed on July 17, 2012 by Twin Ports Environmental Construction and the site assessment was performed by IC Environmental Corp (ICECOR).

We are committed to service excellence.

Visit our survey at http://dnr.wi.gov/customersurvey to evaluate how I did.

Chris Saari

Phone: (715) 685-2920 Christopher.Saari@Wi.gov

From: Smith, Ralph N - DNR

Sent: Monday, October 06, 2014 10:03 AM

To: Saari, Christopher A - DNR

Cc: Bareta, Greg P - DATCP

Subject: RE: Sheldon Schall's Old Job

Hi Chris, I think his successor is Greg Bareta at DATCP.

Greg - Can you help Chris out with this?

Thanks!

We are committed to service excellence.

Visit our survey at http://dnr.wi.gov/customersurvey to evaluate how I did.

Ralph Smith

Phone: (608) 261-6543 Ralph.Smith@wisconsin.gov

From: Saari, Christopher A - DNR

Sent: Monday, October 06, 2014 9:53 AM

To: Smith, Ralph N - DNR

Subject: Sheldon Schall's Old Job

Hi Ralph:

I know that Sheldon Schall was at DSPS, but do you know where his successor would be now (DSPS or DATCP)? If so, would you happen to know who that person is? I'm trying to track down some info on a LUST site where DSPS apparently paid for the UST removals (with federal LUST money?). Schall was supposed to forward me info on who the RP is, but I never received it. Thanks.

We are committed to service excellence.

Visit our survey at http://dnr.wi.gov/customersurvey to evaluate how I did.

Chris Saari

Hydrogeologist – Remediation and Redevelopment Program Wisconsin Department of Natural Resources

Phone: (715) 685-2920 Fax: (715) 685-2909 Christopher.Saari@Wi.gov



STATE OF WISCONSIN

CIRCUIT COURT

BAYFIELD COUNTY

STATE OF WISCONSIN,

Plaintiff,

V.

Case No. 01-CV-0095 FILED
Office of Clerk of Courts
BAYFIELD COUNTY

MAY 2 1 2012

STANLEY A. EVAVOLD,

Defendant.

nay of course

ORDER FOR CONTEMPT

On May 14, 2012, the Court heard the plaintiff's motion for remedial sanctions, brought pursuant to Wis. Stat. §§ 785.03(1)(a) and 785.04(1), which sought an order finding Mr. Evavold in contempt of court and imposing appropriate and purgeable remedial sanctions for his alleged failure to fully comply with the Court's Order for Judgment dated October 21, 2002. The October 21, 2002 Order had required Mr. Evavold to remove unused and noncompliant underground storage tanks that had been used to store gasoline, and to have the excavation site properly assessed.

The plaintiff State of Wisconsin appeared at the hearing by Assistant Attorney General Diane L. Milligan. After being given proper notice, the defendant Stanley A. Evavold appeared in person.

Based on the record, the evidence presented, and arguments of the parties, and for the reasons stated at the hearing, the Court made findings and issued orders as follows.

THE COURT FINDS:

- 1. Defendant Stanley A. Evavold is in contempt of court for failing to comply with the deadlines set by the Court's October 21, 2002 Order.
- 2. Mr. Evavold is unable to pay for the removal of the abandoned underground petroleum storage tank(s) on his property, and removal by the State of Wisconsin Department of Safety and Professional Services (DSPS), pursuant to Wis. Stat. § 101.1435, is in the interest of justice.
- 3. It is fair and reasonable to impose monetary forfeitures of \$50.00 per day as remedial sanctions; to stay those sanctions; and to purge the sanctions if Mr. Evavold cooperates with the DSPS when it has the underground petroleum storage tank(s) on his property removed pursuant to its authority under Wis. Stat. § 101.1435.

IT IS ORDERED:

1. Defendant Stanley A. Evavold shall pay \$50.00 per day in forfeitures to the Bayfield County Clerk of Courts, as a remedial sanction pursuant to Wis. Stat. § 785.04(1)(c).

IT IS FURTHER ORDERED:

- 2. The foregoing order imposing forfeitures is stayed.
- 3. The order imposing forfeitures will be purged in its entirety if Mr. Evavold cooperates with the DSPS, if he works in conjunction with that agency to apply for any and all programs that may be available to assist with payment of removal costs, and if Mr. Evavold signs any and all necessary paperwork to facilitate the removal of the tank(s) and the assessment and backfilling of his property.

4. The DSPS and its contracted agents shall be granted access to the property described in the Complaint for the purpose of removing the underground storage tanks, pursuant to Wis. Stat. § 101.1435(2). DSPS may then file a lien on the property for the amount of the costs incurred for the removal of the tank systems, the assessment of the site, and the backfilling of the excavation, pursuant to Wis. Stat. § 101.1435(3).

Dated this 2 day of May

BY THE COUR

THE HONORABLE JOHN P. ANDERSON

Bayfield County Circuit Court

Real Estate Bayfield County Tax Record Today's Date: 10/6/2014

LISTING FOR TAX YEAR: 2013

Tax Records:	2013	2012	2011	2010	2009	2008	2007	2006	2005	2004	2003	2002

Property Identification				
Tax ID:	26860			
PIN:	04-038-2-48-09-17-3 03-000-20000			
Legacy PIN:	038103405000			
Map ID:				

2013 Ownership	Billing Address
STANLEY A EVAVOLD	STANLEY A EVAVOLD
	14 ROYALTON RD
	SUPERIOR WI 54880

2013 Property Values	
Total Land Value:	600
Total Improved Value:	2,100
Total Forestry Land Value:	0
Total Value:	2,700
Estimated Fair Market - Land:	600
Estimated Fair Market - Improved:	2,000
Estimated Fair Market - Forest Land:	0
Total Estimated Fair Market:	2,600

2013 Levy & Tax Information	
Aggregate Ratio:	1.0533
Mill Rate:	0.015763409
School Credit:	3.33

	Specials
	1

2013 Tax Bill	Status: Paid In F			
	Due	Paid	Balance	
Gross Real Estate	42.56			
First Dollar Credit	- 23.08			
Lottery Credit	- 0.00			
Real Estate	19.48	19.48	0.00	
Special Assessments	0.00	0.00	0.00	
Special Charges	0.00	0.00	0.00	
Delinquent Utilities	0.00	0.00	0.00	
Private Forest	0.00	0.00	0.00	
Managed Forest Open	0.00	0.00	0.00	
Managed Forest Closed	0.00	0.00	0.00	
Amount Due:			0.00	

Installments					
Installment #	Due	Payable To	Amount		
Installment 1	1/31/2014	Municipality	19.48		
Installment 2	7/31/2014	County	0.00		
		Total ->	19 48		

Payments			
Receipt #	Posted	Paid By	Amount
1400652	3/17/2014	HEATHER L OPSAHL	19.87
			VOIDED
1400653	3/17/2014	HEATHER OPSAHL	19.48



03-04-559467

	CECOR
ΙĊ	ENVIRONMENTAL CORPORATION P.O. Box 1105 • Superior, WI 54880 715-395-0965

Date:	
Project#:	
Client:	
RE:	
N.I.	

715-395-0965	Name:
Davielle,	
- Pulled Tomks for State @ Oylo Contact Name or p4 #. St	2 Site, Not Know Owne
	neldon Schall (USAS) Shorld
be Working On it.	
- This 1.5 Your Cop.	
- Call 17 Questions,	
Mike III	
Mike (218)428-6714	

Complete One Form for Each System Service Event

The information you provide may be used for secondary purposes

TANK SYSTEM SERVICE AND CLOSURE ASSESSMENT REPORT

CHECK ONE:
UNDERGROUND

RETURN COMPLETED CHECKLIST TO:

Wisconsin Department of Commerce ERS Division Bureau of Petroleum Products and

[Privacy Law,	s.15.04 (1)	(m), Wis. Stats.]	Ī	ABO	VEGRO	JND	Tar		
		1		R PORTIONS NOT APPLY,			84-). Box 7837 dison, WI 53707-783	37
Part A -	To be co	mpleted by	contractor				` 		
		E X CLOSU		AIR/UPGRAL	<u> </u>				
			serviced if a re	epair, upgrade	or <u>change</u>	-in-service is	s being perfor		
	lemote fill	☐ Tank	☐ Piping	LJ I ran:	sition/conta	inment sum	р Ц Spi	Il bucket	nser
1. Facility N	Name_	(Please Print	<u> </u>	. 0)	2. Owner	Name _	<u> </u>	<i>C</i> = 5	
	7/0	V KNEL (100P-OU	ily Brand	1	11	ron Rive	100P	
racility Stre	et Address	INDIPII ROV	by Huy E	_	3. Contac	a Name			Job Title
Municipality	Ou		· I		Mailing A	ddress 33	7 Mains	, leet, PO Box	8
☐ City ☐	Village	Town of:			Post Office	e Iron	River	State W T	Zip Code 54847
Zip Code 5	4820	County	Douglas	Barfield	County	Dougl	BEYFIELD	Telephone No. (inclu	
4. Primary S	Service Co	ntractor Sectio	n A above	· · · · · · · · · · · ·	Service, C		reet Address	Clarati	
			Martal Conclude area co				olorado	Street	
(A/X) 343	19. (12. (1. (1. (1. (1. (1. (1. (1. (1. (1. (1	riciude area co	ue)	Service	Ontractor C	ity, State, Zip	204	
					<u> </u>	13111	<u></u>	De 1	7500
			lete for all ser						
a	b	C	Dining	e Tank	f		g - System	h If "Yes" to "g", Then Sp	·
Tank ID#	Type of Closure ¹	Tank Material of	Piping Material of	Tank Capacity	Contents ²	Integrity C	ompromised	of Rei	
	Ciosure	Construction	Construction	(gallons)		connect	cracks, loose tion, etc)?	Source of Release ³	Cause of Release ⁴
92499T	ρ	Steel	Steel	<i>350</i>	UG	X Y	□N	T	POMD
254221	- P	Steel	Steel	750	UB/LG	XY	□ N	·T	POMD
#3	Ρ_	steel	steel	550	(16/40	XY	□ N		PomD
					,	☐ Y	□N		
						☐ Y	□ N		
				i		□ Y	N		
			ent, TOS = Temp	-	-				
 Indicate ty PX = Premix 	ype of produ . WO = Wa:	ict: DL = Diesel, ste/Used Motor (LG = Leaded G Dil FCHZW = Fl	asoline, UG = ammable/Com	Unleaded Ga	asoline, FO =	Fuel Oil, GH =	Gasohol, AF = Aviation Chemical (indicate the che	Fuel, K = Kerosene, mical name(s):
	,		J., . J	u,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	00011070 1 102	ardoub vvdoto	, 00 - 01101 0	momodi (maiodio ino ono	modificatio(o).
CAS number	r(s):				·	·····	· · · · · · · · · · · · · · · · · · ·		
		= tank, P = pipi	ng, D = dispense	er, STP = subm	nersible turbi	ne pump, DP	= delivery prob	lem, O = other	
		•			•	e, C = corrosi	on, IP = installa	ation problem, O = other	
			artment of Natur				-	evident at this time	
D. CLOSU	RES (Che	eck applicable	box at right in to the local age	n response to	o all staten	nents in sec	ction D)	□ N	Come Must
All Jacai	permits we	ere obtained be	efore beginning	closure.	□Y	□n DXN	IA (*)	ΥUN	J 51917
D UST	Form ERS	6-7437 or A	ST Form ERS-	8731 filed by	owner with	the Dept. of	f Commerce ir		Y XN DNA
		VICE CHECKL		r EHS-8/31 S	SIGNED BY	THE OWN	ER MOST RE	SUBMITTED WITH EA	AUTH CLOSURE OF
D.1 🔲	TEMPORA	RILY OUT-OF			····			. — .	Inspector NA
	Oduct remo		tank (ar ather	container\ ==	d liquid re-	and and		Verified	vernied
			tank (or other		ia iiquia ren	ioveu, and			☐Y ☐N ☐

4. Dispensers/pumps left in place but locked and power disconnected.	
5. Vent lines left open.	
6. Inventory form filed indicating temporarily out-of-service (TOS) closure.	
D.2. CLOSURE BY REMOVAL OR IN-PLACE	
1. General Requirements	
a. Product from piping drained into tank (or other container).	MY N DY N
b. Piping disconnected from tank and removed.	\square Y \square N \square Y \square N \square
c. All liquid and residue removed from tank using explosion-proof pumps or hand pumps.	ZY N MAYON
d. All pump motors and suction hoses bonded to tank or otherwise grounded.	XY ON BEYON O
e. Fill pipes, gauge pipes, vapor recovery connections, submersible pumps and other fixtures	XY N MONTON
removed.	
f. Vent lines left connected until tanks purged.	
g. Tank openings temporarily plugged so vapors exit through vent.	ZIY N DOY N
h. Tank atmosphere reduced to 10% of the lower flammable range (LEL) - see Section E.	XY IN IN IN I
2. Specific Closure-by-Removal Requirements	
a. Tank removed from excavation after PURGING/INERTING; placed on level ground and	XIY ON XZY ON O
blocked to prevent movement.	
b. Tank cleaned before being removed from site.	XY N DY N
c. Tank labeled in 2" high letters after removal but before being moved from site.	XY DN (DZAY-DN D
NOTE: COMPLETE TANK LABELING SHOULD INCLUDE WARNING AGAINST REUSE; FORMER	
CONTENTS; VAPOR STATE; VAPOR FREEING TREATMENT; DATE.	
d. Tank vent hole (1/8" in uppermost part of tank) installed prior to moving the tank from site.	NY N NY N
e. Site security is provided while the excavation is open.	XIY IN DDAY IN I
3. Specific Closure-In-Place Requirements	
NOTE: CLOSURES IN-PLACE ARE ONLY ALLOWED WITH THE PRIOR WRITTEN APPROVAL OF THE D LOCAL AGENT.	EPARTMENT OF COMMERCE OR
a. Tank properly cleaned to remove all sludge and residue.	TOY TO DEFINE
b. Solid inert material (sand, cyclone boiler slag, or pea gravel recommended) introduced and	TY IN TY IN
tank filled.	
c. Vent line disconnected or removed.	Y N ZY N
d. Inventory form filed by owner with the Department of Commerce indicating closure in-place.	TY N DAZ N I
E. REPAIR. UPGRADE OR CHANGE-IN-SERVICE	
E. REPAIR, UPGRADE OR CHANGE-IN-SERVICE Written notification was provided to the local agent 15 days in advance of service date.	ПУ ПИПЛА
Written notification was provided to the local agent 15 days in advance of service date.	OY ON ONA
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service.	□Y □N □NA
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ☐ ERS-8731 filed by owner with the Department of Commerce indicating change	□Y □N □NA
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK	□Y □N □NA
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower.	-in-service. Y N NA
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK	-in-service. Y N NA
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum	-in-service. Y N NA
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS	Y N NA -in-service. Y N NA of 12 feet above ground. SPHERE. LEL METERS MAY NOT
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP	Y N NA -in-service. Y N NA of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT.
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tank	Y N NA -in-service. Y N NA of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. ik opposite the vent.
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tark Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing	Y N NA -in-service. Y N NA of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. Isk opposite the vent. Ig device grounded.
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tank Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed.	Y N NA -in-service. Y N NA of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. ak opposite the vent. g device grounded. ang tank from ground.
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tark Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. alk opposite the vent. g device grounded. and tank from ground.
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tark Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to one call before the combustible gas indicator and/or oxygen meter prior to use.	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. alk opposite the vent. g device grounded. and tank from ground.
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change. F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tan Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to monitored at bottom, middle and upper portion of tank.	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. alk opposite the vent. g device grounded. and tank from ground.
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tark Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to one call before the combustible gas indicator and/or oxygen meter prior to use.	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. alk opposite the vent. g device grounded. and tank from ground.
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change. F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tar Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to monitored at bottom, middle and upper portion of tank.	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. alk opposite the vent. g device grounded. and tank from ground.
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change. F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tar Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to monitored at bottom, middle and upper portion of tank. G. REMOVER/CLEANER INFORMATION August 15 days in advance of services and services are serviced before removed prior to the combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to the monitored at bottom, middle and upper portion of tank.	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. Isk opposite the vent. Is device grounded. Ing tank from ground. I and cutting. Checking atmosphere. Tank space
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change. F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tank gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removing Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to a monitored at bottom, middle and upper portion of tank. G. REMOVER/CLEANER INFORMATION Remover/Cleaner Name (print) Remover/Cleaner Signature Certification of tank.	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. also opposite the vent. g device grounded. and tank from ground. and cutting. checking atmosphere. Tank space
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change. F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tar Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to monitored at bottom, middle and upper portion of tank. G. REMOVER/CLEANER INFORMATION Remover/Cleaner Signature Certiful attest that the procedures and information which I have provided as the tank closure contractor are correct and complete that the correct and complete the tank closure contractor are correct and complete the tank closure contractor are correct and complete that the procedures and information which I have provided as the tank closure contractor are correct and complete the tank closu	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. also opposite the vent. g device grounded. and tank from ground. and cutting. checking atmosphere. Tank space
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change. F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tark Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to monitored at bottom, middle and upper portion of tank. G. REMOVER/CLEANER INFORMATION Remover/Cleaner Name (print) Remover/Cleaner Signature Certil attest that the procedures and information which I have provided as the tank closure contractor are correct and common company expected to perform soil contamination assessment	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. also opposite the vent. g device grounded. and tank from ground. and cutting. checking atmosphere. Tank space
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change. F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO ₂ or N ₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tar Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to monitored at bottom, middle and upper portion of tank. G. REMOVER/CLEANER INFORMATION Remover/Cleaner Signature Certiful attest that the procedures and information which I have provided as the tank closure contractor are correct and complete that the correct and complete the tank closure contractor are correct and complete the tank closure contractor are correct and complete that the procedures and information which I have provided as the tank closure contractor are correct and complete the tank closu	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. also opposite the vent. g device grounded. and tank from ground. and cutting. checking atmosphere. Tank space
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change. F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO₂ or N₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tar Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removing Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to a monitored at bottom, middle and upper portion of tank. G. REMOVER/CLEANER INFORMATION Remover/Cleaner Signature Certical Lattest that the procedures and information which I have provided as the tank closure contractor are correct and common company expected to perform soil contamination assessment I. INSPECTOR INFORMATION	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. also opposite the vent. g device grounded. and tank from ground. and cutting. checking atmosphere. Tank space
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filled by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO2 or N2 NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP. Gas introduced through a single opening at a point near the bottom of the tank at the end of the tar. Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to compite the attent that the procedures and information which I have provided as the tank closure contractor are correct and come Company expected to perform soil contamination assessment H. INSPECTOR INFORMATION H. INSPECTOR INFORMATION Which is a day of the local agent with the Department of Command and Department of Command and Department of Command and Department of Command and Department of Command Comman	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. Isk opposite the vent. Isk opposite the ven
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filed by owner with the Department of Commerce indicating change. F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO₂ or N₂ NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP Gas introduced through a single opening at a point near the bottom of the tank at the end of the tar Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removing Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to a monitored at bottom, middle and upper portion of tank. G. REMOVER/CLEANER INFORMATION Remover/Cleaner Signature Certical Lates that the procedures and information which I have provided as the tank closure contractor are correct and com Company expected to perform soil contamination assessment I. INSPECTOR INFORMATION	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. also opposite the vent. g device grounded. and tank from ground. and cutting. checking atmosphere. Tank space
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filled by owner with the Department of Commerce indicating change F. ME7HOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO2 or N2 NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP. Gas introduced through a single opening at a point near the bottom of the tank at the end of the tar. Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to componitored at bottom, middle and upper portion of tank. G. REMOVER/CLEANER INFORMATION Remover/Cleaner Signature Certil attest that the procedures and information which I have provided as the tank closure contractor are correct and come Company expected to perform soil contamination assessment H. INSPECTOR INFORMATION H. INSPECTOR INFORMATION	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. Isk opposite the vent. Isk opposite the ven
Written notification was provided to the local agent 15 days in advance of service date. All local permits were obtained before beginning service. Form ERS-7437 or ERS-8731 filled by owner with the Department of Commerce indicating change F. METHOD OF VAPOR FREEING OF TANK Displacement of vapors by eductor or diffused air blower. Eductor driven by compressed air, bonded and drop tube left in place; vapors discharged minimum Diffused air blower bonded and drop tube removed. Air pressure not exceeding 5 psig. Inert gas using dry ice or liquid carbon dioxide. Inert gas using CO2 or N2 NOTE: INERT GASSES PRODUCE AN OXYGEN DEFICIENT ATMOS FUNCTION ACCURATELY. THE TANK MAY NOT BE ENTERED IN THIS STATE WITHOUT SP. Gas introduced through a single opening at a point near the bottom of the tank at the end of the tar. Gas introduced under low pressure not to exceed 5 psig to reduce static electricity. Gas introducing Readings of 10% or less of the lower flammable range (LEL) or 0% oxygen obtained before removed Tank atmosphere monitored for flammable or combustible vapor levels prior to and during cleaning Calibrate combustible gas indicator and/or oxygen meter prior to use. Drop tube removed prior to compite the attent that the procedures and information which I have provided as the tank closure contractor are correct and come Company expected to perform soil contamination assessment H. INSPECTOR INFORMATION H. INSPECTOR INFORMATION Which is a day of the local agent with the Department of Command and Department of Command and Department of Command and Department of Command and Department of Command Comman	of 12 feet above ground. SPHERE. LEL METERS MAY NOT PECIAL EQUIPMENT. Isk opposite the vent. Isk opposite the ven

c. All product removed to within 1" of bottom.

2. Fill pipe, gauge pipe, tank truck vapor recovery fittings, and vapor return lines capped.

3. All product lines at the islands or pumps located elsewhere are removed and capped, OR

□Y □N □Y □N

Part B – To be completed by environmental professional Submit original Part B to the WDNR along with a copy of Part A I. TANK-SYSTEM SITE ASSESSMENT (TSSA) Iron River Coop - Oulu Branch Site Name: 73010 County Hwy B, Oulu, WI 54820 Address: Note: Site name and address must match with Part A Section 1. To determine if a TSSA is required, see Comm 10 and section II part B of ASSESSMENT AND REPORTING OF SUSPECTED AND OBVIOUS RELEASES FROM UNDERGROUND AND ABOVEGROUND STORAGE TANK SYSTEMS. If a TSSA is required, then follow the procedures detailed in ASSESSMENT AND REPORTING OF SUSPECTED AND OBVIOUS RELEASES FROM UNDERGROUND AND ABOVEGROUND STORAGE TANK SYSTEMS. 1. Site Information If yes, provide the Commerce # USTs 3 b. Number of active tanks¹ at facility prior to completion of current services ASTs (NOTE 1: Do not include previously closed systems or system components.) c. Excavation/trench dimensions (in feet). (Photos must be provided.) EXCAVATION/TRENCH # LENGTH WIDTH **DEPTH** Tanks 1 and 2 22' 9' 6' 7' 11' 8' Tank 3 2. Visual Excavation/Trench Inspection (Photos must be provided for "Yes" responses, except item b.) Do any of the following conditions exist in or about the excavation(s)? X Y N b. Petroleum odor: X Y N c. Water In excavation/trench: a. Stained soils: d. Free product in the excavation/trench: $\prod Y \stackrel{[X]}{=} N$ e. Sheen or free product on water: $\prod Y \times N$ 3. Geology/Hydrogeology feet b. Indicate type of geology² C (tank basin backfill cobbles and wood chunks) a. Depth to groundwater Est. 22' (Note 2: Use these symbols individually or in combination as appropriate: C = Clay, SLT = Silt, S = Sand, Gr = Gravel) 4. Receptors b. Surface water(s) within 1000 feet of the facility? X Y N If yes, specify Reefer Creek 400' NE of site 5. Sampling a. Follow the procedures detailed in ASSESSMENT AND REPORTING OF SUSPECTED AND OBVIOUS RELEASES FROM UNDERGROUND AND ABOVEGROUND STORAGE TANK SYSTEMS. b. Complete Tables 1 and 2 as appropriate. (Attach chain-of-custody and laboratory analytical reports.) c. Attach a detailed map of site features and sample locations. J. NOTE RELEVANT OBSERVATIONS, SPECIFIC PROBLEMS OR CONCERNS BELOW Tanks 1 and 2 had dents and crimps in metal prior to removal, lots of cobbles and wood chunks in tank basin backfill. All tanks had holes in the bottoms, and were full of water. Dispensers had been removed in the past. Tank #3 was found during the removal of vent piping and wasn't known to be present prior to that time.

TABLE 1 Sample ID	Sample Location & Soil/Geologic		mple Colle			Depth Below Tank/Piping	Field Screening	GRO	DRO
#	Description	Grab	Shelby Tube	Direct Push	Split Spoon	(feet)	Result (ppm)	(mg/kg)	(mg/kg)
B-1 (6')	Tank Basin, Clay	x				1'	502	4850	
B-2 (6')	Tank Basin, Clay	X				1'	644	4040	
B-3 (6')	Tank Basin, Clay	x				1'	332	102	
B-4 (6')	Tank Basin, Clay	X				1'	205	59.6	
B-5 (7')	Tank Basin, Clay	X				1'	1589	10300	
B-6 (7')	Tank Basin, Clay	X				1'	668	5590	
							 	1	
									1

Sample ID#	BENZENE	TOLUENE	ETHYLBENZENE	MTBE	TRIMETHYL - BENZENES (TOTAL)	XYLENES (TOTAL)	NAPHTHALENE
	ug/kg	ug/kg	ug/kg	ug/kg	ug/kg	ug/kg	ug/kg
B-1 (6')	12100	277000	91900	2170	344400	566000	25700
B-2 (6')	3760	177000	78700	1480	304900	455000	18900
B-3 (6')	34.2	142	266	<25.0	2180	1534	425
B-4 (6')	141	323	642	<25.0	2847	3414	749
B-5 (7')	<2500	138000	124000	<2500	1241000	1507000	94300
B-6 (7')	23900	294000	85700	1760	427000	721000	37300
		-		<u></u>			
			 				-

				I			
K. TANK-SYS	TEM SITE ASSESSI	MENT INFORMA	TION				
	ystem site assessor substance to the envi		is. Admin. Code section	on Comm 5.83, it is n	ny opinion that there	is no indication of a	release
Wis. Stats. sect release of a reg	ion 292.11 (2) (a), th julated substance to mum of \$5000 for ea	e owner or opera the Wisconsin D	elease to the environm ator or contractor perfo epartment of Natural F er Wis. Stats. section 1	orming work under ch Resources. Failure to	apter Comm 10 sha do so may result ir	Il immediately repor forfeitures of a min	t any imum of
Michael L. K			This I	Holin		41672	
Tank-System S	ite Assessor Name (print)	Tank-System Site As	sessor Signature		Certification Num	ber#
(715) 39	5-0965		9-25-2012		ICECOR		
Tank-System S	ite Assessor Telepho	one Number	Date Sigr	ned	Co	mpany Name	
					· · · · · · · · · · · · · · · · · · ·	 -	

TDID#:	
Reg Obj #:	

UNDERGROUND FLAMMABLE/COMBUSTIBLE/HAZARDOUS LIQUID STORAGE TANK REGISTRATION

Send Completed Form To:

Department of Commerce
Bureau of Petroleum Products and

Tanks

P.O. Box 7837 Information Required By Section 101.142, Wis. Stats. Madison, WI 53707-7837 Underground tanks in Wisconsin that have stored or currently store petroleum or regulated substances must be registered. A separate form is needed for each tank. Send each completed form to the agency designated in the top right corner. Have you previously registered this tank by submitting a form? Yes Do If yes, are you correcting/updating information only? Yes Personal information you provide may be used for secondary purposes [Privacy Law, s. 15.04 (1)(m)]. This registration applies to a tank status that is (check one): Fire Department providing fire Closed - Tank Removed ☐ In Use☐ Newly Installed ☐ Ownership Change (Indicate coverage where tank is located: Closed - Filled with Inert Materials City | Village new owner name in block 2) Abandoned with Product ☐ Abandon with Water ☐ Town of: ☐ Temporarily Out of Service - Provide Date: ☐ Abandoned without Product (empty) Iron River A. IDENTIFICATION (Please Print) 1. Tank Site Name Site Street Address Site Telephone Number Iron River Coop - Oulu Branch 73010 County Highway B ☐ Village State County ☐ Citv **▼** Town of: Zip Code WISCONSIN Oulu 54820 Bayfield 2. Tank Owner Name Mailing Address Telephone Number Iron River Coop 307 Main Street, PO Box 8 State Zip Code County City √Village Town of: Iron River 54847 Wisconsin Bayfield 3. Property Owner Name (if different than tank owner) Property Owner Address if different than #1 Facility ID #: 89958 B. Site ID #: 254222 Customer ID #: Tank Age (age or date installed): 11/1/1983 C. Tank Capacity (gallons): 550 Vehicle fueling: Yes No D. LAND OWNER TYPE (check one) Refer to back State Federal Leased Tribal Nation Municipal Other Government Private County Federal Owned E. OCCUPANCY TYPE (check one) Refer to back Retail Fuel Sales Bulk Storage ☐ Terminal Storage ☐ Mercantile/Commercial ☐ Residential ☐ Industrial ☐ School ☐ Agricultural (crop or livestock production) ☐ Backup or Emergency Generator ☐ Gov't Fleet ☐ Utility Other (specify:) F. Tank Construction: ■ Bare Steel ☐ Coated Steel ☐ Stainless steel ☐ Steel – Fiberglass Reinforced Plastic Composite Overfill Protection? Yes No ☐ Yes **N**o Spill Containment? ☐ Fiberglass ☐ Unknown Other (specify): Lined (date): ☐ Yes
☐ No G. Tank Cathodic Protection: ☐ Sacrificial Anodes **Tank Double Walled?** ☐ Impressed Current □ N/A H. Primary Tank Leak Detection Method: ☐ Interstitial monitoring ☐ Inventory control and tightness testing ☐ Groundwater monitoring Automatic tank gauging □ Vapor monitoring Manual tank gauging (only for tanks of 1,000 gallons or less) ☐ Statistical Inventory Reconciliation (SIR) Unknown I. Piping Construction: Bare Steel ☐ Coated Steel ☐ Stainless Steel ☐ Fiberglass ☐ Flexible ☐ Copper ☐ Unknown ☐ NA ☐ Other J. Piping Cathodic Protection: ☐ Sacrificial Anodes ☐ Impressed Current □ N/A Pipe Double Walled? ☐ Yes No K. Primary Piping System Type: ☐ Pressurized piping with ↓ A. ☐ auto shutoff; B. ☐ alarm, or C. ☐ flow restrictor Unknown ☐ Suction piping with check valve at tank ☐ Suction piping with check valve at pump and inspectable ☐ Not needed if waste oil L. Piping Leak Detection Method: (used if pressurized or check valve at tank): ☐ SIR ☐ Tightness testing ☐ Electronic line leak monitor ☐ Groundwater monitoring ☐ Vapor monitoring ☐ Interstitial monitoring ☐ Not required Unknown M. Vapor Recovery/Stage II ☐ Fiberglass ☐ Flexible Other: CARB #: ☐ Non-Operational - Provide Date (mo./day/yr.): ☐ Operational - Provide Date (mo./day/yr.): N. TANK CONTENTS (Current, or previous product (if tank now empty)) Leaded
☐ Unleaded ☐ Gasohol ☐ E85 ☐ Diesel ☐ Bio-diesel ☐ Aviation ☐ Premix ☐ Fuel Oil ☐ Kerosene ☐ New Oil Waste/Used Motor Oil ☐ Hazardous Waste* ☐ Unknown ☐ Empty* ☐ Sand/Gravel/Slurry* ☐ Other (specify): ☐ Chemical* Name Geo Latitude: Geo Longitude: * NOT PECFA eligible. O. If Tank Closed, Abandoned or Out of Service Has a site assessment been completed? (see reverse side for details) Give date (mo/day/yr): 7/17/2012 Yes No Tank Owner Name (please print): Tank Owner Signature (Note: By signing, signer is accepting legal and financial responsibility for the storage tank system.) Date

TDID#:	
Reg Obj #:	

UNDERGROUND FLAMMABLE/COMBUSTIBLE/HAZARDOUS LIQUID STORAGE TANK REGISTRATION

Information Required By Section 101.142, Wis. Stats.

Send Completed Form To:

Department of Commerce Bureau of Petroleum Products and

Tanks

P.O. Box 7837

Madison, WI 53707-7837 Underground tanks in Wisconsin that have stored or currently store petroleum or regulated substances must be registered. A separate form is needed for each tank. Send each completed form to the agency designated in the top right corner. Have you previously registered this tank by submitting a form? Yes Do If yes, are you correcting/updating information only? Yes Personal information you provide may be used for secondary purposes [Privacy Law, s. 15.04 (1)(m)]. This registration applies to a tank status that is (check one): Fire Department providing fire Closed - Tank Removed ☐ In Use☐ Newly Installed ☐ Ownership Change (Indicate coverage where tank is located: Closed - Filled with Inert Materials City | Village new owner name in block 2) Abandoned with Product ☐ Abandon with Water ☐ Town of: ☐ Temporarily Out of Service - Provide Date: ☐ Abandoned without Product (empty) Iron River A. IDENTIFICATION (Please Print) 1. Tank Site Name Site Street Address Site Telephone Number Iron River Coop - Oulu Branch 73010 County Highway B ☐ Village State County ☐ Citv **▼** Town of: Zip Code WISCONSIN Oulu 54820 Bayfield 2. Tank Owner Name Mailing Address Telephone Number Iron River Coop 307 Main Street, PO Box 8 State Zip Code County City √Village Town of: Iron River 54847 Wisconsin Bayfield 3. Property Owner Name (if different than tank owner) Property Owner Address if different than #1 Facility ID #: 89958 B. Site ID #: 254221 Customer ID #: Tank Age (age or date installed): 11/1/1983 C. Tank Capacity (gallons): 750 Vehicle fueling: Yes No D. LAND OWNER TYPE (check one) Refer to back State Federal Leased Tribal Nation Municipal Other Government Private County Federal Owned E. OCCUPANCY TYPE (check one) Refer to back Retail Fuel Sales Bulk Storage ☐ Terminal Storage ☐ Mercantile/Commercial ☐ Residential ☐ Industrial ☐ School ☐ Agricultural (crop or livestock production) ☐ Backup or Emergency Generator ☐ Gov't Fleet ☐ Utility Other (specify:) F. Tank Construction: ■ Bare Steel ☐ Coated Steel ☐ Stainless steel ☐ Steel – Fiberglass Reinforced Plastic Composite Overfill Protection? Yes No ☐ Yes **N**o Spill Containment? ☐ Fiberglass ☐ Unknown Other (specify): Lined (date): Yes No G. Tank Cathodic Protection: ☐ Sacrificial Anodes **Tank Double Walled?** ☐ Impressed Current □ N/A H. Primary Tank Leak Detection Method: ☐ Interstitial monitoring ☐ Inventory control and tightness testing ☐ Groundwater monitoring Automatic tank gauging □ Vapor monitoring Manual tank gauging (only for tanks of 1,000 gallons or less) ☐ Statistical Inventory Reconciliation (SIR) Unknown I. Piping Construction: Bare Steel ☐ Coated Steel ☐ Stainless Steel ☐ Fiberglass ☐ Flexible ☐ Copper ☐ Unknown ☐ NA ☐ Other J. Piping Cathodic Protection: ☐ Sacrificial Anodes ☐ Impressed Current □ N/A Pipe Double Walled? ☐ Yes No K. Primary Piping System Type: ☐ Pressurized piping with ↓ A. ☐ auto shutoff; B. ☐ alarm, or C. ☐ flow restrictor Unknown ☐ Suction piping with check valve at tank ☐ Suction piping with check valve at pump and inspectable ☐ Not needed if waste oil L. Piping Leak Detection Method: (used if pressurized or check valve at tank): ☐ SIR ☐ Tightness testing ☐ Electronic line leak monitor ☐ Groundwater monitoring ☐ Vapor monitoring ☐ Interstitial monitoring ☐ Not required Unknown M. Vapor Recovery/Stage II ☐ Fiberglass ☐ Flexible Other: CARB #: ☐ Non-Operational - Provide Date (mo./day/yr.): ☐ Operational - Provide Date (mo./day/yr.): N. TANK CONTENTS (Current, or previous product (if tank now empty)) ♠ Leaded Unleaded Gasohol E85 Diesel Bio-diesel Aviation Premix Fuel Oil Kerosene New Oil Waste/Used Motor Oil ☐ Hazardous Waste* ☐ Unknown ☐ Empty* ☐ Sand/Gravel/Slurry* ☐ Other (specify): ☐ Chemical* Name Geo Latitude: Geo Longitude: * NOT PECFA eligible. O. If Tank Closed, Abandoned or Out of Service Has a site assessment been completed? (see reverse side for details) Give date (mo/day/yr): 7/17/2012 Yes No Tank Owner Name (please print): Tank Owner Signature (Note: By signing, signer is accepting legal and financial responsibility for the storage tank system.) Date

TDID#:	
Reg Obj #:	

UNDERGROUND FLAMMABLE/COMBUSTIBLE/HAZARDOUS LIQUID STORAGE TANK REGISTRATION

Information Required By Section 101.142, Wis. Stats.

Send Completed Form To:

Department of Commerce
Bureau of Petroleum Products and

Tanks

P.O. Box 7837 Madison, WI 53707-7837

Underground tanks in Wisconsin that have stored or of is needed for each tank. Send each completed form tank by submitting a form? ☐ Yes ☑ No If yes, Personal information you provide	to the agency designated are you correcting/updati	in the top right corning information only?	er. Have	e you previously registered this No
This registration applies to a tank status that is (check one In Use Newly Installed Abandoned with Product This registration applies to a tank status that is (check one Closed - I Abandoned Losed - I Aban): Tank Removed Filled with Inert Materials	Ownership Change (new owner name in I	Indicate	Fire Department providing fire coverage where tank is located: City Village Town of: Iron River
A. IDENTIFICATION (Please Print) 1. Tank Site Name	Site Street Address	h D		Site Telephone Number
Iron River Coop - Oulu Branch	73010 County Hig			,
☐ City ☐ Village ☑ Town of: Oulu	State WISCONSIN	Zip Code 54820		County Bayfield
2. Tank Owner Name	Mailing Address			Telephone Number
Iron River Coop	307 Main Street, PO B	3ox 8		()
City Village Town of:	State	Zip Code		County
Iron River	Wisconsin	54847		Bayfield
Property Owner Name (if different than tank owner)	Property Owner Address if	different than #1		
B. Site ID #:	Facility ID #: 89958		Custon	ner ID #:
C. Tank Capacity (gallons): 550	Tank Age (age or date inst	^{alled):} Unknown		Vehicle fueling: Yes No
D. LAND OWNER TYPE (check one) Refer to back County State Federal Leased	「 Federal Owned ☐ Triba	Nation Municip	al □O	ther Government Private
E. OCCUPANCY TYPE (check one) Refer to back ☐ Retail Fuel Sales ☐ Bulk Storage ☐ Terminal S ☐ Agricultural (crop or livestock production) ☐ Backup				Residential School Other (specify:)
F. Tank Construction:				
Bare Steel ☐ Coated Steel ☐ Stainless steel ☐	☐ Steel – Fiberglass Reinfor	ced Plastic Composite		fill Protection? Yes No
☐ Fiberglass ☐ Unknown ☐ Other (specify): _		ined (date):	- '	Containment? Yes No
G. Tank Cathodic Protection: Sacrificial Anodes	☐ Impressed Current	□ N/A	Tank Do	uble Walled?
H. Primary Tank Leak Detection Method: ☐ Automatic tank gauging ☐ Interstitial monitoring ☐ Manual tank gauging (only for tanks of 1,000 gallons)		ightness testing		er monitoring
I. Piping Construction: ■ Bare Steel □ Coated Steel □ Stainless Steel	☐ Fiberglass ☐ Flexible	☐ Copper ☐ Unk	nown [NA Other
J. Piping Cathodic Protection: Sacrificial Anode:	s	□ N/A	Pipe Dou	uble Walled? 🗌 Yes 🕞 No
K. Primary Piping System Type: Pressurized piping Suction piping with check valve at tank	g with ↓ A. □ auto shutoff uction piping with check valv			ictor Unknown Not needed if waste oil
L. Piping Leak Detection Method: (used if pressurized o ☐ Groundwater monitoring ☐ Vapor monitoring		☐ SIR ☐ Tightness	testing	☐ Electronic line leak monitor ☐ Unknown
		CARB #		J CHRIOWIT
☐ Operational - Provide Date (mo./day/yr.):		erational - Provide Date		v/vr.):
N. TANK CONTENTS (Current, or previous product (if	f tank now empty))		`	
				Fuel Oil
Chemical* Name			CAS #:	
* NOT PECFA eligible.	Geo Lat	itude:		Geo Longitude:
O. If Tank Closed, Abandoned or Out of Service Give date (mo/day/yr): 7/17/2012	Has a s	ite assessment been	complete	ed? (see reverse side for details)
Tank Owner Name (please print):				
Tank Owner Signature (Note: By signing, signer is accep	ting legal and financial respo	nsibility for the storage	tank sys	tem.) Date



FODED

I C ENVIRONMENTAL CORPORATION

USGS Tapagraphic Map

DULU, WI

DULU, WI

DUADRANGLE

Iron River Coop

Dulu, WISCONSIN

SITE LOCATION

MLK

SHEET 1


Iron River Coop – Dulu Brooklu, WISCONSIN

SITE LOCATION MAP

MLK

PAGE 102012022

9/25/12



	(Please Print Clearly)							UPP	ER MIDW	EST R	<u>EGION</u>		Page 1	1 of
Company Name:			ø				•	MN:	612-607-	1700	WI: 920-469-2436			
Branch/Location	: Superior, W	エ		Pace.		ytical	w.						40639	~7 ⁻
Project Contact:		ماد			иши. рас	elabs.com			Ĺ	5	Quote #:		· · · · · · · · · · · · · · · · · · ·	
Phone:	(715) 395-09	165	' (CHA	IN (OF (CUS'	TODY			Mail To Contact:	W	idrael Kol	۸٦
Project Number:	109017079		A=None B=	HCL C=		reservation =HNO3 E		=Methanol G	=NaOH		Mail To Company:	工	CELOR	
Project Name:	Ouly Store	Station	H=Sodium Bist	Ilfate Solutio	on I	Sodium Thic	osulfate J	=Other			Mail To Address:	Po	Box 1105	
Project State:	WI		FILTERED? (YES/NO)	Υ/N								5,	person WI	54
Sampled By (Pri	m): Michael K	ohn	PRESERVATION (CODE)*	Pick Letter	F	F					Invoice To Contact:			
Sampled By (Sig											Invoice To Company:		ame	
PO #:		Regulatory Program:		ester	ال	67E					Invoice To Address:	5		
Data Package		Mat	rix Codes W = Water	n bey	PJOC	1								
EPA Le	evel III (billable)	B = Biota C = Charcoal O = Oil	DW = Drinking Water GW = Ground Water SW = Surface Water	Analyses Requested	9/0	got thealeng					Invoice To Phone:	(71	5)395-096	5
	your sample	SI = Sludge	WW = Waste Water WP = Wipe	Anal	6RO,	\$					CLIENT	LA	B COMMENTS	Pro
PACE LAB#	CLIENT FIELD ID	DATE	TIME MATREX			`					COMMENTS	(L	ab Use Only)	
001	B-1(6')	נו/ה/ר	12:30 5	13 ye	人	X						1-40	52pA - 1-4(OmlF
002	B-2(61)	7/17/12	12135 5		7	X								
003	B-3 (6)'	7/17/12	ک ککالم ا		X	乂								
004	B-4 (6')	7/17/2	1100 S		X.	7								

special pricing and release of liability

005 006

PACE Project No.

Sample Receipt pH

OK / Adjusted

Cooler Custody Seal Present Not Present

Intact / Not Intact

Receipt Temp ≈

54880

Profile #


Pace Analytical

Sample Condition Upon Receipt

Client Name:	: 1	2	COS	Pr	oject#	4063977
Courier: Fed Ex TUPS TUSPS TO	Client Co	mmer	cial T Pace	– Other		
Tracking #: 8008 7445	9031					
Custody Seal on Cooler/Box Present:	no	Seals	intact: yes	∏ no	Optional	
Custody Seal on Samples Present: yes	no	Seals	intact: yes	no	Proj. Due	Date:
Packing Material: Bubble Wrap Bubble	_		ne Other		Proj. Nan	ie.
Thermometer Used ///		١.	Blue Dry None		Samples on ice, cooling	process has begun
Cooler Temperature ROJ	Biological	rissue	is Frozen: 🦳 ye			
Temp Blank Present: yes no			¥, 110	,	Person examining cor	tents:
Temp should be above freezing to 6°C for all sample exce Biota Samples should be received ≤ 0°C.	ept Biota.		Comments:	<u> </u>	Initials: EM	
Chain of Custody Present:	☑Yes □No	□N/A	1			
Chain of Custody Filled Out:	ZÍYes □No	□N/A	2.		<u></u>	
Chain of Custody Relinquished:	☑Yes □No	□N/A	3.		····	
Sampler Name & Signature on COC:		□N/A	4.			
Samples Arrived within Hold Time:	ØYes □Ņo	□N⁄A	5.			- <u>-</u>
Short Hold Time Analysis (<72hr):	□Yes ☑No	□N/A	6.			
Rush Turn Around Time Requested:	□Yes ☑No	□N/A	7			
Sufficient Volume:	ZIYes □No	□N/A	8.			
Correct Containers Used:	☑Yes □No	□N/A	9.			
-Pace Containers Used:	ZYes □No	□N/A				
Containers Intact:	ŹYes □No	□N/A	10.			
Filtered volume received for Dissolved tests	□Yes □No	Z N/A	11			
Sample Labels match COC:	ZYes □No	□n/a	12.			
-Includes date/time/ID/Analysis Matrix:						
All containers needing preservation have been checked.	□Yes □No	ĮΖΝΙΑ	13.			
All containers needing preservation are found to be in	□Yes □No	· /				
compliance with EPA recommendation.	LITES LINO	ZINIA	Initial when	<u> </u>	Lot # of added	
exceptions: VOA, coliform, TOC, O&G, WI-DRO (water)	□Yes □No		completed		preservative	
Samples checked for dechlorination:	□Yes □No	ØN/A	14.			
Headspace in VOA Vials (>6mm):	□Yes □No	ZNA	15			
Trip Blank Present:	□Yes □No	ZIN/A	16.			
Trip Blank Custody Seals Present	□Yes □No	ÐN/A				
Pace Trip Blank Lot # (if purchased):						
Client Notification/ Resolution:					Field Data Required?	Y / N
Person Contacted: Comments/ Resolution:		_Date/	Time:			
Commenter reconducts	<u> </u>					
		<u>-</u>				
Project Manager Review:	1	8			Date:	7-25-12
Note: Whenever there is a discrepancy affecting North Carolina or incorrect preservative, out of temp, incorrect containers)	ompliance/sample	es, a cop	y of this form will be ser	nt to the N	lorth Carolina DEHNR Certifi	cation Office (i.e out of hold,

F-GB-C-031-Rev.00 (29Sept2011) SCUR Form







August 01, 2012

Michael Kohn IC Environmental Corporation 2220Missouri Ave Superior, WI 54880

RE: Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

Dear Michael Kohn:

Enclosed are the analytical results for sample(s) received by the laboratory on July 25, 2012. The results relate only to the samples included in this report. Results reported herein conform to the most current TNI standards and the laboratory's Quality Assurance Manual, where applicable, unless otherwise noted in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Brian Basten

brian.basten@pacelabs.com Project Manager

Enclosures







1241 Bellevue Street - Suite 9 Green Bay, WI 54302 (920)469-2436

CERTIFICATIONS

Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

Green Bay Certification IDs

1241 Bellevue Street, Green Bay, WI 54302 Florida/NELAP Certification #: E87948 Illinois Certification #: 200050 Kentucky Certification #: 82 Louisiana Certification #: 04168 Minnesota Certification #: 055-999-334 New York Certification #: 11888 North Carolina Certification #: 503 North Dakota Certification #: R-150 South Carolina Certification #: 83006001 US Dept of Agriculture #: S-76505 Wisconsin Certification #: 405132750



SAMPLE SUMMARY

Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

Lab ID	Sample ID	Matrix	Date Collected	Date Received
4063977001	B-1 (6')	Solid	07/17/12 12:30	07/25/12 09:20
4063977002	B-2 (6')	Solid	07/17/12 12:35	07/25/12 09:20
4063977003	B-3 (6')	Solid	07/17/12 12:55	07/25/12 09:20
4063977004	B-4 (6')	Solid	07/17/12 13:00	07/25/12 09:20
4063977005	B-5 (7')	Solid	07/17/12 17:15	07/25/12 09:20
4063977006	B-6 (7')	Solid	07/17/12 17:20	07/25/12 09:20





SAMPLE ANALYTE COUNT

Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory
4063977001	B-1 (6')	WI MOD GRO	PMS	11	PASI-G
		ASTM D2974-87	KMF	1	PASI-G
4063977002	B-2 (6')	WI MOD GRO	PMS	11	PASI-G
		ASTM D2974-87	KMF	1	PASI-G
4063977003	B-3 (6')	WI MOD GRO	PMS	11	PASI-G
		ASTM D2974-87	KMF	1	PASI-G
4063977004	B-4 (6')	WI MOD GRO	PMS	11	PASI-G
		ASTM D2974-87	KMF	1	PASI-G
4063977005	B-5 (7')	WI MOD GRO	PMS	11	PASI-G
		ASTM D2974-87	KMF	1	PASI-G
4063977006	B-6 (7')	WI MOD GRO	PMS	11	PASI-G
		ASTM D2974-87	KMF	1	PASI-G





PROJECT NARRATIVE

Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

Method: WI MOD GRO Description: WIGRO GCV

Client: IC Environmental Corporation

Date: August 01, 2012

General Information:

6 samples were analyzed for WI MOD GRO. All samples were received in acceptable condition with any exceptions noted below.

Hold Time:

The samples were analyzed within the method required hold times with any exceptions noted below.

Sample Preparation:

The samples were prepared in accordance with TPH GRO/PVOC WI ext. with any exceptions noted below.

Initial Calibrations (including MS Tune as applicable):

All criteria were within method requirements with any exceptions noted below.

Continuing Calibration:

All criteria were within method requirements with any exceptions noted below.

Internal Standards:

All internal standards were within QC limits with any exceptions noted below.

Surrogates:

All surrogates were within QC limits with any exceptions noted below.

Method Blank:

All analytes were below the report limit in the method blank with any exceptions noted below.

Laboratory Control Spike:

All laboratory control spike compounds were within QC limits with any exceptions noted below.

Matrix Spikes:

All percent recoveries and relative percent differences (RPDs) were within acceptance criteria with any exceptions noted below.

Additional Comments:

This data package has been reviewed for quality and completeness and is approved for release.



ANALYTICAL RESULTS

Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

Sample: B-1 (6') Lab ID: 4063977001 Collected: 07/17/12 12:30 Received: 07/25/12 09:20 Matrix: Solid

Results reported on a "dry-weight" basis

		Units	LOQ	LOD	DF	Prepared	Analyzed	CAS No.	Qual
WIGRO GCV	Analytical	Method: WI	MOD GRO Pr	eparation N	/lethod	: TPH GRO/PVOC	C WI ext.		
Benzene	12100 u	g/kg	3660	1530	50	07/27/12 06:16	07/27/12 15:53	71-43-2	
Ethylbenzene	91900 u	g/kg	3660	1530	50	07/27/12 06:16	07/27/12 15:53	100-41-4	
Gasoline Range Organics	4850 m	ng/kg	153	153	50	07/27/12 06:16	07/27/12 15:53		
Methyl-tert-butyl ether	2170J u	g/kg	3660	1530	50	07/27/12 06:16	07/27/12 15:53	1634-04-4	
Naphthalene	25700 u	g/kg	3660	1530	50	07/27/12 06:16	07/27/12 15:53	91-20-3	
Toluene	277000 u	g/kg	3660	1530	50	07/27/12 06:16	07/27/12 15:53	108-88-3	
1,2,4-Trimethylbenzene	259000 u	g/kg	3660	1530	50	07/27/12 06:16	07/27/12 15:53	95-63-6	
1,3,5-Trimethylbenzene	85400 u	g/kg	3660	1530	50	07/27/12 06:16	07/27/12 15:53	108-67-8	
m&p-Xylene	409000 u		7330	3050	50	07/27/12 06:16	07/27/12 15:53	179601-23-1	
o-Xylene	157000 u		3660	1530	50	07/27/12 06:16	07/27/12 15:53	95-47-6	
Surrogates		5 5							
a,a,a-Trifluorotoluene (S)	109 %	6.	80-120		50	07/27/12 06:16	07/27/12 15:53	98-08-8	
Percent Moisture	Analytical	Method: AST	M D2974-87						
Percent Moisture	18.1 %	6	0.10	0.10	1		07/31/12 16:50		
Sample: B-2 (6')	Lab ID:	4063977002	. Collected	l: 07/17/12	2 12:35	Received: 07/	25/12 09:20 Ma	atrix: Solid	
Results reported on a "dry-weig	ght" basis								
Parameters	Results	Units	LOQ	LOD	DF	Prepared	Analyzed	CAS No.	Qual
WIGRO GCV	Analytical	Method: WI	MOD GRO Pr	eparation N	/lethod	: TPH GRO/PVO	C WI ext.		
Benzene	3760 u	a/ka	2970	1240	40	07/27/12 06:16	07/27/12 16:19	71-43-2	
Ethylbenzene	78700 u	0 0	2970	1240	40	07/27/12 06:16	07/27/12 16:19	-	
Gasoline Range Organics	4040 m	0 0	124	124	40	07/27/12 06:16	07/27/12 16:19		
Methyl-tert-butyl ether	1480J u	0 0	2970	1240	40		07/27/12 16:19	1634-04-4	
Naphthalene	18900 u	~ ~	2970	1240	40	07/27/12 06:16	07/27/12 16:19	91-20-3	
Toluene	177000 u		2970	1240	40	07/27/12 06:16	07/27/12 16:19	108-88-3	
1,2,4-Trimethylbenzene	227000 u	a/ka	2970	1240	40	07/27/12 06:16	07/27/12 16:19	95-63-6	
1,3,5-Trimethylbenzene	77900 u		2970	1240	40	07/27/12 06:16	07/27/12 16:19		
m&p-Xylene	329000 u		5940	2470	40	07/27/12 06:16	07/27/12 16:19		
o-Xylene	126000 u		2970	1240	40		07/27/12 16:19		
Surrogates		5 5			-		=		
•	112 %	/	80-120		40	07/27/12 06:16	07/27/12 16:19	98-08-8	
a,a,a-Trifluorotoluene (S)		0.							
a,a,a-Trifluorotoluene (S) Percent Moisture		o. Method: AST							



ANALYTICAL RESULTS

Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

Sample: B-3 (6') Lab ID: 4063977003 Collected: 07/17/12 12:55 Received: 07/25/12 09:20 Matrix: Solid

Results reported on a "dry-weight" basis

	Results	Units	LOQ	LOD	DF	Prepared	Analyzed	CAS No.	Qua
WIGRO GCV	Analytica	al Method: WI	MOD GRO Pr	eparation I	Method	: TPH GRO/PVO	C WI ext.		
Benzene	34.2J	ug/kg	80.5	33.5	1	07/27/12 06:16	07/27/12 16:45	71-43-2	
Ethylbenzene	266	ug/kg	80.5	33.5	1	07/27/12 06:16	07/27/12 16:45	100-41-4	
Gasoline Range Organics	102	mg/kg	3.4	3.4	1	07/27/12 06:16	07/27/12 16:45		
Methyl-tert-butyl ether	<25.0	ug/kg	60.0	25.0	1	07/27/12 06:16	07/27/12 16:45	1634-04-4	W
Naphthalene	425	ug/kg	80.5	33.5	1	07/27/12 06:16	07/27/12 16:45	91-20-3	
Toluene	142	ug/kg	80.5	33.5	1	07/27/12 06:16	07/27/12 16:45	108-88-3	
1,2,4-Trimethylbenzene	1170	ug/kg	80.5	33.5	1	07/27/12 06:16	07/27/12 16:45	95-63-6	
1,3,5-Trimethylbenzene	1010	ug/kg	80.5	33.5	1	07/27/12 06:16	07/27/12 16:45	108-67-8	
m&p-Xylene	1160		161	67.1	1	07/27/12 06:16	07/27/12 16:45	179601-23-1	
o-Xylene	374	ug/kg	80.5	33.5	1	07/27/12 06:16	07/27/12 16:45	95-47-6	
Surrogates									
a,a,a-Trifluorotoluene (S)	106	%.	80-120		1	07/27/12 06:16	07/27/12 16:45	98-08-8	
Percent Moisture	Analytica	al Method: AS	ΓM D2974-87						
Percent Moisture 25.4 %		0.10	0.10	1		07/31/12 16:51			
Parameters	Results	Units	LOQ	LOD	DF	Prepared	Analyzed	CAS No.	Qua
						Prepared:		CAS No.	Qua
WIGRO GCV	Analytica	al Method: WI	MOD GRO Pr	eparation I	Method	: TPH GRO/PVO	C WI ext.		Qua
WIGRO GCV Benzene	Analytica	al Method: WI	MOD GRO Pr 91.1	eparation I	Method 1	TPH GRO/PVO0	OWI ext.	71-43-2	Qua
WIGRO GCV Benzene Ethylbenzene	Analytica 141 642	al Method: WI ug/kg ug/kg	MOD GRO Pr 91.1 91.1	eparation N 37.9 37.9	Method 1 1	TPH GRO/PVO0 07/27/12 06:16 07/27/12 06:16	OWI ext. 07/27/12 14:10 07/27/12 14:10	71-43-2	Qua
WIGRO GCV Benzene Ethylbenzene Gasoline Range Organics	Analytica 141 642 59.6	al Method: WI ug/kg ug/kg mg/kg	91.1 91.1 3.8	eparation N 37.9 37.9 3.8	Method 1	: TPH GRO/PVOC 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16	07/27/12 14:10 07/27/12 14:10 07/27/12 14:10	71-43-2 100-41-4	Qua
WIGRO GCV Benzene Ethylbenzene Gasoline Range Organics Methyl-tert-butyl ether	Analytica 141 642 59.6 <25.0	al Method: WI ug/kg ug/kg mg/kg ug/kg	91.1 91.1 3.8 60.0	eparation N 37.9 37.9 3.8 25.0	Method 1 1 1 1	: TPH GRO/PVOC 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16	07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10	71-43-2 100-41-4 1634-04-4	
WIGRO GCV Benzene Ethylbenzene Gasoline Range Organics Methyl-tert-butyl ether Naphthalene	Analytica 141 642 59.6 <25.0	al Method: WI ug/kg ug/kg mg/kg ug/kg ug/kg	91.1 91.1 91.1 3.8 60.0 91.1	37.9 37.9 37.9 3.8 25.0 37.9	Method 1 1 1 1 1 1	07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16	0 WI ext. 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10	71-43-2 100-41-4 1634-04-4 91-20-3	
WIGRO GCV Benzene Ethylbenzene Gasoline Range Organics Methyl-tert-butyl ether Naphthalene Toluene	Analytica 141 642 59.6 <25.0 749 323	al Method: WI ug/kg ug/kg mg/kg ug/kg ug/kg ug/kg	91.1 91.1 91.3 3.8 60.0 91.1 91.1	eparation N 37.9 37.9 3.8 25.0 37.9 37.9	Method 1 1 1 1 1 1 1	: TPH GRO/PVOC 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16	07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10	71-43-2 100-41-4 1634-04-4 91-20-3 108-88-3	
WIGRO GCV Benzene Ethylbenzene Gasoline Range Organics Methyl-tert-butyl ether Naphthalene Toluene 1,2,4-Trimethylbenzene	Analytica 141 642 59.6 <25.0 749 323 2020	al Method: WI ug/kg ug/kg mg/kg ug/kg ug/kg ug/kg ug/kg	91.1 91.1 91.1 3.8 60.0 91.1 91.1	eparation N 37.9 37.9 3.8 25.0 37.9 37.9 37.9	Method 1 1 1 1 1 1 1 1	TPH GRO/PVOC 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16	07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10	71-43-2 100-41-4 1634-04-4 91-20-3 108-88-3 95-63-6	
WIGRO GCV Benzene Ethylbenzene Gasoline Range Organics Methyl-tert-butyl ether Naphthalene Toluene 1,2,4-Trimethylbenzene 1,3,5-Trimethylbenzene	Analytica 141 642 59.6 <25.0 749 323 2020 827	al Method: WI ug/kg ug/kg mg/kg ug/kg ug/kg ug/kg ug/kg ug/kg ug/kg	91.1 91.1 91.3 3.8 60.0 91.1 91.1	97.9 37.9 37.9 3.8 25.0 37.9 37.9 37.9	Method 1 1 1 1 1 1 1	: TPH GRO/PVOC 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16	07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10	71-43-2 100-41-4 1634-04-4 91-20-3 108-88-3 95-63-6 108-67-8	
WIGRO GCV Benzene Ethylbenzene Gasoline Range Organics Methyl-tert-butyl ether Naphthalene Toluene 1,2,4-Trimethylbenzene 1,3,5-Trimethylbenzene m&p-Xylene	Analytica 141 642 59.6 <25.0 749 323 2020 827 2520	al Method: WI ug/kg ug/kg mg/kg ug/kg ug/kg ug/kg ug/kg ug/kg ug/kg	91.1 91.1 91.1 3.8 60.0 91.1 91.1 91.1	eparation N 37.9 37.9 3.8 25.0 37.9 37.9 37.9	Method 1 1 1 1 1 1 1 1	TPH GRO/PVOC 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16	07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10	71-43-2 100-41-4 1634-04-4 91-20-3 108-88-3 95-63-6 108-67-8 179601-23-1	
WIGRO GCV Benzene Ethylbenzene Gasoline Range Organics Methyl-tert-butyl ether Naphthalene Toluene 1,2,4-Trimethylbenzene 1,3,5-Trimethylbenzene m&p-Xylene o-Xylene	Analytica 141 642 59.6 <25.0 749 323 2020 827 2520	al Method: WI ug/kg ug/kg mg/kg ug/kg ug/kg ug/kg ug/kg ug/kg ug/kg	91.1 91.1 3.8 60.0 91.1 91.1 91.1 91.1	97.9 37.9 37.9 3.8 25.0 37.9 37.9 37.9 37.9	Method 1 1 1 1 1 1 1 1 1 1	TPH GRO/PVOC 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16	07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10	71-43-2 100-41-4 1634-04-4 91-20-3 108-88-3 95-63-6 108-67-8 179601-23-1	
Parameters WIGRO GCV Benzene Ethylbenzene Gasoline Range Organics Methyl-tert-butyl ether Naphthalene Toluene 1,2,4-Trimethylbenzene 1,3,5-Trimethylbenzene m&p-Xylene o-Xylene Surrogates a,a,a-Trifluorotoluene (S)	Analytica 141 642 59.6 <25.0 749 323 2020 827 2520	al Method: WI ug/kg	91.1 91.1 3.8 60.0 91.1 91.1 91.1 91.1	97.9 37.9 37.9 3.8 25.0 37.9 37.9 37.9 37.9	Method 1 1 1 1 1 1 1 1 1 1	TPH GRO/PVOC 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16	07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10	71-43-2 100-41-4 1634-04-4 91-20-3 108-88-3 95-63-6 108-67-8 179601-23-1 95-47-6	Qua W
WIGRO GCV Benzene Ethylbenzene Gasoline Range Organics Methyl-tert-butyl ether Naphthalene Toluene 1,2,4-Trimethylbenzene 1,3,5-Trimethylbenzene m&p-Xylene o-Xylene Surrogates	Analytica 141 642 59.6 <25.0 749 323 2020 827 2520 894	al Method: WI ug/kg	91.1 91.1 3.8 60.0 91.1 91.1 91.1 91.1 80-120	97.9 37.9 37.9 3.8 25.0 37.9 37.9 37.9 37.9	Method 1 1 1 1 1 1 1 1 1 1 1 1 1 1	TPH GRO/PVOC 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16 07/27/12 06:16	07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10 07/27/12 14:10	71-43-2 100-41-4 1634-04-4 91-20-3 108-88-3 95-63-6 108-67-8 179601-23-1 95-47-6	



ANALYTICAL RESULTS

Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

Sample: B-5 (7') Lab ID: 4063977005 Collected: 07/17/12 17:15 Received: 07/25/12 09:20 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	LOQ	LOD	DF	Prepared	Analyzed	CAS No.	Qual
WIGRO GCV	Analytical	Method: WI	MOD GRO Pr	eparation I	Method:	TPH GRO/PVO	C WI ext.		
Benzene	<2500 u	g/kg	6000	2500	100	07/27/12 06:16	07/27/12 15:02	71-43-2	W
Ethylbenzene	124000 u		8350	3480	100	07/27/12 06:16	07/27/12 15:02	100-41-4	
Gasoline Range Organics	10300 n	ng/kg	348	348	100	07/27/12 06:16	07/27/12 15:02		
Methyl-tert-butyl ether	<2500 u	g/kg	6000	2500	100	07/27/12 06:16	07/27/12 15:02	1634-04-4	W
Naphthalene	94300 u	g/kg	8350	3480	100	07/27/12 06:16	07/27/12 15:02	91-20-3	
Toluene	138000 u	g/kg	8350	3480	100	07/27/12 06:16	07/27/12 15:02	108-88-3	
1,2,4-Trimethylbenzene	905000 u	g/kg	8350	3480	100	07/27/12 06:16	07/27/12 15:02	95-63-6	
1,3,5-Trimethylbenzene	336000 u	g/kg	8350	3480	100	07/27/12 06:16	07/27/12 15:02	108-67-8	
m&p-Xylene	1070000 u	g/kg	16700	6950	100	07/27/12 06:16	07/27/12 15:02	179601-23-1	
o-Xylene	437000 u		8350	3480	100		07/27/12 15:02		
Surrogates		- 0							
a,a,a-Trifluorotoluene (S)	115 %	6.	80-120		100	07/27/12 06:16	07/27/12 15:02	98-08-8	
Percent Moisture	Analytical	Method: AST	ΓM D2974-87						
Percent Moisture	28.1 %	6	0.10	0.10	1		07/31/12 17:31		
Sample: B-6 (7')	Lab ID:	4063977006	6 Collected	l: 07/17/12	2 17:20	Received: 07/	25/12 09:20 Ma	atrix: Solid	
Results reported on a "dry-weig	ght" basis								
Parameters	Results	Units	LOQ	LOD	DF	Prepared	Analyzed	CAS No.	Qual
WIGRO GCV	Analytical	Method: WI	MOD GRO Pr	eparation I	Method:	TPH GRO/PVO	C WI ext.		
Benzene	23900 u	g/kg	4210	1760	50	07/27/12 06:16	07/27/12 15:28	71-43-2	
Ethylbenzene	85700 u		4210	1760	50	07/27/12 06:16	07/27/12 15:28	100-41-4	
Gasoline Range Organics	5590 n		176	176	50	07/27/12 06:16	07/27/12 15:28		
Methyl-tert-butyl ether	1760J u		4210	1760	50	07/27/12 06:16	07/27/12 15:28	1634-04-4	
Naphthalene	37300 u	g/kg	4210	1760	50	07/27/12 06:16	07/27/12 15:28	91-20-3	
Toluene	294000 u		4210	1760	50	07/27/12 06:16	07/27/12 15:28	108-88-3	
1,2,4-Trimethylbenzene	324000 u		4210	1760	50	07/27/12 06:16	07/27/12 15:28	95-63-6	
1,3,5-Trimethylbenzene	103000 u		4210	1760	50	07/27/12 06:16	07/27/12 15:28	108-67-8	
m&p-Xylene	522000 u		8430	3510	50	07/27/12 06:16	07/27/12 15:28	179601-23-1	
o-Xylene	199000 u		4210	1760	50	07/27/12 06:16	07/27/12 15:28	95-47-6	
Surrogates a,a,a-Trifluorotoluene (S)	113 %		80-120		50	07/27/12 06:16	07/27/12 15:28	98-08-8	
Percent Moisture			ГМ D2974-87		-			-	
Percent Moisture	28.8 %		0.10	0.10	1		07/31/12 17:31		



QUALITY CONTROL DATA

Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

QC Batch: GCV/8749 Analysis Method: WI MOD GRO
QC Batch Method: TPH GRO/PVOC WI ext. Analysis Description: WIGRO Solid GCV
Associated Lab Samples: 4063977001, 4063977002, 4063977003, 4063977004, 4063977005, 4063977006

METHOD BLANK: 642683 Matrix: Solid

Associated Lab Samples: 4063977001, 4063977002, 4063977003, 4063977004, 4063977005, 4063977006

		Blank	Reporting		
Parameter	Units	Result	Limit	Analyzed	Qualifiers
1,2,4-Trimethylbenzene	ug/kg	<25.0	60.0	07/27/12 09:02	
1,3,5-Trimethylbenzene	ug/kg	<25.0	60.0	07/27/12 09:02	
Benzene	ug/kg	<25.0	60.0	07/27/12 09:02	
Ethylbenzene	ug/kg	<25.0	60.0	07/27/12 09:02	
Gasoline Range Organics	mg/kg	<2.5	2.5	07/27/12 09:02	
m&p-Xylene	ug/kg	<50.0	120	07/27/12 09:02	
Methyl-tert-butyl ether	ug/kg	<25.0	60.0	07/27/12 09:02	
Naphthalene	ug/kg	<25.0	60.0	07/27/12 09:02	
o-Xylene	ug/kg	<25.0	60.0	07/27/12 09:02	
Toluene	ug/kg	<25.0	60.0	07/27/12 09:02	
a,a,a-Trifluorotoluene (S)	%.	105	80-120	07/27/12 09:02	

LABORATORY CONTROL SAM	PLE & LCSD: 642684		64	12685						
		Spike	LCS	LCSD	LCS	LCSD	% Rec		Max	
Parameter	Units	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	RPD	Qualifiers
1,2,4-Trimethylbenzene	ug/kg	1000	1010	1010	101	101	80-120	0	20	
1,3,5-Trimethylbenzene	ug/kg	1000	1020	1020	102	102	80-120	0	20	
Benzene	ug/kg	1000	970	957	97	96	80-120	1	20	
Ethylbenzene	ug/kg	1000	1050	1040	105	104	80-120	2	20	
Gasoline Range Organics	mg/kg	10	10.4	9.6	104	96	80-120	8	20	
m&p-Xylene	ug/kg	2000	2060	2030	103	101	80-120	2	20	
Methyl-tert-butyl ether	ug/kg	1000	946	929	95	93	80-120	2	20	
Naphthalene	ug/kg	1000	1080	1090	108	109	80-120	2	20	
o-Xylene	ug/kg	1000	1050	1050	105	105	80-120	0	20	
Toluene	ug/kg	1000	1020	1000	102	100	80-120	2	20	
a,a,a-Trifluorotoluene (S)	%.				106	106	80-120			





QUALITY CONTROL DATA

Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

QC Batch: PMST/7390 Analysis Method: ASTM D2974-87

QC Batch Method: ASTM D2974-87 Analysis Description: Dry Weight/Percent Moisture

Associated Lab Samples: 4063977001, 4063977002, 4063977003, 4063977004

SAMPLE DUPLICATE: 645021

4063977001 Dup Max Parameter Units Result Result **RPD** RPD Qualifiers % 18.1 Percent Moisture 18.1 0 10





QUALITY CONTROL DATA

Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

QC Batch: PMST/7391 Analysis Method: ASTM D2974-87

QC Batch Method: ASTM D2974-87 Analysis Description: Dry Weight/Percent Moisture

Associated Lab Samples: 4063977005, 4063977006

SAMPLE DUPLICATE: 645056

Percent Moisture 4064275001 Dup Max Result RPD Qualifiers 7.3 7.2 1 10



QUALIFIERS

Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

DEFINITIONS

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to changes in sample preparation, dilution of the sample aliquot, or moisture content.

ND - Not Detected at or above adjusted reporting limit.

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

PRL - Pace Reporting Limit.

RL - Reporting Limit.

S - Surrogate

1,2-Diphenylhydrazine (8270 listed analyte) decomposes to Azobenzene.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

DUP - Sample Duplicate

RPD - Relative Percent Difference

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Pace Analytical is TNI accredited. Contact your Pace PM for the current list of accredited analytes.

TNI - The NELAC Institute.

LABORATORIES

PASI-G Pace Analytical Services - Green Bay

ANALYTE QUALIFIERS

W Non-detect results are reported on a wet weight basis.



QUALITY CONTROL DATA CROSS REFERENCE TABLE

Project: 102012022 OULU STORE/STATION

Pace Project No.: 4063977

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
4063977001	B-1 (6')	TPH GRO/PVOC WI ext.	GCV/8749	WI MOD GRO	GCV/8750
4063977002	B-2 (6')	TPH GRO/PVOC WI ext.	GCV/8749	WI MOD GRO	GCV/8750
4063977003	B-3 (6')	TPH GRO/PVOC WI ext.	GCV/8749	WI MOD GRO	GCV/8750
4063977004	B-4 (6')	TPH GRO/PVOC WI ext.	GCV/8749	WI MOD GRO	GCV/8750
4063977005	B-5 (7')	TPH GRO/PVOC WI ext.	GCV/8749	WI MOD GRO	GCV/8750
4063977006	B-6 (7')	TPH GRO/PVOC WI ext.	GCV/8749	WI MOD GRO	GCV/8750
4063977001	B-1 (6')	ASTM D2974-87	PMST/7390		
4063977002	B-2 (6')	ASTM D2974-87	PMST/7390		
4063977003	B-3 (6')	ASTM D2974-87	PMST/7390		
4063977004	B-4 (6')	ASTM D2974-87	PMST/7390		
4063977005	B-5 (7')	ASTM D2974-87	PMST/7391		
4063977006	B-6 (7')	ASTM D2974-87	PMST/7391		



























































































Search Results

Petroleum Programs Home

Search Instructions

Search by Tank ID

Search by Site, Owner, or Tank Characteristics

Tank List

Searching for:

Owner ID equal to 325560

Number of matching records: 6


Туре	ID	Facility ID	Address	Status	Contents	Size (gals)	Cust ID	Owner
County: BAYFIELD, FDID: 0412 - Iron River, Municipality: TOWN OF IRON RIVER								
1. UST	254263	89957	307 MAIN ST	Closed/Removed	Other	1000	325560	IRON RIVER
2. UST	254264	89957	307 MAIN ST	Closed/Removed	Diesel	1000	325560	IRON RIVER COOP
3. UST	254280	89957	307 MAIN ST	Closed/Removed	Kerosene	550	325560	IRON RIVER COOP
County: BAYFIELD, FDID: 0412 - Iron River, Municipality: TOWN OF OULU								
4. UST	254150	89958	COUNTY HWY FF & B	Closed/Removed	Fuel Oil	500	325560	IRON RIVER COOP
5. UST	254221	89958	COUNTY HWY FF & B	Abandoned without Product	Leaded Gasoline	500	325560	IRON RIVER COOP
6. UST	254222	89958	COUNTY HWY FF & B	Abandoned without Product	Unleaded Gasoline	500	325560	IRON RIVER COOP
Download								

Close this response window



This document was last revised: 10 November 2004

Wisconsin Department of Commerce



CORRESPONDENCE/MEMORANDUM

DATE:

September 15, 2009

TO:

Chris Saari

FROM:

Fred Strand Fuel

SUBJECT: Brownfield Site Assessment Grant and Underground Storage Tanks

Former Iron River Coop store/Evavold property Small parcel in SWSW, section 17, T48N-R9W

Chris: Can you help me with this, or direct me to the person who can?

I live in the Town of Oulu. The Town board received the attached letter. The Town is interested in pursuing this: to remove any contamination, to protect ground water, remove the buildings, and for possible redevelopment of the site. But they are concerned about potential liability and costs.

Publications RR-579, and RR-652 were included with the letter.

Can you tell me what information exists about the 2 USTs and any possible contamination that might be there?

I'll call you in a couple of days to talk with you about this.

Thanks!





Transportation • Municipal • Site Development • GPS
Remediation • Environmental Assessments • Emergency Response • Safety

September 3, 2009

Ms. Sandra Rantala Town of Oulu 73290 Boulevard Road Iron River, WI 54847

Subject:

Stanley Evavold Property (Former Iron River Co-Op)

73010 County Road B

Town of Oulu

Bayfield County, WI

Dear Sandy,

As a follow up to our recent correspondence, enclosed is some additional information about the Wisconsin Department of Natural Resources (WDNR) Brownfield Site Assessment Grant (SAG) program as it relates to the Evavold Property.

Soil or groundwater contamination has not been confirmed at the property, however three Underground Storage Tanks (USTs) are registered to the site. Two of these USTs are registered as "Abandoned Without Product", indicating that they remain in the ground, as confirmed by site reconnaissance. One UST is registered as removed.

According to Daniel Anderson, Washburn County Treasurer, the taxes are delinquent for 2007 and 2008. WDNR SAG funding is available for removal of the USTs, demolition of the building, and abandonment of the on-site potable well if the Town of Oulu wishes to acquire the property via tax deed. The Town would have 60 days to acquire the property if the grant is awarded. Information regarding the Brownfield Site Assessment Grant process is attached.

As a Local Governmental Unit (LGU), the town would not be responsible for additional investigation or remediation of any contamination detected during the UST removal per Wisconsin Statue 292.11. Information regarding liability protection for LGUs is included.

The Round 11 SAG application has not yet been made available by the WDNR. It will likely be accessible within the next month. A copy of the 2008 application is attached for your review.

If the Town of Oulu is interested in proceeding with a Round 11 Brownfield SAG Application, REI could assist with preparation of the application. If the Town feels they can complete the application, REI would be happy to provide a cost estimate for the UST removal and site assessment as well as Asbestos Containing Building Materials (ACBM) sampling of building components prior to demolition. I would also be happy to attend your next town board meeting to discuss this further.

Please contact me with questions or comments at (715)-675-9784 or adelforge@reiengineering.com.

Sincerely,

REI Engineering, Inc.

Andrew R. Delforge, P.G.

Hydrogeologist/Project Manager