

Detailed Information for Dam Middle

Seq No	272	Field File No	38.24
Size	UNKNOWN	NID	276
Popular Name	Scott	Former Name	

Location

County	Marinette	Longitude	-88.265172
Latitude	45.658020		
Permitted PLSS	NENE2937N18E		

Owners

Type	Private	Name	COLEMAN LAKE CLUB
------	---------	------	-------------------

Waterbody

Drainage Basin (sq mi)

Stream

Local Name	
Row and Official Name	
Navigable?	not determined
When was navigability determined?	

Impoundment

Local Name	
Row and Official Name	
Size (acres)	
Maximum Depth (ft)	

Regulation

Regulatory Authority	Wisconsin	Legal Status	Not Clear
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
Compliance Status			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

Construction Characteristics

Normal Storage (acre-ft)		Max Storage (acre-ft)	
Structural Height (ft)		Hydraulic Height (ft)	
Crest Length (ft)		Spillway Type	
Discharge Through Principal Spillway (cfs)		Width/Diameter of Principal Spillway (ft)	
Total Discharge Through All Spillways (cfs)		Total Width/Diameter of All Spillways (ft)	
Core Type	None	Core Position	None
Power Output (mW)			
Foundation Type	None	Foundation Certainty	
Structural Types			
Structure Purposes			

Detailed Information for Dam Middle

Geomarks

Mark Seq No	Old Mark Id	Elevation	Datum	Status	Status Date	Location Description
9263	571-A	100	Local	Verified (Surveyed)	8/29/1922	BM 571-A IS A BRONZE TABLET MARKED RAILROAD COMMISSION OF WISCONSIN, SET IN A CONCRETE POST FLUSH WITH GROUND, 40 FT. E OF LEFT END OF LEFT FILL 10 FT. S OF POND, 33 FT. NE OF CL OF ROAD AND 64 FT. NE OF UL IN. PINE.
9264	571-C	97.92	Local	Verified (Surveyed)	7/28/1933	BM 571-C IS A SQUARE CUT IN TOP OF PLATFORM OF DAM AT NE CORNER.

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

Construction History

First Dam at Site
No data found.

Outlet Gates

No data found.

Inspection History

No data found.

Followups

No data found.

Approvals

No data found.

Orders

No data found.

Inspection Schedule

No data found.

Analysis

No data found.