

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Butler creek outlet to Menomonee River.

No Image Available

Photo Outlet



Photo - Downstream

Photo Inlet

No Image Available

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Rocky debris jam major.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Rocky debris jam major.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Rocky debris jam major.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID 1723-155 Stream Butler Creek Road Campbell Dr. Date 8/1/2012
Alt ID BCSB55 Type Road Culvert Barrier Pass 0 Pass Method Outlet drop
Habitat NA Scour Pool No Upstream Pond: No

[Photo](#) [Other](#)

Shape Ellipse Drop Freefall into pool
Condition New Material Metal
Drop 0.2 Slope 0.009 Plugged 1%
Length 144.4 Width 11 Height 7.1

Notes

3 large metal corrugated culverts (perched), 3 small concrete stormwater outfalls. Rock blockage upstream of inlet.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Fallen tree impeding stream/changing its course, new course is just a trickle, blockage 13 ft in width.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Triple perched culverts, two storm outfalls in addition to three culverts, plugging occurs at inlet, culverts oversized for stream size.

No Image Available

[Photo Outlet](#)




[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Outlet higher elevation than inlet; culverts over half full during dry weather; deep upstream pond; wide downstream pond.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free spanning bridge, but big blockage at outlet impeding stream, stream width about 16 ft across; bank slump into stream causing blockage across entire width.




[Photo Outlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stream at sharp angle at inlet; dry creek upstream and fairly dry downstream.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Double arch free span bridge. Upstream extent of Butler Creek, dry now - potential wetland habitat in spring.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large culvert; upstream (?) section of lily creek dry, double culvert - upstream/downstream may flipflop (hard to tell in dry stream).

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stream in underground culvert.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stream in underground culvert.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stream in underground culvert.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stream in underground culvert.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stream in underground culvert.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stream in underground culvert.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam impeding stream.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Log spanning stream, minor impediment.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Minor debris jam.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stream widens at the inlet.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large culvert, no impediments.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)

No Image Available

[Photo - Upstream](#)

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large culvert, no impediments.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)

No Image Available

[Photo - Upstream](#)

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span golf course bridge.

No Image Available

[Photo Outlet](#)



[Photo - Downstream](#)

[Photo Inlet](#)



[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Golf Course Bridge.

No Image Available

[Photo Outlet](#)



[Photo - Downstream](#)

[Photo Inlet](#)



[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge on golf course.

No Image Available

[Photo Outlet](#)



[Photo - Downstream](#)

[Photo Inlet](#)



[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge on golf course.

No Image Available

[Photo Outlet](#)



[Photo - Downstream](#)

[Photo Inlet](#)



[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge on golf course.

No Image Available

[Photo Outlet](#)



[Photo - Downstream](#)

[Photo Inlet](#)



[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge on golf course.

No Image Available

Photo Outlet



Photo - Downstream

Photo Inlet



Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge on golf course.

No Image Available

[Photo Outlet](#)



[Photo - Downstream](#)

[Photo Inlet](#)



[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large culvert, no impediments.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large Culvert, no impediments. Wetland upstream.

No Image Available

[Photo Outlet](#)



[Photo - Downstream](#)

[Photo Inlet](#)



[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Wetland upstream, west of Boundary Rd, south of SR 100 / Main St.

No Image Available

[Photo Outlet](#)

No Image Available

[Photo Inlet](#)

No Image Available

[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Triple culvert; plugged but passable.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Triple circular concrete culvert; stream diverges at outlet;
stream comes in at angle to culvert.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Culvert under driveway.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Construction site bridge.

No Image Available

Photo Outlet



Photo - Downstream

Photo Inlet



Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Construction site bridge.

No Image Available

Photo Outlet



Photo - Downstream

Photo Inlet



Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Discontinued railroad spur - culvert.

No Image Available

Photo Outlet



Photo - Downstream

Photo Inlet



Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Collapsed railroad bridge culvert; water still getting through but defintie impediment. Inlet blocked by railroad debris




[Photo Outlet](#)


[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Railroad crossing culvert.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Wetland upstream and downstream.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Lots of cobble blocking both outlets.

No Image Available

[Photo Outlet](#)



[Photo - Downstream](#)



[Photo Inlet](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Cobble blocking the culvert both upstream and downstream.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

On south side of mayfair rd. flows underground approximately 100 yds underneath menomonee river parkway. debris clogging up inlet.



Photo Outlet

Photo Inlet



Photo - Downstream





Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Inlets both blocked with substantial debris.



[Photo Inlet](#)

[Photo Outlet](#)



[Photo - Upstream](#)

[Photo - Downstream](#)



No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Fallen tree blocking stream causing severe erosion.



[Photo Outlet](#)


[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Boulder field , might worsen low water passage.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Bridge opening too wide.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large rock pile. Deep upstream and downstream.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Well built bridge.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID	1725-92	Strea	Grantosa Creek	Road	N 100th St	Dat	8/1/2012
Alt ID		Type	Other	Pass		Pass Method	
Habitat	NA	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	
Length		Width	
		Height	

Notes

Stream comes out from underground culvert here.

No Image Available

Photo Outlet



Photo - Downstream

Photo Inlet

No Image Available

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large debris jam at mouth of Lily Creek; but somewhat passable.



[Photo Inlet](#)



[Photo Outlet](#)



[Photo - Upstream](#)



[Photo - Downstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Tributary stream outlet.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Possible full blockage debris jam; recheck.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Three openings, each partially blocked but passable.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Rock bar impeding flow.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

River island impeding flow, creates two channels.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Rock pile impeding flow.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Lots of water under bridge (2-3 ft deep) but not upstrm or dwnstrm. Giant culvert much too wide for stream size.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Rocky debris jam major.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Rocky debris jam major.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID	1723-91	Strea	Lily Creek	Road		Dat	7/9/2012
Alt ID	LCSB71	Type	Rocky Debris Jam Major	Pass		Pass Method	
Habitat	NA	Scour Pool		Upstream Pond:		Photo Other	

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	
Length		Width	
		Height	

Notes

Rock field impediment impeding flow.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID 1723-87 Strea Lily Creek Road Brentwood Dr Dat 7/11/2012
Alt ID LCSB72 Type Rocky Debris Jam Major Pass 0.5 Pass Method Obstruction
Habitat NA Scour Pool No Upstream Pond: No

[Photo](#) [Other](#)

Shape Open bottom Drop
Condition Good Material Concrete
Drop Slope 0 Plugged 0%
Length 28.6 Width 16 Height 8.15

Notes

Bridge with culvert lining, stagnant water, rock field just beyond outlet impeding the flow; school of small bass.



[Photo Inlet](#)



[Photo Outlet](#)



[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge; no impediment.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Extra storm water culvert at outlet, can't do tailwater - stream dry at outlet, much sediment buildup at both outfalls, road crossing at right angle to stream.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Deep water at inlet side of culvert, streambed at outlet higher in elevation -preventing flow, choked with algae.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free spanning bridge, saw tadpoles.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free spanning bridge.

No Image Available

[Photo Outlet](#)



[Photo - Downstream](#)



[Photo Inlet](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Muskrat/beaver dams at inlet, low power lines, wetland habitat.

No Image Available

[Photo Outlet](#)

No Image Available


[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID	1723-57	Strea	Lily Creek	Road	Silver Spring Rd	Dat	7/9/2012
Alt ID		Type	Road Culvert Passable	Pass		Pass Method	
Habitat	NA	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	At stream grade
Condition	Good	Material	Concrete
Drop		Slope	
Plugged			
Length		Width	
Height			

Notes

Quadruple culverts, dry.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Low water crossing for farm vehicles.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Double concrete culvert under driveway. Culvert two has a rise in the middle. Both culverts perched.

No Image Available


[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Big debris jam; definite impediment.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridgeport.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream





Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Concrete box culvert (double), tree branch blocking inlet.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Concrete box culvert.

No Image Available

Photo Outlet




Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Two perched culverts, hard plastic.

No Image Available


[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Culvert w apron oak leaf trail connecting wetland area to Little Menomonee.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

No impediment. Some sediment built up in channel.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Log span entire stream; most likely impediment.



Photo Outlet


Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID	1722-59	Strea	Little Menomonee River	Road		Dat	3/16/2012
Alt ID		Type	Stormwater Outlet	Pass		Pass Method	
Habitat	Maybe	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	
Length		Width	
		Height	

Notes

Stormwater outlet & ditch.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam, not major impediment.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Minor debris jam.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Log jam, definite impediment; spans stream; two other smaller jams just downstream.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Semi-major debris jam.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Minor debris jam.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond: [Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Minor debris jam.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater ditch outlet.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch; 4 ft deep hole at outlet.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Minor debris jam.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam and impediment.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam with sediment backed up.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Series of minor debris jams.



[Photo Inlet](#)

[Photo Outlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam and impediment.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free spanning bridge; 2 storm drains nearby.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Perched wetland habitat.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Railroad crossing free span brdige.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Mouth to wetland drainage



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Mouth to drainage.



[Photo Inlet](#)

[Photo Outlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam and smaller one upstream.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Mouth to drainage ditch.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam and impediments and minor upstream and downstream blocks.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID	1722-88	Strea	Little Menomonee River	Road		Dat	3/20/2012
Alt ID		Type	Stormwater Outlet	Pass		Pass Method	
Habitat	Maybe	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	
Length		Width	
		Height	

Notes

Woody debris jam major.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch; major woody debris jam.



[Photo Outlet](#)


[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Tributary outlet; potential wetland habitat.



Photo Outlet

Photo Inlet



Photo - Downstream






Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Minor debris blockage.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris blockage with garbage.

No Image Available

Photo Outlet



Photo - Downstream




Photo Inlet

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam possible wetland adjacent to the jam.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris blockage.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris blockage.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Minor debris blockage.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream




Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris blockage.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Minor debris.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam with lots of garbage.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam blocking openings of bridge; rectangular concrete structure; another culvert nearby outlet.



Photo Outlet

Photo Inlet



Photo - Downstream




Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large culvert crossing diagonally under W Mill Rd & Fond du Lac Ave.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID	1722-110	Strea	Little Menomonee River	Road		Dat	3/21/2012
Alt ID		Type	Stormwater Outlet	Pass		Pass Method	
Habitat	Maybe	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	
Length		Width	
		Height	

Notes

Stormwater outlet & ditch.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span road bridge.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Low bridge with two sections of pilons. Storm water culvert nearby.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam spanning width of river.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

2 minor debris jams.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Small drop in elevation from bedrock.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Mouth to drainage outfall.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Minor debris jam.



[Photo Outlet](#)


[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Series of multiple debris jams.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge. Oak Leaf Trail.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Drainage mouth to wetland area.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available



Menomonee Fish Passage Barrier Survey

Site ID Strea Road
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam; change in water elevation; possible beaver.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Mouth to wetland habitat.



[Photo Inlet](#)

[Photo Outlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span road bridge.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Drainage outlet

No Image Available

[Photo Outlet](#)

No Image Available

[Photo Inlet](#)

No Image Available

[Photo - Downstream](#)

No Image Available

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.



[Photo Outlet](#)



[Photo - Downstream](#)



[Photo Inlet](#)



[Photo - Upstream](#)

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Partial blockage.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

2 blockages.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Minor woody debris jam.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.

No Image Available

Photo Outlet

No Image Available

Photo Inlet



Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge; drainage inlet next to bridge.

No Image Available

[Photo Outlet](#)

No Image Available

[Photo Inlet](#)

No Image Available

[Photo - Downstream](#)

No Image Available

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.

No Image Available

Photo Outlet

No Image Available

Photo Inlet



Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.

No Image Available

Photo Outlet

No Image Available

Photo Inlet



Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Fallen branches.

No Image Available

Photo Outlet

No Image Available

Photo Inlet



Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Log blockage.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Log blockage.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Log blockage around the river bend.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam blocking.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Backwater.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span road bridge.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID	1722-140	Strea	Little Menomonee River	Road		Dat	5/8/2012
Alt ID		Type	Stormwater Outlet	Pass		Pass Method	
Habitat	Maybe	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	
Length		Width	
		Height	

Notes

Drainage outlet, concrete bottom.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span railroad bridge.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID	1722-139	Strea	Little Menomonee River	Road		Dat	5/8/2012
Alt ID		Type	Stormwater Outlet	Pass		Pass Method	
Habitat	Maybe	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	
Length		Width	
		Height	

Notes

Stormwater outlet & ditch; major pooling in ditch.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Low water crossing. Saw signs for super fund site.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span railroad bridge.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large road culvert; passable.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free spanning bridge.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Foot bridge dirt & tree stacked with planks on top.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Future impediment.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Passage on west side today - will continue to collect debris to become an impediments.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Farm bridge; seems no impediment 2 + ft deep under bridge today.

No Image Available

[Photo Outlet](#)

No Image Available

[Photo Inlet](#)

No Image Available

[Photo - Downstream](#)

No Image Available

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Several fallen trees mainly on west 2/3 stream some flow east side.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream




Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Fallen tree low water problem.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Several fallen trees & maybe garbage trapped.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Down trees.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge, some sort of drop structure underneath (monitoring station set up).

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

2 to 3 stems in river; 4 to 5 inch DBH.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large tree & several small stems in river.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Two 8 inch trees & several small stems.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Many stems in river junction with creek.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

One large stem many small ones trapped much dirt.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Many branches some soil.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Branches and dirt.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large metal culvert; passable.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Rusty metal culvert.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Minor debris jam.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Mouth drainage ditch.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Scattered medium trees.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Sheep fence across river property boundary.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

2 very large trees + smaller ones.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

2 large trees.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large fallen trees with small ones small pool upstream.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Several fallen trees.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Several fallen trees.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Actually Little Menomonee River; fallen trees block river / double box concrete culvert , boulders all over inlet/outlet

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond: Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large collection of boulders. may be a problem in low water.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Small natural drop, potential low water problem.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Construction debris in river. May be a problem in low water.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Natural bedrock drop.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Remnant road/railroad bridge supports.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge.

No Image Available

Photo Outlet



Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Hart Park bike path bridge.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

3 Remnant bridge supports in river, no impediment.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span railroad bridge.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span pedestrian bridge.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge. No obstruction.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Pedestrian bridge over the Menomonee River.

No Image Available


[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Mouth of ditch; potential limk to upstream pond?

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes


Old stone ford/road spans river.




[Photo Inlet](#)



[Photo Outlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Concrete sewer box; diagonal to bank; exceeded tape length.
Water depth range 1.2, 2.5, 3.6.



[Photo Outlet](#)

[Photo Inlet](#)



[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Diagonal to stream bank, concrete sewer box.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available



[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Pedestrian bridge - Hoyt Park

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream




Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Cut-stone walking path.



[Photo Outlet](#)


[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Concrete sewer box spans stream diagonally. Too deep and cold to survey; come back in spring.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

STRUCTURE 1 - 6 staggered concrete slabs spanning the river, 2 channels divided by barrier spanning the bridge. (structure 1) headwater depth = 1.82 / tailwater depth = 1.05. STRUCTURE 2 - headwater depth = 1.44 / tailwater depth = 0.24. very low flow.




[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Golf cart bridge causing debris jam.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge.



[Photo Outlet](#)


[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Fallen tree partial block.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID	1725-142	Strea	Menomonee River	Road		Dat	2/21/2012
Alt ID		Type	Rocky Debris Jam Minor	Pass		Pass Method	
Habitat	NA	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	0%
Length	0	Width	0
		Height	0

Notes

Pile of boulders . Return to survey.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Fallen tree upstream - no impediment. debris jam under bridge.



Photo Outlet


Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID	1725-102	Strea	Menomonee River	Road		Dat	2/24/2012
Alt ID		Type	Waterfall / Cascade	Pass		Pass Method	
Habitat	NA	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	
Length		Width	
		Height	

Notes

Small natural drop, boulders across stream.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Impoundment w/ dam/bridge; bridge collapsed & causing debris backup.



[Photo Outlet](#)



[Photo - Downstream](#)



[Photo Inlet](#)



[Photo - Upstream](#)

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Old stone river crossing.



Photo Outlet



Photo - Downstream



Photo Inlet




Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Line of boulders across river and multiple fallen trees.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Downstream picture shows Grantosa Creek.



[Photo Outlet](#)


[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID	1725-107	Strea	Menomonee River	Road		Dat	2/24/2012
Alt ID		Type	Stormwater Outlet	Pass		Pass Method	
Habitat	Maybe	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	
Length		Width	
		Height	

Notes

Outlet from stormwater ditch.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Golf cart bridge. No impediment. Possible weir.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Low water bridge/ debris jam; fallen tree upstream.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Golf cart bridge, somewhat low. evidence of beavers nearby.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Huge highway bridge.



[Photo Outlet](#)


[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID	1725-146	Strea	Menomonee River	Road		Dat	3/1/2012
Alt ID		Type	Woody Debris Jam Minor	Pass	1	Pass Method	No drop, depth and velocity
Habitat	NA	Scour Pool		Upstream Pond:		Photo Other	

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	0%
Length	0	Width	0
		Height	0

Notes

Debris jam possible habitat west bank.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Ford spans stream diagonally. Too deep and cold to survey;
come back in spring.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam braided stream.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Possible debris jam.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond: [Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam; excellent habitat on east bank.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Passable debris jam.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Passable debris jam.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Oxbow off of main channel; buried culvert.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Natural debris jam extending majority of river width.

No Image Available

[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam.

No Image Available

Photo Outlet

No Image Available


Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Small inlet to brook.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Severe log jam.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Severe log jam; created its own divergence around that is dry.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Small inlet off river.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Small inlet.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam, potential to become worse.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span train bridge.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span road bridge.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Sewer Drainage.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Pedestrian Bridge; free span.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Fallen tree debris jam.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Small inlet.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span road bridge.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

No longer a bridge here; brdige abutment remains in stream.



Photo Outlet



Photo - Downstream

Photo Inlet



Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Train trestle, totally passable.

No Image Available

[Photo Outlet](#)

No Image Available

[Photo Inlet](#)



[Photo - Downstream](#)

No Image Available

[Photo - Upstream](#)

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey


Site ID Stream Road
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam.



[Photo](#) [Outlet](#)




[Photo](#) [Inlet](#)



[Photo](#) - [Downstream](#)



[Photo](#) - [Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch; minor woody debris jam.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large debris jam with suspicious rebar lodged in middle.



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge; no impediment.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Someone lined up rocks across stream channel next to a storm outfall.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam partial impediment.



[Photo Outlet](#)



[Photo - Downstream](#)

[Photo Inlet](#)



[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Severe debris jam, high potential for being an impediment.



[Photo Outlet](#)



[Photo - Downstream](#)

[Photo Inlet](#)



[Photo - Upstream](#)



No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam causing backup of surface debris.



[Photo Outlet](#)

[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large debris jam; passable?



[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Tributary outlet; potential wetland habitat.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Woody debris jam major.



[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Serious debris jam; still passable.



Photo Outlet



Photo - Downstream



Photo Inlet



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Big debris jam; passable but may become a problem.



[Photo Outlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span road bridge.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam; passable now, may become an issue soon.



[Photo Inlet](#)


[Photo Outlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam spans river, but passable.



[Photo Inlet](#)

[Photo Outlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Passable; looks like neighbors built a small rock wall dam here



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Big debris jam.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge on golf course.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge on golf course.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge on golf course.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge on golf course.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge on golf course.

No Image Available

[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Mouth of storm ditch; has tons of construction rubble in it.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam; lots of garbage, should be cleaned up.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Over 3.5 feet under bridge and downstream. too deep for tailwater calculations , did outlet elevation from top of bridge. saw large turtle, few small bass and 100's crawfish.

No Image Available

[Photo Outlet](#)




[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Pedestrian bridge in Rotary Park.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Outlet for ditch, observed lots of minnows, crayfish, small bass.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Passable, but large riprap under bridge is starting to become dislodged and fill stream channel. Saw several sucker fish (redhorse?) in deep pool on upstream side of bridge; probably 12-18 inch long. Also saw small pike and panfish.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Fairly large debris jam; seems passable, but not sure. Lots of schmutz built up behind downed trees Flaggging delineating wetlands on streambank; Bonestro name on them.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available



[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free spanning bridge, lots of rock debris, cobble impeding outlet, upstream pond (deeper not wider), small natural falls upstream.

No Image Available


[Photo Outlet](#)




[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater ditch enters here.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Fairly large natural drop.



[Photo Outlet](#)

[Photo Inlet](#)



[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond: [Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

2 to 3 ft falls; probably passable.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Small (1 ft in low water) natural falls; appears passable.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

8 in diameter pipe spanning creek bed running parallel with overhead power lines.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Menomonee Falls Dam.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

No impediment , bridge over millpond.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream




Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID 1721-148 Strea Menomonee River Road north of Grand Ave Dat 7/6/2012
Alt ID Type Rocky Debris Jam Minor Pass 0 Pass Method Obstruction
Habitat NA Scour Pool No Upstream Pond: No

[Photo](#) [Other](#)

Shape Square or rec Drop At stream grade
Condition Good Material Concrete
Drop Slope 0.014 Plugged 90%
Length 36 Width 34 Height 5.2

Notes

Rocks across entire width of outlet; low water impediment.
Small drop structure upstream; 0.6 ft high, 0.38 ft tailwater in low water.




[Photo Outlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large Tree branch spanning stream.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Medium width tree spanning river. Psbl low water impediment.

No Image Available

Photo Outlet



Photo - Downstream



Photo Inlet



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Tree spanning width of river. Possible low water barrier.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)

No Image Available

[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID	1721-152	Strea	Menomonee River	Road		Dat	7/9/2012
Alt ID		Type	Fence	Pass	1	Pass Method	No drop, depth and velocity
Habitat	NA	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	0%
Length		Width	
		Height	

Notes

Barbed wire fence spanning river.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID	1721-171	Strea	Menomonee River	Road		Dat	7/19/2012
Alt ID		Type	Fence	Pass		Pass Method	
Habitat	NA	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	
Condition		Material	
Drop		Slope	
		Plugged	
Length		Width	
		Height	

Notes

Barbed wire fence crossing the stream.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam (fairly major) spanning river.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free spanning bridge (private), debris jam just downstream.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream




Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Private free spanning bridge, no impediment.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream




Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span road bridge.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available



[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major debris jam spans entire river.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Tiny drop/riffle under bridge. Re-visited on 7/19/12 and big blockage at inlet (80%) during low water. Several large boulders lining stream channel under bridge.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free spanning bridge, just downstream from golf course.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Pedestrian Bridge at Golf Course. Ponded up behind bridge but no apparent blockage.

No Image Available

[Photo Outlet](#)

No Image Available

[Photo Inlet](#)

No Image Available

[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span road bridge.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Very deep silt on bottom.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span railroad bridge

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Srream comes in at bad angle.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span road bridge.

No Image Available

Photo Outlet



Photo - Downstream



Photo Inlet



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID 1721-26 Strea Nor-X-Way Channel Road Fond du Lac Ave Dat 6/14/2012
Alt ID NXWSB75 Type Rocky Debris Jam Major Pass 0.5 Pass Method Obstruction
Habitat NA Scour Pool Yes Upstream Pond: No

Photo Other

Shape Square or rec Drop
Condition Good Material Concrete
Drop Slope 0 Plugged 100
Length 86 Width 8 Height 6

Notes

Double concrete box, rocks and debris buildup at inlet and outlet (esp. structure 1 - impeding in channel and upstream).

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Open bottom bridge / no major impediments.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Couldnt do full survey; road too high; no impeds under bridge.

No Image Available

[Photo Outlet](#)



[Photo - Downstream](#)



[Photo Inlet](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Passable; double culvert may be a bit much for the stream, especially during low water.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID 1721-32 Stream Nor-X-Way Channel Road State Highway 100 Date 10/17/2012
Alt ID NXWSB76 Type Road Culvert Barrier Pass 0.5 Pass Method Obstruction
Habitat NA Scour Pool Yes Upstream Pond: No

[Photo](#) [Other](#)

Shape Square or rec Drop At stream grade
Condition New Material Concrete
Drop 0.1 Slope 0.001 Plugged 1%
Length 125 Width 12 Height 8

Notes

Quadruple culvert. Structures 3 & 4 blocked 50% at outfall. Structure 3 is main channel. Too many culverts. Structure 4 data on data sheet.



[Photo Inlet](#)



[Photo Outlet](#)



[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Double box concrete channel.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge.

No Image Available

[Photo Outlet](#)




[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

R&R not active; take down bridge. 5 pilons in center of stream.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Major impediment, easy fix. Wood plank platform blocking channel.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Concrete stormwater channel completely cuts off stream at a right angle, then stream becomes channelized concrete from here downstream. Channel wall about 2 ft high; water backed up behind and leaking through weepholes. Water surface 0.7 ft blw channel.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Possible impediment; medium debris jam.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Road culvert.

No Image Available


[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Triple, elliptical concrete culverts; little drop/cascade figured into tailwater measurement.

No Image Available


[Photo Outlet](#)

No Image Available


[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Log spanning stream, medium impediment.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Tributary stream outlet.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Small debris jam.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Tributary stream outlet.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Tributary stream outlet. May connect to wetland.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Railroad culvert. Railroad tie blocking inlet & impeding stream.

No Image Available

[Photo Outlet](#)

No Image Available

[Photo Inlet](#)



[Photo - Downstream](#)

No Image Available

[Photo - Upstream](#)

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Metal culvert lining, too tall to survey, upstream wetland.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)

No Image Available

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Concrete box culvert, high standing water; River is basically in a wetland with a slightly defined channel.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Metal culvert buried by pond, b/w markers to locate where (May 2012 observation). In October 2012, wetland almost completely dry, did full survey. Is this the correct crossing? Another crossing to the south, both come from same wetland complex.

No Image Available

[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Metal culvert, weir dam at outlet.



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large culvert over Noyes Park Creek.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Culvert, rusted/some corrosion.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Very low water; both culverts filled 1/3 with sediment (1 ft deep). Sediment bars upstream and downstream of culvert. Stream comes into culverts at bad angle.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Snowmobile trail bridge.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Tree spanning river.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Large tree spanning creek> Definite impairment.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Intermittent stream enters on NE side of stream.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam (fallen tree) spanning river.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Debris jam spanning river, probable impediment.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

See paper records for structure 4 measurements. Poorly constructed wingwall at inlet -loose rock , major silt deposition at culvert outlets.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Passable private tractor bridge; no impediment.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream




Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Makeshift footbridge potential cause of blockage.



[Photo Outlet](#)

[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Very large tree blocking majority of stream; somewhat passable.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

2 somewhat problem trees across river.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)



No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Tributary stream outlet; blocked by debris jam.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Medium debris jam; passable.



[Photo Outlet](#)

[Photo Inlet](#)

No Image Available

No Image Available

[Photo - Downstream](#)

[Photo - Upstream](#)

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Potential barrier debris jam spanning creek. Rocky bottom changing to silt as move downstream.

No Image Available

Photo Outlet



Photo - Downstream



Photo Inlet



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Private bridge overr creek; free span, passable.

No Image Available

Photo Outlet




Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Private bridge crumbling over creek; Garbage strewn about.



Photo Outlet



Photo - Downstream



Photo Inlet



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge, no blockage. Small rock pile spanning creek just dwnstrm of bridge is an impairment. Also rocks upstream of bridge.



[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Water in culvert but stream is dry.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Corrugated metal culvert, inlet overgrown with vegetation and dry, outlet totally buried. No sure of flow but lots of wetland habitat.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Modifications on upstream side (pile of mud by inlet).

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Metal culvert, appears passable, survey if time.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Big metal culvert.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Potential spawning habitat, series of connected ponds in Germantown; Square concrete culvert (blocked), drop structure also at outlet of pond (stream not on unit's map).



[Photo Outlet](#)



[Photo Inlet](#)

No Image Available



[Photo - Downstream](#)

[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Potential spawning habitat, series of connected ponds in Germantown; metal corrugated culvert - two-thirds inundated , stream flowing into pond around apartment complex (stream not on unit's map), passable.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Potential spawning habitat, series of connected ponds in Germantown; free spanning bridge crossing stream (stream not on unit's map).

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Potential spawning habitat, series of connected ponds in Germantown; bridge crossing stream.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Above dam trib to Menomonee, Germantown; elliptical metal culvert.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Above dam trib to Menomonee, Germantown; two metal elliptical culverts (very dry area) , b/w posts marking location.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Above dam trib to Menomonee, Germantown; rusty metal culvert.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Trib stream, survey later if time. Box concrete culvert, outlet channel with some sediment / vegetation at outlet.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Intermittent stream, inlet crushed badly.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Question if its half- or full culvert (metal).

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Potential wetland habitat; intermittent stream, dry.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Double metal circular culverts, heavily eroded /lots of silt.

No Image Available

Photo Outlet



Photo Inlet



Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Free span bridge, flows into series of ponds, plugged at outlet.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Two metal corrugated culverts (possibly oversized).

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Concrete circular culvert.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream



Photo - Upstream



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch; acts as beginning of tributary to Dretzka Park Creek.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Stream Road Date
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

[Photo](#) [Other](#)

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Perched culvert at outlet, upstream plugged, impediments inside culvert, at least two full blockages downstream, evidence of rusting (some holes), severe erosion of road at inlet, deep scour pool before blockages.

No Image Available

[Photo Outlet](#)



[Photo Inlet](#)



[Photo - Downstream](#)



[Photo - Upstream](#)



Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Intermittent stream; wetland connection potential.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Possible tributary to wetland / stormwater pond habitat.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Intermittent stream; wetland connection potential.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID	1723-78	Strea	x(WBIC 5034482) Unnamed	Road	Judith Ln	Dat	7/9/2012
Alt ID		Type	1 Culvert	Pass		Pass Method	
Habitat	Maybe	Scour Pool		Upstream Pond:			

Photo Other

Shape		Drop	At stream grade
Condition	Good	Material	Concrete
Drop		Slope	
		Plugged	
Length		Width	
		Height	

Notes

Possible tributary to wetland / stormwater pond habitat.

No Image Available

Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Small culvert; intermittent stream.

No Image Available

Photo Outlet

No Image Available

Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Potential fish access to pond but dry currently.

No Image Available

Photo Outlet



Photo Inlet

No Image Available

Photo - Downstream

No Image Available

Photo - Upstream

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Potential access to pond for fish habitat, storm overflow culvert.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

No Image Available

Menomonee Fish Passage Barrier Survey

Site ID Strea Road Dat
Alt ID Type Pass Pass Method
Habitat Scour Pool Upstream Pond:

Photo Other

Shape Drop
Condition Material
Drop Slope Plugged
Length Width Height

Notes

Stormwater outlet & ditch.



Photo Outlet

Photo Inlet

No Image Available

No Image Available

Photo - Downstream

Photo - Upstream

No Image Available

