

## **Attachment D – Maintenance Plans – Cover Sheet**

There are no remedial systems or covers requiring maintenance at this site, therefore this attachment is not applicable.

A cap maintenance plan was put in place as part of the previous site closure in 2009 based on direct contact RCL exceedances of benzo(a)pyrene. At that time, the non-industrial direct contact RCL for benzo(a)pyrene was 8.8 ug/kg. The current 2022 non-industrial direct contact RCL for benzo(a)pyrene is 115 ug/kg. None of the surface soil samples collected during the previous site investigation activities exceed the revised standard. Based on the revised standard, MSA recommends that the cap maintenance requirement put in place as part of the previous site closure be removed.