Notifications to Owners of Affected Properties (Attachment G)

							Reasons Notification Letter Sent:												
ID	Address of Affected Property	Parcel ID No.	Date of Receipt of Letter	Type of Property Owner	WTMX	WTMY	Residual Groundwater Contamination = or > ES	Residual Soil Contamination Exceeds RCLs	Monitoring Wells: Not Abandoned	Monitoring Wells: Continued Monitoring	Cover/Barrier/Engineered Control	Structural Impediment	Industrial RCLs Met/Applied	Vapor Mitigation System(VMS)	Dewatering System Needed for VMS	Compounds of Concern in Use	Commercial/Industrial Vapor Exposure Assumptions Applied	Residual Volatile Contamination Poses Future Risk of Vapor Intrusion	Site Specification Situation
A	8570 Huber Lane, Minocqua, WI	MI-2178	01/25/2024	APO	543139	600704	X												
B	8566 Huber Lane, Minocqua, WI	MI-2179-8	02/14/2024	APO	543163	600660	X												
C	Huber Lane, Minocqua, WI		01/19/2024	ROWH	543112	600693	X												
D	Serenity Trail, Minocqua, WI	MI-2178-12	05/01/2024	APO	543132	600743	X												