BAY CLEANERS

(VACANT - June 2021)

MAY 18, 2021 SOIL EXCAVATION LIMITS (189.22 TONS)

SB-6 (Sigma) HA-1 & SP/SD-1 (Moraine)

SB-7

SS-1

F.D.

F.D.

Access Door

A

A'

SS-4

SS-3

SS-2

OE-5

OE-4

OE-1

HA-2/SP-7

SP/SD-6

SP/SD-10

HA-3 /SP-3

Rear Sidewalk

Storm - 18" deep ditch

SP/SD-11

SP/SD-2

SP/SD-9

MW-1

PZ-1

Swale

Ditch Line

HA-4

SP-8

SP-5

SCALE IN FEET

Horizontal 1"=10'

MW-2

OE-6

OE-3

SP/SD-4

OE-2

Stormwater to pond

N

Notes:

1. Soil Types shown within the excavated area are pre-remedial. The excavation was backfilled with gravel.

2. Similarly, pre-remedial soil analytical results in the excavated area are shown @ HA-1/SP/SD-1, SP/SD-2 HA-3/SP-3, and SP/SD-9 which were removed and replaced with clean fill.

Moraine Environmental, Inc.
Environmental Management Services
766 Tower Drive, Fredonia, WI 53021
262-692-3345 | Fax 262-692-3348

FIGURE B.3.a
GEOLOGIC CROSS-SECTION

BAY CLEANERS SITE / JENIOR-BAGNESKI, LLC PROPERTY
201 - 207 S. MAIN STREET, THIENSVILLE, WI 53092



SCALE IN FEET

Horizontal 1"=10'

Vertical 1"=10'

Legend

Horizontal Scale 1" = 10'
Vertical Scale 1" = 10'

Soil Sample location

Shallow water table

<22.7 - Concentration Less than Detectable Levels

504 - PCE concentration (ug/kg) other detection above GWP RCL listed

Excavation Limits - Crushed Sand & Gravel Backfill

cis: 105 GWP - cis-1,2-DCE concentration in (ug/kg)

TCE: 23.1J - Trichloroethene concentration in (ug/kg)

GWP - Value exceeds groundwater pathway RCL

VOCs: ND - Volatile Organic Compounds Not Detected

TS - Top Soil

S & G - Sand & Gravel

5,400 - Soil excavated - Contamination no longer present

Extent of Residual Unsaturated Soil Contamination (Post-Remedial)

Graphic Scale

Revised by CTS
Revised: 5-31-22
Project File: Meteker\6733 Working.dwg
*Note: Depiction prepared field measurements and historical project drawings. Boundaries are not surveyed.