Detailed Information for Dam Gollon, Bill

Seq No	1075	Field File No	60.39
Size	LARGE	NID	1189
Popular Name		Former Name	

Location

County	Taylor		
Latitude	45.042637	Longitude	-90.853966
Permitted PLSS	NENW3430N04W		

Owners

Type	Private	**Name**	Doro, Adam

Waterbody

Drainage Basin (sq mi)	0.60		
Stream		**Impoundment**	
Local Name	WOLF RIVER	Local Name	GOLLON BAIT FARM
Row and Official Name		Row and Official Name	
Navigable?	non-navigable	Size (acres)	45.00
When was navigability determined?	1966	Maximum Depth (ft)	6.00

Regulation

Regulatory Authority	Wisconsin	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Normal Operation	Low Head Dam Assessment	No
Compliance Status			
Ch. 31.19 Owner Inspection	Compliant	Ch 31.19 DNR Inspection	Compliant
NR 333 Standards	Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year	1995	Stability NR 333 Year	1990
D/S NR 333 Year	2024		

Construction Characteristics

Normal Storage (acre-ft)	260.00	Max Storage (acre-ft)	350.00
Structural Height (ft)	11.00	Hydraulic Height (ft)	7.00
Crest Length (ft)	1,445.00	Spillway Type	Controlled
Discharge Through Principal Spillway (cfs)	41.30	Width/Diameter of Principal Spillway (ft)	2.00
Total Discharge Through All Spillways (cfs)	343.50	Total Width/Diameter of All Spillways (ft)	47.00
Core Type	None	Core Position	None
Power Output (mW)			
Foundation Type	None	Foundation Certainty	
Structural Types	Earth		
Sturcture Purposes	Fish Pond, Aquaculture and Wildlife		

Detailed Information for Dam Gollon, Bill

Geomarks

No data found.

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

Construction History

First Dam at Site

Designer	Construction Firm	Completed (year)
SCS		1966

Outlet Gates

No data found.

Inspection History

Inspection Date	Inspection Report Date	Inspection Type
11/14/2024	7/16/2025	Transfer Inspection
4/18/2017	9/18/2017	Inspection by Owner/Engineering Consultant under Ch. 31.19(2)(ag)
9/20/2007	9/24/2007	Inspection conducted by DNR under Ch. 31.19(2)decennial
6/14/2001		Informal Inspection to check on status or progress on work directives
10/24/1990		None

Followups

Type of Followup	Due Date	Extension Date	Completion Date
Benchmarks	09/30/2010	08/01/2026	
Water levels	09/01/2025		
Embankment repairs	08/01/2026		
Inspection, Operation & Maintenance Manual	08/01/2026		
Emergency Action Plan	08/01/2026		
Monitoring	12/31/2034		

Approvals

Approval Date	Approval Type
7/29/2025	Dam Transfer; Stat 31.185B
8/16/1999	Dam Transfer; Stat 31.185B
9/1/1995	Dam Failure Analysis
1/1/1990	Plan Appr. Repair/Recon; Stat 31.18
4/28/1966	Plan Appr. New Dam on Non-Nav Str; Stat 31.33

Orders

No data found.

Inspection Schedule

Inspection Year	Inspection Type
2034	Owner
2044	Owner

Analysis

No data found.