Detailed Information for Cranberry Dam Remington 11

Seq No	563	Field File No	71.14
Size	LARGE	NID	
Popular Name		Former Name	

Location

County	Wood		
Latitude	44.249821	Longitude	-90.160297
Permitted PLSS	SWSW3321N03E		

Owners

Type	Private	**Name**	John Hancock Life Insurance Co

Waterbody

Drainage Basin (sq mi)	44.00		
Stream		**Impoundment**	
Local Name	REMINGTON DITCH NO. 1	Local Name	
Row and Official Name		Row and Official Name	
Navigable?	navigable	Size (acres)	50.00
When was navigability determined?	1935	Maximum Depth (ft)	7.00

Regulation

Regulatory Authority	Wisconsin	Legal Status	Authorized (31.04)
Physical Status	On Landscape	Hazard Rating	Low
Operational Status	Not Applicable	Low Head Dam Assessment	Not Evaluated
Compliance Status			
Ch. 31.19 Owner Inspection	Not Applicable	Ch 31.19 DNR Inspection	Not Applicable
NR 333 Standards	Not Required		
NR 333 Compliance Items			
EAP NR 333 Year		IOM NR 333 Year	
Capacity NR 333 Year		Stability NR 333 Year	
D/S NR 333 Year			

Construction Characteristics

Normal Storage (acre-ft)	160.00	Max Storage (acre-ft)	210.00
Structural Height (ft)	9.00	Hydraulic Height (ft)	7.00
Crest Length (ft)	54.00	Spillway Type	Controlled
Discharge Through Principal Spillway (cfs)	970.00	Width/Diameter of Principal Spillway (ft)	20.00
Total Discharge Through All Spillways (cfs)	970.00	Total Width/Diameter of All Spillways (ft)	
Core Type	None	Core Position	None
Power Output (mW)	0.00		
Foundation Type	None	Foundation Certainty	
Structural Types	Gravity, Earth		
Sturcture Purposes	Other - Cranberry, Wetland Restoration, Waste		

Detailed Information for Cranberry Dam Remington 11

Geomarks

No data found.

Water Levels

	Normal	Winter
Minimum	Not established	Not established
Normal	Not established	Not established
Maximum	Not established	Not established

Construction History

First Dam at Site 1935

Designer	Construction Firm	Completed (year)
WI EMERGENCY RELIEF ADM		1935

Outlet Gates

No data found.

Inspection History

Inspection Date	Inspection Report Date	Inspection Type
8/26/2015	8/26/2015	Inspection by Owner/Engineering Consultant under Ch. 31.19(2)(ag)
4/10/1937		None

Followups

No data found.

Approvals

No data found.

Orders

No data found.

Inspection Schedule

No data found.

Analysis

No data found.