#04-05-521255

04-05-521255

STATE DIVISION OF ENVIRONMENT GOVERNMENT 608/266-1231
U.S. NATIONAL RESPONSE CENTER 800/424-8802
CHEMTREC/PESTICIDES 800/424-9300

5-79

DEPARTMENT OF NATURAL RESOURCES

TOXIC AND HAZARDOUS INCIDENT REPORT FORM Form 3200-49

Date of Incident: 73/05/16	Time of Incident: 3401 AM PM	Reported by (Name): Norman L. Hicks	Telephone Number:
Date Reported:	Time Reported: AM PM	Agency or Firm Reporting:	Reported Thru Div. Emer. Govt. ☐ Yes ☐ No
Substance Involved: Road Salt	Quantity:	Units:	Person or firm Responsible: Northern Coal + Supply Co.
Substance Involved:	Quantity:	Units:	Contact Name: / Telephone Number: / -

Physical Characteristics: ☐ Solid ☐ Semisolid ☒ Liquid ☐ Gas Color ____ Odor ____

Address: 239 Arndt

Cause of Incident: Road Salt Pile uncovered - Runoff

City: Green Bay State: Wis. Zip Code: 54303

☐ Transporation Related ☒ Facility Related SPCC Plan Yes ☐ No ☐

Exact Location Description (Intersection, Mileage, Etc.): Northern Coal + Supply Co. - Green Bay

County Location: Brown

¼,¼ Section, Town, Range: T 23 N, R 20E

DNR District: L.M. DNR Area: G.B. Surface Waters Affected: ☒ Yes ☐ No Drainage Basin: 113

Name of Surface Water: Fox River Distance to Surface water ft. Distance to Storm Sewer ft.

Groundwaters Affected ? ☐ Yes ☐ No Distance to Nearest Well ☐ Municipal ☐ Private ft

Date District Notified: Time District Notified: AM PM District person Notified: Telephone Number: / -

Date Investigated: 73/05/16 Time Investigated: AM PM Person Investigating: Norman Hicks Telephone Number: 414/432-4105

Action Taken by Spiller:
☐ No Action Taken ☐ No Notification ☐ Delayed Notificat.
☐ Containment type ____
☐ Cleanup Method ____
☐ Disposal Location ____
☐ Fire Department Action ____
☐ Contractor Hired (Name) ____
☒ Other Action pile covered w/canvas.

Weather Conditions: Temperature ____ Wind Speed ____
Precipition ☒ Yes ☐ No Wind direction ____
Direction of Spill Movement ____

Action Taken by DNR:
☐ No Action Taken ☒ Investigation ☐ 29:29 enforcement
☐ Containment type ____
☐ Cleanup Method ____
☐ Supervise Cleanup (person) ____
☐ Disposal Location ____
☐ Spiller Required to take Action (type) ____
☐ Contractor Hired by DNR (name) ____
☐ DNR Spill Expenses sent to Madison Central Office
☐ Evidence Collected:
☐ Photographs # ____ ☐ Statements of Witnesses
☐ Samples # ____ ☐ others ____

List Human Hazards or Casualties: ☐ Real ☐ Potential

Environmental Hazards or Damage: ☐ Real ☐ Potential
☐ Vegetation ____
☐ Fish ____
☐ Wildlife ____
☐ Birds ____
☐ Other ____
Comments: ____

Other Agencies on Scene:
Local: ____
State: ____
Federal: ____

Person Filing This Report (Print)
Signature Date

Additional Comments:

Closed 5/16/73

MADISON OFFICE COPY

DEPARTMENT OF NATURAL RESOURCES

TOXIC AND HAZARDOUS INCIDENT REPORT FORM

FORM 3200-49 11-78

DATE OF INCIDENT (Y/M/D)	TIME OF INCIDENT (24 HR)	DATE INCIDENT REPORTED	TIME INCIDENT REPORTED
73/05/16			

INCIDENT REPORTED BY (NAME)	AGENCY OR FIRM	TELEPHONE NUMBER
Norman L. Hicks		/ -

SUBSTANCE OR TRADE NAME OF MATERIAL(S) INVOLVED: ROAD SALT

QUANTITY LOST	UNITS	COUNTY OF INCIDENT LOCATION
		Brown

EXACT LOCATION DESCRIPTION (HIGHWAY INTERSECTION, MILEAGE, ETC.): Northern Coal and Supply Co.

CAUSE OF INCIDENT

☐ TRANSPORTATION RELATED

☒ FACILITY RELATED

BIGGEST TIME	OF ROAD	SALT LEFT	UNCOVERED	
IN THE	BUILDING	IT SUPPLY	CO. PROPERTY	
YARD	SPILLS	SEEPAGE	IN THE	YARD
HEAD	WATER			

PERSON OR FIRM RESPONSIBLE FOR INCIDENT	TELEPHONE NUMBER
Northern Coal and Supply Co	1432-3364

P.O. BOX, STREET OR ROUTE	CITY	STATE	ZIP CODE
239 Arndt	Green Bay	Wis	54303

INCIDENT INVESTIGATED BY	AGENCY TELEPHONE NUMBER	DATE INCIDENT INVESTIGATED	TIME INCIDENT INVESTIGATED
Norman L. Hicks	1432-4105	73/05/16	

DNR DISTRICT	DNR AREA	TOWN, RANGE, SECTION, ¼, ¼¼ SECTION	SURFACE WATERS AFFECTED	GROUND WATERS AFFECTED
K.M.	Green Bay	T 23 N, R 2 E,	☐ YES ☐ NO ☒ POTENTIAL	☐ YES ☐ NO ☒ POTENTIAL

DISTANCE TO NEAREST WELL	DISTANCE TO NEAREST SURFACE WATERS	NAME OF SURFACE WATER AFFECTED	DRAINAGE BASIN
Unknown FT.	40-50 FT.	Fox River	113

LIST HAZARDS, INJURIES OR DEATHS TO HUMANS	LIST HAZARDS TO VEGETATION, FISH, BIRDS OR WILDLIFE
None	

ACTION TAKEN BY DNR:
- ☒ Investigation
- ☐ Containment
- ☐ Supervise Cleanup
- ☐ Cleanup
- ☐ Disposal
- ☐ Enforcement
- ☐ Spiller Required to Take Action
- ☐ Contractor Hired by DNR
- ☐ Spiller Billed for Expenses
- ☐ No Action Taken

ACTION TAKEN BY SPILLER:
- ☐ No Notification Made
- ☐ Delayed Notification
- ☐ Containment
- ☐ Supervise Cleanup
- ☐ Cleanup
- ☐ Disposal
- ☐ Contractor Hired by Spiller
- ☒ Other Action: Pile covered w/Canvas.
- ☐ No Action Taken
- ☐ Yes ☐ No ☐ N/A SPCC Plan

ADDITIONAL REMARKS TO BE COMPUTER STORED:

PILE COVERED BY CANVAS AND BAGS AROUND PERIMETER

ADDITIONAL REMARKS NOT TO BE COMPUTER STORED:

X

TOXIC AND HAZARDOUS SUBSTANCE INCIDENT REPORT
Form 1500-18

Department of Natural Resources

	Date of Incident 5-16-73
Report Prepared By Norman L. Hicks	Telephone Number 432-4105
DNR District IM	County Brown
Location of Incident Northern Coal & Supply	Waters Affected Fox River

Nature of Incident

- [ ] Fish Kill
- [ ] Bird Kill
- [ ] Wildlife Kill
- [ ] Vegetation Kill
- [ ] Hazard to Humans
- [x] Hazard to Fish, Birds, or Wildlife
- [x] Other (Specify) Pollution

Cause of Incident

- [ ] Cause Unknown
- [ ] Agricultural Application of Pesticide or Other Chemicals
- [ ] Industrial Use of Pesticide or Other Chemicals.
- [ ] Spill of Pesticide, Chemicals, or Petroleum Products.
- [x] Discharge of Oxygen Demanding, Wastes By Industry or a Municipality.
- [x] Other (Specify) Stockpile of road salt in flood plain.

Toxic and Hazardous Substance(s) Involved (Name the Pesticides, Chemicals, or Other Substances and Estimate Quantities Involved) Road salt 13,660 tons of road salt. This is the total amount of salt to be stored.

Name of Persons or Firm Responsible for Incident Northern Coal & Supply Co.	Telephone Number 432-3364
Street or Route 239 Arndt	City, State, Zip Code Green Bay, Wis. 54303

Action Taken by DNR (Check One or More)

- [ ] No Action Taken by DNR
- [x] Incident Investigated
- [ ] Enforcement Action Taken
- [x] Measures Taken by DNR to See That Person Responsible for the Incident Performs Cleanup.
- [ ] Cleanup Measures Taken by DNR to Protect the Environment
- [x] Other Action (Specify) Recommended measures to help prevent salt from getting into the Fox River.

Additional Remarks
A stockpile of 13,660 tons of road salt is situated on the property of Northern Coal and Supply for storage during the summer months. This salt arrived by boat transportation

3-73 (over)

Additional Remarks Continued:

on May 10, 1973, and is owned by Domtar Chemicals, LTD., Sifto Salt Division, 9950 West Lawrence Avenue, Shiller Park, Illinois 60176. The stockpile is between 40-50 feet west of the banks of the Fox River and is piled on the bare ground without any protective device placed around it to contain the pile. The pile is not covered on this date. Plans to cover the pile have been made for May 21 or 22 and will be covered by a Milwaukee concern who has the canvas covering at the Northern property at this date. Reason for not being covered is that no equipment is available to date to flatten out from the present cone shape of the pile. Area where pile is located is approximately one foot above the normal water level of the Fox River. The water level of Green Bay is high, as is the Fox River level. With strong NE winds Green Bay waters are backed up the Fox River banks, flooding the Northern Coal & Supply property where salt is piled. Such conditions occurred during the early morning hours of May 16, causing waters to reach the salt pile with depth of 3 to 4 inches of water around such pile. It has been recommended that after covering the salt pile a dike of sand bags be placed around the pile to a height of approximately 2 feet. There would be areas in the dike left open for rain drainage, and closing materials (filled bags) there to close opening when wind conditions are such to cause flooding. This recommendation was agreed to by Mr. Leonard Doe, foreman, Northern Coal & Supply Co. The area will be watched for compliance to recommendations. This incident was reported by phone to Mr. Kondoll, phone 224-3162, Milwaukee Coast Guard. Mr. Kondoll agreed to recommendation.

Norman L. Seals