State of Wisconsin - Department of Natural Resources
Substance Release Notification Report (SERTS)
Report created on 02/24/2010

Incident Date & Time:	Reported Date & Time:	BRRTS No:	Spill ID:
11/04/2008 16:00	11/06/2008 09:47	#04-49-554951	20081106NO49-1
DATCP Reported? No **DATCP Transferred? No**	**NFA Letter Sent?** No	**ERP Transferred?** ~~No~~ Yes #02-49-554944	**Incident Closed?** Yes : 02/24/2010

Location

Region:	County:	Municipality:
NO	Polk	FREDERIC, VILLAGE OF

Facility/Property Name and Street Address:	Description:
NW WI ELECTRIC CO 106 ASH STREET	

Facility Type: Power Generating Plant/Utility Co/Electrical Trnsf/Dist Stn

Lat/Long:	PLSS:	WTM:

Weather Conditions: Cloudy

Responsible Parties

Name/Address (1):	Contact:	Other Contact:	Spill Packet:
NW WI ELECTRIC COMPANY 104 S PINE ST GRANTSBURG, WI 54840-0009 (715) 463-5371 x Primary	JOHN DAHLBERG		

Cause

VALVE MALFUNCTION.

Cause Type: Equipment Failure

Substances

Name	Other / Comments	Amt Released	Amt Recovered	Type	Color	Odor
Diesel	#2	288.0 Gal	5.0 Gal	LIQUID		

Environmental Impacts / Damages

Environmental Impacts:	Resource Damages:	Injuries:	Evacuation:
GROUNDWATER : Potential SOIL	No	No	No

Cleanup Actions

Method	Description
Absorbent (oil dry, sand, sawdust)	
Other	ENVIRONMENTAL INVESTIGATION

Cleanup Action Comments

SOAKER PADS INSIDE THE TRAILOR AND OUTSIDE AREA WHERE VISIBLE. MOST OF THE SPILL SOAKED INTO THE GROUND BEFORE AN IMMEDIATE ACTION COULD BE TAKEN.

Contractors Hired

Name	Description
OTHER	SEH

Waste Destinations

Location	Description

State of Wisconsin - Department of Natural Resources
Substance Release Notification Report (SERTS)
Report created on 02/24/2010

Agencies Notified / On Scene

Agency	Notified	On Scene
DNR	X	

Additional Comments

SAGER SPOKE WITH DARRELL REED, SEH, ON 11/06/08. REED TOLD SAGER THAT MOST OF THE PRODUCT SOAKED INTO THE GROUND. SEH WILL CONDUCT A SOIL AND IF NECESSARY A GROUNDWATER INVESTIGATION TO DEFINE THE EXTENT OF CONTAMINATION. DARRELL REED, SEH, CALLED SAGER ON 11/19/08. REMOVING THE GENERATORS TO ACCESS THE CONTAMIANTTED SOIL TO EXCAVATE IT MAY BE TOO DIFFICULT. THERE ARE THREE GENERATORS AND THE SPILL OCCURRED AT THE CENTER GENERATOR. SEH IS LOOKING AT AN SVE SYSTEM TO REDUCE THE SOURCE AREA CONTAMINATION AS MUCH AS POSSIBLE. SAGER TOLD REED THAT MWS ARE NEEDED TO DEFINE THE EXTENT OF CONTAMAINTION AND THE THE SVE SYSTEM IS PROBABLY A GOOD IDEA. SAGER TOLD REED WE WOULD PROCEED AS AN IMMEDIATE ACTION FOR NOW. JOHN DAHLBERG NW WI ELECTRIC CALLED SAGER AT 1130HRS ON 11/20/08. DAHLBERG SAID THEY ARE GOING TO TRY SVE IN THE AREA OF THE SPILL. SAGER SPOKE WITH DARRELL REED ON 2/19/2009. FOUR SVE WELLS ARE INSTALLED ON SITE AND SEH WILL START THE SVE SYSTEM ON FRIDAY. SEH WILL COLLECT AIR SAMPLES ON FRIDAY AND USE A PID TO FIELD MONITOR. THEY WILL BE CYCLING THE SVE SYSTEM. SEH WILL SEND AS BUILT REPORTS AND STATUS REPORT. SAGER RECEIVED IMMEDIATE ACTION REPORT ON 2/5/10. SAGER TRANSFERED TO ERP FOR ADDITIONAL INVESTIGATION AND CLEANUP. SEE BRRTS ID #: 02-49-554944

Enforcement Action/Citation

Enforcement Action/Citation? No

Case Activity Reports:	

Person Reporting

Name	Representing / Address	Primary Phone	Secondary Phone
DARRELL REED	SEH	(715) 720-6220 x	

Contractors Hired

Name / Address	Zone Contractor Hired by DNR?
	No

Contacts

Role	Name	Office Phone	Date	Time
Prepared By:	JOHN SAGER	(715) 365-8959 x	11/11/2008	
Person Notified:	JESSE ASHTON		11/06/2008	
Investigated By:			11/06/2008	
Incident Commander:				
Spill Coordinator:	JOHN SAGER, NO Region	(715) 365-8959 x	02/24/2010	

Electronic Attachments (list)

Name	Type