State of Wisconsin - Department of Natural Resources
Substance Release Notification Report (SERTS)
Report created on 08/20/2012

SPILL ID# 20120612WC06-1 BRRTS# 04-06-559216

Incident Date & Time:	Reported Date & Time:	BRRTS No:	Spill ID:
08/15/2012 24:00	06/12/2012 12:00	04-06-559216	**20120612WC06-1**
DATCP Reported? No **DATCP Transferred? No**	**NFA Letter Sent?** No	**ERP Transferred?** No	**Incident Closed?** Yes : 08/20/2012

Location

Region:	County:	Municipality:
WC	Buffalo	ALMA, TOWNSHIP OF

Facility/Property Name and Street Address:	Description:
JP MADGETT STATION 500 OLD STATE HWY 35	ALMA, WI 54610

Facility Type: Power Generating Plant/Utility Co/Electrical Trnsf/Dist Stn

Lat/Long:	PLSS:	WTM:

Weather Conditions:

Responsible Parties

Name/Address (1):	Contact:	Other Contact:	Spill Packet:
DIARYLAND POWER 3200 E AVE LACROSSE, WI 54602-0817 (608) 788-4000 x Primary	LEIF TOLOKKEN (608) 787-1311 x primary		

Cause

RUPTURED HOSE

Cause Type: Hydraulic Line Break

Substances

Name	Other / Comments	Amt Released	Amt Recovered	Type	Color	Odor
Hydraulic Oil		20.0 Gal	0.0 Gal	LIQUID		

Environmental Impacts / Damages

Environmental Impacts:	Resource Damages:	Injuries:	Evacuation:
SOIL	No	No	No

Cleanup Actions

Method	Description
Absorbent (oil dry, sand, sawdust)	
Excavation	

Cleanup Action Comments

EXCAVATED CONTAMINATED SOIL WAS HAULED AWAY BY WABASHA SAND & GRAVEL CO - WHO OWNED THE TRUCK THAT HAD THE HYDRAULIC LINE RUPTURE.

Contractors Hired

Name	Description

Waste Destinations

Location	Description

Agencies Notified / On Scene

Agency	Notified	On Scene
DNR	X	

SPILL ID# 20120612WC06-1 BRRTS# 04-06-559216

Additional Comments

REPORTED ON JUNE 12, 2012 - RESEND OF PREVIOUS NOTIFICATION FORM WHICH WAS MISSING FROM SERTS ***
SUBMITTED VIA SERTS WEB FORM REF # 6656

Enforcement Action/Citation

Enforcement Action/Citation? No

Case Activity Reports:	

Person Reporting

Name	Representing / Address	Primary Phone	Secondary Phone
LEIF TOLOKKEN	DAIRYLAND POWER	(608) 787-1311 x	

Contractors Hired

Name / Address	Zone Contractor Hired by DNR?
	No

Contacts

Role	Name	Office Phone	Date	Time
Prepared By:	Deena Kinney	(715) 839-2784 x	08/16/2012	
Person Notified:	TOM KENDZIERSKI		06/12/2012	
Investigated By:			06/12/2012	
Incident Commander:				
Spill Coordinator:	THOMAS KENDZIERSKI, WC Region	(715) 839-1604 x	08/20/2012	

Electronic Attachments (list)

Name	Type

DAIRYLAND POWER
COOPERATIVE

June 12, 2012

Thomas Kendzierski
Regional Spills Coordinator/Hydrogeologist
WDNR
P.O. Box 4001
Eau Claire, WI 54702-4001

Dear Mr. Kendzierski:

SUBJECT: Oil Spill on May 21, 2012 at Dairyland Power Cooperative's J.P. Madgett Station

On May 21, 2012, a contract driver delivering goods to our J.P. Madgett (JPM) site ruptured a hydraulic hose on a large gravel area on the east side of the JPM station. The approximately 20-gallon spill was quickly discovered, and spill materials were dispersed to soak up any visible oil on the gravel. The gravel was then scraped up so that no visible oil staining could be observed.

The contaminated soil was hauled away by Wabasha Sand and Gravel Company (the company who owned the truck that broke the hydraulic line) to be properly disposed of. PAH samples were taken on May 22, and as the attached report will show, there is no residual oil contamination at the site.

Dairyland Power Cooperative will consider this area clean and will consider this incident closed by submittal of this letter.

If you have any questions or concerns, feel free to contact me at 608-787-1311 at any time.

Sincerely,

Leif Tolokken
Solid and Hazardous Materials Specialist

LCT:krm
G:\ENV Letters_Word\Tolokken\JPM Hydraulic Oil Spill on 05212012 Letter to WDNR with Lab Results 06122012.docx.

Pace Analytical®
www.pacelabs.com

Pace Analytical Services, Inc.
1241 Bellevue Street - Suite 9
Green Bay, WI 54302
(920)469-2436

ANALYTICAL RESULTS

Project: ALMA TRUCK HYDRAULIC OIL
Pace Project No.: 4060874

Sample: OIL CLEANUP CONFIRMATION **Lab ID: 4060874001** Collected: 05/22/12 09:30 Received: 05/25/12 09:40 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	LOQ	LOD	DF	Prepared	Analyzed	CAS No.	Qual
8270 MSSV PAH by SIM	Analytical Method: EPA 8270 by SIM Preparation Method: EPA 3546								
Acenaphthene	**<2.4**	ug/kg	17.0	2.4	1	05/30/12 06:39	05/30/12 13:01	83-32-9	
Acenaphthylene	**<2.7**	ug/kg	17.0	2.7	1	05/30/12 06:39	05/30/12 13:01	208-96-8	
Anthracene	**<4.0**	ug/kg	17.0	4.0	1	05/30/12 06:39	05/30/12 13:01	120-12-7	
Benzo(a)anthracene	**<2.4**	ug/kg	17.0	2.4	1	05/30/12 06:39	05/30/12 13:01	56-55-3	
Benzo(a)pyrene	**<2.8**	ug/kg	17.0	2.8	1	05/30/12 06:39	05/30/12 13:01	50-32-8	
Benzo(b)fluoranthene	**<2.9**	ug/kg	17.0	2.9	1	05/30/12 06:39	05/30/12 13:01	205-99-2	
Benzo(g,h,i)perylene	**<2.2**	ug/kg	17.0	2.2	1	05/30/12 06:39	05/30/12 13:01	191-24-2	
Benzo(k)fluoranthene	**<3.2**	ug/kg	17.0	3.2	1	05/30/12 06:39	05/30/12 13:01	207-08-9	
Chrysene	**<3.1**	ug/kg	17.0	3.1	1	05/30/12 06:39	05/30/12 13:01	218-01-9	
Dibenz(a,h)anthracene	**<4.6**	ug/kg	17.0	4.6	1	05/30/12 06:39	05/30/12 13:01	53-70-3	
Fluoranthene	**<8.5**	ug/kg	17.0	8.5	1	05/30/12 06:39	05/30/12 13:01	206-44-0	
Fluorene	**<4.2**	ug/kg	17.0	4.2	1	05/30/12 06:39	05/30/12 13:01	86-73-7	
Indeno(1,2,3-cd)pyrene	**<2.4**	ug/kg	17.0	2.4	1	05/30/12 06:39	05/30/12 13:01	193-39-5	
Naphthalene	**<3.0**	ug/kg	17.0	3.0	1	05/30/12 06:39	05/30/12 13:01	91-20-3	
Phenanthrene	**<3.7**	ug/kg	17.0	3.7	1	05/30/12 06:39	05/30/12 13:01	85-01-8	
Pyrene	**<3.1**	ug/kg	17.0	3.1	1	05/30/12 06:39	05/30/12 13:01	129-00-0	
Surrogates									
2-Fluorobiphenyl (S)	78	%.	43-130		1	05/30/12 06:39	05/30/12 13:01	321-60-8	
Terphenyl-d14 (S)	102	%.	32-130		1	05/30/12 06:39	05/30/12 13:01	1718-51-0	
Percent Moisture	Analytical Method: ASTM D2974-87								
Percent Moisture	**2.1**	%	0.10	0.10	1		06/08/12 18:38		

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..