9-050730 TOXIC AND HAZARDOUS SPILL REPORT State of Wisconsin Form 4400-91 Department of Natural Resources (608) 266-3232 State Div. Emergency Gov't. Spill ID Number U.S. Nat'l. Response Center (800) 424-8802 Chemtrec/Pesticides/Chlorine (800) 424-9300 Y Y M M D D 0-99 Date of Incident Day of Week Time of Incident ☐ A.M. Reported By (Name) 5-17-95 ☐ P.M. Wed (felder ☐ A.M. Date Reported Day of Week Time Reported Agency or Firm Reporting Gov't. 5-17-95 Dilhr ☐ P.M. Substance Involved Quantity Units Person or Firm Responsible gallons Weller's gasoline Atz Substance Involved Units Contact Name Quantity Kobert

Telephone Number Reported thru Div. Emergen. ☐ Yes No No Telephone Number 1715 1258-8377 Physical Characteristics Address - Street or Route 1386 Liquid Solid Color. City, State, Zip Code Gas Semisolid Odor Kural Cause of Incident Action Taken By Spiller 1420 No Action No ☐ Investigate Exact Location Description (Intersection, mileage, etc.) Notification Taken 61386 Mainst Containment; Type County Location 1/41/4, 1/4, Section, Town, Range Cleanup; Method 950% Amount Recovered ☐ Monitor DNR Dist DNR Area Groundwaters Affected Contractor Hired; Name Yes No No LMD M ☐ Potential Other Action Surface Waters Affected Name of Surface Water Yes No. Potential Spill Location Date District Day of Week Time District Notified Industrial Facility/Paper Mill/Chem. Co. Notified A.M. Gas/Service Station/Garage, Auto Dealer, Repair Shop Wed 5-17-95 ☐ P.M. Ag Coop/Facility/Cheese Factory/Creamery District Person Notified Telephone Number Other Small Business (bank, grocery, insurance co., etc.) Koxanne 14/4 11/92 Public Property (city, county, state, church, school, etc.) Day of Week Date Investigated Time Investigated 5-27-95 mon A.M. Utility Co., Power Generating/Transfer Facility 5-17-95 P.M. Private Property (home/farm) Person Investigating Telephone Number Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler 15210-4230 Ton Sturm Transportation Accident, Fuel Supply Tank Spill Action Taken By DNR Transportation Accident, Load Spill No Action Supervise/Conduct Construction, Excavation, Wrecking, Quarry, Mine Investigation Taken Cleanup Other Spiller Required To excavate / Land spread Spilled Substance Destination Take Action; Type Contractor Hired Soil By DNR; Name Groundwater ☐ Amount Recovered Surface Water 29.29 Enforcement Storm Sewer Other Agencies on Scene ☐ Sanitary Sewer Contained/Recovered Other State Dilly Person, Filing This Report (print name) Koxanne Signature Date Signed Federal Additional Comments:

closed 5/30/95

CORRESPONDENCE/MEMORANDUM

RECEIVED

MAY 3 0 1995

TO: Waupaca County Files

DATE: May 24, 1995

LMD SOLID WASTE

FROM: Tom Sturm - WDNR, Shawano

SUBJECT: Release at Weller's Store, Rural, Waupaca County.

On May 17, 1995, I received a call from the DILHR Petroleum Inspection Office in Stevens Point. Brian Feldner had called his office to report that a gas station operator in Rural had pumped the water that was in his USTs into the roadway. Brian had requested that I receive this information.

I arrived at the site around noon on May 17, 1995. I observed stained pavement on the Weller's Store property. I could follow the staining down Main St.approximately 150 feet to a small culvert that ran under the road. Staining and odors were also noted in the soil on the road and in a small area off the road. No odors or other evidence of petroleum were noted in the drainage swale across the road.

While I was assessing the situation, the owner, Mr. Robert Weller Jr., arrived. I told him who I was, what was reported and what I was doing. He admitted that he had pumped the material from his tanks and that it was sludge and water from the bottom. I told him that this was not the proper way to dispose of this and I had concerns about the material entering the Crystal River. He asked who had reported it and I told him, Brian Feldner of DILHR. Mr Weller explained that DILHR is requiring him to upgraded his pumps and that he is required to have tightness testing done on his USTs because of their age. He had recently had two of the tanks tested and they passed according to the tester. He also brought up that another complaint was filed a couple of years ago. I told him that I was the one that responded at that time and determined that the reported sheen on the water was a result of a natural source such as iron bacteria.

I requested that he remove the contaminated material, on and off the road and in the upstream end of the culvert. I told him that it would need to be stored on and covered with plastic. He asked if he could take it to his nearby farm; OK. I told him to replace the material off the road with clean fill to alleviate any hazard that would be created by the removal. I suggested that he contact the town to let them know what he was doing. He declined saying he did not want to make things more complicated.

Mr. Weller said he would get on it that afternoon. I told him I will come back at a later date to see if it had been taken care of. He indicated that he would be leaving the following day for South Dakota but would be back by Mon; I would try and get back then. I told him that I would consider allowing him to spread the material on his farm field depending on the amount and field conditions.

I received a call form Brian Feldner later that afternoon. He indicated that approximately 4 inches of water was in the tanks and may have been a result of poorly designed fill pipes that allowed surface water to seep in. Among other things, he was ordered to remove this water. The code is not specific on disposal of this water. I summarized my meeting with Mr. Weller.


Station Address - E1380 Main St., Rural, WI
Phone - Store, 715-258-8377; Mr. Weller's House - 715-258-3893

LANE MICH. DIST

I returned to the site on Monday, May 22, 1995. I observed that some material had been removed on and along the road. A slight odor remained in some of the soil. No odor was noted in the culvert. Approximately 1-2 cubic yards was covered with plastic at the store. Mr, Weller then arrived and showed me what he had done. I showed him where some of the contaminated soil remained. He indicated that he would try and remove the material. We then went to his farmland to see if it was suitable for spreading of the material. The site was on a upland and was they with no evidence of shallow groundwater or wetland. He asked if he could use the material to fill in some of the ruts in the dirt road; OK. I reiterated that next time he needs to remove water from his tanks he will need to contact a waste hauler qualified to accept this water.

Any potential environmental impact form this incident has been alleviated by Mr. Weller's actions and cooperation.

cc: Roxanne Nelezen - LMD



RECEIVED DNR
MAY 3 0 1995
LAKE MICH. DIST.