

State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Jim Doyle, Governor Scott Hassett, Secretary Gloria L. McCutcheon, Regional Director Southeast Region Headquarters 2300 N. Dr. Martin Luther King, Jr. Drive P O Box 12436 Milwaukee, Wisconsin 53212-0436 Telephone 414-263-8500 FAX 414-263-8483 TTY 414-263-8713

March 24, 2003

Mr. James B. Hugg P O Box 3262 Milwaukee, WI 53201-3262

Subject: Reported Contamination at Speedy Lube, 117 E. Capitol Dr., Milwaukee, WI

FID: 241081280

BRRTS: 02-41-182420

Dear Mr. Hugg:

On October 21, 2002 the Department of Natural Resources ("the Department") sent a letter to Mr. Gerald W. Hunn describing his responsibility to address soil and/or groundwater contamination that was detected at the site referenced above (see enclosed letter). On November 3, 1997 Michael Carlton (von Briesen, Purtell & Roper) provided information from Drake Environmental that contamination was detected above laboratory detection limits for chlorobenzene (2,000 ppb), tetrachloroethene (1,4000,000 ppb), and 1,2,4-trimethlybenzene (2,900 ppb). A "no response" from Mr. Hunn prompted further research into the ownership of this property. Tax Code, #273022400Z, lists you and Julie A. Hugg as owners.

The Department found no indication that any action has been taken at the site since Environmental Associates submitted a workplan on August 4, 1998. Under Section 292.11 of the Wisconsin Statutes, a person who possesses or controls a hazardous substance release (e.g., the owner of the property where a spill has occurred) is required to take actions necessary to restore the environment to the extent practicable. Because the release of contaminants into soil and groundwater may have significant environmental or health implications, it is important that the extent and degree of the released contaminants be determined and that the contamination be remediated to the extent practicable.

Please submit the name, address and phone number of the environmental consultant you have retained to investigate the release at the site, along with a work plan and schedule for the investigation, within 30 days of receipt of this letter. If you have other information, such as reports or laboratory results from samples collected at the site, you should submit these as well. All applicable information should be submitted IN WRITING to:

Ms. Victoria Stovall Remediation and Redevelopment Program Wisconsin Department of Natural Resources Box 12436 Milwaukee, WI 53212

Correspondence should reference the "Subject" name and file reference numbers listed above. Please include a copy of this letter with your submittal.



If we do not hear from you, the Department may pursue enforcement action. If you have questions on your responsibilities in this matter, I can be reached at 414-263-8644.


Sincerely,

John J. Hnat Hydrogeologist

Remediation and Redevelopment Program

Southeast Region

C: WDNR SER Files



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Scott McCallum, Governor Darrell Bazzell, Secretary Gloria L. McCutcheon, Regional Director Southeast Regional Headquarters 2300 N. Dr. ML King Drive, PO Box 12436 Milwaukee, Wisconsin 53212-0436 Telephone 414-263-8500 FAX 414-263-8713

October 21, 2002

Mr. Gerald W. Hunn 8615 Town Hall Road Menomonee Falls, WI 53051-2570

Subject: Reported Contamination at Speedy Lube, 117 E. Capitol Dr., Milwaukee, WI

FID 241081280

BRRTS: 02-41-182420

Dear Mr. Hunn:

On February 24, 1998 the Department of Natural Resources ("the Department") sent a letter to your attention, describing your responsibility to address soil and/or groundwater contamination that was detected at the site referenced above. On November 3, 1997 Michael Carlton (von Briesen Purtell & Roper) provided information from Drake Environmental that contamination was detected above laboratory detection limits for chlorobenzene (2,000 ppb), tetrachloroethene (1,400,000 ppb) and 1,2,4-trimethlybenzene (ppb).

The earlier letter requested the name of the environmental consultant who would direct remedial activities at the site and established a deadline for submittal of a work plan and investigation schedule.

In a recent audit of case files, the Department found no indication that any action has been taken at the site since Environmental Associates submitted a workplan on August 4, 1998. Under Section 292.11 of the Wisconsin Statutes, a person who possesses or controls a hazardous substance release (e.g., the owner of the property where a spill has occurred) is required to take actions necessary to restore the environment to the extent practicable. Because the release of contaminants into soil and groundwater may have significant environmental or health implications, it is important that the extent and degree of the released contaminants be determined and that the contamination be remediated to the extent practicable.

Please submit the name, address and phone number of the environmental consultant you have retained to investigate the release at the site, along with a work plan and schedule for the investigation, within 30 days of receipt of this letter. If you have other information, such as reports or laboratory results from samples collected at the site, you should submit these as well. All applicable information should be submitted IN WRITING to:

Ms. Victoria Stovall Remediation and Redevelopment Program Wisconsin Department of Natural Resources Box 12436 Milwaukee, WI 53212



Correspondence should reference the "Subject" name and file reference numbers listed above. Please include a copy of this letter with your submittal.

If we do not hear from you, the Department may pursue enforcement action. If you have questions on your responsibilities in this matter, I can be reached at 414-263-8644.

Sincerely,

John J. Hnat Hydrogeologist

Remediation and Redevelopment Program

Southeast Region

C: Jim & Julie Hugg c/o Attorney Michael Carlton Hunn Family Trust c/o Attorney John Tellman

WDNR SER Files