Willkom, Mae - DNR

From: Sent: To: Subject: Dean Duescher <duescherd@gmail.com> Monday, May 09, 2016 2:53 PM Willkom, Mae - DNR Re: Hustler Hardware Monitoring Well

Thank you

Dean

On Mon, May 9, 2016 at 1:58 PM, Willkom, Mae - DNR <<u>Mae.Willkom@wisconsin.gov</u>> wrote:

Dean,

I placed a call to Richard Lyster at Midwest Professional Services (MSA), the consulting firm that conducted the well abandonments for the Hustler Hardware site. He said he would have one of their technicians go by the site and photograph the well, so that we can assess what needs to be done to eliminate any trip hazard from the well casing. I will keep you apprised of our progress. Thanks for alerting me to this situation.

Mae

We are committed to service excellence.

Visit our survey at http://dnr.wi.gov/customersurvey to evaluate how I did.

Mae E. Willkom Hydrogeologist—Remediation and Redevelopment Wisconsin Department of Natural Resources 1300 W. Clairemont Ave., Eau Claire, WI 54701 Phone: 715-839-3748

Fax: <u>715-839-6076</u> mae.willkom@wi.gov



Ca a

INTER-OFFICE MEMO

Department of Natural Resources

Form 9500-55 Rev. 5-89

To Dick Ays	ter, MSA	Date 5/9/16 1:35 p.M.
Mae Willkom		
Comment Note	Sign Revise	Route to:
 See me Investigate Take necessary action Approve 	 Prepare reply for my signature Reply directly For your information 	And Return File
M.W. Spoke W/D		r, Village Pres.
@ Hustler. protrudin	g from the	ground
surface be	Iside Inn.	Hustler Inn Roese a Poses
a trip haze	1 11 10 1	andoment
form' says	casing wa face. Dan	you have
plan. Someon		bok when
frigie	mount wel	Isarepten
to Ant to Aler	difficult	to cut off
below Surfa	inding con	reaking up
have some	eone photo	traph the
well of let i	jou know w	that we find.