

## Willkom, Mae - DNR

---

**From:** Willkom, Mae - DNR  
**Sent:** Friday, July 22, 2016 8:55 AM  
**To:** Panzer, Timothy J - DNR  
**Subject:** FW: Hustler Hardware  
**Attachments:** P5270002.JPG

Hoping to get back to the Village of Hustler on this. Did you get a chance to consider it? Thanks.

**We are committed to service excellence.**

Visit our survey at <http://dnr.wi.gov/customersurvey> to evaluate how I did.

Mae E. Willkom  
Phone: 715-839-3748  
[mae.willkom@wi.gov](mailto:mae.willkom@wi.gov)

---

**From:** Willkom, Mae - DNR  
**Sent:** Thursday, June 09, 2016 8:45 AM  
**To:** Panzer, Timothy J - DNR  
**Subject:** FW: Hustler Hardware

Tim,

I got a call about a month ago from the Village President (VP) at Hustler (near New Lisbon). We did a state lead there a few years ago to remediate some old petroleum contamination at an abandoned hardware store property. The VP was concerned about a flush-mounted well casing (abandoned) that had heaved up through the sidewalk in front of a local tavern (pic attached). He's concerned that someone will trip and fall.

I asked our former consultant to take a look and give me a recommendation, and his reply is below. Is this something that the state would be willing to fund? Thanks for your consideration of this.

**We are committed to service excellence.**

Visit our survey at <http://dnr.wi.gov/customersurvey> to evaluate how I did.

Mae E. Willkom  
Phone: 715-839-3748  
[mae.willkom@wi.gov](mailto:mae.willkom@wi.gov)

---

**From:** Dick Lyster [<mailto:dlyster@msa-ps.com>]  
**Sent:** Monday, June 06, 2016 4:01 PM  
**To:** Willkom, Mae - DNR  
**Subject:** RE: Hustler

Mae: Even though the concrete plug in the well is heaved above the sidewalk surface, the sidewalk slab is also broken. With the large cracking, it may be best to replace the section of the sidewalk with the cracking. Not sure if the cracking was caused by the well installation, guess the one large crack goes through the old well borehole. If his idea is sidewalk replacement, almost seems the best fix is have a concrete contractor replace the sidewalk section. Not sure you want us getting involved in that, let me know what you think. Dick

**From:** Willkom, Mae - DNR [mailto:Mae.Willkom@wisconsin.gov]  
**Sent:** Monday, June 06, 2016 3:05 PM  
**To:** Dick Lyster <dlyster@msa-ps.com>  
**Subject:** RE: Hustler

Thank you very much, Dick, for looking into this. The village president views it as a safety hazard, and based on your photos I would have to agree. Can you please give me your recommendation for how best to eliminate it, together with a corresponding cost estimate? Thanks, again.

**We are committed to service excellence.**

Visit our survey at <http://dnr.wi.gov/customersurvey> to evaluate how I did.

Mae E. Willkom  
Phone: 715-839-3748  
[mae.willkom@wi.gov](mailto:mae.willkom@wi.gov)

---

**From:** Dick Lyster [mailto:dlyster@msa-ps.com]  
**Sent:** Tuesday, May 31, 2016 10:21 AM  
**To:** Willkom, Mae - DNR  
**Subject:** RE: Hustler

Mae: Good morning, attached are 2 photos I took on Friday of the abandoned well MW-8 at the Village of Hustler. The abandoned well plug has heaved about an inch or two above the broken sidewalk and someone has installed an orange cone on it. The sidewalk slab is broken also, but not sure when that happened, I think this well was abandoned in June 2011.



**Richard Lyster, PG, CPG | Team Leader**

MSA Professional Services, Inc.

+1 (608) 355-8901

Cell (608) 963-2800



---

**From:** Willkom, Mae - DNR [mailto:Mae.Willkom@wisconsin.gov]  
**Sent:** Friday, May 20, 2016 11:27 AM  
**To:** Dick Lyster <dlyster@msa-ps.com>  
**Subject:** RE: Hustler

No, I have not. Thanks for the update. Your follow-up would be most appreciated.

**We are committed to service excellence.**

Visit our survey at <http://dnr.wi.gov/customersurvey> to evaluate how I did.

Mae E. Willkom  
Phone: 715-839-3748  
[mae.willkom@wi.gov](mailto:mae.willkom@wi.gov)

---

**From:** Dick Lyster [mailto:dlyster@msa-ps.com]  
**Sent:** Friday, May 20, 2016 11:26 AM  
**To:** Willkom, Mae - DNR  
**Subject:** Hustler

Mae: Hi, by coincidence, we haven't had anyone go near Hustler since you called on 5/9. I will try to get there next week to check MW-8 but not till Thur/Friday. Just wanted to make sure you still needed a visit and did not have the chance to check it yourself. Let me know. Thanks. Dick



**Richard Lyster, PG, CPG** | Team Leader

MSA Professional Services, Inc.

+1 (608) 355-8901

Cell (608) 963-2800

