


## Smith, Ralph N - DNR

---

**From:** Dave Larsen <dlarsen@reiengineering.com>  
**Sent:** Tuesday, January 30, 2018 10:27 AM  
**To:** Smith, Ralph N - DNR  
**Cc:** Matthew Michalski  
**Subject:** FW: Bob's Service Station - Falun (BRRTS# 03-07-000148) Update Report  
**Attachments:** 7679 Closure.pdf

Hello Ralph, attached is a U&C approval request for the closure submittal at Bob Svc in Falun. The offsite CO notification is for DOT notification of the residual soil impacts in r-o-w. Please contact me if you have any concerns.




Thank you,  
*David N. Larsen P.G.*  
*Senior Hydrogeologist / Professional Geologist*



**David N. Larsen, P.G.**  
Senior Hydrogeologist  
Dlarsen@REIengineering.com

Tel: 1-877-734-7745  
715-675-9784  
Cell: 715-551-3434  
Fax: 715-675-4060



Connect with us :   

*Confidentiality Notice: This message is intended for the recipient only. If you have received this e-mail in error please disregard.*

---

**From:** Smith, Ralph N - DNR [<mailto:Ralph.Smith@wisconsin.gov>]  
**Sent:** Tuesday, January 30, 2018 10:08 AM  
**To:** Matthew Michalski <[mmichalski@reiengineering.com](mailto:mmichalski@reiengineering.com)>  
**Subject:** RE: Bob's Service Station - Falun (BRRTS# 03-07-000148) Update Report

Hi Matthew,

Good Morning. Thanks for the Update Report, in my opinion, this case can submit for case closure. Please provide the DNR Fees in the amount of \$1050 for the closure request, GIS Fees for soil in the amount of \$300 for a total of \$1,350 payable to the DNR and a closure request - and we will review it before the Northern Region Closure Committee.

It appears this case can submit for case closure as a NR 726 Soil Only CO Packet listing (formerly known as a Soil Only GIS Registry). There appears to be no direct contact for soils and the site is zoned as residential/commercial. The degree and extent of soil contamination by petroleum products appear to be defined on the Bobs Service Station - Falun property. Groundwater contamination on the Bobs Service Station property is minimal, however the main source of groundwater contamination by petroleum is the Hedlund DX - Falun site located hydraulically upgradient which migrated from west to easterly to the Bobs Service Station property. A groundwater GIS Registry listing for the source property (Hedlund) will include Bobs Service Station as an adjacent property GIS Registry Listing for Groundwater. A

1,000-gallon gasoline UST from the former Hedlund DX – Falun is an encroachment on the Bobs Service Station property. Soil contamination is present and in the 1996 SIR from Ayres and Associates, Inc. – the firm concluded the contaminated soil mass degree and extent is defined. A proposed Remedial Action Plan (RAP) was never implemented in 1996. Petroleum contaminated groundwater exceeding the PAL and diesel contaminated soil was found in 1989 along the south side of STH 70 in the R-O-W. Mr. Anderson never sold diesel fuel on his property. STH 70 ROW notification to the WDOT with source unknown is warranted – because there are two distinct contaminated soil masses on the property.

Thanks,

**We are committed to service excellence.**

Visit our survey at <http://dnr.wi.gov/customersurvey> to evaluate how I did.

**Ralph N. Smith**

**Northern Region Hydrogeologist**

Phone: (608) 261-6543

[Ralph.Smith@wisconsin.gov](mailto:Ralph.Smith@wisconsin.gov)

---

**From:** Matthew Michalski [<mailto:mmichalski@reiengineering.com>]

**Sent:** Thursday, January 25, 2018 10:09 AM

**To:** Smith, Ralph N - DNR

**Cc:** Dave Larsen

**Subject:** Bob's Service Station - Falun (BRRS# 03-07-000148) Update Report


Ralph,

Ralph attached is a copy of the latest report. A hardcopy has forwarded to you and a copy has been uploaded to the WDNR FTP site in the folder for the Northern Region (7679\_0307000148\_Update\_Report-Bobs\_Service\_Station-Falun.pdf). Please let me know if you need any additional information.

Thank you,

*Matthew Michalski*

Matthew Michalski – Hydrogeologist/ Environmental Compliance Consultant



**Matthew C. Michalski**  
Hydrogeologist/  
Environmental Compliance Consultant  
[Mmichalski@REIengineering.com](mailto:Mmichalski@REIengineering.com)

Tel: 1-877-734-7745

715-675-9784

Cell: 715-393-7758

Fax: 715-675-4080



Connect with us : [in](#) [f](#) [g+](#) [@](#)

*Confidentiality Notice: This message is intended for the recipient only. If you have received this e-mail in error please disregard.*

# Usual and Customary Standardized Invoice #23

## January 2018- July 2018



RR-092a

PECFA #: 54872-8522-31  
 BRRTS #: 03-07-000148  
 Site Name: Bob's Service  
 Site Address: 10545 State Highway 70, Falun

Vendor Name: REI  
 Invoice #: \_\_\_\_\_  
 Invoice Date: Proposal Date 1-30-2018  
 Check #: \_\_\_\_\_

U&C Total \$ 3,811.85  
 Variance to U&C Total \$ -  
 Grand Total \$ 3,811.85

TASK	TASK DESCRIPTION	SERVICES	ACTIVITY CODE	ACTIVITY REFERENCE CODE DESCRIPTION	UNIT	MAX UNIT COST	UNITS	TOTAL MAX
5	Closure Request		CR05	Primary Closure Request	Submittal	\$ 2,700.00	1	\$ 2,700.00
5	Closure Request		CR15	Continuing Obligation Packet Submittal (For Source Property	Packet	\$ 507.36	1	\$ 507.36
5	Closure Request		CR20	Continuing Obligation Packet Submittal (For off-site Propertie	Per Additional Property	\$ 222.71	1	\$ 222.71
36	Change Order Request		COR05	Change Order Request (cost cap exceedance requests)	Change Order	\$ 381.78	1	\$ 381.78