

Stoltz, Carrie R - DNR

From: Stoltz, Carrie R - DNR
Sent: Tuesday, March 13, 2018 1:11 PM
To: 'Dave Larsen (dlarsen@reiengineering.com)'
Subject: Moose Junction status report review

Hi Dave, I just finished reviewing the Moose Junction report. Soil borings HSB 2,3,& 4 are labeled HAP 2,3,4 on Figure 2B-Site Map. What is the correct name for these? No results were shown for HAP-1 on Table 1c. I agree with the proposed injection areas and thought about mentioning GP-18 (has benzene at 44.6 increasing). Not a lot, but maybe we could think about placing an injection point near or by it. Also, for GP-8 soils with D.C.-these would need to be further defined and excavated or capped-I am good either way. I am also ok with continued GW monitoring and would recommend waiting for maybe a couple of months after injection unless that is not recommended by the commodity provider. Lastly, did you hear from Francine's life attorney? He never returned by call. I thought maybe you heard something because you mention replacing her PW. If you have any questions, let me know. Thanks, Carrie

We are committed to service excellence.

Visit our survey at <http://dnr.wi.gov/customersurvey> to evaluate how I did.

Carrie Stoltz

Hydrogeologist-Remediation and Redevelopment, AWARE Division
Wisconsin Department of Natural Resources
107 Sutliff Avenue, Rhinelander, WI 54501
Phone: (715)365-8942
Fax: (715)365-8932
Carrie.Stoltz@Wisconsin.gov



dnr.wi.gov

