From: Welch, Tim <Tim.Welch@terracon.com>
Sent: Friday, December 10, 2021 11:17 AM

To: Schultz, Josie M - DNR **Subject:** OHM-G. Bay: PFE Results

Attachments: Vacuum Table_12102021.pdf; EX3_58217038C1.pdf

Follow Up Flag: Follow up Flag Status: Flagged

CAUTION: This email originated from outside the organization.

Do not click links or open attachments unless you recognize the sender and know the content is safe.

Morning Josie,

As discussed, we did collect manometer readings from sub-slab points; however, we did not include in table/narrative.

A summary table from 8/23/21 readings, along with a Site Diagram is attached.

When you have a chance, if you could forward info on Commissioning Report contents would be appreciated.

BR,


Timothy P. Welch, P.G. Senior Project Manager I Environmental Services

Terracon

9856 South 57th Street I Franklin, Wisconsin 53132 D (414) 209.7634 I F (414) 423.0566 I M (262) 617.6809 tpwelch@terracon.comI terracon.com

Terracon provides environmental, facilities, geotechnical, and materials consulting engineering services delivered with responsiveness, resourcefulness, and reliability.

Private and confidential as detailed here (<u>www.terracon.com/disclaimer</u>). If you cannot access the hyperlink, please e-mail sender.



Vacuum Monitoring Summary

Sub-Slab Vapor Monitoring Points

Martinizing Dry Cleaner and Laundry Service 1233 South Military Avenue Green Bay, Wisconsin Terracon Project No. 58217038

Location	Date	Vacuum (" H2O)
M1	8/23/2021	0.83
M2	8/23/2021	0.00
M3	8/23/2021	0.00
M4	8/23/2021	0.00
M5	8/23/2021	0.00