From: Ken Shimko <kshimko.meridianenv@gmail.com>

Sent: Friday, July 10, 2020 10:07 AM

To: Stoltz, Carrie R - DNR

Subject: Dougs Tire update re: paving and wells

Attachments: IMG_1955.JPG; IMG_1956.JPG; IMG_1957.JPG; IMG_1958.JPG;

IMG 1959.JPG; IMG 1960.JPG; IMG 1953.JPG

Carrie.

This note follows our phone call this morning.

See attached pictures of EX-4 for reference.

As you know, Dougs Tire is getting re-paved. We prepared a Cap Maintenance Plan and will rely on this re-paving as a remedial cap for the diesel LNAPL area.

This involves removing the existing pavement. After this was completed, the contractor (Monarch Paving) determined there is too much clay content in the underlying soil. Therefore, they excavated (yesterday) additional soil (down to 30 inches in northern portion of lot....I didn't stay to see how much they excavated elsewhere).

I have been staying in contact with Monarch and due to this additional excavation, I traveled to the site yesterday to see what impact this had on the existing wells.

EX-4 manway had to be removed/replaced. However, when I went to cut down the PVC riser, I discovered it was broken about 3 feet down (see pictures). This extraction well was installed in the alleyway and endured heavy traffic and frost-heaving (see pictures). I suspect it has been broken for awhile because it kept coming up on us. Due to its location in the City's alley, we abandoned this extraction well to allow the alley to be excavated and repaved.

I am worried about EX-10. It is located in the center of the entrance ramp to the entire lot and sees a lot of traffic. I worry it will be a problem down the road. It is probably best to abandon it and if more work is needed in the future, a new well can be installed there. We are saving the nearby MW-4 which will provide all of the information needed from that area.

Will keep you posted.

Kenneth Shimko, PG Meridian Environmental Consulting, LLC 2711 North Elco Road Fall Creek, Wisconsin 54742 (715)832-6608 (office) (715)579-0723 (cell) Email: kshimko.meridianenv@gmail.com







IMG_1957.JPG



IMG_1958.JPG





IMG_1960.JPG

