BRRTS Number: 02-16-222670

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (Revised 2/11)

Reviewer: Erin Endsley Review Date: 7/22/13 Site Name: Tanks S-1 and S-2 Region: NOR

See RR-5242 for instructions. Steps with an *denote DNR follow up; ** denote RP/property owner follow up.

FILE REVIEW:	
1. Review the file and BRF	RTS, identify the following:
Address/ City/Zip Code:2407	Stinson Ave, Superior, WI, 54880
County Parcel Identification N	lumber (PIN): 01-801-03339-00 FID Number: 816009590
Current Property Owner: Calu	imet Superior LLC
Original RP: Murphy Oil	
Has the property been transfe	erred since the restriction was recorded/condition applied? \Box No $oxtimes$ Yes
How was site selected for aud Vapor Mitigation AC 226 VPLE with AC 56 Enforcement Follow-up Other:	dit? (AC = BRRTS Action Code) Green Space Grant AC 605 AGe of Remedy Complaint Received Deed Restriction AC 52 or 696 (LGU) Regional Priority
Date of: ⊠ Final Closure 11/04/04	Remedial Action Plan Approval
	=
Crean Space Creat	General Liability Clarification Letter
Green Space Grant	Local Gov't Unit (LGU) letter

*Check all continuing obligations applied (at case closure or RAP approval or letter to LGU):

Add to BRRTS	AC in BRRTS	Action Code	Action Code Meaning
		51	Deed notice
	Х	52	Deed restriction for soil
		730	Groundwater use restriction
		95	Deed instrument conditions met (for audits, use if deed restriction
			was updated by filing a deed notice)
		101	GIS Registry PDF modified – date DNR letter sent
		104	Site removed from GIS Registry – date DNR letter sent
		696	Continuing obligation required of LGU to maintain liability exemption
		605	Green Space Grant awarded (deed restriction)
Х		56	Continuing Obligation applied (use with codes 220-238)
		220	Soil at industrial use level
X		222	Cover/engineered containment system (pavement, soil cover, etc.)
		224	Structural impediment (buildings or other structures)
		226	Vapor mitigation/response
		228	Site-specific (identify in comment field)
		230	LGU was directed to take a protective action
	Х	232	Residual soil contamination > RCLs/SS RCLs (use with AC 222,224)
		234	Monitoring well needs to be abandoned
		236	Site closed with groundwater contamination > ES
		238	Maintenance and inspection documentation required to be submitted
Х		185	Closure Compliance Review completed
		186	Closure Compliance Review – RP follow up needed
		187	Closure Compliance Review follow up completed

BRRTS Number: 02-16-222670

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 8/09)

Describe any site-specific requirements that the site owner and/or responsible party needed to address.
Is the site on the GIS Registry? Yes No - Add it to the GIS Registry* Were neighboring properties affected? No Yes - Are these properties listed on the GIS Registry and in BRRTS? Yes No Update the GIS Registry/BRRTS, use form 4400-246*.
Was a maintenance plan required at closure? ☐ NA ☐ No ☐ Yes Is it in the file ☐ or PDF ☐ or missing ☐ ? If no maintenance plan was required, offer the property owner the template model with inspection log, and note in the follow up section of the audit that one was provided on the audit date.
Was/were the appropriate restriction(s) recorded with the Register of Deeds? ☐ NA ☐ No ☐ Yes
Has a restriction been amended, or been nullified by DNR? ☑ No ☐ Yes If Yes: Was BRRTS updated? (95) ☐ No * ☐ Yes Was the GIS Registry PDF updated? ☐ No * ☐ Yes Site Visit: 2. Contact the site owner for access.
3. Walk the site (ideally with the owner or responsible party) to review the site conditions against the conditions documented at closure/other to verify or change answers to questions in #1.
 4. With the site owner/RP (if possible), answer the following for DNR RR records: Did the site owner know about the continuing obligation(s)? ☐ Yes ☐ No
Have site conditions changed since closure that would affect either a deed restriction or other restrictions or requirements associated with the site? ☑ No ☐ Yes Explain.
Examples: 1)a building has been razed and investigation and remediation occurred. 2)excavation or residential development has occurred in a restricted area.
Is an asphalt cover or soil cover removed or in disrepair? ☑ No/NA ☐ Yes Should it be replaced or repaired? ☐ No ☐ Yes **
If a performance standard was the final remedy, has it been altered? ☐ No/NA

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 8/09)

BRRTS Number: 02-16-222670

☐ Yes Describe
If Yes - Was DNR notified?
Have local zoning changes occurred since closure? ⊠ No/NA
Yes If Yes - Does it appear to impact the effectiveness of the restriction?
☐ No ☐Yes Describe:
Is soil sampling needed to determine if the final remedy has been modified such that a direct contact threat exists?
Yes** Describe:
For example, an asphalt cover has been removed or is in disrepair, or a new contaminated site is present upgradient, etc.
Has additional monitoring or remediation been done since the site was closed? ☐ No ☐ Yes Describe:
Does a new threat to public health or the environment exist (e.g. new sources or exposure routes)? ☑ No
Yes If Yes - Does sampling need to be performed?
NoYes** Describe what should be done to address the problem, and by whom:
Is the vapor mitigation system or sub-slab depressurization system (SSDS) operating as designed? (pressure gradient being maintained)
YesNo** − if not, describe any follow up needed.
Have any of the exposure assumptions used for closure changed at this site? ☐ NA ☐ No
Yes - if yes, describe any follow up needed.

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 8/09)

BRRTS Number: 02-16-222670

Has the land use at this site changed such that a vapor intrusion pathway may now exist? No
Yes - If Yes, describe any follow up needed
COMPLIANCE AND FOLLOW-UP:
5. Identify compliance and any follow up needed. Is the site in compliance with the continuing obligations/closure approval document?
No - Describe what's not in compliance:
(May depend on extent of non-compliance, non-maintenance of remedy or changed ownership or conditions. If case is out of compliance, it should be prioritized by the region, for new casework or enforcement, as needed.)
If the site is not in compliance, what are the reasons?
Has the maintenance agreement required at closure been followed? ☐ NA ☐ Yes
No Describe:
6. **Are additional actions by the RP or property owner warranted at the site? (The intent is to return the site to compliance with continuing obligation. If further remedial action is needed, determine if the site meets the NR 726 reopening criteria.) No
Yes Describe any actions needed to return the site to compliance, and identify who's responsible: (Add AC 186, use AC 99 for actions not listed under AC186)
7. *Does the site require follow up by DNR? ⊠ No
☐ Yes
contact or enforcement to return site to compliance with continuing obligation
updating BRRTS (check all codes that apply on pg. 1)
updating the GIS Registry (adding or modifying a packet) reopen site (add ACs 186 and 13)
other:
8. *Attach photographs of the site, documenting site conditions. 9. *Identify and update any applicable action codes (Table on page 1).

10. *Add a copy of this audit to the case file. Follow the instructions in RR-5242, (http://intranet.dnr.state.wi.us/int/aw/rr/Guidance/RR5242.pdf). Send a copy electronically (PDF) to Central Office, using the following naming convention: BRRTS#_COAUDIT_Year.pdf (example: 0365001149_COAUDIT_2008.pdf)

Site photographs
The concrete basin is the cover – crack shown in the photo has been caulked. Otherwise in good shape.

