

State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Southeast District - Annex building

Post Office Box 12436 4041 N. Richards St. Milwaukee, Wisconsin 53212 TELEPHONE: 414-961-2727 TELEFAX # : 414-961-2770

File Ref: 4440

Carroll D. Besadny Secretary

February 23, 1993

Kris Buettner Route 1 Box 308 Elkhart Lake, Wisconsin 53020

Dear Ms. Buettner,

RE: Redi-Quick Dry Cleaners 9510 W. Greenfield Ave. West Allis, WI

This letter is in response to the Miller Engineering "Groundwater Sampling Results Report" dated January 29, 1993.

The groundwater results in the report show that some chlorinated groundwater contaminants are increasing with time.

The WDNR requests that your consultant submit by April 1, 1993, a proposal to initiate or complete the following:

- 1. Initiate active groundwater treatment.
- 2. Determine the extent of groundwater contamination.
- 3. Determine the groundwater flow direction.
- 4. Determine the source of solvent contamination at the referenced property.

The chlorinated contaminants do not appear to be related to the underground storage tanks which were removed from the site. Unfortunately this means that investigative and remedial work conducted from this point forward will not be eligible for reimbursement under the PECFA Program. PECFA payments are for releases from underground storage tanks which have stored petroleum products.

Please have your consultant contact me within two weeks with a proposal for groundwater treatment as outlined above, in order to prevent further migration of contaminants.

Charles Krohn Hydrogeologist

