



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Southeast District - Annex building
Post Office Box 12436
4041 N. Richards St.
Milwaukee, Wisconsin 53212
TELEPHONE: 414-961-2727
TELEFAX #: 414-961-2770

George E. Meyer
Secretary

June 28, 1994

File Ref: Milwaukee Co.
ERR/ERP
FID#241170490

Ms. Kristine Buettner
P.O. Box 551
Florence, WI 54121

Dear Ms. Buettner:

RE: Redi-Quick Dry Cleaners
9510 W. Greenfield Ave., West Allis

This letter is in response to the Miller Engineers "Ground Water Sampling Results" reports dated January 29 and April 1, 1993.

The groundwater results in the report show that some chlorinated groundwater contaminants are increasing with time. These results are also above the Department's Wisconsin Administrative Code NR140 Enforcement Standards.

The Department requests that your consultant submit by August 15, 1994, a proposal to initiate or complete the following:

1. Initiate active groundwater treatment.
2. Determine the extent of groundwater contamination.
3. Determine the groundwater flow direction.
4. Determine the source of solvent contamination at the referenced property.

The chlorinated contaminants do not appear to be related to the underground storage tanks removed from the site. Unfortunately this means that investigative and remedial work conducted from this point forward will not be eligible for reimbursement under the PECFA Program. PECFA payments are for releases from underground storage tanks which have stored petroleum products only.

Please have your consultant contact me within two weeks with a proposal for groundwater treatment as outlined above, in order to prevent further migration of contaminants.

Sincerely,

Margaret M. Graefe
Hydrogeologist, Environmental Repair Program

c: Sam Gruichich