**Note:** In order to fill and save this form electronically, it must be opened using Adobe Reader or Acrobat software. Save a copy of the file, open Adobe Reader, select File > Open and browse for the file you saved.

State of Wisconsin Department of Natural Resources PO Box 7921, Madison WI 53707-7921

### Remediation & Redevelopment Continuing Obligation Review

Form 4400-232 (R 07/22) Page 1 of 7

BRRTS I	No. <u>06-3</u>	2-56049	95	7 3	(1100 202 (1101/22)	1 ago 1 oi 7		
Reviewer: Tim Zeichert			Regi	on: WC	Review Date:	09/26/2022		
Site Name	Site Name: Kwik Trip Bakery Expansion							
follow up	; ** denote	RP/pro	s <a href="http://intranet.dnr.state.wi.us/int/aw">http://intranet.dnr.state.wi.us/int/aw</a> perty owner follow up. If auditing a Viea in each section to add information	PLE site, use the ap	plicable LUST or E	n * denote DNR RP BRRTS		
File Revie	:W:							
1. Review	BRRTS,	and the	file if needed, to identify the File Revie	ew information:				
Site Address City ZIP Code								
2326 Commerce Street				La Crosse		54603		
County Parcel Identification Number (PIN)				FID Number				
17-10307-20				632025460				
Original R	esponsible	Person						
Troy Batz	zel - Kwik	Trip, Ir	ic.					
Has the p	roperty bee	en transf	erred since the continuing obligation was	recorded/applied?	○ No ● Yes			
If Yes: C	urrent Pro	perty Ov	/ner					
<u>C</u>	ity of La	Crosse -	Kwik Trip leases the property					
Р	hone Num	ber	Email					
Select all		obligatio	ns applied (at case closure or RAP approv	val or letter to LGU):				
Add to BRRTS	AC in BRRTS	AC	Actio	on Code (AC) Mean	ing			
		51	Deed notice					
		52	Deed restriction for soil					
		730	Groundwater use restriction					
		95	Deed instrument conditions met (for audits, use if deed restriction was updated by filing a deed notice)					
		101	GIS Registry PDF modified - date DNR letter sent					
		104	Site removed from GIS Registry - date DN					
		696	Continuing obligation required of LGU to n	naintain liability exemp	otion			
		605	Green Space Grant awarded (deed restric					
	$\boxtimes$	56	Continuing Obligation applied (use with co	des 220-238)				
		46	Impacted Right-of-Way					
		220	Soil at industrial use level					
$\Box$		222	Cover/engineered containment system (pavement, soil cover, etc.)					
		224	Structural impediment (buildings or other structures)					
		226	Vapor mitigation/response					
		228	Site-specific (identify in comment field)					
		230	LGU was directed to take a protective action					
		232	Residual soil contamination > RCLs/SS RCLs (use with AC 220, 222, 224)					
- H		234	Monitoring well needs to be abandoned	> 50				
		236	Site closed with groundwater contamination > ES					
		238	Maintenance and inspection documentation required to be submitted					
		185	Closure Compliance Review completed	n noodod				
		186	Closure Compliance Review - RP follow up needed					
	<ul> <li>187 Closure Compliance Review follow up completed</li> <li>99 Use this code with comments, for actions not listed under AC 186 (i.e. submittal of inspection reports)</li> </ul>							
		99	Use this code with comments, for actions i	not listed under AC 18	סכ (i.e. supmittal of ins	spection reports)		

### Remediation & Redevelopment **Continuing Obligation Review** Form 4400-232 (R 07/22) Page 2 of BRRTS Number: 06-32-560495

Page 2 of 7

Но	w was site selected for audit? (AC	= BRRTS Action Code)				
	☑ Vapor Mitigation AC 226	Green Space G	Grant AC 605	Age of Remedy		
	∇PLE with AC 56	X AC 220, 222, 2	24, 228, or 230	Complaint Recei	mplaint Received	
	Enforcement Follow-up	Deed Restriction	on AC 52 or 696 (LGU)	Regional Priority		
	Other:					
Da	te of:					
	⊠ Final Closure	07/11/2017	Remedial Action P	lan Approval		
	Certificate of Completion	08/24/2017	General Liability C	larification Letter		
	Green Space Grant		Local Gov't Unit (L	GU) Letter		
De	scribe any site-specific requireme	nts (AC 228) that the site	e owner and/or responsib	ole party needed to add	dress:	
ls t	he site on BRRTS as having resid	lual contamination and c	ontinuing obligations?			
		• Yes		TS using applicable ac	ction codes (56, etc.)	
We	ere neighboring properties affected	d? ● Yes	○ No			
	If yes, are these properties listed	I in BRRTS with AC 56?	Yes ○ No – Up	date BRRTS, use forn	1 4400-246*	
Wa	as a maintenance plan required at	closure? O NA O No	● Yes – It is: ○ in	the file   PDF	missing	
	If no maintenance plan was requ up section of the audit that one v			l with inspection log, a	nd note in the follow	
Wa	as/were the appropriate restriction	(s) recorded with the Reg	gister of Deeds? O Ye	es O No 💿 N	IA	
	Has a restriction been amended,	, or been nullified by DNF	R? ○ No			
			O Yes: Was BRRT	S updated? (95)	○ Yes ○ No*	
				D PDF updated?	○ Yes ○ No*	
No	tes:				0 100 0 110	
	is is a VPLE site and is the same	e property as Desmond's	s Men's Wear 02-32-00	0203.		
O:4	o Vioit.					
	e Visit:  Contact the site owner for acc	ess. Provide a copy of	the maintenance plan.	if applicable. If the a	audit is being	
	conducted for a CO which wor plan was required at closure, f	uld now require a maint	tenance plan, provide a			
3.	Walk the site (ideally with the documented at closure/other tor template.					
4.	With the site owner/RP (if poss	sible), answer the follow	wing for DNR RR recor	ds:		
Dic	I the site owner know about the co	ontinuing obligation(s)?				
	ve site conditions changed since of sociated with the site?	closure that would affect	either a deed restriction	or other restrictions or	requirements	
	No					
	○ Yes - Explain:					
	-					

Examples: 1) a building has been razed and investigation and remediation occurred. 2) excavation or residential development has occurred in a restricted area. BRRTS Number: 06-32-560495

# Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 07/22) Page 3 of 7

Page 3 of 7

Has a paven disrepair?	nent (asphalt or concrete) cover, soil cover or other sort of cover, such as a building, been removed or is it in  No/NA
	○ Yes – Should it be replaced or repaired? ○ Yes** ○ No
<ul><li>No</li></ul>	ance standard was the final remedy, has it been altered? - Explain:
<ul><li>No/N</li><li>Yes -</li><li>1</li></ul>	- Does it appear to impact the effectiveness of the restriction?
<ul><li>No</li></ul>	ing needed to determine if the final remedy has been modified such that a direct contact threat exists?  Describe:
For example	, an asphalt cover has been removed or is in disrepair, or a new contaminated site is present upgradient, etc.
<ul><li>No</li></ul>	al monitoring or remediation been done since the site was closed? - Describe:
<ul><li>No</li></ul>	threat to public health or the environment exist (e.g. new sources or exposure routes)?  - Does sampling need to be performed?  O No O Yes** - Describe what should be done to address the problem, and by whom:
maintained)  • Yes  · NA · No**  Have any of · NA • No	mitigation system or sub-slab depressurization system (SSDS) operating as designed? (pressure gradient being  – Describe any follow up needed: the exposure assumptions used for closure changed at this site?  – Describe any follow up needed:
<ul><li>No</li></ul>	l use at this site changed such that a vapor intrusion pathway may now exist?  - Describe any follow up needed:

#### BRRTS Number: 06-32-560495

## Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 07/22) Page 4 of 7

Page 4 of 7

Has the land use changed such that there are either health or safety issues?
No
Yes – Describe any follow up needed:
Notes:
COMPLIANCE AND FOLLOW-UP SUMMARY:
5. Identify compliance and any follow up needed.
Is the site in compliance with the continuing obligations/closure approval document?
Yes
○ No – Describe what's not in compliance and the reasons for noncompliance:
(May depend on extent of non-compliance, non-maintenance of remedy or changed ownership or conditions. If case is out of
compliance, it should be prioritized by the region, for new casework or enforcement, as needed.)
Has the maintenance agreement required at closure been followed?
<ul><li></li></ul>
○ NA
○ No – Describe:
Was the property owner reminded to complete and document the (yearly) inspections?
Yes
○ NA
○ No – Why not?
Was a maintenance plan or template provided to the property owner at the site visit?
○ Yes
○ NA
No – If no, why not?
Kwik Trip already has the maintenance plan and is aware of their obligations.
6.** Are additional actions by the RP property owner warranted at the site? The intent is to return the site to compliance
with continuing obligation. If a significant land use change has occurred, and/or further remedial action is needed,
determine if the site meets the NR 726 reopening criteria.)
<ul><li>No</li></ul>
Yes – Summarize the actions needed to return the site to compliance and identify who is responsible:

Notes:

**Continuing Obligation Review** BRRTS Number: 06-32-560495 Form 4400-232 (R 07/22) Page 5 of 7

Add AC 186 for RP/property owner follow-up required. Use AC 99 if a reminder was provided to the property owner to complete and document inspections.

7. * Does the site require follow up by DNR?					
<ul><li>No</li></ul>					
Yes:      □	contact or enforcement to return site to compliance with continuing obligation				
	updating BRRTS for the CO PDF (adding or modifying a packet)				
	reopen site (add ACs 186, 12 and 13)				
	other:				

- 8. \* Attach photographs of the site, documenting site conditions. Label the photos with the site name/BRRTS Activity number/date/view. If a follow-up letter is sent, include a copy with the audit. (audit/photos/follow-up letter)
- 9. \* Save a copy of the audit using the following naming convention: YYYYMMDD\_185\_CO\_Audit.pdf. For follow-up documentation use YYYYMMDD\_186\_Follow\_Up\_Needed.pdf.
- 10. Update applicable BRRTS action codes on the Table on page 1. Use the regional tracking sheet, and have your Regional EPA update the ACs and upload the audit PDF into BRRTS.
- 11. Notify Central Office when the audit has been completed and loaded into BRRTS.

{Click to add an image file (\*.bmp, \*.jpg, \*.gif, \*.png, \*.tif) For best results, insert a photo with horizontal orientation. Crop vertical photos to a horizontal orientation, if needed.} Date added: 09/28/2022



Title: Kwik Trip Bakery Expansion/0632560495/20220926/left bank of VMS manifold piping - all valves open

Form 4400-232 (R 07/22)

Page 6 of 7

{Click to add an image file (\*.bmp, \*.jpg, \*.gif, \*.png, \*.tif) For best results, insert a photo with horizontal orientation. Crop vertical photos to a horizontal orientation, if needed.}

BRRTS Number: 06-32-560495

Date added: 09/28/2022



Title: Kwik Trip Bakery Expansion/0632560495/20220926/right bank of VMS manifold piping - all valves open

{Click to add an image file (\*.bmp, \*.jpg, \*.gif, \*.png, \*.tif) For best results, insert a photo Date added: 09/28/2022 with horizontal orientation. Crop vertical photos to a horizontal orientation, if needed.}




Title: Kwik Trip Bakery Expansion/0632560495/20220926/VMS piping to roof

BRRTS Number: 06-32-560495

Form 4400-232 (R 07/22) Page 7 of 7

{Click to add an image file (\*.bmp, \*.jpg, \*.gif, \*.png, \*.tif) For best results, insert a photo Date added: 09/28/2022 with horizontal orientation. Crop vertical photos to a horizontal orientation, if needed.}



Title: Kwik Trip Bakery Expansion/0632560495/20220926/VMS exhaust with wind turbines functioning properly

{Click to add an image file (\*.bmp, \*.jpg, \*.gif, \*.png, \*.tif) For best results, insert a photo with horizontal orientation. Crop vertical photos to a horizontal orientation, if needed.}



Title: Kwik Trip Bakery Expansion/0632560495/20220926/Loading dock area - west end of bakery expansion