



## Field & Technical Services

200 Third Avenue ♦ Carnegie, PA 15106 ♦ Phone: 412-429-2694 ♦ Fax: 412-279-4512

December 1, 2022

Mr. John Sager  
Wisconsin Department of Natural Resources  
1701 N 4<sup>th</sup> Street  
Superior, WI 54880

**Re: Summary of 2022 Sign Inspection Activities  
Koppers Inc. Facility  
Superior, Wisconsin**

Dear Mr. Sager:

On behalf of Beazer East, Inc. (Beazer), Field & Technical Services, LLC (FTS) is pleased to submit this letter summarizing the results of the April 2022 inspection of warning signs posted along the tributary to Crawford Creek (formerly referred to as Outfall 001 drainage ditch) and select areas within the Crawford Creek floodplain located near the Koppers Inc. (KI) facility in Superior, Wisconsin.

In the fall of 2001, at the request of the Wisconsin Department of Natural Resources (WDNR), Beazer posted warning signs along the tributary to Crawford Creek and a portion of the Crawford Creek floodplain located near the KI facility in Superior, Wisconsin. In September 2005, 68 new signs reflecting updated contact information for the WDNR and Douglas County Department of Health and Human Services were posted, and all of the old signs were removed. In general, signs are posted at approximately 250-foot intervals along both sides of the tributary to Crawford Creek from the KI property boundary downstream to the confluence with the Crawford Creek floodplain, and along both sides of the Crawford Creek floodplain from Hammond Avenue downstream to the railroad crossing. Additional signs are posted at potential access areas, such as near roads, hunting stands, bridges, and railroad tracks.

Since the warning signs were initially posted in 2001, periodic inspections have been made to identify damaged, disoriented, and/or missing signs. The most recent sign inspection was conducted on April 26, 2022. During the inspection, a total of 7 warning signs were replaced. All remaining signs were observed to be in good condition.

The construction fencing installed around the tributary to Crawford Creek from Hammond Avenue to the railroad crossing in September 2005 was inspected on April 26, 2022. During the April 26, 2022 inspection, the construction fencing was re-secured to existing posts where necessary during the inspection.

Please feel free to contact Jane Patarcity of Beazer at (412) 208-8813 or the undersigned at (412) 428-9397 if you have any questions or comments regarding the sign inspection activities summarized above.

Sincerely,

**Field & Technical Services, LLC**



Hank Pappert  
Project Manager

cc: Jane Patarcity-Beazer  
David Bessingpas-ARCADIS

# Attachment



**Koppers, Inc. Facility  
Superior, Wisconsin**

**Snow Fence Inspection**

Fence Segment	Repair/Modification Required?	Comments
DD1-DD2	No	Re-attached fence to T-Post
DD2-DD3	No	Re-attached fence to T-Post
DD3-DD4	No	Re-attached fence to T-Post
DD4-DD5	No	Re-attached fence to T-Post
DD5-DD6	No	Re-attached fence to T-Post
DD6-DD7	No	Re-attached fence to T-Post
DD7-DD22	No	Re-attached fence to T-Post
DD22-DD23	No	Re-attached fence to T-Post
DD23-DD24	No	Re-attached fence to T-Post
DD24-DD25	No	Re-attached fence to T-Post
DD25-DD26	No	Re-attached fence to T-Post
DD26-DD27	No	Re-attached fence to T-Post
DD27-DD28	No	Re-attached fence to T-Post
DD28-DD1	No	Re-attached fence to T-Post

Table 1

Koppers, Inc. Facility  
Superior, Wisconsin

Summary Warning Sign Inspection

Sign ID	Secured To	Repair/Modification Required?	Comments
CC-1	Steel T-Post	No	
CC-2	Tree	No	
CC-3	Tree	No	
CC-4	Tree	No	Sign Replaced
CC-5	Steel T-Post	No	Sign Replaced
CC-6	Tree	No	
CC-7	Tree	No	
CC-8	Tree	No	
CC-9	Tree	No	
CC-10	Tree	No	
CC-11	Steel T-Post	No	
CC-12	Steel T-Post	No	
CC-13	Steel T-Post	No	Sign Replaced on F-Post
CC-14	Steel T-Post	No	
CC-15	Steel T-Post	No	Sign Replaced on T-Post
CC-16	Tree	No	
CC-17	Tree	No	
CC-18	Tree	No	
CC-19	Tree	No	
CC-20	Tree	No	
CC-21	Tree	No	
CC-22	Tree	No	
CC-23	Tree	No	Sign Replaced
CC-24	Tree	No	
CC-25	Tree	No	
CC-26	Tree	No	
CC-27	Tree	No	
CC-28	Tree	No	
CC-29	Tree	No	
CC-30	Steel T-Post	No	
CC-31	Steel T-Post	No	Sign Replaced on T-Post
CC-32	Steel T-Post	No	Sign Replaced on T-Post
CC-33	Steel T-Post	No	
CC-34	Steel T-Post	No	
DD-1	Tree	No	
DD-2	Steel T-Post	No	
DD-3	Steel T-Post	No	
DD-4	Tree	No	
DD-5	Tree	No	
DD-6	Tree	No	

Table 1

Koppers, Inc. Facility  
Superior, Wisconsin

Summary Warning Sign Inspection

Sign ID	Secured To	Repair/Modification Required?	Comments
DD-7	Tree	No	
DD-8	Tree	No	
DD-9	Tree	No	
DD-10	Tree	No	
DD-11	Tree	No	
DD-12	Tree	No	
DD-13	Tree	No	
DD-14	Tree	No	
DD-15	Tree	No	
DD-16	Tree	No	
DD-17	Tree	No	
DD-18	Tree	No	
DD-19	Tree	No	
DD-20	Tree	No	
DD-21	Tree	No	
DD-22	Tree	No	
DD-23	Tree	No	
DD-24	Tree	No	
DD-25	Tree	No	
DD-26	Tree	No	
DD-27	Steel T-Post	No	
DD-28	Tree	No	
DD-29	Tree	No	
DD-30	Tree	No	
DD-31	Tree	No	Sign on T-Post
DD-32	Tree	No	
DD-33	Tree	No	Sign-on T-Post
DD-34	Tree	No	Sign on T-Post