	<b>Activity Number:</b>	04-71-037718			
	Activity Type:	Spill			
2	Activity Name:	204 RR ST			
	Region:	Northeast Region	County: Winnebago	<b>FID:</b> 471155410	
)	<b>Location Name:</b>	AMERICAN QUALITY FIBERS		<b>EPA ID:</b> WIR0000417	15
)	<b>Location Address:</b>	204 RAILROAD ST		Start Date: 07/05/1979	End Date: OPEN
•	Municipality:	MENASHA		Project Manager: ROXANNE	CHRONERT
	Legal Desc:	None Found			
	Latitude:	None Found			
Ž.	Longitude:	None Found			
	Incident Date/Time:	07/05/1979 00:00	Reported Date/Time:	DNR Notif	y Immediate:
	Physical Char:				
Physical Color:			Physical Odor:		
	Spill Cause:	OVERFLOWED MIX TANK			
	Spill Source:	Chemical Company			
	<b>Source Comment:</b>				
Resource Damage: Comment:		DNR Investigator:			
	Spill Comment:				
V	Vho:				
		SPONSIBLE PARTY		Phone: (608) 33-9-36 Ext:	
	Name: Title:			Fax: E-Mail:	
		DRITE CHEMICAL		Z) IVIIII	
		S WATER ST			
	PO	BOX 4159			
					1
Iı	mpacts:			Closed 7/5	179
	oil Contamination				
S	piller Actions:			64 TAA 11/30	116
	Cleanup Method		SOIL		

Notification

Auto populated via migration process

07/05/1979

DEPARTMENT OF NATURAL RESOURCES	TOXIC AND HAZARDOUS INCIDENT REPORT FORM 8-77
MADISON USE ONLY 10 DATE OF INCIDENT (Y/M/D) 6	TIME OF INCIDENT (24 HR) 4 INCIDENT REPORTED BY 2 (AGENCY)
501 74/7/5	9.9 AM
DATE INCIDENT REPORTED 6 TIME INCIDENT REPORTED 4	INCIDENT INVESTIGATED BY 3 AGENCY TELEPHONE NUMBER 10
7-5-79 DISTAN 901AM	6TICHR/DR 4141417 - 4040
DATE INCIDENT INVESTIGATED 6 TIME INCIDENT INVESTIGATED 4	DNR DISTRICT/AREA INVOLVED 3 COUNTY OF INCIDENT LOCATION
7-5-79 /1 9xy	LAD/ Ochlow Winnibeca
TOWN, RANGE, SECTION, 4, 44 SECTION 10 EXACT LOCATION	DESCRIPTION (HIGHWAY INTERSECTION, MILEAGE, ETC.) 18
TN, RE,,,	
MADISON USE ONLY 18 SUBSTANCE OR TRADE NAME OF MATERIAL	(S) INVOLVED 22 QUANTITY LOST 7 UNITS 2
502 R6 R8 Clerice /weter	J000 9M
MADISON USE ONLY 18 PERSON OR FIRM RESPONSIBLE FOR INCIDE	NT 50 TELEPHONE NUMBER 10
503 R6 R8 Hy (1:10 (4ny:0)	11,160, MAIN. 1776-9401
MADISON USE ONLY 18 PO BOX, STREET OR ROUTE 32	CITY 23 STATE 2 ZIP CODE 5
504 R6 R8 204 RP CL	Married 1215
MADISON USE ONLY 18 CAUSE OF INCIDENT 4	SURFACE WATERS AFFECTED 2 GROUND WATERS AFFECTED 2
505 R6 R8 Over (pill on Mix toule	YES NO POTENTIAL YES NO POTENTIAL
DISTANCE TO NEAREST WELL 4 DISTANCE TO NEAREST SURFACE WATERS	NAME OF SURFACE WATER AFFECTED 23 DRAINAGE 3 BASIN
FT. 3-44 /200FT.	Little Laker Bust, Mayte
LIST HAZARDS, INJURIES OR DEATHS TO HUMANS	LIST HAZARDS TO VEGETATION, FISH, BIRDS OR WILDLIFE 4
Posion	Posion
DNR: Investigation Only	Cleanup Only Spiller Required to Take Action 7
☐ Containment Only	Disposal Contractor Hired by DNR
No Action Taken Containment & Cleanup	Enforcement Spiller Billed for Expenses
ACTION TAKEN BY  SPILLER:  No Notification Made	Containment & Cleanup Contractor Hired by Spiller
☐ Delayed Notification ☐	Cleanup Only Other Action
□ No Action Taken □ Containment Only □	Disposal Yes No N/A SPCC Plan
ADDITIONAL REMARKS: 25 % (1000) 12 PPM	- Jones Diney Com
found in allumb at 4-10	An at 11th + oppn
INT DIAME A IT DOM	
DISTRICT OFFICE COPY	

SITE NAME	MAP SITE NUMBER			
Hydrite Chemical	Rd. yellow-12			
LOCATION	TOWNSHIP			
Winnebago	<u>SE 1/4 MW1/4 SEC QQ T QON R 17E</u>			
STREET ADDRESS	SITE OWNER/MANAGER			
204 Railroad Street	ADDRESS 204 Railroad Street			
ADVITOTDAL TOW	Menasha, WI			
MUNICIPALITY X CITY VILLAGE TOWN Menasha				
DNR PROGRAM Solid Waste DECRIPTION OF HAZARDOUS SUBSTANCE/CONTAMINATION TYPE				
DECRIPTION OF HAZARDOUS SUBSTANCE/CC	NIAMINATION TIFE			
Chlorine/water (25% chlorine)				
COLD STATE OF COMMANDIA STATE OF	NAME OF THOTDERM OF BANKED AOMIONS MAKEN			
	DATE OF INCIDENT, CLEANUP ACTIONS TAKEN			
7/5/79 - An overspill on the mix tank				
coursed a spill of a	2000 gallons, Salling			
caused a spill of 2000 gallons, Spill was				
contained and clear	real up			

