Perding Rodda

UNDERGROUND STORAGE TANK (UST) SITE CLOSURE ASSESSMENT

Of A Former 500 Gallon Fuel Oil (UST)

Located At KNOLLS SERVICE STATION PROPERTY

13825 State Highway ' 32' Mountain, Wisconsin

ARMSTRONG, TN

Prepared For

LAVERN KNOLL

Mountain, Wisconsin







ENGINEERS ■ ARCHITECTS PROJ. MGRS. ■ SURVEYORS

1445 McMahon Drive Neenah, WI 54956 Mailing Address: P.O. Box 1025 Neenah, WI 54957-1025 Tel: (920) 751-4200 Fax: (920) 751-4284 e-mail: mcm@mcmqrp.com

July 12, 2002

LaVern Knoll 15565 Meadow Circle Mountain, WI 54149

Re:

Underground Storage Tank (UST)

Closure Report Assessment – 500 Gal. Fuel Oil UST Knolls Service Station Property – Mountain, WI

McM No. K908-90229.36

Dear LaVern:

This correspondence will serve to report the findings of an Underground Storage Tank (UST) closure site assessment for the former 500 gallon fuel oil UST located at the Knolls Service Station Property, 13825 State Highway '32', Mountain, Wisconsin.

The purpose of the assessment was to evaluate for the presence of spilled or leaking petroleum product that may have impacted the soil in the former UST area.

Based upon the results of our UST Closure Site Assessment, it is the opinion of McMahon Associates, Inc. that the soil in the former UST area was not adversely impacted by petroleum hydrocarbon contamination.

The McMahon Associates, Inc. assessment procedures and results are contained in the following report.

Very truly yours,

McMahon associates, Inc.

Stuart A. Boerst

Senior Hydrogeologist, P.S., P.H.

SAB:lml Enclosure

cc:

Tank Response Unit – Wisconsin DNR-Madison

Melissa Tarlton, Tarlton Inspections, Inc.

Cathy Rodda, DNR



UNDERGROUND STORAGE TANK (UST) SITE CLOSURE ASSESSMENT

Of A Former

500 Gallon Fuel Oil (UST)

Located At The

KNOLLS SERVICE STATION PROPERTY

13825 State Highway '32' Mountain, Wisconsin

Prepared For

LAVERN KNOLL

Mountain, Wisconsin

Prepared By:

McMahon Associates, Inc.

Neenah, Wisconsin

July 12, 2002 McM No. K908-90229.36

Table of Contents

I. INTRODUCTION

A. Site History

B. Property Owner Information

II. SITE OBSERVATIONS

A. UST Inspection

B. Soil Sampling & Analytical Results

III. CONCLUSIONS

List of Figures

Figure #1 - Soil Sampling Locations

List of Appendices

Appendix A - Tank Inventory Form

Appendix B - Soil Sampling Procedures

Appendix C - Laboratory Analytical Reports

UNDERGROUND STORAGE TANK (UST) SITE CLOSURE ASSESSMENT

Of A Former

500 Gallon Fuel Oil (UST)

Located At The

KNOLLS SERVICE STATION PROPERTY

13825 State Highway '32' Mountain, Wisconsin

Prepared For

LAVERN KNOLL

Mountain, Wisconsin

I. INTRODUCTION

A. Site History

The Knoll's Service Station property is located at 13825 State Highway 32, Mountain, Wisconsin. On May 20, 2002, a 500 gallon heating oil underground storage tank (UST) was removed from the ground by an uncertified contractor. Consequently, on May 28, 2002, Tariton Inspections, Inc., an agent of the Wisconsin Department of Commerce ordered that a site assessment be completed.

B. <u>Property Owner Information</u>

The property owner, address, and telephone number is listed below:

LaVern Knoll 15565 Meadow Circle Mountain, WI 54149 Telephone: (715) 276-7197

II. SITE OBSERVATIONS

A. UST Inspection

On June 4, 2002, Stuart A. Boerst, of McMahon Associates, Inc., a State Certified Site Assessor, conducted a site visit to inspect the 500 gallon heating oil UST and collect soil samples from beneath the tank bed area. The UST appeared in good condition. There were no holes observed and there was only a few areas with some surficial rust. Many parts of the UST contained the original paint. The UST is singled walled painted steel. The UST sounded empty or nearly empty based on tapping the steal and rolling the UST slightly to observe all of the sides. The UST was formerly located approximately 8 inches from the side of the building. The piping was formerly located between the UST and the building. The piping appeared in good condition with no observed holes. The piping was made of steel.

A copy of the form titled "Underground Petroleum Product Tank Inventory" is presented in Appendix A.

B. Soil Sampling & Analytical Results

Soil samples were collected from beneath the bottom of the former UST. The top of the UST was located 16 inches below grade. Therefore, since the UST was 4 feet in diameter, the bottom of the UST was formerly 5 feet 4 inches below grade. Two soil borings (B-01 and B-02) were completed in the areas that were formerly the ends of the UST. The borings were completed with a 2-inch diameter hand auger. The locations of the soil borings and former UST area are shown on Figure #1. The location of the former UST area was staked by LaVern Knoll.


The soil encountered consisted of fine to medium-grained sand and some gravel. Two soil samples were collected 7 feet below grade, one from each soil boring. The soil sampling procedures are included in Appendix B. The soil samples were submitted to a DNR-certified analytical laboratory for analysis of diesel range organics (DRO). The laboratory reports are presented in Appendix C.

The laboratory reports indicated no detection of DRO. Therefore, based on the soil sample laboratory reports, there was no release from the former 500 gallon heating oil UST.

III. CONCLUSIONS

On June 4, 2002, McMahon Associates, Inc. completed a UST site assessment for a 500 gallon heating oil UST. The UST and piping did not contain any obvious holes, which would indicate a potential release. Furthermore, two soil samples collected at depths beneath the former 500 gallon heating oil UST did not contain any detection of DRO. Therefore, it is the opinion of McMahon Associates, Inc. that the former 500 gallon heating oil UST did not release product to the environment.

I.D.\REPORT\K908\90229SiteClosure-SAB.doc(lml)



APPENDIX A

TANK INVENTORY FORM

Wisconsin Department of Industry, Labor and Human Relations

UNDERGROUND PETROLEUM PRODUCT TANK INVENTORY

Send Completed Form To: Safety & Buildings Division P.O. Box 7969 Madison, WI 53707

For Office Use Only: Information Required By Sec. 101.142, Wis. Stats. Telephone (608) 267-5280 Tank ID # Underground tanks in Wisconsin that have stored or currently store petroleum or regulated substances must be registered. Please see the reverse side for additional information on this program. An underground storage tank is defined as any tank with at least 10 percent of its total volume (included piping) located below ground level. A separate form is needed for each tank. Send each completed form to the agency designated in the top right corner. Have you previously registered this tank by submitting a form? XYES \(\subseteq \text{NO} \) If yes, are you correcting/updating information only? \(\subseteq \text{Yes} \) This registration applies to a tank that is (check one): Fire Department Providing Fire Coverage 4. Closed - Tank Removed 8. Changed Ownership 1A. In Use or 1B. Newly installed Where Tank Located: 2. Abandoned With Product 6. Closed - Filled With (Indicate new owner Mountain below) 3.

Abandoned No Product (empty) Inert Material or With Water 7. ☐ Out of Service - Provide Date: IDENTIFICATION: (Please Print) Site Address 1. Tank Site Name Site Telephone No. 05/2/2 ☐ Village State County ☐ City Town of: Code 54914 2. Owner Name (mail sent here unless indicated otherwise in #3 below) Owner Mailing Address (mail sent here unless indicated other Mead Kno 556 -a [/e/n ☐ Village Zip Code X Town of: State County ☐ City Alternate Mailing Street Address If Different From #2 3. Alternate Mailing Name If Different Than #2 ☐ City ☐ Village ☐ Town of: Zip Code County 4. Tank Age (date installed, if known: or years old) 5. Tank Capacity (gallons) 6. Tank Manufacturer's Name (if known) 0/01/75 5 U TYPE OF USER (check one): Gas Station 2. Bulk Storage 3. Utility 4. Mercantile 1. 8. Residential 7. School 6.

Government Industrial 9. ☐ Agricultural 10. Other (specify): TANK CONSTRUCTION: 1. Bare Steel 2. 📋 Cathodically Protected and Coated Steel (A. 📋 Sacrificial Anodes or B. 📋 Impressed Current) Coated Steel 4. Fiberglass 5. Other (specify): 3. Steel - Fiberglass Reinforced Plastic Composite 9. Relined - Date 7. ☐ Unknown 3. Other: is Tank Double Walled? Yes PNo Approval: 1. | Nat'l Std. 2. 🔲 UL **Overfill Protection Provided?** ☐ Yes ☐ No If yes, identify type: Spill Containment? ☐ Yes 2.

Vapor monitoring Tank leak detection method: 1. Automatic tank gauging 3 ☐ Groundwater monitoring 4. ☐ Inventory control and tightness testing 5. Interstitial monitoring 6. Not required at present 7. Manual Tank Gauging (only for tanks of 1,000 gallons or less) PIPING CONSTRUCTION 🕱 Bare Steel 2. 🗆 Cathodically Protected and Coated or Wrapped Steel (A. 🗆 Sacrificial Anodes or B. 🗀 Impressed Current) 3. 🗀 Coated Steel 5. Other (specify): Fiberglass Piping System Type: 1. Pressurized piping with: A. auto shutoff; B. alarm; or C. flow restrictor 2. Suction piping with check valve at tank 3.

Suction piping with check valve at pump and inspectable Piping leak detection method: used if pressurized or check valve at tank: 1. ☐ Vapor monitoring 2. | Interstitial monitoring 3. Groundwater monitoring 4. Tightness testing 5. Thine Leak Detector 6. Not Required Approval: 1. Nat'l Std 2. 🗍 UL 3. Other: Double Walled: ☐ Yes ☐ No TANK CONTENTS E. Y Fuel Oil 1. Diesel 2. | Leaded 3. Unleaded 5. Gasohol 6.
Other 7. Empty R Sand/Gravel/Slurry 9. Unknown 10. 🔲 Premix 11.

Waste Oil 12. Propane 13.

Chemical * 15.
Aviation 14.

Kerosene If # 13 is checked, indicate the chemical name(s) or number(s) of the chemical or waste. If Tank Closed, Give Date (mo/day/yr) Has a site assessment been completed? (see reverse side for details) 20-02 Yes \ No If installation of a new tank is being reported, indicate who performed the installation inspection: 1.
| Fire Department 3.

Other (identify) Name of Owner or Operator (please print): Indicate Whether: 🛛 Owner or 🗌 Operator Signature of Owner or

7-8-02

APPENDIX B

SOIL SAMPLING PROCEDURES

APPENDIX B

METHODS & PROCEDURES

SOIL SAMPLING PROCEDURES

Soil samples were submitted to a laboratory for analysis. The laboratory samples were collected by placing a portion of the soil sample into a laboratory supplied sampling container by a soil by a clean, vinyl-gloved hand, and immediately placed in an ice-packed cooler. The soil samples were picked up by U.S. Analytical Laboratory. A chain-of-custody form was maintained during sample transportation.

DECONTAMINATION

All the down hole sampling equipment was steam cleaned prior to use on-site. Soil sampling equipment was washed with detergent and double rinsed with potable water between sampling events. No lubricants or similar substances were used on the drilling or sampling equipment.

APPENDIX C

LABORATORY ANALYTICAL REPORTS

CHAIN OF JUSTODY RECORD

Lab I.D.#



A. lytical Lab v. Date. 12-17-98 1090 Kennedy Ave. • Kimberly, WI 54136 (920) 735-8295 • FAX 920-739-1738 • 800-490-4902 LAB@USOIL COM Chain # 30211

Account No. :	(Quote N	0.:		EAD @ OSOIL.OOM					rage oi								
Project #:	0_		1				eted by receiving lab. Temp		Rlei	nk	,	e c	in Ice	T.				
Sampler: (signature)	True.	AB					√L Yes No	1		8.200,000,000	d By:	****	<u> </u>	W. Carrie				
Project (Name / Lo	cation):	0//5	Ser	vire St	Jan 138	25 Huy32	Moun air,	u1-				An	alys	is Re	que	sted		
Reports To: Shu			Invoice To	: Wornte	, ,		Sample Handling					\prod				Othe	er An	alysis
Company Mc				15565	4 .	w Circle	Request											
,	0-Brd 10	•	Address		in, wi		_ Rush Analysis Date Required			= :			524.2) 1)					
	senaly WI		Gity State	Zip			Normal Turn Arou	TPH)	HEL	802	(EPA 8021) (EPA 8021)	(EPA 8260)	PA 5	8310)				
Phone	751-42		Phone				_ Normal Tulli Aloc	pos	Yod	(EPA	PA	PA	DW (EPA (EPA 41)	(EPA	Point			
Lab I.D.	Sample I.D.	1	ection			Description*	Preservation	ion	GRO (Mod/TPH)	18		VOC (F		PAH (E				PID/ FID
<u> </u>	011	Date	Time	Size an			NI.				ฎ∣≥	>	<u>≯ o</u>	0 0	15	\dashv	_	FID
$\frac{P}{\alpha}$	6-0/17	6/4/02			/syringe	1	More		,	\vdash		\vdash	-	\vdash	++	\dashv		
	B-02/71			7	/syringe	1	Mone	X	+	X	+	H	+	++	++	++		
	Laundremattle	Y.K		366	JT	G.W.	Hel		+-	$ \uparrow \rangle$	+	H	-	++	++	++		, .
						-			+	\vdash		\vdash	-	++	+	-	-	
			-						+	++	+-	\vdash	+	++	++	\dashv	+	
				· · · · · · · · · · · · · · · · · · ·					\dagger	H	+	H	+	++	++	+	-	
									\top	H		H	-		\Box	++		
				- AND WILL SEE STATE OF STATE						\Box			+-		H	+		
Split Samples: Off	artment Use C ered ? Yo epted? Yo	es	_No		/ Special Instroundwater "G		Water "DW", Waste	Water "W	/ /W"	', So	il "S'	", Ai	r "A"	, etc.	<u> </u>			
Department Us	e Optional fo	r Soll Sa	amples	Relinquish	eg By. (sign)		 Γime Date	Receive	ı Rv	<i>J.</i> (si	an)					Time		Date
Disposition of unuse				Tiomiquism	(Sign)		:16 06/04/02	Ol	د ک سدای	. (5!, ¬ ⊁	ر پرک	<u>.</u>	لآو ر،	21.		91	//	4/6
₌ab Should:				Cole	Pog. well		145 6/4/07		1	/	0		acr				7	1712
Dispose	Retai		2-00 (0-000 (0.00 per 10-000 et 10.00 per 10.00 pe		1000		1										_	
Return	Othe	r .		Received i	n Laboratory	By: Max	Jania		Tin	ne:	LOU	-				ate:	ī. I.i	lan

U.S. Analytical Lab

STUART BOERST MCMAHON ASSOCIATES PO BOX 1025 NEENAH WI 54957-1025

Proiect #

NONE

Project Name

KNOLLS SERVICE STATION

Invoice # E40567

Report Date 12-Jun-02

	Analyte	Result	Units	LOD	LOQ	Dil	Run Date	Method A	nalyst	QC Cod	e
Lab Code Sample ID	5040567A B-01/7'						Sample Type Sample Date				
Inorganic											
General											
Solids I	Percent	96.1	%			. 1	6/5/2002	5021	AJV	i	
Organic											
General											
	Range Organics	< 10	mg/kg	2.2	7.2	1	6/7/2002	DRO95	KAH	1	
Lab Code	5040567B						Sample Type	Soil			
Sample ID	B-02/7'						Sample Date				
norganic											
General						_	`c.d.=00=	-0-1			
Solids	Percent	92.8	%			. 1	6/5/2002	5021	AJV	1	
Organic											
General											
Diesel I	Range Organics	< 10	mg/kg	2.2	7.2	I	6/7/2002	DRO95	KAH	1	
Lab Code	5040567C						Sample Type	Water			
Sample ID	LAUNDROMA	r w					Sample Date	6/4/2002	,		
Organic											
PVOC			9 - 4								
Benzen	e	< 0.43	ug/l	0.43	1.4	1	6/11/2002	8021A	CAH	1	
Ethylbe	enzene	< 0.49	ug/l	0.49	1.6	1	6/11/2002	8021A	CAH	. 1	
Methyl	tert-butyl ether (MTBE)) 1.8	ug/l	0.49	1.6	1	6/11/2002	8021A	CAH	1	
Toluene		< 0.63	ug/l	0.63	2	1	6/11/2002	8021A	CAH	1	
1,2,4-T	rimethylbenzene	< 0.42	ug/l	0.42	1.3	1	6/11/2002	8021A	CAH	: 1	
1,3,5-T	rimethylbenzene	< 0.72	ug/l	0.72	2.3	1	6/11/2002	8021A	CAH	1	
m&p-X	(ylene	< 1	ug/l	. 1	3	. 1	6/11/2002	8021A	CAH	1	
o-Xyler	20	< 0.45	ug/l	0.45	1.4	1	6/11/2002	8021A	CAH	1 1	

U.S. Analytical Lab

STUART BOERST MCMAHON ASSOCIATES PO BOX 1025 NEENAH WI 54957-1025

Project #

NONE

Project Name

KNOLLS SERVICE STATION

Invoice # E40567

Report Date 12-Jun-02

Analyte LOD Limit of Detection		Result	Units	LOD	LOQ	Dil	Run Date	Method	Analyst	QC Code
		"J" F	LOQ Limit of Quantitation							
	Code	Comment								
	1	All laboratory	QC requiren	nents were	met for	this sa	mple.			

Authorized Signature