

SW/S

04-16-039675

DATE OF INCIDENT *	DAY OF WEEK	TIME OF INCIDENT <input type="checkbox"/> AM <input type="checkbox"/> PM	REPORTED BY (NAME) Richard Asbury	TELEPHONE NUMBER 715 1 398 3
DATE REPORTED 4/20/84	DAY OF WEEK Fri.	TIME REPORTED 11:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	AGENCY OR FIRM REPORTING Parkland Tr. Fire Dept	REPORTED THRU DIV. EMER. GOVT. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
SUBSTANCE INVOLVED gasoline	QUANTITY ?	UNITS	PERSON OR FIRM RESPONSIBLE Tallakson's Gen. Store	CONTACT NAME Shirley Timmons
SUBSTANCE INVOLVED	QUANTITY	UNITS	ADDRESS STREET OR ROUTE CTH "L" @ CTH "K"	TELEPHONE NUMBER 715 1 398 30
PHYSICAL CHARACTERISTICS <input type="checkbox"/> SOLID <input type="checkbox"/> LIQUID <input type="checkbox"/> SEMISOLID <input type="checkbox"/> GAS COLOR _____ ODOR _____			CITY, STATE, ZIP CODE South Range, Wis	
CAUSE OF INCIDENT broken valve between buried tank and pump			ACTION TAKEN BY SPILLER <input type="checkbox"/> NO ACTION <input type="checkbox"/> NO NOTIFICATION <input type="checkbox"/> DELAYED NOTIFICATION <input type="checkbox"/> TAKEN <input type="checkbox"/> CONTAINMENT, TYPE _____ <input type="checkbox"/> CLEANUP, METHOD _____ <input type="checkbox"/> DISPOSAL, LOCATION _____ <input type="checkbox"/> FIRE DEPARTMENT ACTION _____ <input type="checkbox"/> CONTRACTOR HIRED; NAME Petroleum Equip. Serv. <input type="checkbox"/> OTHER ACTION _____	
EXACT LOCATION DESCRIPTION (INTERSECTION, MILEAGE, ETC.)				
COUNTY LOCATION Douglas Co.	TWP., W., SECTION, TOWN, RANGE T. N. R.			
DNR DISTRICT NWD	DNR AREA Brule	SURFACE WATERS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> POT	DRAIN BASIN	WEATHER CONDITIONS
NAME OF SURFACE WATER	NEAREST SURF. WATER _____ FT.	NEAREST STORM SEWER _____ FT.	TEMPERATURE 50 °F	WIND SPEED _____ MPH DIRECTION OF WIND _____
GROUNDWATERS AFFECTED <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> POT	NEAREST WELL <input checked="" type="checkbox"/> PRIV. <input type="checkbox"/> MUNIC. 50 FT.	DATE DISTRICT NOTIFIED 4/20/84	PRECIPITATION: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	DIRECTION OF SPILL MOVEMENT _____
DATE INVESTIGATED 4/20/84	DAY OF WEEK Friday	TIME INVESTIGATED 11:30 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	DISTRICT PERSON NOTIFIED Barry O'Flanagan	TELEPHONE NUMBER 715 1635 210
ACTION TAKEN BY DNR <input type="checkbox"/> NO ACTION <input type="checkbox"/> INVESTIGATION <input type="checkbox"/> 29.29 ENFORCEMENT <input type="checkbox"/> TAKEN <input type="checkbox"/> CONTAINMENT, TYPE _____ <input type="checkbox"/> CLEANUP, METHOD excavation of sump pit <input checked="" type="checkbox"/> SUPERVISE CLEANUP (PERSON) J. Lund <input type="checkbox"/> DISPOSAL, LOCATION _____ <input checked="" type="checkbox"/> SPILLER REQUIRED TO TAKE ACTION; TYPE empty tank, excavate <input type="checkbox"/> CONTRACTOR HIRED BY DNR; NAME _____ <input type="checkbox"/> DNR SPILL EXPENSE SENT TO MADISON CENTRAL OFFICE. <input type="checkbox"/> EVIDENCE COLLECTED: <input type="checkbox"/> PHOTOGRAPHS _____ <input type="checkbox"/> STATEMENTS OF WITNESSES _____ <input type="checkbox"/> SAMPLES _____ <input type="checkbox"/> OTHER _____			PERSON INVESTIGATING Jim Lund	
OTHER AGENCIES ON SCENE			LIST HUMAN HAZARDS OR CASUALTIES <input type="checkbox"/> REAL <input checked="" type="checkbox"/> POTENTIAL <input type="checkbox"/> NONE explosion hazard	
LOCAL _____	ENVIRONMENTAL HAZARD/DAMAGE <input type="checkbox"/> REAL <input type="checkbox"/> POTENTIAL			
STATE _____	<input type="checkbox"/> VEGETATION _____ <input type="checkbox"/> FISH _____ <input type="checkbox"/> WILDLIFE _____ <input type="checkbox"/> BIRDS _____ <input type="checkbox"/> OTHER _____ <input checked="" type="checkbox"/> NONE			
FEDERAL _____	COMMENTS: PERSON FILING THIS REPORT (PRINT NAME) Jim Lund SIGNATURE James B. Lund DATE SIGNED 4/20/84			

ADDITIONAL COMMENTS:
*** Has been an ongoing problem. Tank was serviced 2-3 times by Petroleum & Equip Serv. (Bill Lingquist 715/392-6181). Valve between tank and pump malfunctioned last winter. When repair occurred product spilled & apparently seeped beneath store.**