BRRTS Number: 02-41-420848

Remediation & Redevelopment Continuing Obligation Review
Form 4400-232 (Revised 2/11)

Steve Mueller Reviewer: Site Name: Express Cleaners

Review Date: Mon. 8/27/12

Region: SER

See RR-5242 for instructions. Steps with an *denote DNR follow up; ** denote RP/property owner follow un

owner ronow up.
FILE REVIEW: 1. Review the file and BRRTS, identify the following: Address/ City/Zip Code: 5620 S. 108 th St., Hales Corners, WI, 53130 Parcel Identification Number (PIN): part of 659-9977-004 Current Property Owner: Country Fair, LLC / registered agent: Robert F. Nielsen, 380 Linden
St., Reno, NV, 89502 (775/825-0999)
Original RP: Malan Liquidating Trust, 30200 Telegraph Rd., Ste. 105, Bingham Farms, MI, 48025 Has the property been transferred since the restriction was recorded/condition applied? ☐ No ☑Yes
How was site selected for audit? (AC = BRRTS Action Code) Vapor Mitigation AC 226 Green Space Grant AC 605 Age of Remedy VPLE with AC 56 AC 220, 222, 224, 228 or 230 Complaint Received Enforcement Follow-up Deed Restriction AC 52 or 696 (LGU) Regional Priority Other:
Date of:
⊠ Final Closure May 10, 2005
Certificate of Completion General Liability Clarification Letter
Green Space Grant Local Gov't Unit (LGU) letter

*Check all continuing obligations applied (at case closure or RAP approval or letter to LGU):

Add to BRRTS	AC in BRRTS	Action Code	Action Code Meaning
24		51	Deed notice
	Х	52	Deed restriction for soil
		730	Groundwater use restriction
		95	Deed instrument conditions met (for audits, use if deed restriction was updated by filing a deed notice)
		101	GIS Registry PDF modified – date DNR letter sent
		104	Site removed from GIS Registry – date DNR letter sent
		696	Continuing obligation required of LGU to maintain liability exemption
		605	Green Space Grant awarded (deed restriction)
Х		56	Continuing Obligation applied (use with codes 220-238)
		220	Soil at industrial use level
		222	Cover/engineered containment system (pavement, soil cover, etc.)
		224	Structural impediment (buildings or other structures)
X	(86)	226	Vapor mitigation/response
	A CONTRACTOR	228	Site-specific (identify in comment field)
		230	LGU was directed to take a protective action
	Х	232	Residual soil contamination > RCLs/SS RCLs (use with AC 222,224)
		234	Monitoring well needs to be abandoned
		236	Site closed with groundwater contamination > ES
		238	Maintenance and inspection documentation required to be submitted
Х		185	Closure Compliance Review completed
Х		186	Closure Compliance Review – RP follow up needed
		187	Closure Compliance Review follow up completed

BRRTS Number: 02-41-420848

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 8/09)

Describe any site-specific requirements that the site owner and/or responsible party needed to address.
Is the site on the GIS Registry? Yes No - Add it to the GIS Registry* Were neighboring properties affected? No Yes - Are these properties listed on the GIS Registry and in BRRTS? Yes No Update the GIS Registry/BRRTS, use form 4400-246*.
Was a maintenance plan required at closure? ☐ NA ☐ No ☐ Yes Is it in the file ☐ or PDF ☐ or missing ☐ ? If no maintenance plan was required, offer the property owner the template model with inspection log, and note in the follow up section of the audit that one was provided on the audit date.
Was/were the appropriate restriction(s) recorded with the Register of Deeds? ☐ NA ☐ No ☐ Yes
Has a restriction been amended, or been nullified by DNR? ☑ No ☐ Yes ☐ If Yes: Was BRRTS updated? (95) ☐ No * ☐ Yes ☐ Was the GIS Registry PDF updated? ☐ No * ☐ Yes ☐ Site Visit: 2. Contact the site owner for access. Contacted he facility maintenance manager, Tom Ziefle, in Aug. 2012 and scheduled this CO inspection.
3. Walk the site (ideally with the owner or responsible party) to review the site conditions against the conditions documented at closure/other to verify or change answers to questions in #1. Conducted CO inspection with Tom Ziefle.
 4. With the site owner/RP (if possible), answer the following for DNR RR records: Did the site owner know about the continuing obligation(s)? ∑ Yes No
Have site conditions changed since closure that would affect either a deed restriction or other restrictions or requirements associated with the site? ☑ No ☐ Yes Explain.
Examples: 1) a building has been razed and investigation and remediation occurred. 2) excavation or residential development has occurred in a restricted area.
Is an asphalt cover or soil cover removed or in disrepair? ☑ No/NA ☐ Yes Should it be replaced or repaired? ☐ No ☐ Yes **

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 8/09)

BRRTS Number: 02-41-420848

If a performance standard was the final remedy, has it been altered? ☑ No/NA ☐ Yes Describe
If Yes - Was DNR notified?
Have local zoning changes occurred since closure? ☑ No/NA ☐ Yes If Yes - Does it appear to impact the effectiveness of the restriction? ☐ No ☐ Yes Describe:
Is soil sampling needed to determine if the final remedy has been modified such that a direct contact threat exists? No Yes** Describe:
For example, an asphalt cover has been removed or is in disrepair, or a new contaminated site is present upgradient, etc.
Has additional monitoring or remediation been done since the site was closed? ☑ No ☐ Yes Describe:
Does a new threat to public health or the environment exist (e.g. new sources or exposure routes)? ☑ No ☐ Yes If Yes - Does sampling need to be performed? ☐ No ☐ Yes** Describe what should be done to address the problem, and by whom:
Is the vapor mitigation system (VMS) or sub-slab depressurization system (SSDS) operating as designed? (pressure gradient being maintained) NA Yes No** – if not, describe any follow up needed. The motorized fan felt as if it was running; however, the ball-valve on the vapor vent pipe was closed in the building's mop closet,
thereby preventing proper collection, flow, and discharge of sub-slab vapors; and the manometer is dry. The valve was reopened during the inspection; the manometer must be refilled or replaced.
Have any of the exposure assumptions used for closure changed at this site? ☐ NA ☐ No ☐ Yes - if yes, describe any follow up needed.

BRRTS Number: 02-41-420848

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 8/09)

	Has the land use at this site changed such that a vapor intrusion pathway may now exist? No Yes - If Yes, describe any follow up needed.
	COMPLIANCE AND FOLLOW-UP: 5. Identify compliance and any follow up needed. Is the site in compliance with the continuing obligations/closure approval document? Yes No - Describe what's not in compliance: The SSDS was not operating properly and has apparently not been routinely inspected; the on-site maintenance log has not been completed. (May depend on extent of non-compliance, non-maintenance of remedy or changed ownership or conditions. If case is out of compliance, it should be prioritized by the region, for new casework or enforcement, as needed.)
	If the site is not in compliance, what are the reasons? The on-site maintenance log was not transferred to the current owner; a new copy will be sent. A copy of the WDNR's GIS Registry packet for the site will also be forwarded to the current owner.
	Has the maintenance agreement required at closure been followed? ☐ NA ☐ Yes ☐ No Describe: (see above comments)
	6. **Are additional actions by the RP or property owner warranted at the site? (The intent is to return the site to compliance with continuing obligation. If further remedial action is needed, determine if the site meets the NR 726 reopening criteria.) No Yes Describe any actions needed to return the site to compliance, and identify who's responsible: (Add AC 186, use AC 99 for actions not listed under AC186) The vent pipe valve must remain open and the manometer recharged/maintained in order to confirm proper operation of the SSDS; a "keep open" sign should be attached to the valve or pipe. Weather seals on equipment on the roof should be re-caulked. The SSDS (including sealed floor) must be inspected annually and documented in the on-site inspection log.
	7. *Does the site require follow up by DNR? No Yes Contact or enforcement to return site to compliance with continuing obligation updating BRRTS (check all codes that apply on pg. 1) updating the GIS Registry (adding or modifying a packet)
	reopen site (add ACs 186 and 13) other: 8. *Attach photographs of the site, documenting site conditions. 9. *Identify and update any applicable action codes (Table on page 1).
1	0. *Add a copy of this audit to the case file. Follow the instructions in RR-5242, (http://intranet.dnr.state.wi.us/int/aw/rr/Guidance/RR5242.pdf). Send a copy
	electronically (PDF) to Central Office, using the following naming convention:
	BRRTS#_COAUDIT_Year.pdf (example: 0365001149_COAUDIT_2008.pdf)



Vent pipe ball-valve in reopened position; empty manometer to right of valve.



Vent pipe stack on roof.



Depressurization blower in galvanized box; vent pipe in on right, out on left.













