

State of Wisconsin
Department of Natural ResourcesState Div. Emergency Gov't.
U.S. Nat'l. Response Center
Chemtrec/Pesticides/ChlorineTOXIC AND HAZARDOUS SPILL REPORT
Form 4400-91 Rev. 6-86

Spill ID Number

Y Y M M D D 0-99

Date of Incident 4/12/94	Day of Week Tuesday	Time of Incident <input type="checkbox"/> A.M. <input type="checkbox"/> P.M.	Reported By (Name) Frank Braswell	Telephone Number (715) 723-5710
Date Reported 4/12/94	Day of Week Tuesday	Time Reported <input type="checkbox"/> A.M. <input type="checkbox"/> P.M.	Agency or Firm Reporting Chippewa Falls Fire Dept.	Reported thru Div. Emergen. Gov't. <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Substance Involved Petroleum	Quantity Link	Units	Person or Firm Responsible Bradley R. Hu Oil Company	
Substance Involved	Quantity	Units	Contact Name Bradley R. Hu	Telephone Number (715) 726-1122

Physical Characteristics

☐ Solid ☒ Liquid Color _____
☐ Semisolid ☐ Gas Odor _____

Cause of Incident

Spillage during transfer process

Exact Location Description (intersection, mileage, etc.)

304 W. River St. Chippewa Falls, WI

County Location 1/4 1/4, 1/4, Section, Town, Range

Chippewa _____, _____, _____, T _____ N, R _____

DNR Dist Western DNR Area ECA Groundwaters Affected
☐ Yes ☐ No ☒ Potential

Surface Waters Affected
☐ Yes ☐ No ☒ Potential Name of Surface Water
 Chippewa River

Date District Notified 4/22/94 Day of Week Friday Time District Notified 10:15
☒ A.M. ☐ P.M.

District Person Notified John Grunp Telephone Number (715) 839-3775

Date Investigated 4/29/94 Day of Week Fri. Day Time Investigated 9:15
☒ A.M. ☐ P.M.

Person Investigating John Grunp Telephone Number (715) 839-3775

Action Taken By DNR

☐ No Action Taken ☒ Investigation ☐ Supervise/Conduct Cleanup

☒ Spiller Required To Take Action; Type Hire consultant/Remediate

☐ Contractor Hired By DNR; Name _____

☐ Amount Recovered _____

☐ 29.29 Enforcement

Other Agencies on Scene

Local _____

State John Andersen, DNR

Federal _____

Additional Comments:

NOV sent 5/3/94

Address - Street or Route

104 Well

City, State, Zip Code

Chippewa Falls, WI 54729

Action Taken By Spiller

☒ No Action Taken ☐ No Notification ☐ Investigate

☐ Containment; Type _____

☐ Cleanup; Method _____

☐ Amount Recovered _____

☐ Monitor _____

☐ Contractor Hired; Name _____

☐ Other Action _____

Spill Location

☐ Industrial Facility/Paper Mill/Chem. Co.
☒ Gas/Service Station/Garage, Auto Dealer, Repair Shop
☐ Ag Coop/Facility/Cheese Factory/Creamery
☐ Other Small Business (bank, grocery, insurance co., etc.)
☐ Public Property (city, county, state, church, school, etc.)
☐ Utility Co., Power Generating/Transfer Facility
☐ Private Property (home/farm)
☐ Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler
☐ Transportation Accident, Fuel Supply Tank Spill
☐ Transportation Accident, Load Spill
☐ Construction, Excavation, Wrecking, Quarry, Mine
☐ Other _____

Spilled Substance Destination

☐ Air
☒ Soil
☐ Groundwater
☐ Surface Water
☐ Storm Sewer
☐ Sanitary Sewer
☐ Contained/Recovered
☐ Other _____

Person Filing This Report (print name)


John R. Grunp

Signature

John R. Grunp

Date Signed

5/3/94



George E. Meyer
Secretary

State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

2004 Highland Avenue
Eau Claire, WI 54701-4346
TELEPHONE 715-839-3777
TELEFAX 715-839-1605

May 3, 1994

File Ref: 4440
Chippewa County
CERTIFIED MAIL

Mr. Bradley Rihn
Rihn Oil Company
104 Well
Chippewa Falls, WI 54729

SUBJECT: NOTICE OF VIOLATION

**Petroleum Spills and Contaminated Soil at the Rihn Oil Service
Station Located at 304 West River Street, Chippewa Falls, WI**

Dear Mr. Rihn:

On April 29, 1994, John Andersen, DILHR, and myself responded to complaints of spillage and overfills of petroleum products. These complaints were submitted to Frank Braswell, Chippewa Falls Fire Department. According to the complaints, petroleum product has been spilled during the transfer from one tanker to another. During our inspection, we took photographs of stained soil, oily run-off water and an uncovered underground storage tank access manhole. The complaint of surface spillage was verified during our inspection.

Since a hazardous material has been released to the environment, you are responsible for restoring the environment to the extent practicable according to 144.76 State Statutes.

The petroleum contaminated soil must be removed and treated in an approved manner. These would include thermal or biological treatment. You must hire a competent environmental consulting firm to oversee the restoration and sampling of subsurface soils.


Failure to notify this Department within thirty (30) days from receipt of this letter will result in the issuance of an Administrative Order. This notification must include proof of retention of an environmental consultant.

Mr. Bradley Rihn - May 3, 1994

2

If you have any questions concerning this letter, please contact me at
(715) 839-3775.

Sincerely,



John R. Grump
Hydrogeologist

JRG/ah

c: Bill Evans
Dave Lundberg
Darrell Solberg
Frank Braswell, CFFD
John Andersen, DILHR

RECEIVED

MAY 3 1994

DNR-WD

File -
Choppura
Q Spill