State of Wisconsin Department of Natural Resources PO Box 7921, Madison WI 53707-7921

Remediation & Redevelopment Continuing Obligation Review

Form 4400-232 (R 04/19) Page 1 of 9

BRRTS IE	No. 02-3	36-5214	30		10	m 4400-232 (10 04/19)	rage rors	
Reviewer:	Tauren	Beggs	_	Region: No.	rtheast	Review Date:	09/10/2021	
Site Name: WI DOT Eggers Industries West Plt								
follow up	; ** denot Use the N	e RP/pro	perty owner follow i	state.wi.us/int/aw/rr/guid up. If auditing a VPLE sit o add information not oth	e, use the	applicable LUST or E		
		and the	file if needed, to ide	ntify the File Review info	rmation:			
Site Addre		and the	The fi ficeded, to ide	City	illiation.		ZIP Code	
					:			
1702 13th		ification	Number (PIN)	Two R			54241	
053-000-0			ramber (i iia)	436010				
Original R			1	430010	0300			
-	•			r Street, Two Rivers, WI	54241			
				uing obligation was record		? ONo Yes		
If Yes: C	urrent Pro	perty Ov	vner					
S	teven Sch	nenian, E	Bright Horizon Prope	rties, LLC, 500 Americar	n Drive, PO	D Box 249, Francis Ci	reek, WI 54214	
	hone Nun			Email		·	,	
		(920) 6	82-5166	sschenian@scheniantruc	king.com			
Select all	continuing	obligatio	ns applied (at case clo	sure or RAP approval or le	tter to LGU):		
Add to BRRTS	AC in BRRTS AC Action Code (AC) Meaning							
		51	Deed notice					
		52	Deed restriction for so	il				
		730	Groundwater use restr	Groundwater use restriction				
		95	Deed instrument cond	itions met (for audits, use if	deed restric	tion was updated by fili	ng a deed notice)	
		101	GIS Registry PDF mod	dified - date DNR letter sent				
		104	Site removed from GIS	Registry - date DNR letter	sent			
		696	Continuing obligation r	equired of LGU to maintain	liability exe	mption		
		605		varded (deed restriction)				
	\boxtimes	56	Continuing Obligation	applied (use with codes 220)-238)			
		46	Impacted Right-of-Wa	У				
		220	Soil at industrial use le					
		222						
		224		Structural impediment (buildings or other structures)				
		226	Vapor mitigation/respo					
		228	Site-specific (identify in comment field)					
		230	LGU was directed to take a protective action					
		232		Residual soil contamination > RCLs/SS RCLs (use with AC 220, 222, 224)				
		234	Monitoring well needs					
$oxed{oxed}$		236		dwater contamination > ES				
		238		ection documentation requir	ed to be su	bmitted		
\boxtimes		185	Closure Compliance R	·	_			
\square		186	-	Review - RP follow up neede	d			
		187		Review follow up completed				
		99	IUse this code with cor	nments, for actions not listed	d under AC	186 (i.e. submittal of ins	spection reports)	

Remediation & Redevelopment Continuing Obligation Review

Form 4400-232 (R 04/19) Page 2 of 9

Ηο	w was site selected for audit? (AC = BRRTS Action Code)					
	☐ Vapor Mitigation AC 226 ☐ Green Space Grant AC 605 ☐ Age of Remedy					
	VPLE with AC 56					
	Enforcement Follow-up Deed Restriction AC 52 or 696 (LGU) Regional Priority					
	Other:					
Dat	te of:					
	∑ Final Closure 01/10/2007 ☐ Remedial Action Plan Approval					
	Certificate of Completion General Liability Clarification Letter					
	Green Space Grant Local Gov't Unit (LGU) Letter					
De	scribe any site-specific requirements (AC 228) that the site owner and/or responsible party needed to address:					
ls t	he site on BRRTS as having residual contamination and continuing obligations?					
We	 Yes	:.)*				
	If yes, are these properties listed in BRRTS with AC 56? Yes O No – Update BRRTS, use form 4400-246*					
Wa	s a maintenance plan required at closure?					
	If no maintenance plan was required, offer the property owner the template model with inspection log, and note in the folloup section of the audit that one was provided on the audit date)W				
Wa	s/were the appropriate restriction(s) recorded with the Register of Deeds? Yes No No					
	Has a restriction been amended, or been nullified by DNR? O No					
	○ Yes: Was BRRTS updated? (95) ○ Yes ○ N	0*				
	Was the CO PDF updated?	0*				
No	tes:					
est	et with Steve Schenian (current owner) and Que El-Amin (Principal with potential buyer Scott Crawford, Inc., a real atte development company, email: Que@scott-crawford.com). Scott Crawford, Inc. is looking to acquire this parcel for nulti-family apartment complex redevelopment utilizing tax credits.	r				
por afte	e City of Two Rivers has an easement on this property for utilities. The City of Two Rivers disturbed the very eastern tion of the pavement cap for installation/replacement of utilities in 2014. The cap was replaced with asphalt pavement the utility installation was completed. No changes were needed to the cap maintenance plan at that time. The City iffied DNR for the work that was completed prior to the implementation of the official Post Closure Modification access.					
_	e Visit:					
2.	Contact the site owner for access. Provide a copy of the maintenance plan, if applicable. If the audit is being conducted for a CO which would now require a maintenance plan, provide a template version if no maintenance plan was required at closure, for the property owner's use (voluntary).					
3.	Walk the site (ideally with the owner or responsible party) to review the site conditions against the conditions documented at closure/other to verify or change answers to questions in #1. Discuss use of the maintenance plan or template.					
4.	With the site owner/RP (if possible), answer the following for DNR RR records:					
Did	the site owner know about the continuing obligation(s)?					
Uc.	vo aits conditions abanged since alcours that would affect either a dead restriction or other restrictions or requirements					

Have site conditions changed since closure that would affect either a deed restriction or other restrictions or requirements associated with the site?

Remediation & Redevelopment Continuing Obligation Review Form 4400-232 (R 04/19) Page 3 of 9

Page 3 of 9

No	
◯ Yes – Ex	plain:
Ex	amples: 1) a building has been razed and investigation and remediation occurred. 2) excavation or residential development has occurred in a restricted area.
disrepair?	(asphalt or concrete) cover, soil cover or other sort of cover, such as a building, been removed or is it in No/NA
0,	Yes – Should it be replaced or repaired? ○ Yes** ○ No
· _	standard was the final remedy, has it been altered?
No	
◯ Yes – Ex	olain:
Was	s the DNR notified? Yes No
Have local zoning No/NA	changes occurred since closure?
_	es it appear to impact the effectiveness of the restriction?
○ No	
~	Describe:
Is soil sampling no No Yes - De	eeded to determine if the final remedy has been modified such that a direct contact threat exists? scribe:
•	asphalt cover has been removed or is in disrepair, or a new contaminated site is present upgradient, etc. onitoring or remediation been done since the site was closed?
No Yes – Des	cribe:
Does a new threa	t to public health or the environment exist (e.g. new sources or exposure routes)?
Yes – Doe	es sampling need to be performed?
\bigcirc	No
0	Yes** – Describe what should be done to address the problem, and by whom:
maintained) Organization	ation system or sub-slab depressurization system (SSDS) operating as designed? (pressure gradient being
● NA	scribe any follow up needed:
•	exposure assumptions used for closure changed at this site?
NA	Aposure assumptions used for diosure changed at this site!
No	
_	scribe any follow up needed:

Remediation & Redevelopment Continuing Obligation Review

Form 4400-232 (R 04/19) Page 4 of 9

Has	s the land use at this site changed such that a vapor intrusion pathway may now exist? No Yes – Describe any follow up needed:
Has	s the land use changed such that there are either health or safety issues? No Yes – Describe any follow up needed:
No	It was mentioned a Phase I and Phase II ESA was recently completed for the property as due diligence for a property transaction with Scott Crawford, Inc. I indicated the results are required to be reported to the DNR and the property owner would have all the environmental liability under the spill law, unless a viable causer could be identified. Que indicated the property was historically owned by Mirro Aluminum. If the property acquisition occurred, then the new owner would be liable. Also went through the post-closure modification process with them so they understood that any changes to the cap would require prior DNR approval before moving forward.
5.	MPLIANCE AND FOLLOW-UP SUMMARY: Identify compliance and any follow up needed. he site in compliance with the continuing obligations/closure approval document? Yes No – Describe what's not in compliance and the reasons for noncompliance:
con	ay depend on extent of non-compliance, non-maintenance of remedy or changed ownership or conditions. If case is out of inpliance, it should be prioritized by the region, for new casework or enforcement, as needed.) Is the maintenance agreement required at closure been followed? Yes NA No – Describe:
Wa	s the property owner reminded to complete and document the (yearly) inspections? O Yes NA No – Why not?
Wa	s a maintenance plan or template provided to the property owner at the site visit? • Yes • NA • No – If no, why not?

^{6.**} Are additional actions by the RP property owner warranted at the site? The intent is to return the site to compliance with continuing obligation. If a significant land use change has occurred, and/or further remedial action is needed, determine if the site meets the NR 726 reopening criteria.)

Remediation & Redevelopment Continuing Obligation Review

Form 4400-232 (R 04/19) Page 5 of 9

 No Yes – Summarize the actions needed to return the site to compliance and identify who is responsible:
Notes: The property owner was not aware of the continuing obligations. I went through the closure letter and cap maintenance plan with him and filled out an inspection log for the cap (attached). The asphalt pavement was in fair condition and didn't need any repair or maintenance.
Add AC 186 for RP/property owner follow-up required. Use AC 99 if a reminder was provided to the property owner to complete and document inspections.
7. * Does the site require follow up by DNR?
No
Yes: contact or enforcement to return site to compliance with continuing obligation
updating BRRTS for the CO PDF (adding or modifying a packet)
reopen site (add ACs 186, 12 and 13)
other:
8. * Attach photographs of the site, documenting site conditions. Label the photos with the site name/BRRTS Activity number/date/view. If a follow-up letter is sent, include a copy with the audit. (audit/photos/follow-up letter)
9. * Save a copy of the audit using the following naming convention: YYYYMMDD_185_CO_Audit.pdf. For follow-up documentation use YYYYMMDD_186_Follow_Up_Needed.pdf.
10. Update applicable BRRTS action codes on the Table on page 1. Use the regional tracking sheet, and have your Regional EPA update the ACs and upload the audit PDF into BRRTS.

11. Notify Central Office when the audit has been completed and loaded into BRRTS.

Date added: 09/14/2021

Form 4400-232 (R 04/19) Page 6 of 9

{Click to Add/Edit Image File (*.bmp;*.jpg;*.gif;*.png;*.tif)}



Title: Google aerial that shows the entire parking lot and the area where the asphalt was replaced.

Date added: 09/14/2021

Page 7 of 9

Form 4400-232 (R 04/19)

{Click to Add/Edit Image File (*.bmp;*.jpg;*.gif;*.png;*.tif)}



Title: Asphalt cap area to be maintained in area where PAHs were documented in soil, looking southeast.

Date added: 09/14/2021

Form 4400-232 (R 04/19)

Page 8 of 9

{Click to Add/Edit Image File (*.bmp;*.jpg;*.gif;*.png;*.tif)}



Title: Required asphalt pavement cap (right side of photo), easement area where asphalt was replaced after utility work in 2014 (left side of photo), looking west.

Date added: 09/14/2021

Form 4400-232 (R 04/19)

Page 9 of 9

{Click to Add/Edit Image File (*.bmp;*.jpg;*.gif;*.png;*.tif)}



Title: Portion of the required asphalt pavement cap on the east side of the property that was replaced by the City of Two Rivers after utility work in 2014, looking southeast.

State of Wisconsin Department of Natural Resources dnr.wi.gov

Continuing Obligations Inspection and Maintenance Log

Form 4400-305 (R 7/20)

Page 1 of 2

Directions: In accordance with s. NR 727.05 (1) (b) 3., Wis. Adm. Code, use of this form for documenting the inspections and maintenance of certain continuing obligations is required. Personal information collected will be used for administrative purposes and may be provided to requesters to the extent required by Wisconsin's Public Records law [ss. 19.31-19.39, Wis. Stats.]. When using this form, identify the condition that is being inspected. See the closure approval letter for this site for requirements regarding the submittal of this form to the Department of Natural Resources. A copy of this inspection log is required to be maintained either on the property, or at a location specified in the closure approval letter. Do NOT delete previous inspection results. This form was developed to provide a continuous history of site inspection results. The Department of Natural Resources project manager is identified in the closure letter. The project manager may also be identified from the database, BRRTS on the Web, at http://dnr.wi.gov/botw/SetUpBasicSearchForm.do, by searching for the site using the BRRTS ID number, and then looking in the "Who" section.

Activity (Site) Name WI DOT Eggers Industries West Plt				BRRTS No. 02-36-521430			
Inspections are required to be conducted (see closure approval letter): annually semi-annually other – specify				When submittal of this form is required, submit the form electronically to the DNR project manager. An electronic version of this filled out form, or a scanned version may be sent to the following email address (see closure approval letter):			
Inspection Date			Describe the condition of the item that is being inspected	Recommendations for repair or maintenance	Previous recommendations implemented? Photographs taken and attached?		
09/10/2021	Tauren Beggs and Steve Schenian	monitoring well cover/barrier for soil sediment cap other:	Asphalt pavement in fair condition.	Not applicable at this time.	OY ON	● Y ○ N	
		monitoring well cover/barrier for soil sediment cap other:			OY ON	OY ON	
		monitoring well cover/barrier for soil sediment cap other:			OY ON	O Y O N	
		monitoring well cover/barrier for soil sediment cap other:			OY ON	O Y O N	
		monitoring well cover/barrier for soil sediment cap other:			OY ON	OY ON	
		monitoring well cover/barrier for soil sediment cap other:			OY ON	OY ON	

WI DOT Eggers Industries West Plt

Activity (Site) Name

Continuing Obligations Inspection and Maintenance Log Form 4400-305 (R 7/20)

Page 2 of 2

{Click to Add/Edit Image}



Title: Google aerial of entire parking lot.

Date added: 09/14/2021

Date added: 09/14/2021

{Click to Add/Edit Image}




Title: Main area of asphalt cap to be maintained, looking southeast.

{Click to Add/Edit Image}



Title: Utility work asphalt replaced (left side), Asphalt cap (right side).

{Click to Add/Edit Image}



Title: East portion of asphalt cap replaced by City of Two Rivers in 2014.

Date added: 09/14/2021