

**From:** Swenson, Steve R <steves@st-ma.com>  
**Sent:** Friday, December 11, 2020 6:45 AM  
**To:** Grittner, Paul V - DNR  
**Subject:** RE: Superior Health Linens - 02-41-532649

Thank you Paul – I'll let Bill & Jim know

**Steven R. Swenson, P.G., CHMM**  
**Senior Geologist**

**St. John-Mittelhauser & Associates, A Terracon Company**

1893 S. Trainer Road | Rockford, IL 61108

D (815) 255-8300 | M (815) 289-0400

[steves@st-ma.com](mailto:steves@st-ma.com) | [www.st-ma.com](http://www.st-ma.com) | [terracon.com](http://terracon.com)

---

**From:** Grittner, Paul V - DNR <[Paul.Grittner@wisconsin.gov](mailto:Paul.Grittner@wisconsin.gov)>  
**Sent:** Friday, December 11, 2020 6:44 AM  
**To:** Swenson, Steve R <[steves@st-ma.com](mailto:steves@st-ma.com)>  
**Subject:** RE: Superior Health Linens - 02-41-532649

Steve,

You are correct, based on our recent review of site conditions, the DNR has agreed that no further groundwater investigation is required for this site and does not expect that further sampling of these wells to be needed. However, as the site investigation (and potentially remediation) is not complete, and more information will be obtained, the DNR cannot guarantee that groundwater sample data from this general area would not be needed in the future if our understanding of the site changes.

The monitoring wells can be abandoned at any time without DNR approval. It is ultimately up to the property owner or responsible party to determine when they should be removed.

Please let me know if you have any further questions.

**We are committed to service excellence.**

Visit our survey at <http://dnr.wi.gov/customersurvey> to evaluate how I did.

**Paul Grittner**

Phone: (414) 405-0764

[paul.grittner@wisconsin.gov](mailto:paul.grittner@wisconsin.gov)

---

**From:** Swenson, Steve R <[steves@st-ma.com](mailto:steves@st-ma.com)>  
**Sent:** Thursday, December 10, 2020 10:16 AM  
**To:** Grittner, Paul V - DNR <[Paul.Grittner@wisconsin.gov](mailto:Paul.Grittner@wisconsin.gov)>  
**Cc:** Jim Baumgartner <[jbaum777@gmail.com](mailto:jbaum777@gmail.com)>; Bill Nicklas <[wjnicklas@gmail.com](mailto:wjnicklas@gmail.com)>; St. John, Ron B <[rons@st-ma.com](mailto:rons@st-ma.com)>  
**Subject:** Superior Health Linens - 02-41-532649

Paul,

D&C Partners contacted me this morning regarding the addition to the building that is currently being constructed on site. The contractor is on site doing foundation work and they discovered that monitoring wells MW-6 and PZ-3 are located within the foundation foot print. For your reference, I have attached a copy of the Figure with the location of MW-6 and PZ-3 circled in red.

As we understand it, the WDNR has determined that no further assessment or sampling of the groundwater is necessary to obtain closure of this Site. Therefore, we would like to abandon these two monitoring wells to allow the construction of the addition to the building. All work will be done in accordance with NR 141.25(2)(d)

Does the WDNR have any concerns or reservations with the abandonment of these two monitoring wells?

If you need additional information, please feel free to contact me.

Thank you again for your time and attention to this matter.

**Steven R. Swenson, P.G., CHMM**  
**Senior Geologist**

**St. John-Mittelhauser & Associates, A Terracon Company**

1893 S. Trainer Road | Rockford, IL 61108

D (815) 255-8300 | M (815) 289-0400

[steves@st-ma.com](mailto:steves@st-ma.com) | [www.st-ma.com](http://www.st-ma.com) | [terracon.com](http://terracon.com)

Terracon provides environmental, facilities, geotechnical, and materials consulting engineering services delivered with responsiveness, resourcefulness, and reliability.

---

*Private and confidential as detailed here ([www.terracon.com/disclaimer](http://www.terracon.com/disclaimer)). If you cannot access the hyperlink, please e-mail sender.*