May 24, 2022

CONSTRUCTION DOCUMENTATION REPORT

FORMER KLINKE CLEANERS – FOX RUN
2346 WEST ST. PAUL AVENUE
WAUKESHA, WISCONSIN

BRRTS #: 02-68-535535 / FID #: 268188910

ENDPOINT PROJECT No. 525-008-005

PREPARED FOR:

Fox Run 3, LLC

C/O: VJS DEVELOPMENT GROUP W233N2847 ROUNDY CIRCLE WEST PEWAUKEE, WI 53072

PREPARED BY:

Endpoint Solutions

6871 South Lover's Lane Franklin, Wisconsin 53132 (414) 427-1200

CONSTRUCTION DOCUMENTATION REPORT

FORMER KLINKE CLEANERS – FOX RUN
2346 WEST ST. PAUL AVENUE
WAUKESHA, WISCONSIN

BRRTS #: 02-68-535535 / FID #: 268188910

May 24, 2022

Prepared By:	Later A Col	May 24, 2022	
. ,	Robert A. Cigale, P.G.	Date	
	Principal Geologist		
Reviewed By:	Kirk L. Kapfhammer, P.G.	May 24, 2022 Date	
	-	Date	
	Principal Geologist		



TABLE OF CONTENTS

Certifica	tion	11
1.0	General Information	1
1.1	Site Name and Address	1
1.2	Locational Information	1
1.3	Site Owner / Responsible Party	1
1.4	Environmental Consultant	
1.5	Site Topography	
2.0	Background	3
2.1	Site History	3
2.2	Redevelopment Plan	3
3.0	Background	4
4.0	Observations and Documentation	5
5.0	Conclusions	7
FIGU	RES	
B.1	.A LOCATION MAP	
B.1	B DETAILED SITE MAP	
B.1	.c Proposed Site Plan	
B.2	.c Cut/Fill Areas	
APPEN	DICES	
Α	SANITARY SEWER TRENCH ABANDONMENT PHOTO-DOCUMENTATION	
В	SOIL EXCAVATION AND RELOCATION PHOTO-DOCUMENTATION	

CERTIFICATION

HYDROGEOLOGIST

I, Robert A. Cigale, hereby certify that I am a hydrogeologist as that term is defined in s. NR 712.03 (1), Wis. Adm. Code, am registered in accordance with the requirements of ch. GHSS 2, Wis. Adm. Code, or licensed in accordance with the requirements of ch. GHSS 3, Wis. Adm. Code, and that, to the best of my knowledge, all of the information contained in this document is correct and the document was prepared in compliance with all applicable requirements in chs. NR 700 to 726, Wis. Adm. Code.

ignature 332 May 24, 2022
P.G. number Date



1.0 GENERAL INFORMATION

The purpose of this Construction Documentation Report (CDR) is to summarize the soil excavation and relocation activities performed at the Former Klinke Cleaners – Fox Run site located at 2346 West St. Paul Avenue in the City of Waukesha, Waukesha County, Wisconsin (the "Site" or "subject property") between September 20, 2020 and November 2021 since redevelopment of the Site has started. The location of the Site is depicted on **Figure B.1.a –Location Map**. The bounds of the subject property are depicted on **Figure B.1.b – Detailed Site Map**.

1.1 SITE NAME AND ADDRESS

Klinke Cleaners – Fox Run 2346 West St. Paul Avenue Waukesha, Wisconsin BRRTS #: 02-68-535535 FID #: 268188910

1.2 LOCATIONAL INFORMATION

The Former Klinke Cleaners site is located on a parcel identified with Tax Key WAKC1328999001 totaling approximately 11.6-acres. The Site is the former location of four (4) separate structures including: a commercial strip mall (2306 to 2350 West St. Paul Avenue) where Klinke Cleaners was formerly located in the 2346 West St. Paul Avenue tenant space (2346 tenant space), a Sentry grocery store (2304 West St. Paul Avenue), an occupied Chase Bank branch (2302 West St. Paul Avenue) and a vacant former Denny's restaurant (2300 West St. Paul Avenue). As part of the redevelopment process, the strip mall, Denny's restaurant and Sentry grocery store were demolished. An unimproved 1.7815-acre parcel adjoins the aforementioned parcel to the west. The Site is located in the Southeast ¼ of the Southeast ¼ of Section 8, Township 6 North, Range 19 East. WTM coordinates for the approximate center of the Site are 661,073 / 281,170.

1.3 SITE OWNER / RESPONSIBLE PARTY

Fox Run 3, LLC c/o VJS Development Group W233N2847 Roundy Circle West Pewaukee, WI 53072

Contact: Ms. Bailey Copeland

Phone: 262-893-1720

Email: bcopeland@vjsdevelopment.com

1.4 Environmental Consultant

Endpoint Solutions Corp. (Endpoint) 6871 South Lovers Lane Franklin, WI 53132

Contact: Mr. Robert Cigale Phone: 414-858-1202

Email: bob@endpointcorporation.com



1.5 SITE TOPOGRAPHY

The Site is relatively flat and is situated at an elevation of approximately 802 feet above mean sea level (ft amsl). The surface topography in the vicinity of the Site slopes gently to the east. The nearest surface water body is the Fox River located approximately 500 feet to the east. Based upon groundwater flow data previously collected on the Site and topographic map interpretation, the direction of shallow groundwater flow beneath the subject property is primarily to the northeast.

2.0 BACKGROUND

2.1 SITE HISTORY

The original development on the subject property consisted of a farmstead in the southeast corner of the subject property near the intersection of Sunset Drive and St. Paul Avenue. The remainder of the subject property appeared to have been utilized as a cultivated field. Based on a review of historical aerial photographs, the agricultural use of the subject property was observed from prior to 1941 through circa 1970. By 1980, the farmstead had been removed and the Site was developed with three (3) structures consisting of the Fox Run Shopping Center along the north portion of the Site, the Sentry store in the southwest corner of the Site and the former Denny's restaurant in the eastern portion of the Site, with the majority of the remaining area paved for use as parking around the buildings.

In September 2004, Drake Environmental, Inc. (Drake) conducted a limited Phase II Environmental Assessment (EA) of the Klinke Cleaners site. Soil analytical results indicated elevated concentrations of tetrachloroethene (PCE) and groundwater analytical results indicated elevated concentrations of PCE, trichloroethene (TCE), toluene, cis-1,2-dichloroethene, isopropylbenzene and methyl tert-butyl ether (MTBE). Based on the results from the initial Phase II EA performed by Drake, additional assessment was recommended and the WDNR was notified of the contamination on October 29, 2004. The resulting open Wisconsin Department of Natural Resources (WDNR) Environmental Repair Program (ERP) case (BRRTS #: 02-68-535535) discussed herein is the only documented release on the Site. No other previously reported discharges have been noted on the subject property.

Following numerous iterations of investigative activities performed between 2004 and 2021, the extent of the contamination in the soil was delineated to the degree that the WDNR approved the proposed redevelopment plans for the Site, including the management of residually contaminated soils excavated as part of the proposed redevelopment in an onsite location (WDNR Letter – April 5, 2021). At the time the Soil Management Plan was approved, the WDNR requested that groundwater continued to be monitored through the construction phase to determine whether changes to the Site due to the proposed redevelopment affected the groundwater regime.

2.2 REDEVELOPMENT PLAN

The Site redevelopment includes three (3) two (2) story apartment buildings with a single level of underground parking in each. A depiction of the proposed redevelopment of the Site is shown on **Figure B.1.c**. Two (2) of the apartment buildings are located directly to the south of the delineated area of soil and groundwater contamination associated with the former dry-cleaning operation.



3.0 BACKGROUND

On February 9, 2021, Endpoint submitted a *NR 718 Material Management Plan* to the Wisconsin Department of Natural Resources (WDNR) to manage a small volume of potentially contaminated soil onsite for review and approval. Based on analytical results from soil samples collected during investigative activities, two (2) small isolated areas of low concentration PCE-contaminated soils were identified within areas that would require excavation as part of the redevelopment plan for the Site. A small area in the northeast corner of the 16-unit building was identified as having an estimated PCE concentration of 0.042 micrograms per kilogram (μ g/kg) at six (6) to eight (8) feet below the ground surface (ft bgs). The subgrade elevation for the building at this location was approximately six and one-half (6.5) ft bgs. In addition, an area on the ramp to the underground parking level in the 24-unit building contained elevated concentrations of PCE ranging between 0.14 μ g/kg to 0.82 μ g/kg from the ground surface to approximately five and one-half (5.5) ft bgs. The required cut in this area was approximately three (3) ft bgs.

On April 5, 2021, the WDNR approved the Material Management Plan within the Area of Contamination as outlined in Figure B.2.c. The Material Management Plan proposed placing the potentially contaminated soils excavated from these two (2) locations within the screening berm constructed on the north side of the Site. The potentially contaminated soils were to be placed in the berm such that the contaminated soils would be covered with a minimum two (2) feet of clean compacted soil.

4.0 OBSERVATIONS AND DOCUMENTATION

4.1 SANITARY SEWER TRENCH ABANDONMENT

Prior to Site redevelopment activities, a gravity sanitary sewer was located approximately seven (7) feet south of the Property line and is located beneath the groundwater table and was assumed to be installed in an open trench. This sanitary sewer conveyed sanitary wastes from the former Denny's restaurant, the existing Chase Bank branch and the former Sentry grocery store on the east side of the Fox Run Shopping Center, then westward along the north property line. This sanitary sewer was abandoned as part of the redevelopment to be replaced with a new sewer on the south side of the proposed residential developments. On August 26, 2020, Endpoint witnessed Veit excavate the sanitary sewer trench immediately west of Manhole MH4 and immediately east of Manhole MH2 to sever the sanitary sewer pipe and to remove any granular bedding and/or backfill within the pipe trench. Once the pipes were severed and the majority of the granular bedding materials were removed, the resulting excavations were backfilled with clean silty clay soils excavated from other portions of the Site. Photo-documentation of the sanitary sewer trench abandonment activities are included in **Appendix A**.

4.2 CONTAMINATED SOIL EXCAVATION AND RELOCATION

The excavation of the two (2) areas of contaminated soils were performed on June 4, 2021 and July 28, 2021. Prior to excavation of the basement and the ramp area, the line depicting the approximate extent of the soils exceeding the soil-to-groundwater pathway residual contaminant level (RCL) was staked by a surveyor using real-time kinetic global positioning system (RTK GPS) technology. Once the extent of approximate RCL exceedances was surveyed, the areas requiring excavation within the delineated area were addressed.

On June 4, 2021, the area in the northeast corner of the 16-unit building was excavated. All soils excavated within the surveyed extent of contaminated soil within the building footprint from the ground surface to the building subgrade elevation was excavated and transported to the screening berm constructed on the north side of the Site. As the screening berm had already been partially constructed, the excavation contractor excavated an area within the screening berm sufficient to deposit the volume of soil to be excavated while allowing for a minimum of two (2) feet of cover over the contaminated soils.

On July 28, 2021, the area within the ramp to the underground level of parking beneath the 24-unit building was excavated. The excavation of the ramp proceeding in the same method as the excavation of the northeast corner of the 16-unit building. After the area of concern was surveyed, the excavator direct-loaded the spoils into dump trucks which delivered the soil to an area within the screening berm. An area of the screening berm to the east of the area which was exposed for the deposit of the soils excavated from the northeast corner of the 16-unit building was prepared for depositing the soils excavated from the ramp. Again, the screening berm was prepared by excavating an area sufficient for the proposed volume of the contaminated soils while allowing for a minimum of two (2) feet of clean cover over the contaminated soils.



The locations of the areas of excavation of the contaminated soils and the approximate locations		
where the contaminated soils were placed within the screening berm are depicted on Figure B.2.c .		
Photographs taken during the excavation activities are provided in Appendix B .		

5.0 CONCLUSIONS

Per the conditions of the April 5, 2021 *Approval to Manage Contaminated Soil within the Area of Contamination,* potentially contaminated soils excavated from the northeast corner of the 16-unit building and the ramp to the underground parking level for the 24-unit building were managed onsite within the north screening berm within the previously established area of contamination. We estimate approximately 135 cubic yards of potentially contaminated soils, approximately 43 cubic yards from the 16-unit building and approximately 92 cubic yards from the ramp area, were transported and placed within the north screening berm.

Based on the potentially contaminated soils being placed in the screening berm within the delineated area of contamination beneath a minimum two (2) feet of clean soil, it is our opinion the potentially contaminated soil has been managed in accordance with the requirements of the approved Material Management Plan. Furthermore, it is our opinion, the placement of the potentially contaminated soils in the berm within the delineated area of contamination is protective of human health and the environment.




FIGURES


FIGURE B.1.A LOCATION MAP


FIGURE B.1.B DETAILED SITE MAP

FIGURE B.1.C PROPOSED SITE PLAN

FIGURE B.2.C CUT/FILL AREAS







APPENDIX A

SANITARY SEWER TRENCH ABANDONMENT PHOTO-DOCUMENTATION



1. Six-inch (6") sanitary sewer pipe removed from west of MH 4 at the northeast corner of the Site.

2. Excavating sanitary sewer trench west of MH 4 at the northeast corner of the Site.





3. Excavating sanitary sewer trench west of MH 4 at the northeast corner of the Site.

SITE PHOTOGRAPHS


2346 WEST ST. PAUL AVENUE

WAUKESHA, WISCONSIN





4. Backfilling sanitary sewer trench with compacted clay west of MH 4 at the northeast corner of the Site.







6. Compacted clay within the sanitary sewer trench west of MH 4 at the northeast corner of the Site.


SITE PHOTOGRAPHS

2346 WEST ST. PAUL AVENUE
WAUKESHA, WISCONSIN





7. Compacted clay within the sanitary sewer trench west of MH 4 at the northeast corner of the Site.







9. Excavating east of MH 2 with one (1) underground fiber optic utility exposed in the northwest corner of the Site.


SITE PHOTOGRAPHS

2346 WEST ST. PAUL AVENUE
WAUKESHA, WISCONSIN





10. Excavating east of MH 2 with two (2) underground fiber optic and one (1) underground electric utility exposed in the northwest corner of the Site.







12. Backfilled sanitary sewer trench east of MH 2 with compacted clay.

SITE PHOTOGRAPHS

2346 WEST ST. PAUL AVENUE
WAUKESHA, WISCONSIN



APPENDIX B

SOIL EXCAVATION AND RELOCATION PHOTO-DOCUMENTATION



1. 16-unit building excavation viewed from the east.

2. Approximate area of contaminated soils marked in northeast building corner.





3. View of the excavation profile looking into the area of contaminated soils.

SITE PHOTOGRAPHS

FOX DEN APARTMENTS
WAUKESHA, WISCONSIN





4. Screening berm along north boundary of the Site.

5. Area prepared in screening berm to accept contaminated soils.





6. Area prepared in screening berm to accept contaminated soils.

SITE PHOTOGRAPHS

FOX DEN APARTMENTS
WAUKESHA, WISCONSIN





7. Area prepared in screening berm to accept contaminated soils.

8. Location of prepared area of screening berm viewed from the south.





9. Excavation of contaminated soil area in progress.


SITE PHOTOGRAPHS

FOX DEN APARTMENTS
WAUKESHA, WISCONSIN





10. First load of contaminated soil being deposited in the screening berm.







12. Dozer spreading contaminated soil in prepared area of screening berm.

SITE PHOTOGRAPHS

FOX DEN APARTMENTS
WAUKESHA, WISCONSIN





13. First load deposited in screening berm.

14. Excavation of contaminated soils nearly complete.





15. Excavation of contaminated soils nearly complete.

SITE PHOTOGRAPHS

FOX DEN APARTMENTS
WAUKESHA, WISCONSIN





16. Excavation of contaminated soils complete.

17. Contaminated soils placed in screening berm ready for clean soil cover.



SITE PHOTOGRAPHS

FOX DEN APARTMENTS
WAUKESHA, WISCONSIN



Endpoint Solutions

6871 South Lovers Lane Franklin, Wisconsin 53132 Phone: 414-427-1200 Fax: 414-427-1259

www.endpointcorporation.com