State of Wisconsin Department of Natural Resources PO Box 7921, Madison WI 53707-7921

187

99

reports)

### Remediation & Redevelopment Continuing Obligation Review

Form 4400-232 (R 5/15)

Page 1 of 9

BRRTS I	No. 02-3	0-5537	65			Villa endante Nancia	
Reviewer: Ethan Guyant / Doug Cieslak				Region	: SE	Review Date:	07/27/2016
Site Name	e: Holiday	Village	e Coin Laundry				
ollow up	; ** denote	RP/pr	operty owner follow	nr.state.wi.us/int/aw/rr w up. If auditing a VPL n to add information no	E site, use the	ne applicable LUST or	
ile Revie	ew:						
. Review	BRRTS, a	and the	file if needed, to ic	dentify the File Review	information	:	
ite Addre	ess			C	ity		ZIP Code
4924 W	I-50			S	alem		53168
ounty Pa	arcel Identi	fication	Number (PIN)	F	FID Number		
0412003	341040			23	30037280		
riginal R	esponsible	Person	n				
oe Riess							
		en trans	sferred since the con	tinuing obligation was r	ecorded/appli	ed? ONo OYe	3
200	Current Pro		5445441 - 144 5 T 144 11 1 1 1			0,,5	
			n Properties LLC				
	hone Num		i Properties LLC	[Email			
	none mun		542,0522				
la tasta	a a mtimulina	, ,	542-0522	tom@tkolsen.com	al or latter to	LCII):	
		obligati	ions applied (at case	e closure of RAP approv	al or letter to	LGU).	
Add to BRRTS	AC in BRRTS	AC		Action	Code (AC)	Meaning	
DICICIO	DICKTO	51	Deed notice	Action	oode (AO)	neuming	
-		52	Deed restriction for	r soil			
		730	Groundwater use r				
		95	Deed instrument o	onditions met (for audits	s, use if deed	restriction was updated	by filing a deed
		101	notice)	modified - date DNR let	tor cont		
		101		GIS Registry - date DN	A STATE OF THE REAL PROPERTY.		
		696		on required of LGU to r		ty exemption	
		605		nt awarded (deed restric		ty exemption	
	×	56	The second secon	tion applied (use with co	V 1	1	
		220	Soil at industrial us		1000 220-230,		
	×	222		containment system (pa	avement soil	cover etc.)	
	×	224		nent (buildings or other		00,01, 010.)	
	×	226	Vapor mitigation/re		Ju dolar 63)		
		228		lify in comment field)			
		230		to take a protective acti	on		
	×	232		amination > RCLs/SS R		AC 220 222 2241	
	/	234		eds to be abandoned	o Lo (uoo witi	7.10 220, 222, 227	
	×	236		oundwater contamination	n > ES		
		238		inspection documentation		be submitted	
X		185	_	ce Review completed			
X		186		ce Review - RP follow u	p needed		

Closure Compliance Review follow up completed

Use this code with comments, for actions not listed under AC 186 (i.e. submittal of inspection

### BRRTS Number: 02-30-553765 Cor

Remediation & Redevelopment Continuing Obligation Review

Page 2 of 9

Form 4400-232 (R 5/15)

How was site selected for audit? (AC = BRRTS Action Code) ▼ Vapor Mitigation AC 226 Green Space Grant AC 605 Age of Remedy VPLE with AC 56 AC 220, 222, 224, 228, or 230 Complaint Received Enforcement Follow-up Deed Restriction AC 52 or 696 (LGU) Regional Priority Other: Date of: 02/24/2012 Remedial Action Plan Approval Certificate of Completion General Liability Clarification Letter Green Space Grant Local Gov't Unit (LGU) Letter Describe any site-specific requirements (AC 228) that the site owner and/or responsible party needed to address: Is the site on the GIS Registry? ○ No – Add it to the GIS Registry\* Yes Were neighboring properties affected? ( Yes ( ) No If yes, are these properties listed on the GIS Registry and in BRRTS? 

No - Update the GIS Registry/BRRTS, use form 4400-246\* Was a maintenance plan required at closure? ONA ONO Yes - It is: O in the file PDF O missing If no maintenance plan was required, offer the property owner the template model with inspection log, and note in the follow up section of the audit that one was provided on the audit date Was/were the appropriate restriction(s) recorded with the Register of Deeds? Yes ()No () NA Has a restriction been amended, or been nullified by DNR? \( \) No Yes: Was BRRTS updated? (95) O Yes O No\* Was the GIS Registry PDF updated? () Yes () No\* Notes: Site Visit: Contact the site owner for access. Provide a copy of the maintenance plan, if applicable. If the audit is being conducted for a CO which would now require a maintenance plan, provide a template version if no maintenance plan was required at closure, for the property owner's use (voluntary). Walk the site (ideally with the owner or responsible party) to review the site conditions against the conditions documented at closure/other to verify or change answers to questions in #1. Discuss use of the maintenance plan or template. 4. With the site owner/RP (if possible), answer the following for DNR RR records: Did the site owner know about the continuing obligation(s)? () No Have site conditions changed since closure that would affect either a deed restriction or other restrictions or requirements associated with the site? No

Examples: 1) a building has been razed and investigation and remediation occurred.

Yes - Explain:

2) excavation or residential development has occurred in a restricted area.

#### BRRTS Number: 02-30-553765

# Remediation & Redevelopment Continuing Obligation Review

Form 4400-232 (R 5/15)

Page 3 of 9

Has a pavement (asphalt or concrete) cover, soil cover or other sort of cover, such as a building, been removed or is it in disrepair?  No/NA  Yes - Should it be replaced or repaired? Yes** No  If a performance standard was the final remedy, has it been altered?  No  Yes - Explain:
Was the DNR notified?
Is soil sampling needed to determine if the final remedy has been modified such that a direct contact threat exists?  No Yes - Describe:
For example, an asphalt cover has been removed or is in disrepair, or a new contaminated site is present upgradient, etc.  Has additional monitoring or remediation been done since the site was closed?  No  Yes - Describe:
Does a new threat to public health or the environment exist (e.g. new sources or exposure routes)? <ul> <li>No</li> <li>Yes – Does sampling need to be performed?</li> <li>No</li> <li>Yes** – Describe what should be done to address the problem, and by whom:</li> </ul>
Is the vapor mitigation system or sub-slab depressurization system (SSDS) operating as designed? (pressure gradient being maintained)  Output  Output
Have any of the exposure assumptions used for closure changed at this site?  NA  No  Yes - Describe any follow up needed:
Has the land use at this site changed such that a vapor intrusion pathway may now exist?   No  Yes - Describe any follow up needed:

### Remediation & Redevelopment Continuing Obligation Review

Form 4400-232 (R 5/15)

Page 4 of 9

Has the land use changed such that there are either health or safety issues?	
No     No	
○ Yes - Describe any follow up needed:	
Notes:	
COMPLIANCE AND FOLLOW-UP SUMMARY:	
5. Identify compliance and any follow up needed.	
Is the site in compliance with the continuing obligations/closure approval document?	
○ Yes	
<ul> <li>No - Describe what's not in compliance and the reasons for noncompliance:</li> <li>Vapor mitigation system not operational. Fan not running.</li> </ul>	
(May depend on extent of non-compliance, non-maintenance of remedy or changed ownership or conditions. If case is out of compliance, it should be prioritized by the region, for new casework or enforcement, as needed.)	
Has the maintenance agreement required at closure been followed?	
○ Yes	
<ul> <li>No - Describe: Vapor mitigation system not operating and no maintenance logs kept.</li> <li>NA</li> </ul>	
Was the property owner reminded to complete and document the (yearly) inspections?	
Yes	
○ No - Why not?	
○ NA	
Was a maintenance plan or template provided to the property owner at the site visit?	
Yes	
○ No − If no, why not?	
○ NA	
6.** Are additional actions by the RP property owner warranted at the site? The intent is to return the site to complia with continuing obligation. If a significant land use change has occurred, and/or further remedial action is needed, determine if the site meets the NR 726 reopening criteria.)	nce
○ No	
Yes – Summarize the actions needed to return the site to compliance and identify who is responsible: Vapor mitigation system need to be repaired and operated and maintained as as designed. Electrical panel should clearly label dedicated circuit for vapor mitigation system.	
Notes:	

BRRTS Number: 02-30-553765

Add AC 186 for RP/property owner follow-up required. Use AC 99 if a reminder was provided to the property owner to complete and document inspections.

#### Remediation & Redevelopment Continuing Obligation Review

Form 4400-232 (R 5/15) Page 5 of 9

Date added: 07/29/2016

7	*	D	41		follow up	L. DNIDO
1		Does	the site	require	tollow up	DV DNR!

BRRTS Number: 02-30-553765

0	No	
•	Yes:	ontact or enforcement to return site to compliance with continuing obligation
		updating the GIS Registry (adding or modifying a packet)
		reopen site (add ACs 186, 12 and 13)
		other:

- 8. \* Attach photographs of the site, documenting site conditions. Label the photos with the site name/BRRTS Activity number/date/view. If a follow-up letter is sent, include a copy with the audit. (audit/photos/follow-up letter)
- 9. \* Save a copy of the audit using the following naming convention: BRRTS#\_COAUDIT\_Year.pdf (example: 0365001149\_COAUDIT\_2008.pdf).
- 10. Update applicable BRRTS action codes on the Table on page 1. Send a copy of the audit to your Regional EPA for updating ACs and uploading the PDF into BRRTS.
- 11. Notify Central Office when the audit has been completed and loaded into BRRTS.

{Click to Add/Edit Image File (\*.bmp;\*.jpg;\*.gif;\*.png;\*.tif)}



Title: Holiday Village Coin Laundry/0230553765/07272016/Radonaway RP145 Blower

## Remediation & Redevelopment Continuing Obligation Review

Date added: 07/29/2016

Form 4400-232 (R 5/15)

Page 6 of 9

{Click to Add/Edit Image File (\*.bmp;\*.jpg;\*.gif;\*.png;\*.tif)}



Title: Holiday Village Coin Laundry/0230553765/07272016/Radonaway RP145 Blower and outdoor switch

{Click to Add/Edit Image File (\*.bmp;\*.jpg;\*.gif;\*.png;\*.tif)}

Title: Holiday Village Coin Laundry/0230553765/07272016/PVC Vent Stack

Date added: 07/29/2016

Page 7 of 9

{Click to Add/Edit Image File (\*.bmp;\*.jpg;\*.gif;\*.png;\*.tif)}



Date added: 07/29/2016

Date added: 07/29/2016

Title: Holiday Village Coin Laundry/0230553765/07272016/Back of building and neighboring property cover

{Click to Add/Edit Image File (\*.bmp;\*.jpg;\*.gif;\*.png;\*.tif)}



Title: Holiday Village Coin Laundry/0230553765/07272016/Front of building cover

Form 4400-232 (R 5/15)

Page 8 of 9

{Click to Add/Edit Image File (\*.bmp;\*.jpg;\*.gif;\*.png;\*.tif)}

BRRTS Number: 02-30-553765



Title: Holiday Village Coin Laundry/0230553765/07272016/Piping sealed suction pint

{Click to Add/Edit Image File (\*.bmp;\*.jpg;\*.gif;\*.png;\*.tif)}



Title: Holiday Village Coin Laundry/0230553765/07272016/Vapor System Vacuum gauge

Date added: 07/29/2016

Date added: 07/29/2016

BRRTS Number: 02-30-553765


# Remediation & Redevelopment Continuing Obligation Review

Date added: 07/29/2016

Form 4400-232 (R 5/15)

Page 9 of 9

{Click to Add/Edit Image File (\*.bmp;\*.jpg;\*.gif;\*.png;\*.tif)}



Title: Holiday Village Coin Laundry/0230553765/07272016/Electric Panel