### **GIS REGISTRY**

### **Cover Sheet**

July, 2008 (RR 5367)

Source Pro	perty Information		CLOSURE DATE	E: Feb 24, 2012
BRRTS #:	02-30-553765			
ACTIVITY NAME:	HOLIDAY VILLAGE COIN LAUNDRY		FID #:	230037280
PROPERTY ADDRESS:	24924 71ST ST		DATCP #:	
MUNICIPALITY:	PADDOCK LAKE		COMM #:	
PARCEL ID #:				
	*WTM COORDINATES:	WTM COORDINATES	REPRESENT:	
3	X: <b>675004</b> Y: <b>234632</b>	C Approximate Center Of Co	ontaminant Sour	ce
	* Coordinates are in WTM83, NAD83 (1991)	Approximate Source Parce	el Center	
lease check as appr	opriate: (BRRTS Action Code)			
	Contamin	ated Media:		
▼ Gro	oundwater Contamination > ES (236)	▼ Soil Contamination	n > *RCL or **SSR	CL (232)
	Contamination in ROW	Contamination	n in ROW	
0.5%	Off-Source Contamination	▼ Off-Source Co		
	ote: for list of off-source properties "Impacted Off-Source Property")	( <b>note:</b> for list of off-so see "Impacted Off-So		
	Land Use	e Controls:		
×	Soil: maintain industrial zoning (220)	ズ Cover or Barr	ier <i>(222)</i>	
	ote: soil contamination concentrations ween residential and industrial levels)	( <b>note:</b> maintenanc groundwater or dire		
×	Structural Impediment (224)	▼ Vapor Mitigat	tion <i>(226)</i>	
Site Specific Condition (228)			oility Exemption (	(230)
		( <b>note:</b> local govern development corpo		
	Monitoring wells prop	perly abandoned? (234)		
	<b>⊚</b> Yes <b>○</b> N	lo ON/A		

<sup>\*</sup> Residual Contaminant Level \*\*Site Specific Residual Contaminant Level

State of Wisconsin

Department of Natural Resources http://dnr.wi.gov

### PLEASE ASSEMBLE IN THIS ORDER

### GIS Registry Checklist

Form 4400-245 (R 8/11)

Page 1 of 3

This Adobe Fillable form is intended to provide a list of information that is required for evaluation for case closure. It is to be used in conjunction with Form 4400-202, Case Closure Request. The closure of a case means that the Department has determined that no further response is required at that time based on the information that has been submitted to the Department.

NOTICE: Completion of this form is mandatory for applications for case closure pursuant to ch. 292, Wis. Stats. and ch. NR 726, Wis. Adm. Code, including cases closed under ch. NR 746 and ch. NR 726. The Department will not consider, or act upon your application, unless all applicable sections are completed on this form and the closure fee and any other applicable fees, required under ch. NR 749, Wis. Adm. Code, Table 1 are included. It is not the Department's intention to use any personally identifiable information from this form for any purpose other than reviewing closure requests and determining the need for additional response action. The Department may provide this information to requesters as required by Wisconsin's Open Records law [ss. 19.31 - 19.39, Wis. Stats.].

BRRTS #:	02-30-553765	(No Dashes)	PARCEL ID #:	40-4-120-034-1040		
ACTIVITY NAME:	HOLIDAY VILLA	GE COIN LAUNDRY		WTM COORDINATES:	X: Y:	
CLOSURE DOC	JMENTS (the D	epartment adds thes	se items to the	final GIS packet for posting o	on the Registry)	
	er					
<b>⊠</b> Maintenance	Plan (if activity i	is closed with a land use	limitation or con	dition (land use control) under s.	292.12, Wis. Stats.)	
Continuing Obligation Cover Letter (for property owners affected by residual contamination and/or continuing obligations)						
Conditional Closure Letter						
Certificate of Completion (COC) (for VPLE sites)						
SOURCE LEGAL DOCUMENTS						

Deed: The most recent deed as well as legal descriptions, for the Source Property (where the contamination originated). Deeds for other, off-source (off-site) properties are located in the **Notification** section.

**Note:** If a property has been purchased with a land contract and the purchaser has not yet received a deed, a copy of the land contract which includes the legal description shall be submitted instead of the most recent deed. If the property has been inherited, written documentation of the property transfer should be submitted along with the most recent deed.

Certified Survey Map: A copy of the certified survey map or the relevant section of the recorded plat map for those properties where the legal description in the most recent deed refers to a certified survey map or a recorded plat map. (lots on subdivided or platted property (e.g. lot 2 of xyz subdivision)).

Title: Figure #: 1

Signed Statement: A statement signed by the Responsible Party (RP), which states that he or she believes that the attached legal description accurately describes the correct contaminated property.

### MAPS (meeting the visual aid requirements of s. NR 716.15(2)(h))

Maps must be no larger than  $11 \times 17$  inches unless the map is submitted electronically.

Location Map: A map outlining all properties within the contaminated site boundaries on a U.S.G.S. topographic map or plat map in sufficient detail to permit easy location of all parcels. If groundwater standards are exceeded, include the location of all potable wells within 1200 feet of the site.

**Note:** Due to security reasons municipal wells are not identified on GIS Packet maps. However, the locations of these municipal wells must be identified on Case Closure Request maps.

Figure #: Title: Topo Map

Detailed Site Map: A map that shows all relevant features (buildings, roads, individual property boundaries, contaminant sources, utility lines, monitoring wells and potable wells) within the contaminated area. This map is to show the location of all contaminated public streets, and highway and railroad rights-of-way in relation to the source property and in relation to the boundaries of groundwater contamination exceeding a ch. NR 140 Enforcement Standard (ES), and/or in relation to the boundaries of soil contamination exceeding a Residual Contaminant Level (RCL) or a Site Specific Residual Contaminant Levels (SSRCL) as determined under s. NR 720.09, 720.11 and 720.19.

#### Figure #: 1 **Title: Site Features**

Soil Contamination Contour Map: For sites closing with residual soil contamination, this map is to show the location of all contaminated soil and a single contour showing the horizontal extent of each area of contiguous residual soil contamination that exceeds a Residual Contaminant Level (RCL) or a Site Specific Residual Contaminant Level (SSRCL) as determined under s. NR 720.09, 720.11 and 720.19.

Title: Estimated Extent of PCE Contaminated Soil Figure #: 3

State of Wisconsin
Department of Natural Resources
http://dnr.wi.gov

GIS Registry Checklist
Form 4400-245 (R 8/11) Page 2 of 3

BRRTS #: 02-30-553765 ACTIVITY NAME: HOLIDAY VILLAGE COIN LAUNDRY

### MAPS (continued)

Geologic Cross-Section Map: A map showing the source location and vertical extent of residual soil contamination exceeding a Residual Contaminant Level (RCL) or a Site Specific Residual Contaminant Level (SSRCL). If groundwater contamination exceeds a ch. NR 140 Enforcement Standard (ES) when closure is requested, show the source location and vertical extent, water table and piezometric elevations, and locations and elevations of geologic units, bedrock and confining units, if any.

Figure #: 4 Title: Cross-Section Identification

Figure #: 5 Title: North - South Cross Section

Groundwater Isoconcentration Map: For sites closing with residual groundwater contamination, this map shows the horizontal extent of all groundwater contamination exceeding a ch. NR140 Preventive Action Limit (PAL) and an Enforcement Standard (ES). Indicate the direction and date of groundwater flow, based on the most recent sampling data.

**Note:** This is intended to show the total area of contaminated groundwater.

Figure #: 6 Title: Estimated Extent of Contaminated Groundwater

Groundwater Flow Direction Map: A map that represents groundwater movement at the site. If the flow direction varies by more then 20° over the history of the site, submit 2 groundwater flow maps showing the maximum variation in flow direction.

Figure #: 6 Title: Groundwater Elevations 4/27/2011

Figure #: Title:

### TABLES (meeting the requirements of s. NR 716.15(2)(h)(3))

Tables must be no larger than 11 x 17 inches unless the table is submitted electronically. Tables <u>must not</u> contain shading and/or cross-hatching. The use of **BOLD** or *ITALICS* is acceptable.

Soil Analytical Table: A table showing <u>remaining</u> soil contamination with analytical results and collection dates.

**Note:** This is one table of results for the contaminants of concern. Contaminants of concern are those that were found during the site investigation, that remain after remediation. It may be necessary to create a new table to meet this requirement.

Table #: 1 Title: Analytical Results - Soil

Groundwater Analytical Table: Table(s) that show the <u>most recent</u> analytical results and collection dates, for all monitoring wells and any potable wells for which samples have been collected.

Table #: 2 Title: Analytical Results - Groundwater

Water Level Elevations: Table(s) that show the previous four (at minimum) water level elevation measurements/dates from all monitoring wells. If present, free product is to be noted on the table.

Table #: Title: Not Available

### **IMPROPERLY ABANDONED MONITORING WELLS**

For each monitoring well <u>not</u> properly abandoned according to requirements of s. NR 141.25 include the following documents. **Note:** If the site is being listed on the GIS Registry for only an improperly abandoned monitoring well you will only need to submit the documents in this section for the GIS Registry Packet.

do	cuments in this section for the GIS Registry Packet.
X	Not Applicable
	Site Location Map: A map showing all surveyed monitoring wells with specific identification of the monitoring wells which

**Note:** If the applicable monitoring wells are distinctly identified on the Detailed Site Map this Site Location Map is not needed.

Figure #: Title:

not been properly abandoned.

Well Construction Report: Form 4440-113A for the applicable monitoring wells.

Deed: The most recent deed as well as legal descriptions for each property where a monitoring well was not properly abandoned.

Notification Letter: Copy of the notification letter to the affected property owner(s).

State of Wisconsin	GIS Registry Checklist				
Department of Natural Resources http://dnr.wi.gov	Form 4400-245 (R 8/11)	Page 3 of 3			

BRRTS #: 02-30-553765 ACTIVITY NAME: HOLIDAY VILLAGE COIN LAUNDRY

NC	ITC	FI	CA	TI	OI	NS

So	ur	ce	Pı	ro	pe	rty
So	ur	ce	Pi	ro	pe	rty

Letter To Current Source Property Owner: If the source property is owned by someone other than the person who is applying for case closure, include a copy of the letter notifying the current owner of the source property that case closure has been requested.

Return Receipt/Signature Confirmation: Written proof of date on which confirmation was received for notifying current source property owner.

### **Off-Source Property**

Group the following information per individual property and label each group according to alphabetic listing on the "Impacted Off-Source Property" attachment.

### ■ Not Applicable

Example 2015 Note: Note

**Note:** Letters sent to off-source properties regarding residual contamination must contain standard provisions in Appendix A of ch. NR 726.

### Number of "Off-Source" Letters: 1

- Return Receipt/Signature Confirmation: Written proof of date on which confirmation was received for notifying any off-source property owner.
- Deed of "Off-Source" Property: The most recent deed(s) as well as legal descriptions, for all affected deeded off-source property(ies). This does not apply to right-of-ways.

**Note:** If a property has been purchased with a land contract and the purchaser has not yet received a deed, a copy of the land contract which includes the legal description shall be submitted instead of the most recent deed. If the property has been inherited, written documentation of the property transfer should be submitted along with the most recent deed.

Certified Survey Map: A copy of the certified survey map or the relevant section of the recorded plat map for those properties where the legal description in the most recent deed refers to a certified survey map or a recorded plat map. (lots on subdivided or platted property (e.g. lot 2 of xyz subdivision)).

Figure #: Title: County Printout

Letter To "Governmental Unit/Right-Of-Way" Owners: Copies of all letters sent by the Responsible Party (RP) to a city, village, municipality, state agency or any other entity responsible for maintenance of a public street, highway, or railroad right-of-way, within or partially within <a href="maintenance">the contaminated area</a>, for contamination exceeding a groundwater Enforcement Standard (ES) and/or soil exceeding a Residual Contaminant Level (RCL) or a Site Specific Residual Contaminant Level (SSRCL).

Number of "Governmental Unit/Right-Of-Way Owner" Letters:

Department of Natural Resources	Impacted Off-Source Property Information Form 4400-246 (R 3/08)
http://dnr.wi.gov	101111 4-400 2-40 (IT 5/00)

This fillable form is intended to provide a list of information that must be submitted for evaluation for case closure. It is to be used in conjunction with Form 4400-202, Case Closure Request (Section H). The closure of a case means that the Department has determined that no further response is required at that time based on the information that has been submitted to the Department.

NOTICE: Completion of this form is mandatory for applications for case closure pursuant to ch. 292, Wis. Stats. and ch. NR 726, Wis. Adm. Code, including cases closed under ch. NR 746 and ch. NR 726. The Department will not consider, or act upon your application, unless all applicable sections are completed on this form and the closure fee and any other applicable fees, required under ch. NR 749, Wis. Adm. Code, Table 1 are included. It is not the Department's intention to use any personally identifiable information from this form for any purpose other than reviewing closure requests and determining the need for additional response action. The Department may provide this information to requesters as required by Wisconsin's Open Records law [ss. 19.31 - 19.39, Wis. Stats.].

BRRTS #	: 02-30-553765 (No Dashes) Y NAME: HOLIDAY COIN LAUNDRY			
ID .	Off-Source Property Address	Parcel Number	WTM X	WTM Y
В	LOTS 14 AND 15 OF PADDOCK LAKE HIGHLANDS	4041200341050 AND 4041200341055	674975	234635
C				
D				
E				
F				
G				
Н				

State of Wisconsin
DEPARTMENT OF NATURAL RESOURCES
Sturtevant Service Center
9531 Rayne Rd
Sturtevant WI 53177

Scott Walker, Governor Cathy Stepp, Secretary Telephone 608-266-2621 Toll Free 1-888-936-7463 TTY Access via relay - 711



February 24, 2012

Mr. Joe Riesselmann 24909 71<sup>st</sup> St. Paddock Lake, WI 53168

### KEEP THIS DOCUMENT WITH YOUR PROPERTY RECORDS

SUBJECT:

Final Case Closure with Continuing Obligations for Holiday Village Coin Laundry,

24924 71st St., Paddock Lake, WI FID 230037280, BRRTS 02-30-553765

Dear Mr. Riesselmann:

The Department of Natural Resources (DNR) considers Holiday Village Coin Laundry closed, with continuing obligations. No further investigation or remediation is required at this time. However, you and future property owners must comply with the continuing obligations as explained in the conditions of closure in this letter. Please read over this letter closely to ensure that you comply with all conditions and other on-going requirements. Provide this letter and any attached maintenance plan to anyone who purchases this property from you.

This final closure decision is based on the correspondence and data provided, and is issued under ch. NR 726, Wisconsin Administrative Code. The Southeast Region's Closure Committee reviewed the request for closure on October 6, 2011. The Closure Committee reviews environmental remediation cases for compliance with state laws and standards to maintain consistency in the closure of these cases. A closure denial letter was issued by the DNR on October 7, 2011, and documentation that the conditions in that letter were met was received on February 23, 2012.

An operating drycleaner utilizing PCE was at the property from 1980 until 1998. The facility is currently a coin operated laundromat with dry-cleaning drop-off. Site investigation indicates the most likely source of the contamination on the property was from fugitive emissions from venting of the former dry cleaning machine. The conditions of closure and continuing obligations required were based on the property being used for a slab on grade laundromat with commercial use purposes.

### Continuing Obligations

The continuing obligations for this site are summarized below. Further details on actions required are found in the section Closure Conditions.

Groundwater contamination is present above ch. NR 140, Wis. Adm. Code enforcement standards.

- Residual soil contamination exists that must be properly managed should it be excavated or removed.
- -Pavement, an engineered cover or a soil barrier must be maintained over contaminated soil and the DNR must approve any changes to this barrier.
- If a structural impediment that obstructed a complete site investigation or cleanup is removed or modified, additional environmental work must be completed.
- A sub-slab depressurization venting system is installed beneath the building must be operated and maintained, and inspections must be documented.



- Remaining soil contamination could result in vapor intrusion if future construction activities occur. If new building construction is planned, vapor control technologies will be required for occupied buildings, unless the property owner assesses the potential for vapor intrusion, and the DNR agrees that conditions are protective of the new use.

### **GIS Registry**

This site will be listed on the Remediation and Redevelopment Program's internet accessible Geographic Information System (GIS) Registry, to provide notice of residual contamination and of any continuing obligations. DNR approval prior to well construction or reconstruction is required for all sites shown on the GIS Registry, in accordance with s. NR 812.09(4) (w), Wis. Adm. Code. To obtain approval, complete and submit Form 3300-254 to the DNR Drinking and Groundwater program's regional water supply specialist. This form can be obtained on-line at <a href="http://dnr.wi.gov/org/water/dwg/3300254.pdf">http://dnr.wi.gov/org/water/dwg/3300254.pdf</a> or at the web address listed below for the GIS Registry.

All site information is also on file at the Southeast Region's Sturtevant Regional DNR office, at 9531 Rayne Road, Sturtevant, WI 53177. This letter and information that was submitted with your closure request application, including the maintenance plan, will be included on the GIS Registry in a PDF attachment. To review the site on the GIS Registry web page, visit the RR Sites Map page at <a href="http://dnr.wi.gov/org/aw/rr/gis/index.htm">http://dnr.wi.gov/org/aw/rr/gis/index.htm</a>.

### **Prohibited Activities**

Certain activities are prohibited at closed sites because maintenance of a barrier is intended to prevent contact with any remaining contamination. When a barrier is required, the condition of closure requires notification of the DNR before making a change, in order to determine if further action is needed to maintain the protectiveness of the remedy employed. The following activities are prohibited on any portion of the property where pavement, an engineered cover or other barrier, a vapor mitigation system or barrier is required, as shown on the **attached** map, unless prior written approval has been obtained from the DNR:

- removal of the existing barrier;
- replacement with another barrier;
- excavating or grading of the land surface;
- filling on covered or paved areas;
- plowing for agricultural cultivation;
- construction or placement of a building or other structure;
- changing the use or occupancy of the property to a residential exposure setting, which may include certain uses, such as single or multiple family residences, a school, day care, senior center, hospital, or similar residential exposure settings;
- changing the construction of a building that has either a passive or active vapor mitigation system in place.
   Closure Conditions

Compliance with the requirements of this letter is a responsibility to which you, and any subsequent property owners must adhere. DNR staff will conduct periodic prearranged inspections to ensure that the conditions included in this letter and the attached maintenance plans are met. If these requirements are not followed, the DNR may take enforcement action under s. 292.11, Wisconsin Statutes to ensure compliance with the specified requirements, limitations or other conditions related to the property.

Residual Groundwater Contamination (ch. NR 140, 812, Wis. Adm. Code)

Groundwater contamination greater than enforcement standards is present on this contaminated property, as shown on the **attached map**. If you intend to construct a new well, or reconstruct an existing well, you'll need prior DNR approval.

Residual Soil Contamination (ch. NR 718, chs. 500 to 536, Wis. Adm. Code or ch. 289, Wis. Stats.)

Soil contamination remains as indicated on the **attached map**. If soil in the specific locations described above is excavated in the future, the property owner at the time of excavation must sample and analyze the excavated soil to determine if contamination remains. If sampling confirms that contamination is present, the property owner at the time of excavation will need to determine whether the material is considered solid or hazardous waste and ensure that any storage, treatment or disposal is in compliance with applicable standards and rules. In addition, all current and future owners and occupants of the property need to be aware that excavation of the contaminated soil may pose an inhalation or other direct contact hazard and as a result special precautions may need to be taken to prevent a direct contact health threat to humans.

<u>Cover or Barrier</u> (s. 292.12 (2) (a), Wis. Stats.)

The pavement and building that exists in the location shown on the **attached map** shall be maintained in compliance with the **attached maintenance plan** in order to minimize the infiltration of water and prevent additional groundwater contamination that would violate the groundwater quality standards in ch. NR 140, Wis. Adm. Code, and to prevent direct contact with residual soil contamination that might otherwise pose a threat to human health.

In this case, the building is also considered a structural impediment, and additional investigation and response requirements apply as described in the section titled <u>Structural Impediments</u>.

A cover or barrier for industrial land uses, or certain types of commercial land uses may not be protective if use of the property were to change such that a residential exposure would apply. This may include, but is not limited to single or multiple family residences, a school, day care, senior center, hospital or similar settings. Before using the property for such purposes, you must notify the DNR to determine if additional response actions are warranted.

A request may be made to modify or replace a cover or barrier. The replacement or modified cover or barrier must be protective of the revised use of the property, and must be approved in writing by the DNR prior to implementation.

The attached maintenance plan and inspection log are to be kept up-to-date and on-site. Submit the inspection log to the DNR only upon request.

Structural Impediments (s. 292.12 (2) (b), Wis. Stats.)

The building, as shown on the **attached map**, made complete investigation and/or remediation of the soil contamination on this property impracticable. If the structural impediment is to be removed, the property owner shall notify the DNR before removal and conduct an investigation of the degree and extent of chlorinated compounds, PCE and TCE contamination below the structural impediment. If contamination is found at that time, the contamination shall be properly remediated in accordance with applicable statutes and rules.

Vapor Mitigation or Evaluation (s. 292.12 (2), Wis. Stats.)

Vapor intrusion is the movement of vapors coming from volatile chemicals in the soil or groundwater, into buildings where people may breathe air contaminated by the vapors. Vapor mitigation systems are used to interrupt the pathway, thereby reducing or preventing vapors from moving into the building.

Soil vapor beneath the building contains chlorinated VOC's at levels that would pose a long-term risk to human health, if allowed to migrate into an occupied building on the property. The vapor mitigation system, installed on December 28, 2011, must be operated, maintained and inspected in accordance with the attached maintenance plan. System components must be repaired or replaced immediately upon discovery of a malfunction. Annual inspections and any system repairs must be documented in the inspection log. The inspection log shall be kept up-to-date and on-site. Submit the inspection log to the DNR only upon request.

The integrity of the floor, building, pavement or other impervious cap that exists on the property, shown on the attached map, must be maintained in compliance with the attached maintenance plan. This will help ensure proper functioning of the vapor mitigation system, limiting vapor intrusion to indoor air spaces.

Please send written notifications in accordance with the above requirements to Southeast Region, to the attention of Victoria Stovall, Environmental Program Associate, 2300 North Dr. Martin Luther King Jr. Dr., Milwaukee, WI 53212.

Please be aware that the case may be reopened pursuant to s. NR 726.09, Wis, Adm. Code, if additional information regarding site conditions indicates that contamination on or from the site poses a threat to public health, safety, or welfare or to the environment.

The DNR appreciates your efforts to restore the environment at this site. If you have any questions regarding this closure decision or anything outlined in this letter, please contact Shanna L. Laube-Anderson at 262-884-2341.

Sincerely,

Flances M. Koonce

Frances M. Koonce, Team Supervisor

Southeast Region Remediation & Redevelopment Program

Cc: Pete Pavalko, PEP Environmental Svc. LLC, 7147 Cedar Sauk Rd., Saukville, WI 53080

Attach:

Maintenance Plan which includes referenced maps

### UPDATED PAVEMENT COVER AND BUILDING BARRIER MAINTENANCE PLAN

Date: February 23, 2012

### **Property Located at:**

Holiday Village Coin Laundry (HVCL) site 24924 75th Street, Village of Paddock Lake, Kenosha County, Wisconsin. WDNR BRRTS #: 02-30-553765 and FID #230037280. Tax Parcel ID #: 40-4-120-034-1040. PEP Project No. 29004.01

### Introduction

This document is the Maintenance Plan for a pavement cover and building barrier at the above-referenced property and the adjacent Frontier Communications (formerly Verizon) property, adjacent to and west of the HVCL site, in accordance with the requirements of s. NR 724.13(2), Wisconsin Administrative Code. The maintenance activities relate to the existing slab on grade buildings and other paved surfaces occupying the area over the contaminated soil on-site. The contaminated soil is impacted by dry cleaning related VOCs, including tetrachloroethene (PCE), cis-1,2-dichloroethene, trans-1,2-dichloroethene, and trichloroethene (TCE). The location of the paved surfaces and buildings to be maintained in accordance with this Maintenance Plan, as well as the impacted soil are identified in the attached map (Exhibit A).

### Cover and Building Barrier Purpose - HVCL

The paved surfaces and the building foundation over the contaminated soil serve as a barrier to prevent direct human contact with residual soil contamination that might otherwise pose a threat to human health. These paved surfaces and building foundation also act as a partial infiltration barrier to minimize future soil-to-groundwater contamination migration that could violate the groundwater standards in ch. NR 140, Wisconsin Administrative Code. Based on the current and future use of the property, the barrier should function as intended unless disturbed.

### Cover and Building Barrier Purpose – Frontier Communications Building

The Frontier Communications building is an unoccupied switching station located immediately west of the HVCL site. Despite numerous attempts to try and gain entry into the Frontier property to determine if contamination was present, Frontier refused to acknowledge or respond in any way to our requests and would not grant access. Therefore, we have no choice but to assume that the PCE-related contamination from HVCL has migrated onto the Frontier property. Consequently, he Frontier property is included in this maintenance plan. The property consists of a simple rectangular slab on grade brick building, a paved parking area on the north side of the building, and grass covered areas on the west, south, and east sides of the building. The grass covered, paved surfaces, and the building foundation over any potentially contaminated soil will serve as a barrier to prevent direct human contact

Page Two
Holiday Village Coin Laundry – Barrier Maintenance Plan
WDNR BRRTS #: 02-30-553765

with residual soil contamination that might otherwise pose a threat to human health. This property is only infrequently visited by telecommunication technicians and is not regularly occupied and never utilized by retail customers. The biggest risk at this site is presented by the potential for utility work at the site, like the installation, repair, or maintenance of communication lines into the switching station building. However, we have notified Frontier Communications of this potential and it will be there responsibility to manage and monitor any soil excavation at the site.

### Annual Inspection

The paved surfaces and building foundation overlying the contaminated soil and as depicted in Exhibit A will be inspected once a year, normally in the spring after all snow and ice is gone, for deterioration, cracks and other potential problems that can cause additional infiltration into or exposure to underlying soils. The inspections will be performed to evaluate damage due to settling, exposure to the weather, wear from traffic, increasing age and other factors. Any area where soils have become or are likely to become exposed will be documented. A log of the inspections and any repairs will be maintained by the property owner and is included as Exhibit B, Cap Inspection Log. The log will include recommendations for necessary repair of any areas where underlying soils are exposed. Once repairs are completed, they will be documented in the inspection log.

A copy of the inspection log will be sent to the Wisconsin Department of Natural Resources ("WDNR") at least annually after every inspection, unless otherwise directed in the case closure letter.

### **Maintenance Activities**

If problems are noted during the annual inspections or at any other time during the year, repairs will be scheduled as soon as practical. Repairs can include patching and filling operations or they can include larger resurfacing or construction operations. In the event that necessary maintenance activities expose the underlying soil, the owner must inform maintenance workers of the direct contact exposure hazard and provide them with appropriate personal protection equipment ("PPE"). The owner must also sample any soil that is excavated from the site prior to disposal to ascertain if contamination remains. The soil must be treated, stored and disposed of by the owner in accordance with applicable local, state and federal law.

In the event the paved surfaces and/or the building overlying the contaminated soil are removed or replaced, the replacement barrier must be equally impervious. Any replacement barrier will be subject to the same maintenance and inspection guidelines as outlined in this Maintenance Plan unless indicated otherwise by the WDNR or its successor.

Page Three
Holiday Village Coin Laundry – Barrier Maintenance Plan
WDNR BRRTS #: 02-30-553765

The property owner, in order to maintain the integrity of the paved surfaces and the building, will maintain a copy of this Maintenance Plan on-site and make it available to all interested parties (i.e. on-site employees, contractors, future property owners, etc.) for viewing.

### **Sub-Slab Depressurization System**

On December 28, 2011, American Radon Removal Co., LLC, installed a sub-slab depressurization system in the southwest corner of the building. The purpose of the system is to collect and draw potential PCE vapors from below the concrete foundation slab and prevent them from entering the building. The system was installed by extending PVC piping through the concrete slab foundation in the location of the former dry cleaning equipment and suction is generated by a Radonaway RP145 blower mounted externally to the building's west wall. A schematic of the system is provided in Appendix A. In conjunction with the cap maintenance plan, this sub-slab depressurization system is required to operate continuously until the PCE contaminated soil is remediated.

### **Amendment or Withdrawal of Maintenance Plan**

This Maintenance Plan can be amended or withdrawn by the property owner and its successors with the written approval of WDNR.

Contact Information Mr. Joe Riesselmann 24909 71<sup>st</sup> Street Paddock Lake, WI 53168

Cell Phone: 262-206-8109 Site Phone: 262-843-3000

Consultant:


Peter E. Pavalko PEP Environmental Services, LLC 7147 Cedar Sauk Road Saukville, WI 53080 Cell Phone: 414-801-1730

WDNR: Shanna Laube-Anderson WDNR 9531 Rayne Road Sturtevant, WI 53177

Phone: 262-884-2341


Attachment

Figure 3 - Estimated Extent of PCE Contaminated Soil




Attachment

### re 6 - Estimated Extent of Contaminated Groundwater



### Sub-Slab Depressurization Schematic



### Exhibit B

### **Barrier Inspection Log**

Inspection Date:	-		
Inspector:	•9		
Condition of Cap:		8	
	water water		
			7.
	_K		
Have Previous Recommendations Been Implemented:			
Condition of Sub-Slab Depressurization System:			ě

### AMERICAN RADON REMOVAL CO. LLC

6421 94th Avenue • Kenosha, WI 53142
Ph: (262) 657-9000 • Cell: (262) 818-3884 • Fax: (262) 657-9059
E-mail: jtenutal@wi.rr.com • www.americanradonremoval.com

## Radon Systems Diagram Work Order/Invoice

### Home & Owner Information

Seller Re	SELMAN	Pho	ne (home)	Phone (work)	Phone (other)
Buyer HOLIOAY	<b>《唐·八</b> 斯·斯斯·斯·斯斯·斯斯·斯斯·斯斯·斯斯·斯斯·斯斯·斯斯·斯斯·斯斯·斯斯	( GANEDS			
Z49Z4	The company of the second of the	Cry P4 o	DOCK LAKE	State	Zip code
Year Built	Construction type	Basement	Finished	# of Stories	Crawl Space
Radon Level	Sump Pit	Pump type		Sump Pump Installe	ed or Replaced
System Descrip	tion				State Control of the State Con
SSD SPD	SMD	Fan type RP145	System Vacuum		, WCI
Fan Location		(24. p. 4-4.25 p 10.11.2)	Exhaust Location		
	102 - SIC			ofline	
KAF	きじんりょ	m For D	RY CLFAR	JING FUI	พธร
Additional Information	POSITIVE	Suction	UNDER	SLAR	
I hereby affirm the			Materials	& Labor	Total
the above location l	has been installed ac	ion System installed a cording to the protocol	Basic Un		698.00
National Environm	ental Health Associa	gency (U.S.E.P.A.), the ation (N.E.H.A.), and		ttic Installed	
in compliance with (I.D.N.S.) for Rado	the Illinois Departs	nent of Nuclear Safety	/ Sump Pur	np	
		tund	Crawl Spa	ace	
	/ geff T		Fan		
		License# 101809RM7 License# RNM99205	Suction Po	oints	
			Mileage		
			Labor		
			Other		
THE RESERVE AND AND ADDRESS OF THE PARTY OF		to the state of the state of the state of	· Outer		

I hereby acknowledge that the Radon Reduction system herein described has been installed and the system's operation has been explained to me

2.45年的原始的表現的問題計				grafication for the state of the state of				
Signature: (Homeo	Wear FIN	Van	7. 7. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4.	2006年1月18日 1988年1月1日				
orginature, (110lineo	WHELL IN THE	a national designation and the		(1)。11年本日,11月1日)。12		Date:		254
CONTRACTOR SERVICES	在中国中国的社会和企业,15-11			will be the second of the second	(B. 14. 1104 A. 11. 11. 11. 11. 11. 11. 11. 11. 11.		PRINCIPLE OF	Merchania.

	DOCUMENT NO. TRANSFER	BTATE DAR OF WISCONSIN-FORM I WARRANTY DEED THIS SPACE RESERVED FOIL RECORDING DATA
	665799 \$ 3.00 . VOL 1071 :MLE 70	REGISTER'S OFFICE )9.5. Kenosha County, Wis.)
	THIS DEED, made between John Riesselmann and Sharon L.  Riesselmann, his wife	RECORDED AT LINE A. R. W
	Gruntor	ON 1.PR 1 6 1980 III
, i	andJoseph_RiesselmabhGruntue,	RECORDS VOL. 1071. P. 70
X 82	Witnesseth, That the used Grantor for a valuable consideration	A. FD
	convoys to Granton the following described rule entate in Kenosha	neffansen LAW OFFICE P. O. Box 12 Silver Lake, Wis. 53170
		Tax Koy # 1526-K
	Lot twelve (12) of PADDOCK LAKE HIGHLANDS, a subdivision east sixty (60) acres of the southeast quarter (1/4) of three (3) in town one (1) north, range twenty (20) east fourth principal meridian. lying and being in the Villag Paddock Lake, county of Kenosha and state of Wisconsin.	of the section of the se of
and the state of t		- \
	Tagothor with all and singular the hereditaments and appurtenances thereunte belongh And John Riesselmann and Sharon L. Riesselmann, his wife. warrants that the title is good, indefensible in fac simple and free and clear of ansumbranc ordinances, and recorded easements for public utilities; reco	on except municipal and zoning
	and will wurtent and defend the same,	
	Executed inS11 wer Lake, Wisconsin this 8th	7
	SIGNED AND SEALED IN PRESENCE OF John R	esselmann (SEAL)
•	Sharon	L. Riesselmann
		(REAL)
	And the state of t	(8UAL)
	Signatures of	
	authoritiested this	y manual i
	Tjile: Mombur Str Authorjkud undor	its Bur of Wincomain or Other Party Sec. 706,06 etc.
. Us	(life allege audied "" Again 111 Act of 110 and 110 an	WITE.
	to me known to be the purson.5 who executed the foregoing instrument and actinowlody	of the name.
	ThOU 15's DITEST THE ASS. CONTRACTOR STATES AND STATES	Carolt, Jacobi
	The use of witnessen is optional. "My Gommin	10-18-8] (Expires) (88) (10-18-8)
	Numes of persons segming in may capacity abound be typed or printed below their augmature warranty deed state has or wisconsis, form no 1 1971	B. HE Miller Sections
	MUNICIAL DEED STATE HOR OF BUSINESS LAND 14	CONTROL OF THE PROPERTY OF THE

TRANSFER

. VOL 1068 PAUL 337 664241

is not

WARRANTY DEED

DOCUMENT NO

This Dood, made between George M. Illgau, Jr., and Mildred R. Illges, Husband and Wife as Joint Tonants.

dan amaramin and a common of the common and the com Gruntor Joseph Klesselmann and Ann Riesselmann, Husband and Wife as Joint Tenants

Witnesseth, That the said Granter, for a valuable consideration One (\$1.00) Dollar and other good and valuable canalieration conveys to Grantee the following described real estate in ........KRDORDE...... County, State of Wisconsin:

STATE DAR OF WISCONSIN OF FORM 1
WARRANTY DRING
THUS ROADS INTERPRED FOR RECORDING DATA

**∠**003

REGISTER'S OFFICE 38.8.
Kenosha County, Wis.)


FEB 2 5 1980 ACCORDS VOL 1068 , 337

Rose Bloom AUU RECISTER OF DIEDS

George M. Illges, Jr. F,O. Box 67 Tax Key No. 1527 K.

Lot 13, except the South 20 feet of the West 20 feet thereof, in PADDOCK LAKE HIGHLANDS, a subdivision of the east sixty (60) acres of the southeast quarter (1/4) of section three (3) in town one (1) north of range twenty (20) east of the fourth principal meridian, and lying and being in the village of Paddock Lake, county of Kenosha and state of Wisconsin.

This (is) (is not)  Together with all and singular the hereditaments and And George M. Illges, Jr. and Mile	
warrants that the title is good, indefeasible in fee simple at	id thee und citati at encountries and the
public utility easements and restrictions	of record
and will worrant und dofond the same,	00
Dated this 25 + h day of	
(SEAL)	Call of Sonoeth
v	George M. Illega, Jr.
(8EAL)	milared R 300 ges isenti
*	. Mildred R. Illges
AUTHENTICATION	ACKNOWLEDOMENT
Signatures authenticated this day of	State of Misconsin
, , , , , 19	Kenosha County.
	Personally came before me, this 25day of February the above named, will dead 9
TITLE: MEMBER STATE BAR OF WISCONSIN	George M. Illgee, Jr. and Mildred R.
	Illges
(If not, authorized by § 109.06, Wis, Stats.)	
THIS HIGHENT WAS CHAPTED BY	to me known to be the person. S who executed the topography instrument and achievelethe the same.
James F. Kracmer, Attorney	Similar of the tiple
Silver Lake, Wisconsin	Timothy G. McLafferry
(Signalized stay he muthenticated or acknowledged. Both are not poolerary.)	My Commission is permanent. (If not, state comparing the state of the
"Hearter of parsons symble to any capacity should be typed or printed believed to	ow their slengtures



F161

PLAT OF SURVEY

### LOTS 12 + 13 PADDOCK LAKE HIGHLANDS

11 5614 560 8-1-20 - VILL OF PRODUCE LAND - KONDENA DO - WISE

COUNTY SURVEYOR'S OFFICE COURT HOUSE KENOSHA, WIS.

I hereby certify that I surveyed the property shown hereon, in accordance with official records and that this plat is a true representation of said survey and correct to the best of my knowledge and belief.

February 23, 1979

Wis Reg. Land Surveyor



ORDERED BY: GEORGE ILLES - PRODUCE CARE REALTY

July 5, 2009

Ms. Shanna Laube-Anderson c/o: Ms. Victopria Stovall WDNR 2300 N. Dr. Martin Luther King, Jr., Dr. Milwaukee, WI 53212-3128

Re: GIS Registry Certification: Holiday Village Coin Laundry site, 24924 75<sup>th</sup> Street, Paddock Lake, Kenosha County, Wisconsin. WDNR BRRTS #: 02-30-553765 and PEP Project #: 29004.02.

### Dear Ms. Laube-Anderson:


I, Mr. Joe Riesselmann, Owner of Holiday Village Coin Laundry, certify that to the best of my knowledge, the information and legal descriptions submitted in support of the attached GIS registry packet are complete and accurate.

Mr. Joe Riesselmann

Sincerely

Responsible Party and Owner for Holiday Village Coin Laundry

assellour



© 2004 Microsoft Corporation. Terms of Use Privacy Statement

Figure 1 - Site Features




Figure 3 - Estimated Extent of PCE Contaminated Soil





Figure 4 - Cross-Section Identification






Figure 6 - Estimated Extent of Contaminated Groundwater





Figure 6 - Groundwater Elevations 4/27/2011 Residential Utility Easement - Buried Water Line/Fiber Optic Cable and Over Head Electric 96.22 ! B-16 Property Line Asphalt Driveway B-8 97.71<sub>B-10</sub> Shed Fiber Optic Cable Potable Q Well AC AC AC Bathroom UG Natural Gas Service Holiday Village Coin Laundry Mechanical 97.92 Room Abandoned Restaurant Building B-17 Sewer Laundromat Cleanout **MW** B-2 Office/ Former Dry Cash Cleaning 94.83 Register Machine B-12 -13 O B-1 96.70 **⊕** B-7 B-14 B-15 Asphalt Parking Lot JG Natural gas and UG electric Service Asphalt Parking Lot B-4 Fiber Optic Cable DO 00 Sign Grass Concrete Sidewalk Grass Median Overhead Electric STH 50/75th Street X Utility Pole Soil Boring Location and Identification



### TABLE 1

### ANALYTICAL RESULTS-SOIL

### HOLIDAY VILLAGE COIN LAUNDRY SITE

### 24924 75TH STREET, PADDOCK LAKE, KENOSHA COUNTY, WISCONSIN

	COMM 46 COMM 46 Samples							
Sample Name		Table 1	Table 2	SB-1A	SB-2A	SB-3A	SB-4A	TRIP BLANK
Boring	NR 720 GENERIC RCLs	Values (Groundwater Protection)	Values (Direct Contact - Top 4 Feet)	B-1	B-2	B-3	B-4	
Depth (feet)				7-8	11-12	3-4	11-12	
Date				5/8/2009	5/8/2009	5/8/2009	5/8/2009	5/8/2009
PID Reading				0	0	0	0	NA
VOCS (ppb)								
Benzene	5.5	8,500	1,100	< 25	< 25	< 25	< 25	< 25
1,1-Dichloroethene	NS	NS	NS	< 25	< 25	< 25	< 25	< 25
cis-1,2-Dichloroethene	NS	NS	NS	254	< 25	< 25	< 25	< 25
trans-1,2-Dichloroethene	NS	NS	NS	< 25	< 25	< 25	< 25	< 25
Ethylbenzene	2,900	4,600	NS	< 25	< 25	< 25	< 25	< 25
мтве	NS	NS	NS	< 25	< 25	< 25	< 25	< 25
Naphthalene	400	2,700	NS	< 25	< 25	< 25	< 25	< 25
Tetrachloroethene (PCE)	NS	NS	NS	6,090	< 25	< 25	< 25	< 25
Toluene	1,500	38,000	NS	< 25	< 25	< 25	< 25	< 25
Trichloroethene (TCE)	NS	NS	NS	791	< 25	< 25	< 25	< 25
1,2,4-TMB	NS	83,000	NS	< 25	< 25	< 25	< 25	< 25
1,3,5-TMB	NS	11,000	NS	< 25	< 25	< 25	< 25	< 25
Vinyl Chloride	NS	NS	NS	< 25	< 25	< 25	< 25	< 25
Total Xylenes	4,100	42,000	NS	< 50	< 50	< 50	< 50	< 50

NS = no standard has been established for this compound

RCLs = residual contaminant levels

Underlined values exceed the Generic RCL.

Bolding indicates concentrations above the Table 1 and/or Table 2 (direct contact, top 4 feet) values.

NA = Not analyzed

TMB = trimethylbenzene

MTBE = methyl-tert-butyl-ether

For a complete list of VOCs analyzed, see the laboratory report.

### TABLE 1

### ANALYTICAL RESULTS-SOIL

### HOLIDAY VILLAGE COIN LAUNDRY SITE

### 24924 75TH STREET, PADDOCK LAKE, KENOSHA COUNTY, WISCONSIN

		COMM 46	COMM 46	Samples								
Sample Name		Table 1	Table 2	SB-5A	SB-5B	SB-6A	SB-6B	SB-6C	TRIP BLANK			
Boring	NR 720 GENERIC RCLs	Values (Groundwater Protection)	Values (Direct Contact - Top 4 Feet)	B-5	B-5	B-6	B-6	B-6				
Depth (feet)				7-8	14-15	3-4	9-10	14-15				
Date				6/3/2009	6/3/2009	6/3/2009	6/3/2009	6/3/2009	6/3/2009			
PID Reading				0	0	0	0	0	NA			
VOCS (ppb)												
Benzene	5.5	8,500	1,100	< 25	< 25	< 25	< 25	< 25	< 25			
1,1-Dichloroethene	NS	NS	NS	< 25	< 25	< 25	< 25	< 25	< 25			
cis-1,2-Dichloroethene	NS	NS	NS	< 25	< 25	< 25	723	< 25	< 25			
trans-1,2-Dichloroethene	NS	NS	NS	< 25	< 25	< 25	58.5	< 25	< 25			
Ethylbenzene	2,900	4,600	NS	< 25	< 25	< 25	< 25	< 25	< 25			
МТВЕ	NS	NS	NS	< 25	< 25	< 25	< 25	< 25	< 25			
Naphthalene	400	2,700	NS	< 25	< 25	< 25	< 25	< 25	< 25			
Tetrachloroethene (PCE)	NS	NS	NS	< 25	< 25	< 25	< 25	< 25	< 25			
Toluene	1,500	38,000	NS	< 25	< 25	< 25	< 25	< 25	< 25			
Trichloroethene (TCE)	NS	NS	NS	< 25	< 25	< 25	< 25	< 25	< 25			
1,2,4-TMB	NS	83,000	NS	< 25	< 25	< 25	< 25	< 25	< 25			
1,3,5-TMB	NS	11,000	NS	< 25	< 25	< 25	< 25	< 25	< 25			
Vinyl Chloride	NS	NS	NS	< 25	< 25	< 25	< 25	< 25	< 25			
Total Xylenes	4,100	42,000	NS	< 50	< 50	< 50	< 50	< 50	< 50			

NS = no standard has been established for this compound

RCLs = residual contaminant levels

Underlined values exceed the Generic RCL.

Bolding indicates concentrations above the Table 1 and/or Table 2 (direct contact, top 4 feet) values.

NA = Not analyzed

TMB = trimethylbenzene

MTBE = methyl-tert-butyl-ether

For a complete list of VOCs analyzed, see the laboratory report.

## TABLE 1 ANALYTICAL RESULTS-SOIL HOLIDAY VILLAGE COIN LAUNDRY SITE

### 24924 75TH STREET, PADDOCK LAKE, KENOSHA COUNTY, WISCONSIN

		COMM 46	COMM 46			Sam	ples		
Sample Name		Table 1	Table 2	SB-7A	SB-7B	SB-8A	SB-8B	SB-9A	SB-9B
Boring	IGENERIC RUISI	Values (Direct Contact - Top 4 Feet)	B-7	B-7	B-8	B-8	B-9	B-9	
Depth (feet)				7-8	14-15	7-8	14-15	7-8	14-15
Date				6/3/2009	6/3/2009	6/3/2009	6/3/2009	6/3/2009	6/3/2009
PID Reading				0	0	0	0	0	0
VOCS (ppb)									
Benzene	5.5	8,500	1,100	< 25	< 25	< 25	< 25	< 25	< 25
1,1-Dichloroethene	NS	NS	NS	< 25	< 25	< 25	< 25	< 25	< 25
cis-1,2-Dichloroethene	NS	NS	NS	229	< 25	994	< 25	2,100	< 25
trans-1,2-Dichloroethene	NS	NS	NS	< 25	< 25	93.5	< 25	53.1	< 25
Ethylbenzene	2,900	4,600	NS	< 25	< 25	< 25	< 25	< 25	< 25
мтве	NS	NS	NS	< 25	< 25	< 25	< 25	< 25	< 25
Naphthalene	400	2,700	NS	< 25	< 25	< 25	< 25	< 25	< 25
Tetrachloroethene (PCE)	NS	NS	NS	< 25	< 25	< 25	< 25	4,090	< 25
Toluene	1,500	38,000	NS	< 25	< 25	< 25	< 25	< 25	< 25
Trichloroethene (TCE)	NS	NS	NS	< 25	< 25	< 25	< 25	1,510	< 25
1,2,4-TMB	NS	83,000	NS	< 25	< 25	< 25	< 25	< 25	< 25
1,3,5-TMB	NS	11,000	NS	< 25	< 25	< 25	< 25	< 25	< 25
Vinyl Chloride	NS	NS	NS	< 25	< 25	< 25	< 25	< 25	< 25
Total Xylenes	4,100	42,000	NS	< 50	< 50	< 50	< 50	< 50	< 50

NS = no standard has been established for this compound

RCLs = residual contaminant levels

Underlined values exceed the Generic RCL.

Bolding indicates concentrations above the Table 1 and/or Table 2 (direct contact, top 4 feet) values.

NA = Not analyzed

TMB = trimethylbenzene

MTBE = methyl-tert-butyl-ether

For a complete list of VOCs analyzed, see the laboratory report.

Sample Name	WB-1	HVPW	Water Trip Blank			
Location	Temp. Well in B-1	Holiday Village's Potable Well	QA/QC	NR 140 Remedial Action Limits		
Date	5/8/2009	5/8/2009	5/8/2009			
				ES	PAL	
VOCs (ppb)						
Benzene	< 0.41	< 0.41	< 0.41	5	0.5	
1,1-Dichloroethene	< 0.57	< 0.57	< 0.57	7	0.7	
cis-1,2-Dichloroethene	6.9	< 0.83	< 0.83	70	7	
Ethylbenzene	< 0.54	< 0.54	< 0.54	700	140	
MTBE	< 0.61	< 0.61	< 0.61	60	12	
Naphthalene	< 0.89	< 0.89	< 0.89	40	8	
Tetrachloroethene (PCE)	19.4	< 0.45	< 0.45	5	0.5	
Toluene	< 0.67	< 0.67	< 0.67	1,000	200	
Trichloroethene (TCE)	<u>2.7</u>	< 0.48	< 0.48	5	0.5	
1,2,4-Trimethylbenzene	< 0.97	< 0.97	< 0.97	100	96	
1,3,5-Trimethylbenzene	< 0.83	< 0.83	< 0.83	480	90	
Xylene (total)	< 1.8	< 1.8	< 1.8	10,000	1,000	

ND = not detected

NS = no standards

MTBE = methyl-tert-butyl-ether

Bolded values indicate concentrations above ES.

Underlined values indicate concentrations above PAL.

For a complete list of VOCs and detection limits, see Appendix C.

NA = Not Analyzed

Sample Name			MW-10					MW-11				
Location			Well in B-10					Well in B-11		NR 140 Remedial Action Limits		
Date	11/8/2009	3/18/2010	6/25/2010	9/27/2010	4/27/2011	11/8/2009	3/18/2010	6/25/2010	9/27/2010	4/27/2011		
											ES	PAL
VOCs (ppb)									2			
Benzene	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	5	0.5
1,1-Dichloroethene	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	7	0.7
cis-1,2-Dichloroethene	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	70	7
trans-1,2-Dichloroethene	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	100	20
Ethylbenzene	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	700	140
MTBE	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	60	12
Naphthalene	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	40	8
Tetrachloroethene (PCE)	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	5	0.5
Toluene	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	1,000	200
Trichloroethene (TCE)	< 0.48	< 0.48	< 0.48	< 0.48	< 0.48	< 0.48	< 0.48	< 0.48	< 0.48	< 0.48	5	0.5
1,2,4-Trimethylbenzene	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	400	0.0
1,3,5-Trimethylbenzene	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	480	96
Vinyl Chloride	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	0.2	0.02
Xylene (total)	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	10,000	1,000

ND = not detected

NS = no standards

MTBE = methyl-tert-butyl-ether

Bolded values indicate concentrations above ES.

Underlined values indicate concentrations above PAL.

For a complete list of VOCs and detection limits, see Appendix C.

NA = Not Analyzed

Sample Name			MW-12					MW-13				
Location			Well in B-12					Well in B-13	NR 140 Remedial Action Limits			
Date	11/8/2009	3/18/2010	6/25/2010	9/27/2010	4/27/2011	11/8/2009	3/18/2010	6/25/2010	9/27/2010	4/27/2011		
											ES	PAL
VOCs (ppb)												
Benzene	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	5	0.5
1,1-Dichloroethene	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	7	0.7
cis-1,2-Dichloroethene	3.6	1.3	5.7	12.7	2.5	21.8	18.8	54.7	90.1	27.6	70	7
trans-1,2-Dichloroethene	< 0.89	< 0.89	< 0.89	1.1	< 0.89	< 0.89	< 0.89	1.7	3.3	< 0.89	100	20
Ethylbenzene	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	700	140
MTBE	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	60	12
Naphthalene	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	40	8
Tetrachloroethene (PCE)	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	13.2	11.5	45.3	89.4	21.3	5	0.5
Toluene	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	1,000	200
Trichloroethene (TCE)	1.2	< 0.48	1.6	3.4	0.65	5.8	4.3	12.5	24.8	6.2	5	0.5
1,2,4-Trimethylbenzene	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	/00	
1,3,5-Trimethylbenzene	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	480	96
Vinyl Chloride	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	0.2	0.02
Xylene (total)	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	10,000	1.000

ND = not detected

NS = no standards

MTBE = methyl-tert-butyl-ether

Bolded values indicate concentrations above ES.

Underlined values indicate concentrations above PAL.

For a complete list of VOCs and detection limits, see Appendix C.

NA = Not Analyzed

Sample Name			MW-15					MW-16					
Location			Well in B-15					Well in B-16			- 222	NR 140 Remedial Action Limits	
Date	11/8/2009	3/18/2010	6/25/2010	9/27/2010	4/27/2011	11/8/2009	3/18/2010	6/25/2010	9/27/2010	4/27/2011			
											ES	PAL	
VOCs (ppb)													
Benzene	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	5	0.5	
1,1-Dichloroethene	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	7	0.7	
cis-1,2-Dichloroethene	42.7	21.2	21.3	34.6	2.4	15.8	12.6	17.2	11.3	5	70	7	
trans-1,2-Dichloroethene	3.8	1.2	1.7	2.6	< 0.89	2.3	1.2	2.1	1.5	< 0.89	100	20	
Ethylbenzene	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	700	140	
MTBE	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	60	12	
Naphthalene	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	40	8	
Tetrachloroethene (PCE)	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	< 0.45	5	0.5	
Toluene	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	1,000	200	
Trichloroethene (TCE)	< 0.48	< 0.48	< 0.48	< 0.48	< 0.48	< 0.48	< 0.48	< 0.48	< 0.48	< 0.48	5	0.5	
1,2,4-Trimethylbenzene	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97			
1,3,5-Trimethylbenzene	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	480	96	
Vinyl Chloride	3.8	0.78	3	6.8	0.76	< 0.18	< 0.18	< 0.18	< 0.18	< 0.18	0.2	0.02	
Xylene (total)	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	10,000	1,000	

ND = not detected

NS = no standards

MTBE = methyl-tert-butyl-ether

Bolded values indicate concentrations above ES.

Underlined values indicate concentrations above PAL.

For a complete list of VOCs and detection limits, see Appendix C.

NA = Not Analyzed

Sample Name		MW-17			HVPW						
Location		Well in B-17 Holiday Village's Potable Well				NR 140 Remedial Action Limits					
Date	3/18/2010	6/25/2010	9/27/2010	5/8/2009	9/27/2010	4/27/2011					
						27	ES	PAL			
VOCs (ppb)											
Benzene	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	< 0.41	5	0.5			
1,1-Dichloroethene	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	< 0.57	7	0.7			
cis-1,2-Dichloroethene	71.9	97.3	85.7	< 0.83	< 0.83	< 0.83	70	7			
trans-1,2-Dichloroethene	2.4	3.8	3.5	< 0.89	< 0.89	< 0.89	100	20			
Ethylbenzene	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	< 0.54	700	140			
MTBE	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	< 0.61	60	12			
Naphthalene	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	< 0.89	40	8			
Tetrachloroethene (PCE)	<u>0.90</u>	<u>1.20</u>	1.00	< 0.45	< 0.45	< 0.45	5	0.5			
Toluene	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	< 0.67	1,000	200			
Trichloroethene (TCE)	< 0.48	< 0.48	0.53	< 0.48	< 0.48	< 0.48	5	0.5			
1,2,4-Trimethylbenzene	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	< 0.97	400	00			
1,3,5-Trimethylbenzene	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	< 0.83	480	96			
Vinyl Chloride	< 0.18	0.61	0.36	< 0.18	< 0.18	< 0.18	0.2	0.02			
Xylene (total)	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	< 1.8	10,000	1,000			

ND = not detected

NS = no standards

MTBE = methyl-tert-butyl-ether

Bolded values indicate concentrations above ES.

Underlined values indicate concentrations above PAL.

For a complete list of VOCs and detection limits, see Appendix C.

NA = Not Analyzed

State of Wisconsin	Impacted Off-Source Property Information			
Department of Natural Resources http://dnr.wi.gov	Form 4400-246 (R 3/08)			

This fillable form is intended to provide a list of information that must be submitted for evaluation for case closure. It is to be used in conjunction with Form 4400-202, Case Closure Request (Section H). The closure of a case means that the Department has determined that no further response is required at that time based on the information that has been submitted to the Department.

NOTICE: Completion of this form is mandatory for applications for case closure pursuant to ch. 292, Wis. Stats. and ch. NR 726, Wis. Adm. Code, including cases closed under ch. NR 746 and ch. NR 726. The Department will not consider, or act upon your application, unless all applicable sections are completed on this form and the closure fee and any other applicable fees, required under ch. NR 749, Wis. Adm. Code, Table 1 are included. It is not the Department's intention to use any personally identifiable information from this form for any purpose other than reviewing closure requests and determining the need for additional response action. The Department may provide this information to requesters as required by Wisconsin's Open Records law [ss. 19.31 - 19.39, Wis. Stats.].

(44.14.61 12.62)				
BRRTS #:	02-30-553765 (No Dashes)			
ACTIVITY NAM	E: HOLIDAY COIN LAUNDRY			
ID	Off-Source Property Address	Parcel Number	WTM X	WTM Y
A LOTS	14 AND 15 OF PADDOCK LAKE HIGHLANDS	4041200341050 AND 4041200341055	674975	234635
В				
С				
D				
E				
F				
G				
Н				

# PEP ENVIRONMENTAL SERVICES, LLC

December 7, 2011

Ms. Lynne Monaco Frontier Communications 111 Field Street Rochester, NY 14620-1529

Re: Holiday Village Coin Laundry site, 24924 75th Street, Village of Paddock Lake, Kenosha County, Wisconsin. WDNR BRRTS #: 02-30-553765. PEP Project No. 29004.01

Dear Ms. Monaco:

We identified tetrachloroethene (PCE) and its common degradation byproducts in soil and groundwater near the location of the former dry cleaning equipment at the Holiday Village Coin Laundry (HVCL) site. There is a Verizon (Frontier Communications) switching station building west and adjacent to the HVCL building. The approximate address for the switching station is 24964 75<sup>th</sup> Street (State Highway 50), Paddock Lake (Salem), Kenosha County, Wisconsin.

It does not appear that the PCE has migrated very far outside the building's foot print. Based on the predominance very tight silty clay at the site, the extent of PCE-contaminated soil is isolated to the near-surface soils (10 feet or less below ground surface (bgs)) in an area concentrated at the southwest corner of the building, where the former dry cleaning equipment was located, and extends somewhat to the southeast, mimicking the topography at the site (see attached figure).

However, due to the proximity of the switching station to the source of the contamination, it appears likely that some PCE contaminated soil and groundwater are present on the switching station property. We have not previously requested permission to drill on the switching station property due to the abundance of fiber optic cables running into switching station. The WDNR has requested that we either complete borings on the switching station property to confirm the presence and determine the extent of PCE contamination, or we should assume that PCE contamination exists on the switching station property and register your property on the WDNR's GIS database of contaminated sites. Specifically, the WDNR gave us the following two options as listed in their October 7, 2011, closure letter:

- 1. In regards to the soil contamination along the property line that appears to be shared with the Verizon Switching Station you can chose one of the following options:
  - a. Gain access to that property to collect an actual soil sample to define the extent of the soil contamination onto that property and then correct the soil contamination maps to show the extent of contamination as well as notify Verizon that there is contamination on their property and that they will be listed on the GIS registry. You would need to get the deed information for inclusion in your GIS packet.
  - b. Change the soil contamination maps to show that contamination does possibly extend further onto the Verizon property, send a notification to them stating that you are requesting site closure and that soil contamination is possibly on their property and that you will need to include that section of their property on the GIS database with your site. Once you receive a response from them regarding this issue, then submit the corrected maps and the deed information for that property with the remainder of the items in this letter.



Please contact me within two weeks if you will allow us access to the switching station property to complete the soil borings. If we do not receive a response from you within 30 days, we will proceed with option 1.b. above.

We appreciate your attention to this matter and assistance to bringing this site to closure. If you have any questions, please contact me at the phone number or email address listed on this letter.

Sincerely,

Pete Pavalko, CHMM

President

Cc: Mr. Joe Riesselmann, 24909 71st Street, Paddock Lake, WI 53168

Shanna L. Laube-Anderson, WDNR, 9531 Rayne Road, Sturtevant, WI 53177

38	U.S. Postal Service TIM CERTIFIED MAIL TIM RECEIPT (Domestic Mail Only; No Insurance Coverage Provided)				
78	For delivery information visit our website at www.usps.com				
	"O"FFT"C"AL USE				
3785	Postage \$ 30,44 0012				
	Certified Fee				
0000	Return Receipt Fee (Endorsement Required)				
	Restricted Delivery Fee (Endorsement Required)				
323	Total Postage & Fees \$ \$ \( \frac{5}{6} \) \( \frac{5}{1} \) \( \f				
8	SENT TO LYNNE MONACO				
7008	Street, Apt. No.; ///FIELD ST.				
. 1	City, State, ZIP+4 RochESTERNY 14620-1529				
	PS Form 3800, August 2006 See Reverse for Instructions				

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
■ Complete Items 1, 2, and 3, Also complete Item 4 if Restricted Delivery is desired. ■ Print your name and address on the reverse so that we can return the card to you. ■ Attach this card to the back of the maliplece or on the front if space permits.  1. Article Addressed to:  MS. LYWIE MUNACO  FRONTIER COMMUNICATION	A. Signature    A. Signature     Agent     Addressee
MIFIELD ST. RochESTER, NY 14620-	3. Service Type  Certified Mall
2.	9 4 Restricted Delivery? (Extra Fee) (See

## 466481

#### WARRANTY DEED

THIS INDENTURE, MADE this 12th day of August , A. D. 1964 between THE FIRST NATIONAL BANK OF KENOSHA, a corporation duly organized, existing and doing business under and by virtue of the laws of the United States of American, with its office and principal place of business in the City of Kenosha, County of Kenosha and State of Wisconsin, AS TRUSTEE, under the provisions of a trust agreement dated the 19th day of March, A. D. 1929, party of the first part, and GENERAL TELEPHONE COMPANY OF WISCONSIN party of the second part;

part, for and in consideration of the sum of TEN (\$10.00) DOLLARS and other good and valuable considerations, to it paid by the said party of the second part, the receipt whereof is hereby confessed and acknowledged, has given, granted, bargained, sold, remised, released, aliened, conveyed and confirmed, and by these presents does give, grant, bargain, sell, remise, release, alien, convey and confirm unto the said party of the second part, its successors heirs and assigns, forever, the following described real estate, situated in the County of Kenosha and State of Wisconsin, to-wit:

Lots Fourteen (14) and Fifteen (15) of Paddock Lake Highlands, a subdivision of the east sixty (60) acres of the southeast quarter of section three (3) township one (1) north of range twenty (20) east, of the fourth principal meridian and lying and being in the town of Salem, County of Kenosha and State of Wisconsin.

TOGETHER with all and singular the hereditaments and appurtenances thereunto belonging or in any wise appertaining; and all the estate, right, title, interest, claim or demand whatsoever of the said party of the first part, either in law or equity,

either in possession or expectancy of, in and to the above bargained premises, and their hereditaments and appurtenances.

PROVIDED, HOWEVER, that this conveyance is made by the party of the first part and accepted by the party of the second part, subject to the covenants and restrictions hereinafter expressed, namely:

- 1. Lots in "Paddock Lake Highlands" Subdivision shall be used for residential purposes only, except that lots Nos. 1, 2, 14, 15, 278, 279 and 292 to 300, both inclusive, may be used for business purposes.
- 2. Not more than one dwelling with necessary garage shall be built on any one lot, and no garage or shelter shall be erected until after dwelling is erected. No building is to be erected with out first securing written approval of party of first part, or its authorized representative of the plan and specification of said house.
- No outside toilets shall be constructed on any of said lots.
- 4. No fence is to be erected on said property and no "For Sale," "For Rent" or other sign shall be placed thereon without the written consent of party of first part or its authorized representative.
- 5. No building shall be erected within six (6) feet of either side line or within twenty-five (25) feet of front line of said lot.

The following rights, privileges and easements are reserved by the said party of the first part, its successors and assigns:

The right and privilege of granting telephone and electric light companies the right to string wires or pole lines within two feet of the rear line of any lot, or lots, as the said party of the first part may determine from time to time, including the right to said party of the first part to enter upon said premises at reasonable times to install or repair such telephone and electric light lines.

The right to lay and install underground water pipes or drains within four feet of the rear and side lines of any lot, or lots, as the said party of the first part may determine from time to time, including the right to said party of the first part to enter upon said premises at reasonable times to install or repair such underground water pipes or drains.

TO HAVE AND TO HOLD the said premises as above described, with the hereditaments and appurtenances, unto the said party of the second part, and to its successors and assigns, forever.

And the said The First National Bank of Kenosha, as Trustee, party of the first part, for itself and its successors, as trustees, does covenant, grant, bargain and agree to and with the said party of the second part, its successors and assigns, that at the time of the ensealing and delivery of these presents, it is well seized of the premises above described as of a good, sure, perfect, absolute and indefeasible estate of inheritance in the law, in fee simple, and that the same are free and clear from all encumbrances whatever, and that the above bargained premises in the quiet and peaceable possession of the said party of the second part, its successors and assigns, against all and every person or persons lawfully claiming the whole, or any part thereof, it will forever warrant and defend.

IN WITNESS WHEREOF, the said The First Nation	al Bank
of Kenosha, as Trustee, party of the first part, has ca	used these
presents to be signed by L. M. Brickley	
its vice-president, and countersigned by R. M. Hartne assistant	LL J. L. Thomas
its/cashier, at Kenosha, Wisconsin,	and its
corporate seal to be hereunto affixed, this 12th	day of

0.5	
	1964. VOL 680 TALLE 52
August , A. D.	1964.
	THE FIRST NATIONAL BANK OF KENOSHA,
	as Trustee,
Signed and sealed in	
presence of:	
Rich D Creplean	By I'm Siege
	L. M. Hrickley Vice-President.
Ruth D. Criplean	vice-President.
000	
Marian J. Roeder	Attest: Tomes
,	Asst.Cashier.
Marian J. Roeder	
	· · · · · · · · · · · · · · · · · · ·
3	
COMMUNICATION AND AND AND AND AND AND AND AND AND AN	
STATE OF WISCONSIN ) ss	The History
COUNTY OF KENOSHA )	
2 2 2 2	
Personally came	e before me, this 12th day of, August
A. D. 1964,	
	L. M. Brickley vice-president
and J. L. Thomas	assistant cashier, of the
above named corporation,	to me known to be the persons who executed
the foregoing instrument.	and to me known to be such vice-president
assistant	
and cashier of said corpo	oration, and acknowledged that they execu-
+ - 4 + 1 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 -	
ted the foregoing instrum	ment as such officers as the deed of said
corporation by its author	ity.
	vijama)
*	
1	OP WATER OF
	Marian J. Rocclery
	Notary Public, Kenosha County,
	Wisconsin.
- e	ስ ህህ
dy Commission expires 4/	Wisconsin.
My Commission expires 4/	ስ ህህ
My Commission expires 4/	ስ ህህ
	7/68
	7/68 y F. A. Brynelson, Attorney, Madison,
	7/68

En deglare a. 18 Lo Guentor Ono. Maduen



REGISTERIS OFFICE IS.S.
Kenosha County, Wis.)
RECORDED AT 1150 A. M
ON SEP 4. 1964 IN
RECORDS VOLCEO, P. 4252
Wilbur Richard
REGISTER OF DEEDS

4.

-4-



## **Kenosha County**

## **Property Inquiry**

Data is given "As is, With All Faults" and should be verified with the appropriate County Department.

Municipality: Paddock Lake
Parcel Number: 40-4-120-034-1050

**Property Address: 75TH ST** 

Mail-To Address: GTE NORTH INCORPORATED

19845 NORTH U.S. 31 PO BOX 407

WESTFIELD, IN 46074-9685



Show Parcel
Go to Mapping

### Legal Name/Ownership:

GTE NORTH INCORPORATED

#### Land Information (approximate):

This is an irregularly shaped parcel. No frontage or depth information will be displayed.

Frontage: 0
Depth: 0

Property Class:

Total Acres: 0

Land Use: Not Assigned

Zoning: For zoning classifications on properties within the unincorporated

areas of Kenosha County, please refer to the <u>Kenosha County</u> <u>Interactive Mapping website</u>. For zoning classifications in incorporated areas, please contact city or village offices.

### **Building Information (if available):**

Residential Type:

Building Style:

Year Built: 0 Stories: 0

**Exterior Wall:** 

Square Foot: 0

Basement: Heat/Air: Fuel Type:

Heating System:

Bedrooms: 0 Full Baths: 0

1/2 Baths:

0



#### Land Type: (Questions should be directed to the local assessor)

Description	Acres	Land Assessment	Improved Assessment
Other Exempt	.17		

#### **Assessments:**

Year	Land	Improved	Total	
2011	\$0	\$0	\$0	
2010	\$0	\$0	\$0	
2009	\$0	\$0	\$0	
2008	\$0	\$0	\$0	
2007	\$0	\$0	\$0	

**Taxes: Outstanding Tax Statement** 

Year	Total Tax	Interest Paid	Penalties Paid	Total Paid	Last Payment	Bill	Status
2011	\$322.50					<u>View</u>	Delq Tax

#### **Tax Rate Districts**

School: Salem Consolidated J Dst. 2
High School: Central/Westosha High School
VTAE: Gateway Technical College

TIF: Not Applicable
Water: Not Applicable
Sewer: Not Applicable
Light: Not Applicable
Utilities: Not Applicable
Fire: Not Applicable

Lake: Paddock Lake Management Dst

Drainage: Not Applicable

#### **Most Recent Sales:**

Inst	Mo⁄Yr	Document	Conveyance Amount	Volume	Page	Parcels Involved
			No sales data			

### Abbreviated Metes/Bounds - Legal Description:

1528 K LOT 14 PADDOCK LAKE HIGHLANDS SEC 3 T 1 R 20 .166 ACS

> Copyright 2006 Kenosha County, Wisconsin. All rights reserved Acceptable Use Policy | Copyright Information



## **Kenosha County**

## **Property Inquiry**

Data is given "As is, With All Faults" and should be verified with the appropriate County Department.

Municipality: Paddock Lake
Parcel Number: 40-4-120-034-1055

**Property Address: 75TH ST** 

Mail-To Address: GTE NORTH INCORPORATED

19845 NORTH U.S. 31 PO BOX 407

WESTFIELD, IN 46074-9685



Show Parcel
Go to Mapping

### Legal Name/Ownership:

GTE NORTH INCORPORATED

#### Land Information (approximate):

This is an irregularly shaped parcel. No frontage or depth information will be displayed.

Frontage: 0
Depth: 0

Property Class:

Total Acres: 0

Land Use: Not Assigned

Zoning: For zoning classifications on properties within the unincorporated

areas of Kenosha County, please refer to the <u>Kenosha County</u> <u>Interactive Mapping website</u>. For zoning classifications in incorporated areas, please contact city or village offices.

### **Building Information (if available):**

Residential Type:

**Building Style:** 

Year Built: 0 Stories: 0

Exterior Wall:

Square Foot: 0

Basement: Heat/Air: Fuel Type:

Heating System:

Bedrooms: 0
Full Baths: 0

1/2 Baths: 0



#### Land Type: (Questions should be directed to the local assessor)

Description	Acres	Land Assessment	Improved Assessment
Other Exempt	.17		

#### **Assessments:**

Year	Land	Improved	Total	
2011	\$0	\$0	\$0	
2010	\$0	\$0	\$0	
2009	\$0	\$0	\$0	
2008	\$0	\$0	\$0	
2007	\$0	\$0	\$0	

**Taxes: Outstanding Tax Statement** 

Year	Total Tax	Interest Paid	Penalties Paid	Total Paid	Last Payment	Bill	Status
	None found						

#### **Tax Rate Districts**

School: Salem Consolidated J Dst. 2
High School: Central/Westosha High School
VTAE: Gateway Technical College

TIF: Not Applicable
Water: Not Applicable
Sewer: Not Applicable
Light: Not Applicable
Utilities: Not Applicable
Fire: Not Applicable

Lake: Paddock Lake Management Dst

Drainage: Not Applicable

#### **Most Recent Sales:**

Inst	Mo⁄Yr	Document	Conveyance Amount	Volume	Page	Parcels Involved	
			No sales data				

### Abbreviated Metes/Bounds - Legal Description:

1529 K LOT 15 PADDOCK LAKE HIGHLANDS SEC 3 T 1 R 20 .173 ACS

> Copyright 2006 Kenosha County, Wisconsin. All rights reserved Acceptable Use Policy | Copyright Information