

708 Heartland Trail Suite 3000 Madison, WI 53717

608-826-3600 PHONE 608-826-3941 FAX

www.TRCsolutions.com

June 18, 2018

Mr. Mike Schmoller Hydrogeologist Wisconsin Department of Natural Resources 3911 Fish Hatchery Road Fitchburg, WI 53711

Subject: Polychlorinated Biphenyls (PCBs) in Rain Garden – Interim Investigative

Summary Follow-up

Dear Mr. Schmoller:

As requested by Madison Kipp Corporation (MKC), TRC Environmental Corporation (TRC) has been investigating the presence and possible migration of polychlorinated biphenyls (PCBs) to the rain garden just north of the MKC facility which is located at 201 Waubesa Street, Madison, Wisconsin (the site, Figure 1). This letter summarizes the most recent actions completed as outlined in the November 2017 submittal of the Rain Garden – Interim Investigation Report and Proposed Excavation Work Plan (TRC, 2017).

Per the November 2017 report, TRC recommended that the outfall and manhole MH-1A be monitored during heavy snow melt and rainfall events during the 2017-2018 winter and spring seasons. The focus was to monitor sediment accumulation and if possible collect samples after heavy snow melts and high intensity rainfalls (accumulating greater than 1 inch of rainfall in a 24-hour period time).

#### Monitoring

TRC monitored manhole MH-1A and the outfall area for sediment accumulation between December 2017 and May 2018 based on snow melt and rain events. The locations of each monitoring point along with site features are shown on Figure 2. Based on actual snow melt and high intensity rain fall events, monitoring was broken up into two main periods.

Mr. Mike Schmoller Wisconsin Department of Natural Resources June 18, 2018 Page 2

#### December 2017 - February 2018

Between December 2017 and February 2018, only one rain event resulted in greater than 1 inch of rainfall accumulation within one day and the focus during these months, was sediment accumulation into the storm sewer network from heavy snow melting events. On February 21, 2018, TRC inspected manhole MH-1A and the outfall into the rain garden. Sediment was observed in MH-1A and one sample was collected for PCBs. The sediment consisted of a fine to coarse material. Laboratory analytical results reported PCBs at a concentration of 0.33 milligram per kilogram (mg/kg) in this sample. The outfall area was inspected as well and only organic materials (i.e., leaves) were observed within the outfall pipe and no sample could be collected.

#### March 2018 - May 2018

Between March and May 2018, snow melt was observed and four rain events occurred resulting in greater than one inch of rainfall accumulation within one days' time. All four rain events were recorded in May 2018 and none were observed during the months of March or April. Periodic inspections of manhole MH-1A were completed following select rain events in March and April but no significant changes in sediment loading were observed and therefore no samples were collected. On May 10, 2018, manhole MH-1A and the outfall pipe were inspected and fine to coarse grain sediment was observed at both locations with some organics present as well. A sample was collected from manhole MH-1A and from within the outfall pipe. Laboratory analytical results reported PCBs in manhole MH-1A sample at concentration of 0.15 mg/kg and at concentration of 1.9 mg/kg at the outfall area.

Table 1 includes a summary of the results collected through May 2018 and the laboratory analytical report for the February and May 2018 samples are included in Attachment 1.

#### **Discussion**

#### Manhole MH-1A

Monitoring results between December 2017 and May 2018 indicate that sediment accumulation within manhole MH-1A contains PCBs at low concentrations below the Natural Resources (NR) 720 industrial direct contact soil residual contaminant level (RCL) for PCBs. Sediment materials are consistent with previous samples collected in 2017 and consist of a fine to coarse grain material.



Mr. Mike Schmoller Wisconsin Department of Natural Resources June 18, 2018 Page 3

#### Outfall

Monitoring results indicate that sediment observed within the outfall pipe area contained PCBs at a concentration of 1.9 mg/kg. However, based on the concentration of PCBs observed in upstream sediments from manhole MH-1A and the negative drainage pitch of the outfall pipe and outfall pipe discharge area, the higher detections of PCBs could be related to 2017 discharges that are present in the rain garden (pending upcoming excavation). As previously discussed, the outfall pipe and immediate area are negatively pitched which can cause back and forth flow of water and sediment from the rain garden. This could, in this case, have caused migration of PCB impacted sediments known to be present in the rain garden back into the outfall pipe.

In addition, the lack of sediment observed in the outfall pipe from December 2017 to February 2018 corroborates that sediment deposits in the outfall pipe during high intensity rain events. During these rain events, additional sediment load may come from upstream in the storm sewer network, but it is also known that sediment from the garden washes back and forth into the outfall pipe due to the high standing water in the rain garden. The lack sediment accumulation in the outfall pipe could also be the result of the relining work completed in 2017 between manhole MH-3W and MH-1A.

#### Recommendations

Based on the results from monitoring completed between December 2017 and May 2018, MKC plans to excavate the outfall area as outlined in the November 2017 Rain Garden – Interim Investigation Report and Proposed Excavation Work Plan (TRC, 2017).

Following excavation, the outfall area/pipe and manhole MH-1A will continue to be monitored for the remainder of 2018. The frequency of monitoring will be dependent on high intensity rain events (greater than one inch of rainfall accumulation in a 24-hour period). Following large rain events, TRC will visit the Site and observe the conditions in the outfall area/pipe and manhole MH-1A. A sample of sediment will be collected from each location, if present, quarterly (one in the period July – September and one in the period October – December).

TRC will also remove accumulated sediment from MH-1A to reduce the amount of sediment discharging into the rain garden. Accumulated sediment will be removed with dedicated equipment (e.g., wet/dry vacuum) or other hand tools and containerized for disposal.



Mr. Mike Schmoller Wisconsin Department of Natural Resources June 18, 2018 Page 4

A documentation report, as outlined in the November 2017 report submittal, will be completed following the rain garden excavation and restoration. TRC will prepare a separate brief letter report following the remaining 2018 monitoring.

If you have questions or comments please feel free to contact Andrew Stehn (608-826-3665) or Katherine Vater (608-826-3663).

Sincerely,

TRC Environmental Corporation

Andrew Stehn, P.E.

Project Engineer

Katherine Vater, P.E.

Project Manger

Attachments: Table

**Figures** 

Attachment 1 - Laboratory Analytical Report

cc: John Hausbeck, Public Health (electronic)

Mark Sheppard, Madison-Kipp Corporation (electronic)

Peter Ramanauskas and Michael Beedle, U.S. EPA (electronic)

#### Reference

TRC. 2017. Rain Garden – Interim Investigation Report and Proposed Excavation Work Plan. November 29, 2017.



#### Table 1 Storm Sewer System Sediment Sampling Analytical Results Summary Madison-Kipp Corporation 201 Waubesa Street, Madison, Wisconsin

				Extraction of the control of the con																												
					SAMPLE LOCATION AND SAMPLE ID																											
		NR 72	0 RCL									PAVED	SURFACE S	AMPLÉ <sup>4)</sup>								MANHOLE B	OTTOM SAMPLE									
						ROOF DR	AIN SAMPLE				МН	I-4A					MH-1NW		MH-1A								OUTFA	LL SAMPLE				
PARAMETER	UNIT	INDUSTRIAL DIRECT CONTACT <sup>(2)</sup>	HISTORICAL INDUSTRIAL DIRECT CONTACT <sup>(3)</sup>	MH-3WR	MH-4AR	GUTTER 1	GUTTER 2	MH-2AR	RDO	MH-1A (2)	MH4-TOP	MH-4A	MH-5B	MH-3W	MH-5A	PS-1	MH-1NW- BOTTOM	MH-1NW- BASIN	STORM SEWER	MH-1A(3)- BASIN	MH-1A 9/22/17	MH-1A (10/6/17)	MH-1A (10/17/17)	MH-1A-22118	MH-1A-051018	MH-2W	MH-3W	MH5-PIPE	PIPE	OUTFALL (6/30)	OUTFALL 9/22/17	OUTFALL PIPE- 051018
Sample Date			-	5/22/2017	5/22/2017	5/31/2017	5/31/2017	6/14/2017	6/14/2017	5/31/2017	3/9/2017	5/31/2017	5/31/2017	6/14/2017	6/29/2017	6/30/2017	2/15/2017	6/14/2017	12/28/2016	6/30/2017	9/22/2017	10/6/2017	10/17/2017	2/21/2018	5/10/2018	2/15/2017	2/15/2017	3/9/2017	12/19/2016	6/30/2017	9/22/2017	5/10/2018
Matrix (1)				Other	Other	Other	Other	Other	Other	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil
PCB-1016	mg/kg	28	21.2	<0.0074	<0.0074	<0.0074	<0.0074	<0.0074	<0.0074	<0.0081	<0.0078	<0.0088	<0.010	<0.018	<0.0078	<0.0077	<0.0086	<0.010	<0.011	<0.0092	<0.0089	<0.0097	<0.010	<0.0094	<0.0083	<0.014	<0.0086	<0.010	<0.0095	<0.0086	<0.011	<0.0099
PCB-1221	mg/kg	0.883	0.589	<0.0041	<0.0041	<0.0041	<0.0041	<0.0041	<0.0041	<0.0045	<0.0043	<0.0049	<0.0058	<0.0098	<0.0043	<0.0043	<0.0048	<0.0057	<0.0059	<0.0051	<0.0049	<0.0054	<0.0057	<0.0052	<0.0046	<0.0078	<0.0047	<0.0058	<0.0053	<0.0048	<0.0061	<0.0055
PCB-1232	mg/kg	0.792	0.589	<0.0028	<0.0028	<0.0028	<0.0028	<0.0028	<0.0028	<0.0031	<0.0030	<0.0033	<0.0039	<0.0067	<0.0029	<0.0029	<0.0033	<0.0039	<0.0040	<0.0035	<0.0034	<0.0037	<0.0039	<0.0036	<0.0031	<0.0053	<0.0032	<0.0039	<0.0036	<0.0032	<0.0042	<0.0038
PCB-1242	mg/kg	0.972	0.744	<0.0044	<0.0044	<0.0044	<0.0044	<0.0044	<0.0044	<0.0048	<0.0046	<0.0052	<0.0062	<0.011	<0.0046	<0.0046	<0.0051	<0.0061	<0.0063	<0.0055	<0.0053	<0.0058	<0.0061	<0.0056	<0.0049	<0.0083	<0.0051	<0.0062	<0.0057	<0.0051	<0.0066	<0.0059
PCB-1248	mg/kg	0.975	0.744	0.20	<0.0053	<0.0053	0.049 J	<0.0053	0.050 J	0.023 J	0.028 J	0.096 J	0.12 J	0.32	<0.0056	<0.0055	0.28	0.10 J	3.6	2.2	0.11	0.23	0.71	0.33	0.15	120	<0.0061	0.93	9.2	5.0	4.0	1.9
PCB-1254	mg/kg	0.988	0.744	<0.0044	<0.0044	<0.0044	<0.0044	<0.0044	0.013 J	<0.0048	<0.0046	<0.0052	<0.0062	0.099 J	0.071 J	0.034 J	0.41	0.086 J	<0.0063	<0.0055	<0.0053	<0.0058	<0.0061	<0.0056	<0.0049	<0.0083	1.6	<0.0062	<0.0057	<0.0051	<0.0066	<0.0059
PCB-1260	mg/kg	1	0.744	<0.0024	<0.0024	<0.0024	<0.0024	<0.0024	<0.0024	<0.0026	<0.0025	<0.0028	<0.0034	<0.0058	<0.0025	<0.0025	<0.0028	<0.0033	<0.0034	<0.003	<0.0029	<0.0031	<0.0033	<0.0031	<0.0027	<0.0045	<0.0028	<0.0034	0.37	<0.0028	<0.0036	<0.0032
Total PCBs	mg/kg	0.967	0.744	0.20	<0.0074	<0.0074	0.049 J	<0.0074	0.063 J	0.023 J	0.028 J	0.096 J	0.12 J	0.42	0.071 J	0.034 J	0.69	0.19	3.6	2.2	0.11	0.23	0.71	0.33	0.15	120	1.6	0.93	9.6	5.0	4.0	1.9
Notes: < = Less than	•													•						•		•								(		y: A. Stehn 6/7/2018 . Wachholz 6/7/2018

mg/kg = Milligrams per kilogram

J = Estimated value. Analyte detected at a level less than the reporting limit and greater than or equal to the detection limit.

PCBs = Polychlorinated Biphenyls

Bold and Italics = WDNR Industrial Direct Contact Limit Exceedance

Sample ID ending in "R" indicates the sample is from roof drain adjacent the manhole location (e.g., MH-4AR is the roof drain adjacent MH-4A).

(1) PCB results for samples with a matrix of "Other" are reported on an as is (wet weight) basis.

(2) As of March 2017, the WDNR updated the industrial direct contact residual contaminant levels for total PCBs and specific Aroclors.

(3) Historical WDNR industrial direct contact RCLs applied at the MKC site.

(4) Paved surface samples collected at the ground surface inlet to the referenced manhole, with the exception of sample PS-1 which was collected from the paved parking lot area just upstream of the rain garden.

Page 1 of 1 \ntapb-madison\msn-vol6\-\WPMSN\PJT2\268304\0000\2683040000-007.xlsx

SITE LOCATION MAP

Madison, WI 53717 Phone: 608.826.3600 FILE:

268304-001slm.mxd

FIGURE 1

# Attachment 1 Laboratory Analytical Report



March 07, 2018

Andrew Stehn
TRC Environmental Corporation, Inc.
708 Heartland Trail, Ste 3000
Madison, WI 53717

RE: Madison Kipp - Rain Garden Excavation

Enclosed are the analytical results for the samples received by the laboratory on 02/22/2018.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. These results are in compliance with the 2009 NELAC Standards and the appropriate agencies listed below, unless otherwise noted in the case narrative. This analytical report should be reproduced in its entirety.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Jessica Esser

**Project Manager** 

Certification	List		Expires
ADEQ	Arkansas Department of Environmental Quality	17-065-0	09/26/2018
DODELAP	DOD ELAP Accreditation (A2LA)	3269.01	03/31/2018
ILEPA	Illinois Secondary NELAP Accreditation	003174	04/30/2018
KDHE	Kansas Secondary NELAP Accreditation	E-10384	04/30/2018
LELAP	Louisiana Primary NELAP Accreditation	04165	06/30/2018
NCDEQ	North Carolina Dept. of Environmental Quality Accreditation	688	12/31/2018
NJDEP	New Jersey Secondary NELAP Accreditation	WI004	06/30/2018
ODEQ	Oklahoma Department of Environmental Quality Accreditation	2017-154	08/31/2018
TCEQ	Texas Secondary NELAP Accreditation	T104704504-16-7	11/30/2018
WDNR	Wisconsin Certification under NR 149	113289110	08/31/2018



2525 Advance Road Madison, WI 53718 608.221.8700 Phone 608.221.4889 Fax

TRC Environmental Corporation, Inc.

Project: Madison Kipp - Rain Garden Excavation

708 Heartland Trail, Ste 3000 Madison WI, 53717 Project Number: 268304 Project Manager: Andrew Stehn

#### ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
MH-1A-022118	A180807-01	Soil	02/21/2018	02/22/2018

#### **CASE NARRATIVE**

#### **Sample Receipt Information:**

1 sample was received on 02/22/2018. Sample was received on ice. Sample was received in acceptable condition.

Please see the chain of custody (COC) document at the end of this report for additional information.



708 Heartland Trail, Ste 3000 Madison WI, 53717

 ${\it Surrogate: Decachlorobiphenyl}$ 

Project: Madison Kipp - Rain Garden Excavation

Project Number: 268304 Project Manager: Andrew Stehn

MH-1A-022118

**Date Sampled** 

A180807-01 (Soil)

02/21/2018 14:30

EPA 8082A

Analyte	Result	Limit of Detection	Limit of Quantitation	Units	Dilution	Prepared	Analyzed	Method	Qualifiers
			Pace Analy	tical - Madis	son				
Polychlorinated Biphenyls by EPA M	1ethod 8082					Prep	aration Batch: A	802178	
PCB-1016	ND	0.0094	0.13	mg/kg dry	1	02/26/2018	02/26/2018 17:53	EPA 8082A	
PCB-1221	ND	0.0052	0.13	mg/kg dry	1	02/26/2018	02/26/2018 17:53	EPA 8082A	
PCB-1232	ND	0.0036	0.13	mg/kg dry	1	02/26/2018	02/26/2018 17:53	EPA 8082A	
PCB-1242	ND	0.0056	0.13	mg/kg dry	1	02/26/2018	02/26/2018 17:53	EPA 8082A	
PCB-1248	0.33	0.0067	0.13	mg/kg dry	1	02/26/2018	02/26/2018 17:53	EPA 8082A	
PCB-1254	ND	0.0056	0.13	mg/kg dry	1	02/26/2018	02/26/2018 17:53	EPA 8082A	
PCB-1260	ND	0.0031	0.13	mg/kg dry	1	02/26/2018	02/26/2018 17:53	EPA 8082A	
Total PCBs	0.33	0.0094	0.13	mg/kg dry	1	02/26/2018	02/26/2018 17:53	EPA 8082A	

56.6-128

02/26/2018

02/26/2018 17:53

Surrogate: Tetrachloro-meta-xylene		108 %	69.6-121		02/26/2018	02/26/2018 17:53	EPA 8082A
Classical Chemistry Parameters					Prepa	aration Batch: A8	02179
% Solids	78.7	0.00	% by Weight	1	02/26/2018	02/28/2018 11:24	SM 2540B

96.6 %



Project: Madison Kipp - Rain Garden Excavation

708 Heartland Trail, Ste 3000 Madison WI, 53717 Project Number: 268304 Project Manager: Andrew Stehn

#### Polychlorinated Biphenyls by EPA Method 8082 - Quality Control Pace Analytical - Madison

Analyte	Result	Limit of Quantitation	Units	Spike Level	-		%REC Limits	RPD	RPD Limit	Notes
Batch A802178 - EPA 3570										
Blank (A802178-BLK1)			Prep	oared: 02/26	5/2018 Ana	ılyzed: 02/2	26/2018 17:2	28		
PCB-1016	ND	0.10	mg/kg wet							
PCB-1221	ND	0.10	mg/kg wet							
PCB-1232	ND	0.10	mg/kg wet							
PCB-1242	ND	0.10	mg/kg wet							
PCB-1248	ND	0.10	mg/kg wet							
PCB-1254	ND	0.10	mg/kg wet							
PCB-1260	ND	0.10	mg/kg wet							
Total PCBs	ND	0.10	mg/kg wet							
Surrogate: Decachlorobiphenyl	0.256		mg/kg wet	0.2400		107	56.6-128			
Surrogate: Tetrachloro-meta-xylene	0.263		mg/kg wet	0.2400		110	69.6-121			
LCS (A802178-BS1)			Prep	pared: 02/26	5/2018 Ana	ılyzed: 02/2	26/2018 17:0	)3		
PCB-1248	1.93	0.10	mg/kg wet	2.000		96.6	74.4-123			
Surrogate: Decachlorobiphenyl	0.227		mg/kg wet	0.2400		94.5	56.6-128			
Surrogate: Tetrachloro-meta-xylene	0.233		mg/kg wet	0.2400		97.1	69.6-121			
Matrix Spike (A802178-MS1)	Source: A	180807-01	Prep	pared: 02/26	5/2018 Ana	ılyzed: 02/2	26/2018 18:1	8		
PCB-1248	2.83	0.13	mg/kg dry	2.543	0.329	98.2	61.9-141			
Surrogate: Decachlorobiphenyl	0.292		mg/kg dry	0.3051		95.7	56.6-128			
Surrogate: Tetrachloro-meta-xylene	0.333		mg/kg dry	0.3051		109	69.6-121			
Matrix Spike Dup (A802178-MSD1)	Source: A	180807-01	Prep	pared: 02/26	5/2018 Ana	alyzed: 02/2	26/2018 18:4	13		
PCB-1248	2.90	0.13	mg/kg dry	2.543	0.329	101	61.9-141	2.55	20	
Surrogate: Decachlorobiphenyl	0.293		mg/kg dry	0.3051		96.0	56.6-128			
Surrogate: Tetrachloro-meta-xylene	0.337		mg/kg dry	0.3051		110	69.6-121			



Project: Madison Kipp - Rain Garden Excavation

708 Heartland Trail, Ste 3000 Madison WI, 53717 Project Number: 268304 Project Manager: Andrew Stehn

#### **Classical Chemistry Parameters - Quality Control**

#### Pace Analytical - Madison

		Limit of		Spike	Source		%REC		RPD	
Analyte	Result	Quantitation	Units	Level	Result	%REC	Limits	RPD	Limit	Notes

**Batch A802179 - % Solids** 

Duplicate (A802179-DUP1)	Source: A18080	<b>07-01</b> Prepared: 02/26	/2018 Analyzed: 02/28/2018 11:2		
% Solids	74.9	0.00 % by Weight	78.7	4.88	20





TRC Environmental Corporation, Inc. Project: Madison Kipp - Rain Garden Excavation

708 Heartland Trail, Ste 3000 Project Number: 268304
Madison WI, 53717 Project Manager: Andrew Stehn

#### **Notes and Definitions**

ND Analyte NOT DETECTED at or above the reporting limit

NR Not Reported

dry Sample results reported on a dry weight basis. If the word 'dry' does not appear after the units, results are reported on an as-is basis.

RPD Relative Percent Difference

## Pace Analytical \* ECCS Mobile Lab Services

#### Pace Analytical - ECCS Division

2525 Advance Road Madison, WI 53718 608-221-8700 (phone)

### **CHAIN OF CUSTODY**

No. 8309

Page:

of:

608-221-8700 (phone) 608-221-4889 (fax)				Lab Work Order #:						Report To: ANDREW STEHN				
				Δ	16	308	307			Compa	iny: TRC			
Project Number: 268304 PO Number: 1034	78				Pr	eserva	tion Co	des		Addres	s1: 708 Heartland	Truil		
Project Name: MKC - Kain Garden	_				An	alyses	Reque	sted		Address 2: Suite 3000				
Project Location (City, State): Madison、 Wエ				Α						E-mail	Address: astehn o		ins. com	
Turn Around (check one): 🔀 Normal 🔲 Rush				·						Invoice				
If Rush, Report Due Date:			iners							Compa	iny: u.s. C	toole		
Sampled By (Print): ANDREW STEHN UNL A			Sonta	8					000000000000000000000000000000000000000	Addres	s 1:			
			# of C	8			of all factors and a second		00000000000000000000000000000000000000	Addres	s 2:	***************************************	Annania and An	
	ïme	Matrix	Total # of Containers	PC							Comments	Lab ID	Lab Receipt Time	
MH-1A-022118 02/21/18 14:	: 30	S	1	Χ								01		
										***************************************	TOTAL PROMISE AND THE PROPERTY OF THE PROPERTY			
					**************************************									
								mineral control of the control of th						
											Ottober State (1964 to 20 finds the street of the state o			
											· · · · · · · · · · · · · · · · · · ·			
												<u> </u>	······	
	and to													
Preservation Codes A=None B=HCL C=H <sub>2</sub> SO <sub>4</sub> Other Comments:  Relinquished By:	21	*				Date: <i>02/ 2</i> (	110	Time:	20	Receive	Darca Cook	Date:	Time:	
D=HNO <sub>3</sub> E=EnCore F=Methanol Relinquished By:	<u> </u>					Date:	110	Time:	70	Regeive	ed By:	Date:	Time:	
G=NaOH O=Other (Indicate)  Matrix Codes  Custody Seal:					China	ed Via		Doo:	pt Terr					
A=Air S=Soil W=Water O=Other Custody Seal:	ntact	☐ No	t Intac		, ,	led VIa Kら			U (C		Thermometer #/ Exp. Date:		Blank:	



May 17, 2018

Ben Wachholz TRC Environmental Corporation, Inc. 230 W Monroe St, Suite 510 Chicago, IL 60606

RE: MKC Storm Sewer/Raingarden - Madison, WI

Enclosed are the analytical results for the samples received by the laboratory on 05/11/2018.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. These results are in compliance with the 2009 NELAC Standards and the appropriate agencies listed below, unless otherwise noted in the case narrative. This analytical report should be reproduced in its entirety.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Jessica Esser

**Project Manager** 

Certification	List		Expires
ADEQ	Arkansas Department of Environmental Quality	17-065-0	09/26/2018
DODELAP	DOD ELAP Accreditation (A2LA)	3269.01	03/31/2019
ILEPA	Illinois Secondary NELAP Accreditation	004366	04/30/2019
KDHE	Kansas Secondary NELAP Accreditation	E-10384	04/30/2019
LELAP	Louisiana Primary NELAP Accreditation	04165	06/30/2018
NCDEQ	North Carolina Dept. of Environmental Quality Accreditation	688	12/31/2018
NJDEP	New Jersey Secondary NELAP Accreditation	WI004	06/30/2018
ODEQ	Oklahoma Department of Environmental Quality Accreditation	2017-154	08/31/2018
TCEQ	Texas Secondary NELAP Accreditation	T104704504-16-7	11/30/2018
WDNR	Wisconsin Certification under NR 149	113289110	08/31/2018



2525 Advance Road Madison, WI 53718 608.221.8700 Phone 608.221.4889 Fax

TRC Environmental Corporation, Inc.

Project: MKC Storm Sewer/Raingarden - Madison, WI

230 W Monroe St, Suite 510 Chicago IL, 60606

Project Number: 268304 Project Manager: Ben Wachholz

#### ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
OUTFALL PIPE-051018	A181916-01	Soil	05/10/2018	05/11/2018
MH-1A-051018	A181916-02	Soil	05/10/2018	05/11/2018

#### **CASE NARRATIVE**

#### **Sample Receipt Information:**

2 samples were received on 05/11/2018. Samples were received on ice. Samples were received in acceptable condition.

Please see the chain of custody (COC) document at the end of this report for additional information.



230 W Monroe St, Suite 510 Chicago IL, 60606

Surrogate: Decachlorobiphenyl

Project: MKC Storm Sewer/Raingarden - Madison, WI

Project Number: 268304 Project Manager: Ben Wachholz

#### **OUTFALL PIPE-051018**

**Date Sampled** 05/10/2018 13:30

EPA 8082A

A181916-01 (Soil)

		Limit of	Limit of						- 1
Analyte	Result	Detection	Quantitation	Units	Dilution	Prepared	Analyzed	Method	Qualifiers

Pace Analytical - Madison											
Polychlorinated Biphenyls by EPA Method 8082 Preparation Batch: A805176											
PCB-1016	ND	0.0099	0.13	mg/kg dry	1	05/15/2018	05/15/2018 12:44	EPA 8082A			
PCB-1221	ND	0.0055	0.13	mg/kg dry	1	05/15/2018	05/15/2018 12:44	EPA 8082A			
PCB-1232	ND	0.0038	0.13	mg/kg dry	1	05/15/2018	05/15/2018 12:44	EPA 8082A			
PCB-1242	ND	0.0059	0.13	mg/kg dry	1	05/15/2018	05/15/2018 12:44	EPA 8082A			
PCB-1248	1.9	0.0071	0.13	mg/kg dry	1	05/15/2018	05/15/2018 12:44	EPA 8082A			
PCB-1254	ND	0.0059	0.13	mg/kg dry	1	05/15/2018	05/15/2018 12:44	EPA 8082A			
PCB-1260	ND	0.0032	0.13	mg/kg dry	1	05/15/2018	05/15/2018 12:44	EPA 8082A			
Total PCBs	1.9	0.0099	0.13	mg/kg dry	1	05/15/2018	05/15/2018 12:44	EPA 8082A			

56.6-128

05/15/2018

05/15/2018 12:44

Surrogate: Tetrachloro-meta-xylene		101 %	69.6-121		05/15/2018	05/15/2018 12:44	EPA 8082A
Classical Chemistry Parameters					Prepa	aration Batch: A8	05178
% Solids	74.4	0.00	% by Weight	1	05/15/2018	05/16/2018 08:22	SM 2540B

97.5 %



Project: MKC Storm Sewer/Raingarden - Madison, WI

230 W Monroe St, Suite 510 Chicago IL, 60606 Project Number: 268304 Project Manager: Ben Wachholz

MH-1A-051018

A181916-02 (Soil)

Date Sampled 05/10/2018 15:15

Analyte	Result	Limit of Detection	Limit of Quantitation	Units	Dilution	Prepared	Analyzed	Method	Qualifiers
			Pace Analy	tical - Madiso	on				
Polychlorinated Biphenyls by EPA Method 8082 Preparation Batch: A805176									
PCB-1016	ND	0.0083	0.11	mg/kg dry	1	05/15/2018	05/15/2018 14:28	EPA 8082A	
PCB-1221	ND	0.0046	0.11	mg/kg dry	1	05/15/2018	05/15/2018 14:28	EPA 8082A	
PCB-1232	ND	0.0031	0.11	mg/kg dry	1	05/15/2018	05/15/2018 14:28	EPA 8082A	
PCB-1242	ND	0.0049	0.11	mg/kg dry	1	05/15/2018	05/15/2018 14:28	EPA 8082A	
PCB-1248	0.15	0.0059	0.11	mg/kg dry	1	05/15/2018	05/15/2018 14:28	EPA 8082A	
PCB-1254	ND	0.0049	0.11	mg/kg dry	1	05/15/2018	05/15/2018 14:28	EPA 8082A	
PCB-1260	ND	0.0027	0.11	mg/kg dry	1	05/15/2018	05/15/2018 14:28	EPA 8082A	
Total PCBs	0.15	0.0083	0.11	mg/kg dry	1	05/15/2018	05/15/2018 14:28	EPA 8082A	
Surrogate: Decachlorobiphenyl			99.3 %	56.6-128		05/15/2018	05/15/2018 14:28	EPA 8082A	
Surrogate: Tetrachloro-meta-xylene			102 %	69.6-121		05/15/2018	05/15/2018 14:28	EPA 8082A	
Classical Chemistry Parameters Preparation Batch: A805178									
% Solids	89.3		0.00	% by Weight	1	05/15/2018	05/16/2018 08:22	SM 2540B	



Project: MKC Storm Sewer/Raingarden - Madison, WI

230 W Monroe St, Suite 510 Chicago IL, 60606 Project Number: 268304 Project Manager: Ben Wachholz

#### Polychlorinated Biphenyls by EPA Method 8082 - Quality Control Pace Analytical - Madison

Analyte	Result	Limit of Quantitation	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch A805176 - EPA 3570		`								
Blank (A805176-BLK1)			Prep	pared: 05/15	5/2018 Ana	alyzed: 05/	15/2018 12:1	19		
PCB-1016	ND	0.10	mg/kg wet							
PCB-1221	ND	0.10	mg/kg wet							
PCB-1232	ND	0.10	mg/kg wet							
PCB-1242	ND	0.10	mg/kg wet							
PCB-1248	ND	0.10	mg/kg wet							
PCB-1254	ND	0.10	mg/kg wet							
PCB-1260	ND	0.10	mg/kg wet							
Total PCBs	ND	0.10	mg/kg wet							
Surrogate: Decachlorobiphenyl	0.231		mg/kg wet	0.2400		96.3	56.6-128			
Surrogate: Tetrachloro-meta-xylene	0.211		mg/kg wet	0.2400		87.8	69.6-121			
LCS (A805176-BS1)			Prep	pared: 05/15	/2018 Ana	alyzed: 05/	15/2018 11:5	54		
PCB-1254	1.77	0.10	mg/kg wet	2.000		88.6	79.1-109			
Surrogate: Decachlorobiphenyl	0.226		mg/kg wet	0.2400		94.0	56.6-128			
Surrogate: Tetrachloro-meta-xylene	0.206		mg/kg wet	0.2400		85.8	69.6-121			
Matrix Spike (A805176-MS1)	Source: A	181916-02	Prep	pared: 05/15	7/2018 Ana	alyzed: 05/	15/2018 15:2	25		
PCB-1254	2.02	0.11	mg/kg dry	2.241	ND	90.0	66.7-124			
Surrogate: Decachlorobiphenyl	0.240		mg/kg dry	0.2689		89.4	56.6-128			
Surrogate: Tetrachloro-meta-xylene	0.239		mg/kg dry	0.2689		88.8	69.6-121			
Matrix Spike Dup (A805176-MSD1)	Source: A	181916-02	Prep	pared: 05/15	7/2018 Ana	alyzed: 05/	15/2018 15:5	50		
PCB-1254	2.22	0.11	mg/kg dry	2.241	ND	99.3	66.7-124	9.82	20	
Surrogate: Decachlorobiphenyl	0.266		mg/kg dry	0.2689		99.1	56.6-128			
Surrogate: Tetrachloro-meta-xylene	0.277		mg/kg dry	0.2689		103	69.6-121			



Project: MKC Storm Sewer/Raingarden - Madison, WI

230 W Monroe St, Suite 510 Chicago IL, 60606 Project Number: 268304 Project Manager: Ben Wachholz

#### **Classical Chemistry Parameters - Quality Control**

#### Pace Analytical - Madison

		Limit of		Spike	Source		%REC		RPD	
Analyte	Result	Quantitation	Units	Level	Result	%REC	Limits	RPD	Limit	Notes

**Batch A805178 - % Solids** 

Duplicate (A805178-DUP1)	Source: A18191	<b>6-02</b> Prepared: 05/15/	2018 Analyzed: 05/16/2018 08:22	2	
% Solids	84.1	0.00 % by Weight	89.3	5.93	20





TRC Environmental Corporation, Inc.

Project: MKC Storm Sewer/Raingarden - Madison, WI

230 W Monroe St, Suite 510 Project Number: 268304
Chicago IL, 60606 Project Manager: Ben Wachholz

#### **Notes and Definitions**

ND Analyte NOT DETECTED at or above the reporting limit

NR Not Reported

dry Sample results reported on a dry weight basis. If the word 'dry' does not appear after the units, results are reported on an as-is basis.

RPD Relative Percent Difference

Date/Time:

Date/Time:

Relinguished By:

Relinguished By:

Received By:

Received By:

Date/Time

Date/Time:

OK / Adjusted

Cooler Custody Seal Present / Not Present

Intact / Not Intact

Samples on HOLD are subject to

special pricing and release of liability

Telephone: