State of Wisconsin Department of Natural Resources PO Box 7921, Madison WI 53707-7921 dnr.wi.gov

### Technical Assistance, Environmental Liability Clarification or Post-Closure Modification Request

Form 4400-237 (R 9/15) Page 1 of 8

**Notice:** Use this form to request a written response (on agency letterhead) from the Department of Natural Resources (DNR) regarding technical assistance, a post-closure change to a site, a specialized agreement or liability clarification for Property with known or suspected environmental contamination. A fee will be required as is authorized by s. 292.55, Wis. Stats., and NR 749, Wis. Adm. Code., unless noted in the instructions below. Personal information collected will be used for administrative purposes and may be provided to requesters to the extent required by Wisconsin's Open Records law [ss. 19.31 - 19.39, Wis. Stats.].

#### Definitions

- "Property" refers to the subject Property that is perceived to have been or has been impacted by the discharge of hazardous substances.
- "Liability Clarification" refers to a written determination by the Department provided in response to a request made on this form. The response clarifies whether a person is or may become liable for the environmental contamination of a Property, as provided in s. 292.55, Wis. Stats.
- "Technical Assistance" refers to the Department's assistance or comments on the planning and implementation of an environmental investigation or environmental cleanup on a Property in response to a request made on this form as provided in s. 292.55, Wis. Stats.
- "Post-closure modification" refers to changes to Property boundaries and/or continuing obligations for Properties or sites that received closure letters for which continuing obligations have been applied or where contamination remains. Many, but not all, of these sites are included on the GIS Registry layer of RR Sites Map to provide public notice of residual contamination and continuing obligations.

#### Select the Correct Form

This from should be used to request the following from the DNR:

- Technical Assistance
- Liability Clarification
- Post-Closure Modifications
- Specialized Agreements (tax cancellation, negotiated agreements, etc.)

#### Do not use this form if one of the following applies:

- Request for an off-site liability exemption or clarification for Property that has been or is perceived to be contaminated by one
  or more hazardous substances that originated on another Property containing the source of the contamination. Use DNR's Off-Site
  Liability Exemption and Liability Clarification Application Form 4400-201.
- Submittal of an Environmental Assessment for the Lender Liability Exemption, s 292.21, Wis. Stats., if no response or review by DNR is requested. Use the Lender Liability Exemption Environmental Assessment Tracking Form 4400-196.
- Request for an exemption to develop on a historic fill site or licensed landfill. Use DNR's Form 4400-226 or 4400-226A.
- Request for closure for Property where the investigation and cleanup actions are completed. Use DNR's Case Closure GIS Registry Form 4400-202.

All forms, publications and additional information are available on the internet at: dnr.wi.gov/topic/Brownfields/Pubs.html

#### Instructions

- Complete sections 1, 2, 6 and 7 for all requests. Be sure to provide adequate and complete information.
- 2. Select the type of assistance requested: Section 3 for technical assistance or post-closure modifications, Section 4 for a written determination or clarification of environmental liabilities; or Section 5 for a specialized agreement.
- 3. Include the fee payment that is listed in Section 3, 4, or 5, unless you are a "Voluntary Party" enrolled in the Voluntary Party Liability Exemption Program and the questions in Section 2 direct otherwise. Information on to whom and where to send the fee is found in Section 8 of this form.
- 4. Send the completed request, supporting materials and the fee to the appropriate DNR regional office where the Property is located. See the map on the last page of this form. A paper copy of the signed form and all reports and supporting materials shall be sent with an electronic copy of the form and supporting materials on a compact disk. For electronic document submittal requirements see: http://dnr.wi.gov/files/PDF/pubs/rr/RR690.pdf\*

The time required for DNR's determination varies depending on the complexity of the site, and the clarity and completeness of the request and supporting documentation.

### Technical Assistance, Environmental Liability Clarification or Post-Closure Modification Request

Form 4400-237 (R 9/15)

Page 2 of 8

Section 1. Contact and Reci	pient intormation			1.15 4.35		
Requester Information	PERSONAL PROPERTY.	5.1	1 25 -1 20			
This is the person requesting tec specialized agreement and is ide	hnical assistance or a post-centified as the requester in Se	losur	e modification revie 7. DNR will addres	w, that his or her liability bes its response letter to this	e clarif s perso	ied or a
Last Name	First	МІ	Organization/ Bus	siness Name		
Meyers	Tom		Phillips Edison	& Company		
Mailing Address	**************************************		City		State	ZIP Code
11501 Northlake Drive			Cincinnati		OH	45249
Phone # (include area code)	Fax # (include area code)		Email			
(513) 554-1110			tmeyers@PHIL	LIPSEDISON.com		
The requester listed above: (sele	ect all that apply)					
Is currently the owner			Is considering s	selling the Property		
Is renting or leasing the Pr	operty		Is considering a	acquiring the Property		
Is a lender with a mortgage	ee interest in the Property					
Other. Explain the status of	of the Property with respect to	the	applicant:			
Contact Information (to be contact Last Name	ontacted with questions a First				et if sar	me as requester
		МІ				
Meyers Mailing Address	Tom		Phillips Edison City	& Company	State	ZIP Code
11501 Northlake Drive			Cincinnati		OH	45249
Phone # (include area code)	Fax # (include area code)		Email		On	43249
(513) 554-1110			tmevers@PHII	LIPSEDISON.com		
Environmental Consultant	(if applicable)		aneyero(e), Title	ZH BEDISOT GOIN		
Contact Last Name	First	Mi	Organization/ Bus	siness Name		
Newlin	Steve	T	Apex Companie	es LLC		
Mailing Address			City		State	ZIP Code
300 South Wacker Drive, Sui	te 630		Chicago		IL	60606
Phone # (include area code)	Fax # (include area code)		Email			W 255,015,015
(847) 956-8589			snewlin@apexc	os.com		
Section 2. Property Information	ก์		725			6 1 1 10
Property Name				FID No. (	if know	n)
Bright Cleaners				2419289	40	
BRRTS No. (if known)			Parcel Identification	on Number		
02-41-580017			7550192003			
Street Address			City		State	ZIP Code
7249 S 76TH ST			Franklin		IL	53132
County Mur	nicipality where the Property	is loc	ated	Property is composed of:		perty Size Acres
Milwankee	City O Town O Village of	Fran	klin	Single tax Multiple	tax	

#### Technical Assistance, Environmental Liability Clarification or Post-Closure Modification Request

Form 4400-237 (R 9/15)

Page 3 of 8

1.	<ol> <li>Is a response needed by a specific date? (e.g., Proper plan accordingly.</li> </ol>	erty closing date) Note: Most requests are completed within 60 days. Please
	No  ○ Yes	
	Date requested by:	_
	Reason:	
	-	
2.	2. Is the "Requester" enrolled as a Voluntary Party in the	
	No. Include the fee that is required for your re-	
	Yes. Do not include a separate fee. This reques	st will be billed separately through the VPLE Program.
	Fill out the information in Section 3, 4 or 5 which Section 3. Technical Assistance or Post-Closus Section 4. Liability Clarification; or Section 5. S	e Modifications;
S	Section 3. Request for Technical Assistance or Po	HOLI WAY DOWN AND THAT I DAMPEN.
s	Select the type of technical assistance requested: [Nun	bers in brackets are for WI DNR Use]
	No Further Action Letter (NFA) (Immediate Action an immediate action after a discharge of a	ctions) - NR 708.09, [183] - <b>Include a fee of \$350.</b> Use for a written response hazardous substance occurs. Generally, these are for a one-time spill event.
	Review of Site Investigation Work Plan - NR 7	16.09, [135] - <b>include a fee of \$700</b> .
	Review of Site Investigation Report - NR 716.	15, [137] - Include a fee of \$1050.
	Approval of a Site-Specific Soil Cleanup Stand	dard - NR 720.10 or 12, [67] - <b>Include a fee of \$1050</b> .
	Review of a Remedial Action Options Report	- NR 722.13, [143] - Include a fee of \$1050.
	Review of a Remedial Action Design Report -	NR 724.09, [148] - Include a fee of \$1050.
	Review of a Remedial Action Documentation	Report - NR 724.15, [152] - Include a fee of \$350
	Review of a Long-term Monitoring Plan - NR	'24.17, [25] - Include a fee of <b>\$425</b> .
	Review of an Operation and Maintenance Pla	n - NR 724.13, [192] - Include a fee of \$425.
	Other Technical Assistance - s. 292.55, Wis. Stats.	[97] (For request to build on an abandoned landfill use Form 4400-226)
	Schedule a Technical Assistance Meeting - In	nclude a fee of \$700.
	Hazardous Waste Determination - Include a	fee of \$700.
	Other Technical Assistance - Include a fee of	f \$700. Explain your request in an attachment.
	Post-Closure Modifications - NR 727, [181]	
	Post-Closure Modifications: Modification to Posites may be on the GIS Registry. This also in \$1050, and:	roperty boundaries and/or continuing obligations of a closed site or Property; ncludes removal of a site or Property from the GIS Registry. Include a fee of
	Include a fee of \$300 for sites with residua	Il soil contamination; and
	Include a fee of \$350 for sites with residual obligations.	al groundwater contamination, monitoring wells or for vapor intrusion continuing
	to a Property, site or continuing obligation will may be submitted later in the approval proces	roposing, and documentation as to why the changes are needed (if the change result in revised maps, maintenance plans or photographs, those documents s, on a case-by-case basis).  Eyou are requesting is listed above and complete Sections 6 and 7 of this

#### Technical Assistance, Environmental Liability Clarification or Post-Closure Modification Request

Form 4400-237 (R 9/15) Page 4 of 8

Section 4. Request for Liability Clarification  Select the type of liability clarification requested. Use the available space given or attach information, explanations, or specific questions that you need answered in DNR's reply. Complete Sections 6 and 7 of this form. [Numbers In brackets are for DNR Use]
"Lender" liability exemption clarification - s. 292.21, Wis. Stats. [686]
♦ Include a fee of \$700.
Provide the following documentation:
(1) ownership status of the real Property, and/or the personal Property and fixtures;
(2) an environmental assessment, in accordance with s. 292.21, Wis. Stats.;
(3) the date the environmental assessment was conducted by the lender;
(4) the date of the Property acquisition; for foreclosure actions, include a copy of the signed and dated court order confirming the sheriff's sale.
(5) documentation showing how the Property was acquired and the steps followed under the appropriate state statutes.
(6) a copy of the Property deed with the correct legal description; and,
(7) the Lender Liability Exemption Environmental Assessment Tracking Form (Form 4400-196).
(8) If no sampling was done, please provide reasoning as to why it was <b>not</b> conducted. Include this either in the accompanying environmental assessment or as an attachment to this form, and cite language in s. 292. 21(1)(c)2.,hi., Wis. Stats.:
h. The collection and analysis of representative samples of soil or other materials in the ground that are suspected of being contaminated based on observations made during a visual inspection of the real Property or based on aerial photographs, or other information available to the lender, including stained or discolored soil or other materials in the ground and including soil or materials in the ground in areas with dead or distressed vegetation. The collection and analysis shall identify contaminants in the soil or other materials in the ground and shall quantify concentrations.
i. The collection and analysis of representative samples of unknown wastes or potentially hazardous substances found on the real Property and the determination of concentrations of hazardous waste and hazardous substances found in tanks, drums or other containers or in piles or lagoons on the real Property.
Representative" liability exemption clarification (e.g. trustees, receivers, etc.) - s. 292.21, Wis. Stats. [686]
♦ Include a fee of \$700.
Provide the following documentation:
(1) ownership status of the Property;
(2) the date of Property acquisition by the representative;
(3) the means by which the Property was acquired;
(4) documentation that the representative has no beneficial interest in any entity that owns, possesses, or controls the Property;
(5) documentation that the representative has not caused any discharge of a hazardous substance on the Property; and
(6) a copy of the Property deed with the correct legal description.
[ Clarification of local governmental unit (LGU) liability exemption at sites with: (select all that apply)
hazardous substances spills - s. 292.11(9)(e), Wis. Stats. [649];
Perceived environmental contamination - [649];
hazardous waste - s. 292.24 (2), Wis. Stats. [649]; and/or
solid waste - s. 292.23 (2), Wis. Stats. [649].
Include a fee of \$700, a summary of the environmental liability clarification being requested, and the following:
<ol><li>(1) clear supporting documentation showing the acquisition method used, and the steps followed under the appropriate state statute(s).</li></ol>
(2) current and proposed ownership status of the Property;
(3) date and means by which the Property was acquired by the LGU, where applicable;
(4) a map and the ¼, ¼ section location of the Property;
(5) summary of current uses of the Property;
(6) intended or potential use(s) of the Property;

(7) descriptions of other investigations that have taken place on the Property; and(8) (for solid waste clarifications) a summary of the license history of the facility.

## Technical Assistance, Environmental Liability Clarification or Post-Closure Modification Request Form 4400-237 (R 9/15) Page 5 of 8

ection 4. Request for Elability Clarification (cont.)
Lease liability clarification - s. 292.55, Wis. Stats. [646]
Include a fee of \$700 for a single Property, or \$1400 for multiple Properties and the information listed below:
(1) a copy of the proposed lease;
(2) the name of the current owner of the Property and the person who will lease the Property;
<ul> <li>(3) a description of the lease holder's association with any persons who have possession, control, or caused a discharge of a hazardous substance on the Property;</li> </ul>
(4) map(s) showing the Property location and any suspected or known sources of contamination detected on the Property;
(5) a description of the intended use of the Property by the lease holder, with reference to the maps to indicate which areas will be used. Explain how the use will not interfere with any future investigation or cleanup at the Property; and
(6) all reports or investigations (e.g. Phase I and Phase II Environmental Assessments and/or Site Investigation Reports conducted under s. NR 716, Wis. Adm. Code) that identify areas of the Property where a discharge has occurred.
General or other environmental liability clarification - s. 292.55, Wis. Stats. [682] - Explain your request below.
Include a fee of \$700 and an adequate summary of relevant environmental work to date.
No Action Required (NAR) - NR 716.05, [682]  ❖ Include a fee of \$700.
Use where an environmental discharge has or has not occurred, and applicant wants a DNR determination that no further assessment or clean-up work is required. Usually this is requested after a Phase I and Phase II environmental assessment has been conducted; the assessment reports should be submitted with this form. This is not a closure letter.
Clarify the liability associated with a "closed" Property - s. 292.55, Wis. Stats. [682]
Include a fee of \$700.
- Include a copy of any closure documents if a state agency other than DNR approved the closure.
se this space or attach additional sheets to provide necessary information, explanations or specific questions to be answered by the

Use this space or attach additional sheets to provide necessary information, explanations or specific questions to be answered by the DNR.

#### Technical Assistance, Environmental Liability Clarification or Post-Closure Modification Request

Form 4400-237 (R 9/15)

Page 6 of 8

Section 5. Request for a Specialized Agreement
Select the type of agreement needed. Include the appropriate draft agreements and supporting materials. Complete Sections 6 and 7 of this form. More information and model draft agreements are available at: <a href="mailto:dnr.wi.gov/topic/Brownfields/lgu.html#tabx4">dnr.wi.gov/topic/Brownfields/lgu.html#tabx4</a> .
Tax cancellation agreement - s. 75.105(2)(d), Wis. Stats. [654]
Include a fee of \$700, and the information listed below:
<ul> <li>(1) Phase I and II Environmental Site Assessment Reports,</li> <li>(2) a copy of the Property deed with the correct legal description; and,</li> <li>(3) a draft 75.105 agreement based on the DNR's model (dnr.wi.gov/topic/brownfields/documents/mod75-105agrmt.pdf).</li> </ul>
Agreement for assignment of tax foreclosure judgement - s.75.106, Wis. Stats. [666]
Include a fee of \$700, and the information listed below:
<ul> <li>(1) Phase I and II Environmental Site Assessment Reports,</li> <li>(2) a copy of the Property deed with the correct legal description; and,</li> <li>(3) a draft 75.105 agreement based on the DNR's model (dnr.wi.gov/topic/brownfields/documents/mod75-106agrmt.pdf).</li> </ul>
Negotiated agreement - Enforceable contract for non-emergency remediation - s. 292.11(7)(d) and (e), Wis. Stats. [630]
Include a fee of \$1400, and the information listed below:
<ul><li>(1) a draft schedule for remediation; and,</li><li>(2) the name, mailing address, phone and email for each party to the agreement.</li></ul>
Section 6. Other Information Submitted
Identify all materials that are included with this request.
Include one copy of any document from any state agency files that you want the Department to review as part of this request. The person submitting this request is responsible for contacting other state agencies to obtain appropriate reports or information.
Phase I Environmental Site Assessment Report - Date:
Phase II Environmental Site Assessment Report - Date:
Legal Description of Property (required for all liability requests and specialized agreements)
Map of the Property (required for all liability requests and specialized agreements)
Analytical results of the following sampled media: Select all that apply and include date of collection.

For Property with newly identified discharges of hazardous substances only: Has a notification of a discharge of a hazardous substance been sent to the DNR as required by s. NR 706.05(1)(b), Wis. Adm. Code?

Other medium - Describe:

Yes - Date (if known):

Other report(s) or information - Describe:

☐ Soil

☐ Draft agreement for assignment of tax foreclosure judgment

A copy of the closure letter and submittal materials

Groundwater

Date of Collection:

☐ Draft tax cancellation agreement

Note: The Notification for Hazardous Substance Discharge (non-emergency) form is available at: <a href="https://dnc.wi.gov/files/PDF/forms/4400/4400-225.pdf">dnc.wi.gov/files/PDF/forms/4400/4400-225.pdf</a>.

Sediment

# Technical Assistance, Environmental Liability Clarification or Post-Closure Modification Request Form 4400-237 (R 9/15) Page 7 of 8

	Section 7. Certification by the Person who completed this form	
	I am the person submitting this request (requester)	
	I prepared this request for:	_
	Requester Name	
	I certify that I am familiar with the information submitted on this request, and true, accurate and complete to the best of my knowledge. I also certify I have this request.	the legal authority and the applicant's permission to make
_	Signature	Date Signed
	RVP, Portfolio Management	513.554·1110
	Title	Telephone Number (include area code)

#### Technical Assistance, Environmental Liability Clarification or Post-Closure Modification Request

Form 4400-237 (R 9/15)

Page 8 of 8

#### Section 8. DNR Contacts and Addresses for Request Submittals

Send or deliver one paper copy and one electronic copy on a compact disk of the completed request, supporting materials, and fee to the region where the property is located to the address below. Contact a <u>DNR regional brownfields specialist</u> with any questions about this form or a specific situation involving a contaminated property. For electronic document submittal requirements see: <a href="http://dnr.wi.gov/files/PDF/pubs/rr/RR690.pdf">http://dnr.wi.gov/files/PDF/pubs/rr/RR690.pdf</a>.

#### **DNR NORTHERN REGION**

Attn: RR Program Assistant Department of Natural Resources 223 E Steinfest Rd Antigo, WI 54409

#### **DNR NORTHEAST REGION**

Attn: RR Program Assistant Department of Natural Resources 2984 Shawano Avenue Green Bay WI 54313

#### **DNR SOUTH CENTRAL REGION**

Attn: RR Program Assistant Department of Natural Resources 3911 Fish Hatchery Road Fitchburg WI 53711

#### **DNR SOUTHEAST REGION**

Attn: RR Program Assistant Department of Natural Resources 2300 North Martin Luther King Drive Milwaukee WI 53212

#### **DNR WEST CENTRAL REGION**

Attn: RR Program Assistant Department of Natural Resources 1300 Clairemont Ave. Eau Claire WI 54702



Note: These ere the Remediation and Redevelopment Program's designated regions. Other DNR program regional boundaries may be different.

		DNR Use Only	
Date Received	Date Assigned	BRRTS Activity Code	BRRTS No (if used)
DNR Reviewer		Comments	
Fee Enclosed?	Fee Amount	Date Additional Information Requested	Date Requested for DNR Response Letter
○ Yes ○ No	\$		
Date Approved	Final Determination		



# Remedial Action Options and Design Report

for

Bright Cleaners Tenant Space 7249 South 76th Street Franklin, Milwaukee County, Wisconsin

> DNR FID #241928940 DNR BRRTS #02-41-580017

> > January 24, 2018

Apex Project No. PECO\_2017-101

Prepared for:

Franklin Station LLC, c/o Phillips Edison & Company 11501 Northlake Drive Cincinnati, Ohio 45249



January 24, 2018

Mr. Eric Amadi State of Wisconsin Department of Natural Resources Southeast Region Headquarters 2300 N. Dr. Martin Luther King, Jr. Drive Milwaukee, Wisconsin 53212-3128

Re: Remedial Action Options and Design Report Bright Cleaners Tenant Space 7249 South 79<sup>th</sup> Street, Franklin, Wisconsin Wisconsin DNR Facility Identification #241928940 Wisconsin DNR BRRTS Activity #02-41-580017

Dear Mr. Amadi:

Franklin Station LLC retained Apex to prepare this Remedial Action Options and Design Report for the dry cleaner tenant space at 7249 South 76th Street in Franklin, Wisconsin. This tenant space is located within Franklin Centre, a multi-tenant retail strip mall.

Historical records show dry cleaning operations have been conducted in the tenant space from 1995 to present. Soil-gas testing identified volatile organic compounds (VOCs) impacts beneath the floor slab of the tenant space. To close this release, some form of mitigation will be required.

Enclosed is Apex's Remedial Action Options and Design Report. Franklin Station LLC is requesting the Wisconsin DNR to review the attached report. Enclosed is Form 4400-237 and a check for \$1,050.

If you have any questions regarding our findings, please contact Steve Newlin at (847) 956-8589 x3201. Thank you for attention to this matter.

Respectfully Submitted,

**Apex Companies, LLC** 

Jen Alla

Jane Allan Project Manager Steve Newlin

Senior Project Manager

Steve 7 Newlin

cc: Mr. Tom Meyers, Franklin Station LLC

Attachments

#### **TABLE OF CONTENTS**

1.0	BACKGROUND 1
1.1	Site Description1
1.2	Site History1
1.3	Previous Reports & Agency Correspondence
2.0	SUMMARY OF RESULTS4
2.1	Soil Conditions
2.2	Groundwater Conditions
2.3	Soil-Gas Analysis6
3.0	REMEDIAL OPTIONS
4.0	REMEDIAL DESIGN
4.1	Installation of Sub-Slab Depressurization System

#### **FIGURES**

Figure 1: Site Location Map

Figure 2: Site Plan

Figure 3: Site Detail Showing Sample Locations

Figure 4: Cross Section A-A'

Figure 5: Site Detail Showing Groundwater Contours

Figure 6: Site Detail Showing Soil-Vapor VOC Exceedances

#### **TABLES**

Table 1: Summary of Soil Data for Volatile Organic Compounds

Table 2: Summary of Groundwater Data for Volatile Organic Compounds
Table 3: Summary of Soil-gas Data for Volatile Organic Compounds

#### **APPENDICES**

Appendix A: Site Photographs

Appendix B: Field Protocols, Soil-Gas Sample Logs & Well Data Sheets

Appendix C: Boring Logs, Well Construction Diagrams & Wisconsin DNR Well and Borehole Forms

Appendix D: Groundwater Elevation Measurements & Slug Test Analysis

Appendix E: Laboratory Reports
Appendix F: Fan Specifications



#### REMEDIAL ACTION OPTIONS AND DESIGN REPORT FRANKLIN CLEANERS TENANT SPACE, FRANKLIN CENTRE 7249 SOUTH 76<sup>TH</sup> STREET FRANKLIN, MILWAUKEE COUNTY, WISCONSIN

#### 1.0 BACKGROUND

Franklin Station LLC (Client) retained Apex Companies, LLC (Apex) to prepare this report in association with the dry cleaner tenant space at 7249 South 76th Street in Franklin, Wisconsin (the Site). This Site is located within Client's Franklin Centre, a retail strip mall located at 7199-7255 South 76th Street in Franklin, Milwaukee County, Wisconsin. The general vicinity of the Site is shown in **Figure 1**.

As directed by the Wisconsin Department of Natural Resources (DNR), in its letter dated August 22, 2017, Franklin Station LLC has submitted a Site Remediation Report to the DNR and is required to submit a remedial actions options and design report for pursuing closure for volatile organic compounds (VOCs) exceeding applicable standards for soil-gas in the immediate vicinity of the Site. Apex has prepared this report to describe the interim steps for media-specific remediation for the pursuit of agency closure.

#### 1.1 Site Description

The Site is located within the Franklin Centre (the Parent Tract) that consists of a 14.6-acre parcel of land developed with a 120,000-square foot (SF) multi-tenant shopping center, asphalt-paved parking and landscaped areas. Franklin Centre is bounded to the north by an outparcel bank, restaurant, and a multi-tenant commercial retail building followed by W Rawson Avenue; to the east by two outparcel banks and a restaurant followed by S 76th Street; to the south by undeveloped properties and condominium properties followed by Terrace Drive; and to the west by undeveloped properties followed by W Loomis Road/Wisconsin 36. The Site configuration and the adjoining properties are shown in the Site Plan provided as **Figure 2**. Photographs of the Site are included in Appendix A.

#### 1.2 Site History

Historical records show two dry cleaning businesses have operated dry cleaning plants at the Site: Sun Cleaners in 1995 and Bright Cleaners from 1999 to present. Analysis of soil and soil-gas samples detected VOCs at concentration in excess of Soil Residual Contaminant Levels (RCLs) and sub-slab Vapor Action Levels (VALs) cited in Wisconsin regulations. Analysis of groundwater samples did not detect VOCs at concentrations in excess of Groundwater Quality Standards (GQSs) cited in Wisconsin regulations, and it is Apex's opinion that additional groundwater investigation is not warranted. The results of environmental testing were described in Apex's report titled Site Investigation Report, Bright Cleaners Tenant Space, Franklin Centre, 7249 South 76th Street, Franklin, Wisconsin, dated November 3, 2017.

The Wisconsin DNR requires that closure be obtained for VOCs exceeding applicable standards. To meet the agency requirements, remedial action will be required to achieve the applicable cleanup



criteria and to mitigate potential vapor intrusion of VOCs to indoor air. Additionally, periodic reporting to the Wisconsin DNR will be needed to show compliance and to pursue agency closure.

#### 1.3 Previous Reports & Agency Correspondence

Phase I ESA (2016). Apex's September 2016 Phase I ESA report included review of a previous reports by Weaver Boos Consultants North Central, LLC (Weaver) titled *Phase I and Phase II Environmental Site Assessment, Franklin Centre – Parcel 1, 7201 76<sup>th</sup> Street, Franklin, Wisconsin 53132*, dated May 6, 2001; *Phase I Environmental Site Assessment, 7201 South 76<sup>th</sup> Street, Franklin, Wisconsin*, dated May 27, 2011; *Limited Phase II Environmental Site Assessment Report, Bright Cleaners, 7249 South 76<sup>th</sup> Street, Franklin, Wisconsin*, dated June 17, 2011; *and, Supplemental Response Activities, Bright Cleaners, 7249 South 76<sup>th</sup> Street, Franklin, Wisconsin*, dated June 28, 2011. The use of dry cleaning solvents at Bright Cleaners was identified as a Recognized Environmental Condition (REC).

**Phase I ESA (2001 and 2011).** In its 2011 Phase I ESA report, Weaver identified the potential presence of subsurface impacts associated with an active drycleaner facility at the Site. Weaver referenced a previous Phase I and Phase II ESA that they conducted at the Site in 2001. According to the 2001 Phase I ESA, Weaver observed staining on the floor in proximity of the dry cleaning machine and improperly stored hazardous materials.

**Results of Soil Analysis (2001)**. Weaver advanced three soil borings in the vicinity of the dry cleaning machine and outside of the tenant space. Soil samples were analyzed for volatile organic compounds (VOCs). Analytical results were below laboratory detection limits.

Results of Soil Analysis (2011). Weaver conducted a Limited Phase II ESA in June 2011 that included the collection of six soil samples from three soil boring locations for VOC analysis. Weaver compared the laboratory results to the Wisconsin Department of Natural Resources' (Wisconsin DNR) Residual Contaminant Levels (RCLs). One soil sample located outside of the Bright Cleaners by the rear door (SP-1 / 2-4') was found to have concentrations of 1,1,1 trichloroethane (1,1,1-TCA) that exceed the RCLs. The deeper sample from SP-1 had 1,1,1-TCA concentrations below RCLs. Weaver did not encounter groundwater during the Limited Phase II ESA. Weaver concluded that VOC impacts appear to be limited to shallow subsurface soils near SP-1.

Supplemental Response Activities (2011). Weaver conducted additional activities at the Site in response to the results of the Limited Phase II ESA in June 2011. Weaver collected six additional shallow soil samples that were analyzed for VOCs to delineate the extent of contamination beyond SP-1. VOCs were not detected at concentrations in excess of laboratory Method Detection Limits (MDLs). Weaver excavated approximately 58 tons of soil in the vicinity of SP-1. Five confirmatory soil samples were collected from the excavation and analyzed for VOCs. Concentrations of VOCs were not found above RCLs in the five confirmatory samples. Weaver concluded that mitigation of the VOC impacts at the Site was successful.



**Correspondence from Wisconsin DNR (2013).** Apex reviewed a letter from the Wisconsin DNR<sup>1</sup> titled *Final Case Closure, Bright Cleaners, 7249 South 76<sup>th</sup> Street, Franklin, WI, DNR BRRTS Activity* #: 02-41-557111, FID #: 241928940, dated December 27, 2013. In its letter, the Wisconsin DNR stated that the release at Bright Cleaners is closed and no further investigation or remediation was required at that time. Apex notes that Bright Cleaners continued to operate the dry cleaning plant from 2011 to the present.

**Phase II Limited Subsurface Investigation (2016).** To assess the risk of subsurface impacts associated with the continued use of dry cleaning solvents at the Bright Cleaners tenant space since 2011, Apex conducted subsurface assessment on August 31, 2016.

Subsurface assessment included collection of soil samples from three exterior borings (TW-1 through TW-3); collection of groundwater samples from two temporary monitoring wells (TW-1 and TW-3); and collection of sub-slab soil-gas samples from three locations (SV-1 through SV-3). The soil, groundwater and soil-gas samples were submitted for VOC analysis. Apex notes that groundwater was not encountered in one temporary well (TW-2). The locations of the soil borings, temporary monitoring well locations and soil-gas samples are shown in **Figure 3**.

<sup>&</sup>lt;sup>1</sup> Source: Wisconsin Department of Natural Resources (DNR) Bureau for Remediation and Redevelopment Tracking System (BRRTS) data repository.



#### 2.0 SUMMARY OF RESULTS

To date seven soil borings have been advanced in the area of the Bright Cleaners store in response to a release of dry cleaner solvent into the subsurface. Six groundwater monitoring wells have been installed to assess the groundwater quality in the vicinity of the store. Additionally, six soil vapor samples were collected beneath the floor slab of the building to assess the potential for indoor vapor intrusion.

The locations of the soil borings, monitoring wells and sub-slab sample locations are shown in **Figure 3**. Photographs taken at the time of fieldwork are included in **Appendix A**. Apex's field protocols are described in **Appendix B**.

#### 2.1 Soil Conditions

The soil borings encountered the following generalized lithologic sequence:

- Asphalt approximately 4 inches thick was encountered at ground surface in the exterior borings (MW-1 through MW-3). Concrete approximately 5 inches thick was encountered in the interior boring (B-1). Topsoil, asphalt pavements and concrete were generally underlain by approximately 3 inches of crushed stone.
- Silty clay/clayey silt was encountered below the crushed stone/aggregate to a depth of 20 feet bgs, the maximum depth explored.
- A discontinuous silty/clayey sand lens was encountered in MW-2 at depths ranging from 10 to 11 feet bgs.
- Gravel, sand and/or crushed stone was comingled with clay in MW-2 at depths ranging from 4 to 10 feet bgs and may be backfilled material from construction activities.

Refer to boring logs included in **Appendix C** for additional information regarding the soil conditions. A cross section of the Site is provided as **Figure 4**.

Six soil samples were analyzed for VOCs by EPA Method 5035/8260. The results of the soil analysis were compared to Non-Industrial and Industrial RCLs for Direct Contact and the soil (leaching) component to groundwater cited in the U.S. Environmental Protection Agency's (USEPA) Regional Screening Level Web-Calculator (June 2016) in accordance with Wisconsin Administrative Code NR 720 (WAC 720).

The soil analysis detected one VOC, methylene chloride, at concentrations that slightly exceed the RCL for the soil (leaching) component to groundwater exposure pathway. The soil analysis did not detect any VOCs at concentrations in excess of RCLs for direct-contact (non-industrial and industrial), and no additional VOCs at concentrations in excess of RCLs for the soil component to groundwater per WAC 720.



Apex notes that methylene chloride is a common laboratory contaminant and was detected in the method blank associated with sample TW-1. Therefore, it is Apex's opinion that methylene chloride detected in sample TW-1 is a laboratory artifact and does not reflect contamination from historical Site operations.

The results of the soil analysis, RCLs and sample depths are summarized in **Table 1** and the sample locations are shown in **Figure 3**. Copies of the laboratory reports and the chain-of custody form are included in **Appendix E**.

#### 2.2 Groundwater Conditions

Groundwater at the Site occurs in an unconfined (water table) aquifer. Groundwater was generally encountered at depths ranging from 10 to 16 feet bgs at the time of drilling. The top of the monitoring well casings were surveyed for lateral and vertical control by Spaceco, Inc., a licensed surveyor. Stabilized groundwater was measured at depths ranging from 8.40 to 11.97 feet bgs (756.82 to 760.91 feet above mean sea level). Based upon water level measurements, Apex calculates groundwater flows to the south-southwest west at a gradient of 0.03 ft./ft. (horizontal to vertical). Groundwater elevation contours measured on August 17, 2017 are shown in **Figure 5**. The top of the well casings, water level measurements and groundwater elevations are summarized in a table included in **Appendix D**.

The Bouwer & Rice Method<sup>2</sup> was used to calculate a hydraulic conductivity (K) which ranged from  $1.45 \times 10^{-3}$  centimeters/second (for MW-2) to  $3.10 \times 10^{-6}$  centimeters/second (for MW-3) which shows that the hydraulic conductivity is highly variable at the Site. The test parameters, field measurements, and head verses time data generated during the test runs are included as **Attachment D**.

Apex collected two groundwater samples from two temporary monitoring wells (TW-1 and TW-3) and three groundwater samples from three dedicated monitoring wells (MW-1 through MW-3). Apex also collected one duplicate sample (from MW-1) and one trip blank. The groundwater samples were analyzed for VOCs by EPA Method 8260.

The results of the groundwater analysis were compared to GQS (Enforcement Standards and Preventative Action Limits) cited in WAC NR 140.10 Table 1 (WAC 140) and Vapor Risk Screening Levels (VRSLs) for groundwater for a commercial property use based on the USEPA Vapor Intrusion Screening Level Calculator (VISLC, Version 3.5.2, October 2017) with an excess lifetime cancer risk of 1 x 10-5 in accordance with WAC NR 716 (WAC 716).

The groundwater analysis did not detect VOCs at concentrations in excess of GQSs or VRSLs. Apex notes that methylene chloride was detected in two soil samples at concentrations in excess of the soil component to groundwater RCL; however, the groundwater analysis did not detect methylene chloride at concentrations in excess of MDLs in the corresponding monitoring wells.



<sup>&</sup>lt;sup>2</sup> Bouwer, Herman. 1989. The Bouwer and Rice Slug Test – An Update. Groundwater, Vol. 27, No. 3: 304-309.

The results of the groundwater analysis, GQSs and VRSLs are summarized in **Table 2** and the sample locations are shown in **Figure 3**. Copies of the laboratory reports and the chain-of-custody form are included in **Appendix E**.

#### 2.3 Soil-Gas Analysis

Apex collected 6 soil-gas samples immediately below the concrete floor slab in and adjacent to the dry cleaner tenant space at the locations shown in Figure 3. One soil-gas sample was collected near the center of the Bright Cleaners tenant space (SV-1), one adjacent to the dry cleaning plant (SV-2), one adjacent to chemical storage (SV-3) and three samples (SV-4 through SV-6) were used to assess the lateral extent of VOCs in sub-slab soil-gas. The soil-gas samples were analyzed for VOCs by EPA Method TO-15.

The results of the soil-gas analysis were compared to sub-slab Vapor Action Levels (VALs) for a commercial property use based on the USEPA VISL (Version 3.5.1, May 2016) with an excess lifetime cancer risk of 1 x 10-5 in accordance with WAC 716.

The soil-gas analysis detected PCE in two samples at concentrations in excess of commercial VALs per WAC 716 The results of the soil-gas analysis and VALs are summarized in **Table 3**. The sample locations with VOC concentrations in excess of VALs are summarized and shown in **Figure 6**. Copies of the laboratory reports and the chain-of custody form are included in **Appendix E**.



#### 3.0 REMEDIAL OPTIONS

The objective for the proposed remediation at the Site consist of the mitigation of potential indoor vapor intrusion associated with the release of dry cleaning solvent at the Site. Remedial options considered for the Site included the following:

- 1. No Action
- 2. In-situ Injections (biodegradation or chemical degradation)
- 3. Sub-Slab Depressurization System (SSDS) to mitigate vapor intrusion to indoor air

Given that the first two options do not address the short-term risk to human health of the occupants of the building, Apex proposes Option number 3. Natural attenuation associated with Option 1 and the degradation associated with Option 2 require time to take effect and leave current tenants of the building exposed to potential inhalation risk until the attenuation/degradation occurs. These two options would likely require years to achieve regulatory compliance.

The mitigation approach provided by Option 3 will prevent potential vapors from entering the building once the SSDS is installed and operational. This option will reduce the potential health risk to building occupants immediately upon installation. Option 3 mitigates potential indoor vapor intrusion both in the short and long term.

Other more intrusive remedial options are available, however with the existence of the on-site building, these options are not feasible for this Site.



#### 4.0 REMEDIAL DESIGN

It is Apex's opinion that the VOCs detected in soil-gas have been delineated, and that additional investigation is not warranted. To eliminate the soil-gas exposure pathway for building occupants, mitigation will be required. In order to address this exposure route, a SSDS will be installed and follow-up monitoring will be conducted to verify the system is effectively mitigating vapor intrusion to indoor air.

Apex designed a SSDS intended to draw the soil-vapor from below the floor slab in the areas of soil-gas exceedances creating a vacuum beneath the slab which will immediately reduce potential vapor intrusion from the sub-slab to indoor air. The extraction of sub-slab soil vapors and venting to the outside will also decrease the concentrations of VOCs in sub-slab soil vapors over time. The design includes post-installation communication test to determine the radius of influence for the SSDS. The proposed SSDS installation, the post-installation soil-gas sampling/analysis are described below.

#### 4.1 Installation of Sub-Slab Depressurization System

Prior to SSDS installation, a communication test will be performed using a high suction centrifugal vent fan (similar to that to be installed in each exhaust vent) and a micro manometer will be used to determine how easily air can move from one point to another beneath the slab and the radius of depressurization achieved by each extraction sump. During the test a centrifugal fan will be will be installed in a hole that is cored in the floor slab. Small holes will be cored in strategic locations through the slab and a micro manometer will be used to gauge how the air flow is affected by the force of the fan. Monitoring pressure differentials during the soil communication test will determine the most efficient configuration for the active venting system.

The SSDS will be installed to address the potential indoor vapor intrusion. The SSDS will include the following:

- An extraction sump is installed that is at least two cubic feet and extends at least 6 inches below the slab (larger extraction sumps may be excavated as needed to achieve the performance criteria described below);
- 2. A PVC pipe of at least 3 inches in diameter extends from the extraction sump to the intake side of an in-line fan (Specifications enclosed in **Appendix F**) capable of achieving a static vacuum of at least 0.25 inches water column (wc) at the suction point and measurable vacuum at the farthest edges of the area served by the suction pit under worst case conditions (all exhaust fans and heating systems running, during cold weather) as determined by a differential pressure reading of at least -0.003 inches wc below the slab or visible downward flow of air at test holes using chemical or smoke sticks;
- 3. All visible cracks and joints in the slab (including the location where the PVC pipe exits the slab) and foundation walls are sealed:
- 4. The pipe will exhaust outside the building at least 10 feet above ground and at least 10 feet from any door or window; and



5. Additional extraction sumps meeting the requirements described above shall be installed as necessary to achieve measurable vacuum below the slab in all areas that demonstrate the potential for vapor intrusion, including in any area where subsurface or foundation conditions (e.g., a sub-slab grade beam) prevent adequate suction field extension.

All materials and installation techniques will follow guidelines put forth in ASTM E2121: Standard Practice for Installing Radon Mitigation systems in Existing Low-Rise Residential Buildings. Radon systems are nearly identical in design to SSDS and this ASTM Standard was applicable to residential and commercial properties.

Following SSDS installation, an additional communication test will be performed to confirm that the extraction system is performing as intended. Since there are indoor sources of PCE in the Bright Cleaners, no sampling of indoor air will be conducted

Following SSDS installation and post-installation performance testing, Apex will prepare an SSDS installation letter report documenting installation and testing activities with guidelines for visual monitoring of the system on a regular basis by local maintenance staff. We will also provide an annual check list to document system operation for use by maintenance staff.


To better define the area that warrants treatment, Apex proposes to operate the SSDS for a period of four months and then conduct an additional round of post-operation soil-gas sampling. The objective of this additional round of sampling would be to assess whether the SSDS has reduced the target analytes near previous soil-gas samples SV-1 and SV-2 to concentrations below VALs.


Apex proposes that three additional soil-gas samples be collected in the area around SV-1 and SV-2 for analysis. Discrete soil-gas samples will be analyzed for the target analytes by EPA Method TO-15. The soil-gas analysis will be performed by a National Environmental Laboratory Accreditation Conference certified laboratory.





### Figures

















Data Tables



#### Table 1

# Summary of Soil Data for Volatile Organic Compounds (VOCs) EPA Method 5035/8260B Bright Cleaners - Franklin Centre

#### 7249 South 76th Street, Franklin, Wisconsin

concentrations in milligrams per kilogram (mg/kg)

				Residual Contaminant Levels			
Boring Number	TW-1	TW-2	TW-3	Direct C	Soil to		
Sample Depth (feet bgs)	14	11	12	Non-Industrial Industrial		Groundwater	
Date Collected		8/31/2016		Non-Industrial Industrial			
Acetone	0.029	< 0.0016	< 0.0018	63,400	100,000	1.8383	
Benzene	0.0018	0.00044	0.00045	1.6	7.07	0.0026	
Bromodichloromethane	< 0.00039	< 0.00028	< 0.00031	0.418	1.83	0.0002	
Bromoform	< 0.00039	< 0.00028	< 0.00031	25.4	113	0.0012	
Bromomethane	< 0.00049	< 0.00035	< 0.00039	9.6	43	0.0025	
2-Butanone	< 0.0015	< 0.0011	< 0.0012	28,400	28,400	0.833	
Carbon disulfide	0.00019	0.00051	< 0.00015	738	738	0.2959	
Carbon tetrachloride	< 0.00029	< 0.00021	< 0.00023	0.916	4.03	0.0019	
Chlorobenzene	< 0.00019	< 0.00014	< 0.00015	370	761	0.0679	
Chloroethane	< 0.00039	< 0.00028	< 0.00031	2,120	2,120	0.1133	
Chloroform	< 0.00019	< 0.00014	< 0.00015	0.454	1.98	0.0017	
Chloromethane	< 0.00029	< 0.00021	< 0.00023	159	669	0.0078	
Dibromochloromethane	< 0.00039	< 0.00028	< 0.00031	8.28	38.9	0.016	
1,1-Dichloroethane	< 0.00029	< 0.00021	< 0.00023	5.06	22.2	0.2417	
1,2-Dichloroethane	< 0.00058	< 0.00042	< 0.00046	0.652	2.87	0.0014	
1,1-Dichloroethene	< 0.00029	< 0.00021	< 0.00023	320	1,190	0.0025	
cis-1,2-Dichloroethene	< 0.00029	< 0.00021	< 0.00023	156	2,340	0.0206	
trans-1,2-Dichloroethene	< 0.00029	< 0.00021	< 0.00023	1,560	1,850	0.0313	
1,2-Dichloropropane	< 0.00039	< 0.00028	< 0.00031	0.406	1.78	0.0017	
cis-1,3-Dichloropropene	< 0.00019	< 0.00014	< 0.00015	1,210	1,210	0.0001	
trans-1,3-Dichloropropene	< 0.00029	< 0.00021	< 0.00023	1,510	1,510	0.0001	
Ethylbenzene	0.00026	< 0.00007	< 0.000077	8.02	35.4	0.785	
2-Hexanone	< 0.00078	< 0.00056	< 0.00062	237	1,760	NE	
4-Methyl-2-pentanone	< 0.00029	< 0.00021	< 0.00023	2,450	2,450	0.1126	
Methylene Chloride	0.0019	< 0.00056	< 0.00062	61.8	1,150	0.0013	
Methyl tertiary-butyl ether	< 0.00019	< 0.00014	< 0.00015	63.8	282	0.0135	
Styrene	< 0.00019	< 0.00014	< 0.00015	867	867	0.11	
1,1,2,2-Tetrachloroethane	< 0.00019	< 0.00014	< 0.00015	0.81	3.6	0.0000782	
Tetrachloroethene	< 0.00029	< 0.00021	< 0.00023	33	145	0.0023	
Toluene	0.0017	0.00046	0.00041	818	818	0.5536	
1,1,1-Trichloroethane	< 0.00019	< 0.00014	< 0.00015	640	640	0.0701	
1,1,2-Trichloroethane	< 0.00049	< 0.00035	< 0.00039	1.59	7.01	0.0016	
Trichloroethene	< 0.00019	< 0.00014	< 0.00015	1.3	8.41	0.0018	
Vinyl chloride	< 0.00039	< 0.00028	< 0.00031	0.067	2.08	0.000069	
Xylenes (total)	< 0.00039	< 0.00028	< 0.00031	260	260	1.98	

#### Table 1 (Continued)

#### Summary of Soil Data for Volatile Organic Compounds (VOCs) EPA Method 5035/8260B Bright Cleaners - Franklin Centre

#### 7249 South 76th Street, Franklin, Wisconsin

concentrations in milligrams per kilogram (mg/kg)

	Residual Contaminant Levels						
Boring Number	MW-1	MW-2	B-1	Direct 0	Soil to		
Sample Depth (feet bgs)	4	6	2	Non Industrial			
Date Collected		8/11/2017		Non-Industrial	Industrial		
Acetone	0.075	0.025	0.064	63,400	100,000	1.8383	
Benzene	0.0025	0.0021	0.0015	1.6	7.07	0.0026	
Bromodichloromethane	< 0.00036	< 0.00035	< 0.0003	0.418	1.83	0.0002	
Bromoform	< 0.00036	< 0.00035	< 0.0003	25.4	113	0.0012	
Bromomethane	< 0.00045	< 0.00043	< 0.00037	9.6	43	0.0025	
2-Butanone	0.011	0.0040	0.0099	28,400	28,400	0.833	
Carbon disulfide	< 0.00018	< 0.00017	< 0.00015	738	738	0.2959	
Carbon tetrachloride	< 0.00027	< 0.00026	< 0.00022	0.916	4.03	0.0019	
Chlorobenzene	< 0.00018	< 0.00017	< 0.00015	370	761	0.0679	
Chloroethane	< 0.00036	< 0.00035	< 0.0003	2,120	2,120	0.1133	
Chloroform	< 0.00018	< 0.00017	< 0.00015	0.454	1.98	0.0017	
Chloromethane	< 0.00027	< 0.00026	< 0.00022	159	669	0.0078	
Dibromochloromethane	< 0.00036	< 0.00035	< 0.0003	8.28	38.9	0.016	
1,1-Dichloroethane	< 0.00027	< 0.00026	< 0.00022	5.06	22.2	0.2417	
1,2-Dichloroethane	< 0.00054	< 0.00052	< 0.00045	0.652	2.87	0.0014	
1,1-Dichloroethene	< 0.00027	< 0.00026	< 0.00022	320	1,190	0.0025	
cis-1,2-Dichloroethene	< 0.00027	< 0.00026	< 0.00022	156	2,340	0.0206	
trans-1,2-Dichloroethene	< 0.00027	< 0.00026	< 0.00022	1,560	1,850	0.0313	
1,2-Dichloropropane	< 0.00036	< 0.00035	< 0.0003	0.406	1.78	0.0017	
cis-1,3-Dichloropropene	< 0.00018	< 0.00017	< 0.00015	1,210	1,210	0.0001	
trans-1,3-Dichloropropene	< 0.00027	< 0.00026	< 0.00022	1,510	1,510	0.0001	
Ethylbenzene	0.0013	0.00088	0.0010	8.02	35.4	0.785	
2-Hexanone	< 0.00072	< 0.00069	< 0.0006	237	1,760	NE	
4-Methyl-2-pentanone	< 0.00027	< 0.00026	< 0.00022	2,450	2,450	0.1126	
Methylene Chloride	0.0015	< 0.00069	< 0.0006	61.8	1,150	0.0013	
Methyl tertiary-butyl ether	< 0.00018	< 0.00017	< 0.00015	63.8	282	0.0135	
Styrene	< 0.00018	< 0.00017	< 0.00015	867	867	0.11	
1,1,2,2-Tetrachloroethane	< 0.00018	< 0.00017	< 0.00015	0.81	3.6	0.0000782	
Tetrachloroethene	< 0.00027	< 0.00026	0.00067	33	145	0.0023	
Toluene	0.0044	0.0028	0.0028	818	818	0.5536	
1,1,1-Trichloroethane	< 0.00018	< 0.00017	< 0.00015	640	640	0.0701	
1,1,2-Trichloroethane	< 0.00045	< 0.00043	< 0.00037	1.59	7.01	0.0016	
Trichloroethene	< 0.00018	< 0.00017	0.0010	1.3	8.41	0.0018	
Vinyl chloride	< 0.00036	< 0.00035	< 0.0003	0.067	2.08	0.000069	
Xylenes (total)	0.0025	0.0012	0.0014	260	260	1.98	

#### Notes:

bgs = feet below ground surface

TW-2 = Soil boring

< = Not Detected: Concentration less than the indicated laboratory detection limit

Detected compounds are shown as **bold** 

NE = Remedial Objective not established

RCLs (Non-Industrial Direct-Contact) = Residual Contaminant Levels per the U.S. EPA's Regional Screening Level Web-Calculator (updated March 2017) in accordance with Wisconsin Administrative Code NR 720

RCLs (Industrial Direct-Contact) = Residual Contaminant Levels per the U.S. EPA's Regional Screening Level Web-Calculator (updated March 2017) in accordance with Wisconsin Administrative Code NR 720

RCLs (Soil to Groundwater ) = Soil to Groundwater Residual Contaminant Levels per the U.S. EPA Regional Screening Level Web-Calculator (updated June 2016) in accordance with Wisconsin Administrative Code NR 720

Concentrations in excess of RCLs are shaded yellow Exceeded RCLs are shaded green

#### Table 2

#### **Summary of Groundwater Data for**

#### Volatile Organic Compounds (VOCs) EPA Method 8260B Bright Cleaners - Franklin Centre 7249 South 76th Street, Franklin, Wisconsin

concentrations in milligrams per liter (µg/L)

				Duplicate	Groundwater Qu	Vapor Risk Screening	
Well Number	TW-1	TW-3	MW-1	(MW-1)	Enforcement Standards	Preventative Action Limit	Commercial
Date Collected	8/31	/2016	8/17	7/2017			
Acetone	< 3.1	12	< 3.1	< 3.1	9,000	1,800	95,000,000
Benzene	< 0.2	0.24	< 0.2	< 0.2	5	0.5	69
Bromodichloromethane	< 0.2	< 0.2	< 0.2	< 0.2	0.6	0.06	38
Bromoform	< 0.3	< 0.3	< 0.3	< 0.3	4.4	0.44	5,100
Bromomethane	< 2	< 2	< 2	< 2	10	1	73
2-Butanone	< 1.6	< 1.6	< 1.6	< 1.6	4,000	800	9,400,000
Carbon disulfide	< 0.3	0.34	< 0.3	< 0.3	1,000	200	5,200
Carbon tetrachloride	< 1	< 1	< 1	< 1	5	0.5	18
Chlorobenzene	< 0.2	< 0.2	< 0.2	< 0.2	100	20	1,700
Chloroethane	< 0.5	< 0.5	< 0.5	< 0.5	400	80	97,000
Chloroform	< 0.1	< 0.1	< 0.1	< 0.1	6	0.6	36
Chloromethane	< 0.3	< 0.3	< 0.3	< 0.3	30	3	1,100
Dibromochloromethane	< 0.2	< 0.2	< 0.2	< 0.2	60	6	NE
1,1-Dichloroethane	< 0.2	< 0.2	< 0.2	< 0.2	850	85	330
1,2-Dichloroethane	< 0.2	< 0.2	< 0.2	< 0.2	5	0.5	98
1,1-Dichloroethene	< 0.4	< 0.4	< 0.4	< 0.4	7	0.7	820
cis-1,2-Dichloroethene	< 0.2	< 0.2	< 0.2	< 0.2	70	7	NE
trans-1,2-Dichloroethene	< 0.5	< 0.5	< 0.5	< 0.5	100	20	NE
1,2-Dichloropropane	< 0.1	< 0.1	< 0.1	< 0.1	5	0.5	150
cis-1,3-Dichloropropene	< 0.2	< 0.2	< 0.2	< 0.2	0.4	0.04	210
trans-1,3-Dichloropropene	< 0.1	< 0.1	< 0.1	< 0.1	0.4	0.04	210
Ethylbenzene	< 0.3	< 0.3	< 0.3	< 0.3	700	140	150
2-Hexanone	< 0.2	< 0.2	< 0.2	< 0.2	NE	NE	34,000
4-Methyl-2-pentanone	< 0.7	< 0.7	< 0.7	< 0.7	500	50	2,300,000
Methylene Chloride	< 0.2	< 0.2	< 0.2	< 0.2	5	0.5	20,000
Methyl tertiary-butyl ether	< 0.3	< 0.3	< 0.3	< 0.3	60	12	20,000
Styrene	< 0.3	< 0.3	< 0.3	< 0.3	100	10	39,000
1,1,2,2-Tetrachloroethane	< 0.1	< 0.1	< 0.1	< 0.1	0.2	0.02	140
Tetrachloroethene	< 0.3	< 0.3	< 0.3	< 0.3	5	0.5	240
Toluene	< 0.4	< 0.4	< 0.4	< 0.4	800	160	81,000
1,1,1-Trichloroethane	< 0.2	< 0.2	< 0.2	< 0.2	200	40	31,000
1,1,2-Trichloroethane	< 0.1	< 0.1	< 0.1	< 0.1	5	0.5	26
Trichloroethene	< 0.3	< 0.3	< 0.3	< 0.3	5	0.5	22
Vinyl chloride	< 0.3	< 0.3	< 0.3	< 0.3	0.2	0.02	25
Xylenes (total)	< 1	< 1	< 1	< 1	2,000	400	1,600

#### Table 2 (Continued)

#### **Summary of Groundwater Data for**

### Volatile Organic Compounds (VOCs) EPA Method 8260B Bright Cleaners - Franklin Centre 7249 South 76th Street, Franklin, Wisconsin

concentrations in milligrams per liter (µg/L)

				Groundwater Q	uality Standards	Vapor Risi Screening	
Well Number	MW-2 MW-3	Trip Blank	Enforcement Standards	Preventative Action Limit	Commerci		
Date Collected		8/17/2017					
Acetone	< 3.1	< 3.1	< 3.1	9,000	1,800	95,000,000	
Benzene	< 0.2	< 0.2	< 0.2	5	0.5	69	
Bromodichloromethane	< 0.2	< 0.2	< 0.2	0.6	0.06	38	
Bromoform	< 0.3	< 0.3	< 0.3	4.4	0.44	5,100	
Bromomethane	< 2	< 2	< 2	10	1	73	
2-Butanone	< 1.6	< 1.6	< 1.6	4,000	800	9,400,000	
Carbon disulfide	< 0.3	< 0.3	< 0.3	1,000	200	5,200	
Carbon tetrachloride	< 1	< 1	< 1	5	0.5	18	
Chlorobenzene	< 0.2	< 0.2	< 0.2	100	20	1,700	
Chloroethane	< 0.5	< 0.5	< 0.5	400	80	97,000	
Chloroform	< 0.1	< 0.1	< 0.1	6	0.6	36	
Chloromethane	< 0.3	< 0.3	< 0.3	30	3	1,100	
Dibromochloromethane	< 0.2	< 0.2	< 0.2	60	6	NE	
1,1-Dichloroethane	< 0.2	< 0.2	< 0.2	850	85	330	
1,2-Dichloroethane	< 0.2	< 0.2	< 0.2	5	0.5	98	
1,1-Dichloroethene	< 0.4	< 0.4	< 0.4	7	0.7	820	
cis-1,2-Dichloroethene	< 0.2	< 0.2	< 0.2	70	7	NE	
trans-1,2-Dichloroethene	< 0.5	< 0.5	< 0.5	100	20	NE	
1,2-Dichloropropane	< 0.1	< 0.1	< 0.1	5	0.5	150	
cis-1,3-Dichloropropene	< 0.2	< 0.2	< 0.2	0.4	0.04	210	
trans-1,3-Dichloropropene	< 0.1	< 0.1	< 0.1	0.4	0.04	210	
Ethylbenzene	< 0.3	< 0.3	< 0.3	700	140	150	
2-Hexanone	< 0.2	< 0.2	< 0.2	NE	NE	34,000	
4-Methyl-2-pentanone	< 0.7	< 0.7	< 0.7	500	50	2,300,000	
Methylene Chloride	< 0.2	< 0.2	< 0.2	5	0.5	20,000	
Methyl tertiary-butyl ether	< 0.3	< 0.3	< 0.3	60	12	20,000	
Styrene	< 0.3	< 0.3	< 0.3	100	10	39,000	
1,1,2,2-Tetrachloroethane	< 0.1	< 0.1	< 0.1	0.2	0.02	140	
Tetrachloroethene	< 0.3	< 0.3	< 0.3	5	0.5	240	
Toluene	< 0.4	< 0.4	< 0.4	800	160	81,000	
1,1,1-Trichloroethane	< 0.2	< 0.2	< 0.2	200	40	31,000	
1,1,2-Trichloroethane	< 0.1	< 0.1	< 0.1	5	0.5	26	
Trichloroethene	< 0.3	< 0.3	< 0.3	5	0.5	22	
Vinyl chloride	< 0.3	< 0.3	< 0.3	0.2	0.02	25	
Xylenes (total)	< 1	< 1	< 1	2,000	400	1,600	

#### Notes:

TW-3 = Temporary monitoring well

< = Not Detected: Concentration less than the indicated laboratory detection limit.

Detected concentrations are shown in **bold**.

NE = Remedial Objective not established.

Groundwater Quality Standards cited in Wisconsin Administrative Code NR 140.10 Table 1

Vapor Risk Screening Levels for groundwater with a commercial property use based on the U.S. EPA Vapor Intrusion Screening Level Calculator (Version 3.5.2, October 2017) with an excess lifetime cancer risk of 1 x 10<sup>5</sup> in accordance with Wisconsin Administrative Code NR 716

Concentrations in excess of GQSs and/or VRSLs are shaded yellow (none detected)

Exceeded GQSs and/or VRSLs are shaded green

#### Table 3

#### Summary of Soil Gas Data for

### Volatile Organic Compounds (VOCs) EPA Method TO-15

#### **Bright Cleaners - Franklin Centre** 7249 South 76th Street, Franklin, Wisconsin

concentrations in micrograms per cubic meter (µg/m³)

Sub-slab Sample Number	SV-1	SV-2	SV-3	SV-4	SV-5	SV-6	Sub-Slab Vapor Action Levels
Date Collected		8/31/2016			8/14/2017		
Acetone	82	140	100	16	14	5.3	4,500,000
Benzene	2.9	1.4	3.4	0.26	0.26	0.12	520
Benzyl chloride	< 2.4	< 1.9	< 2.6	< 1.3	< 1.3	< 0.59	83
Bromodichloromethane	< 0.21	< 0.17	< 0.23	< 0.28	< 0.28	< 0.13	110
Bromoform	< 0.25	< 0.2	< 0.28	< 0.41	< 0.41	< 0.19	3,700
Bromomethane 1,3-Butadiene	<b>0.54</b> < 0.13	<b>0.50</b> < 0.11	<b>0.79</b> < 0.14	<b>0.47</b> < 0.42	< 0.37 < 0.42	<b>0.22</b> < 0.19	730 140
2-Butanone	6.7	7.7	12	1.7	< 0.42	0.72	730,000
Carbon disulfide	0.50	< 0.29	0.48	< 0.26	< 0.26	< 0.12	100,000
Carbon tetrachloride	< 0.41	< 0.33	< 0.45	< 1.2	< 1.1	< 0.53	680
Chlorobenzene	< 0.13	< 0.11	< 0.14	< 0.94	< 3.7	< 0.43	7,300
Chloroethane	< 1.2	< 0.98	< 1.3	< 0.44	< 0.43	< 0.2	1,500,000
Chloroform	0.22	0.36	0.62	< 0.22	< 0.22	0.37	180
Chloromethane	< 0.24	< 0.19	< 2.6	< 0.95	< 0.95	< 0.44	13,000
Cyclohexane	2.5	1.3	4.6	< 0.6	< 0.59	< 0.27	880,000
Dibromochloromethane	< 0.32	< 0.25	< 0.35	< 0.43	< 0.43	< 0.2	NE
1,2-Dibromoethane	< 0.4	< 0.32	< 0.44	< 0.68	< 0.68	< 0.31	6.8
1,1-Dichloroethane	< 0.09	< 0.073	< 0.1	< 0.14	< 0.14	< 0.066	2,600
1,2-Dichlorobenzene	0.42	< 0.19	< 0.26	< 0.39	< 0.39	< 0.18	29,000
1,3-Dichlorobenzene 1,4-Dichlorobenzene	<b>1.9</b> < 0.29	1.1 < 0.24	<b>4.9</b> < 0.32	< 0.37 < 0.42	< 0.36 < 0.42	< 0.17 < 0.19	NE 370
Dichlorodifluoromethane	2.3	2.3	2.1	2.0	2.0	2.2	15,000
1.2-Dichloroethane	< 0.21	< 0.17	< 0.23	< 0.38	< 0.68	< 0.18	160
1,1-Dichloroethene	< 0.12	< 0.093	< 0.13	< 0.2	< 0.2	< 0.094	29,000
cis-1,2-Dichloroethene	1.7	18	32	< 0.63	< 0.62	< 0.29	NE
trans-1,2-Dichloroethene	< 0.13	0.15	< 0.14	< 0.22	< 0.22	< 0.1	NE
1,2-Dichloropropane	< 0.15	< 0.12	< 0.16	< 0.7	< 0.69	< 0.32	580
cis-1,3-Dichloropropene	< 0.25	< 0.2	< 0.27	< 0.44	< 0.44	< 0.2	1,000
trans-1,3-Dichloropropene	< 0.28	< 0.23	< 0.32	< 3.7	< 3.7	< 1.7	1,000
1,4-Dioxane	< 0.48	2.7	2.4	< 1.2	< 1.1	< 0.54	820
Ethyl acetate	< 0.33	< 0.27	< 0.37	< 1	< 1	< 0.48	10,000
Ethylbenzene	3.9	2.8	6.1	< 0.26	< 0.26	< 0.12	1,600
4-Ethyltoluene	1.4	0.91	1.6	< 0.42	< 0.42	< 0.19	NE 700.000
Freon-113 Freon-114	< 0.13	0.57	0.59	0.31	0.62	0.57	730,000
Heptane	< 0.46 <b>5.5</b>	< 0.37 <b>2.7</b>	< 0.51 13	< 0.29 < 0.28	< 0.29 < 0.28	< 0.13 < 0.13	NE NE
Hexachlorobutadiene	0.74	< 0.45	< 0.61	< 0.28	< 0.9	< 0.13	190
Hexane	6.4	2.7	11	< 0.5	< 0.5	< 0.23	100,000
2-Hexanone	3.1	2.9	4.9	< 2.1	< 2.1	< 0.97	4,400
Isopropyl alcohol	310	110	65	50	36	0.64	29,000
4-Methyl-2-pentanone	12	6.1	9.4	< 1.1	< 1.1	< 0.52	440,000
Methylene Chloride	0.96	< 0.69	< 0.95	4.0	3.8	2.0	88,000
Methyl tertiary-butyl ether	0.25	0.33	0.28	< 0.17	< 0.17	< 0.076	16,000
Naphthalene	2.8	1.8	4.1	< 1.2	< 1.1	0.59	120
Propene	6.3	3.6	5.5	0.42	< 0.39	0.23	440,000
Styrene	0.78	0.32	0.54	< 0.82	< 0.81	< 0.38	150,000
1,1,2,2-Tetrachloroethane	< 0.22	< 0.18	< 0.24	< 0.38	< 0.38	< 0.18	70
Tetrachloroethene	12,000	44,000	1,900	2,400	520	26	5,800
Tetrahydrofuran Toluene	8.4	4.1 46	5.6 47	< 1.1	< 1.1	< 0.52	290,000
1,2,4-Trichlorobenzene	81 1.9	0.96	1.1	< 0.35 < 1.1	< 0.34 < 1.1	< 0.16 < 0.53	730,000 290
1,1,1-Trichloroethane	< 0.13	< 0.11	< 0.14	< 0.21	0.88	< 0.098	730,000
1,1,2-Trichloroethane	< 0.13	< 0.11	< 0.14	< 0.56	< 0.56	< 0.096	29
Trichloroethene	22	41	26	12	26	< 0.15	290
Trichlorofluoromethane	1.6	1.6	1.3	1.4	1.8	1.4	NE NE
1,2,4-Trimethylbenzene	5.1	3.9	7.5	0.40	< 0.22	0.37	8,800
1,3,5-Trimethylbenzene	1.4	0.91	2.0	< 0.28	< 0.27	< 0.13	NE
Vinyl acetate	< 0.22	< 0.18	< 0.24	< 1.1	< 1.1	< 0.53	29,000
Vinyl chloride	< 0.099	< 0.08	< 0.11	< 0.18	< 0.17	< 0.081	930
m,p-Xylene	8.8	6.0	12	< 0.44	< 0.44	0.24	15,000
o-Xylene	3.6	2.4	4.8	< 0.23	< 0.22	0.16	15,000
Xylenes (total)	12	8.5	17	< 0.65	< 0.65	0.41	15,000

#### Notes:

SV-2 = Sub-slab vapor sample

< = Not Detected: Concentration less than the indicated laboratory detection limit.

Detected concentrations are shown in **bold**.

NE = Remedial Objective not established.

Sub-Slab Vapor Action Levels for a commercial property use based on the U.S. EPA Vapor Instrusion Screening Level Calculator (Version 3.5.2, October 2017) with an excess lifetime cancer risk of 1 x 10<sup>-5</sup> in accordance with Wisconsin Administrative Code NR

Concentrations in excess of Remediation Objectives are shaded yellow

Exceeded Remedial Objectives are shaded green

# Appendix A Site Photographs



#### PHOTO LOG FOR BRIGHT CLEANERS – FRANLIN CENTRE 7249 SOUTH 76<sup>TH</sup> STREET, FRANKLIN, WISCONSIN

Photo No. 1 showing front of the Bright Cleaners tenant space, view to the south.



Photo No. 2 showing the clearance of underground utilities in the rear of the Bright Cleaners tenant space using ground penetrating radar, view to the northeast.






Photo No. 3 showing the advancement of a boring (TW-1) in the driveway south of the Bright Cleaners tenant space, view to the east.

August 31, 2016





#### PHOTO LOG FOR BRIGHT CLEANERS – FRANLIN CENTRE 7249 SOUTH 76<sup>TH</sup> STREET, FRANKLIN, WISCONSIN

Photo No. 4 showing a temporary well (TW-1, red arrow) in the driveway south of the Bright Cleaners tenant space in the foreground and the advancement of a boring (TW-3) in the background, view to the northeast.

August 31, 2016



Photo No. 5 showing a temporary well (TW-2, red arrow) located near the rear door of the Bright Cleaners tenant space, view to the north.



August 31, 2016

Photo No. 6 showing the interior of the Bright Cleaners tenant space with the dry cleaning plant on the right, view to the north.





Photo No. 7 showing a sub-slab vapor probe (SV-2) installed next to the dry cleaning plant. Leak testing is being performed on the probe by mechanical means using the water dam method.

August 31, 2016



Photo No. 8 showing a Summa® canister sample train being leak tested with a shut-in test by applying a negative pressure using a syringe and plunger.



Photo No. 9 showing a vapor probe (SV-3) located near the rear door of the Bright Cleaners tenant space being purged and screened for volatile emissions using a photoionization detector prior to sample collection, view to the south.

August 31, 2016





Photo No. 10 showing a sub-slab vapor probe installed north of the dry cleaning plant (SV-1) in the foreground and a second installed next to the plan (SV-2), view to the south.

August 31, 2016



Photo No. 11 showing the collection of a sub-slab vapor sample (SV-1) located north of the dry cleaning plant in the Bright Cleaners tenant space, view to the north.

August 31, 2016



Photo No. 12 showing the collection of a sub-slab vapor sample (SV-2) located adjacent to the dry cleaning plant in the Bright Cleaners tenant space, view to the north.

August 31, 2016





Photo No. 13 showing a monitoring well (MW-1) being installed south of the Bright Cleaners tenant space, view to the west.



August 11, 2017

Photo No. 14 showing a monitoring well (MW-2) being installed southwest of the Bright Cleaners tenant space, view to the northeast.



August 11, 2017

Photo No. 15 showing a monitoring well (MW-3) being installed north of the Bright Cleaners tenant space, view to the south.



August 11, 2017



Photo No. 16 showing a vapor probe (SV-4) located in the northern portion of the Bright Cleaners tenant space being purged and screened for volatile emissions using a photoionization detector prior to sample collection, view to the south.

August 14, 2017



Photo No. 17 showing a vapor probe (SV-6) located in the Pizza Hut tenant space being purged and screened for volatile emissions using a photoionization detector prior to sample collection, view to the west.

August 14, 2017





# Appendix B Field Protocols, Soil-Gas Sample Logs & Well Data Sheets



# SUMMARY OF FIELD PROTOCOLS ADDITIONAL SUBSURFACE INVESTIGATION BRIGHT CLEANERS – FRANKLIN CENTRE 7249 SOUTH 76<sup>TH</sup> STREET FRANKLIN, MILWAUKEE COUNTY, WISCONSIN

Franklin Station LLC (Client) retained Apex Companies, LLC (Apex) to perform subsurface environmental assessment and pursue agency closure for the Bright Cleaners tenant at a 14.6-acre multi-tenant shopping center located at 7249 South 76<sup>th</sup> Street in Franklin, Wisconsin (the Site). We understand that Client recently acquired the Site for continued use as a multi-tenant retail shopping center.

Apex previously conducted a Limited Phase II Subsurface Investigation in the vicinity of the current dry cleaner tenant space in August 2016. The subsurface investigation detected tetrachloroethene (PCE) in soil gas at concentrations in excess of Wisconsin remediation objectives in two sub-slab soil gas samples. The additional subsurface investigation was conducted to delineate subsurface impacts due to the presence of the current Bright Cleaners operations, and to pursue agency closure regarding the release.

Additional subsurface assessment included performance of a non-invasive geophysical survey to clear underground utilities in the vicinity of soil borings; the collection of soil samples from three soil borings; installation/sampling of groundwater from three dedicated groundwater monitoring wells; installation/sampling of three permanent soil vapor extraction points; an elevation survey of the monitoring wells; water level measurement; and hydraulic conductivity testing.

#### **Geophysical Survey**

In an effort to avoid damaging substructures such as buried utilities at the Site, Apex retained Ground Penetrating Systems, Inc. (GPRS) to perform a non-invasive geophysical survey. The geophysical survey was performed using a combination of ground-penetrating radar (GPR) and radio detection (RD) techniques.

GPR transmits an electromagnetic pulse using a 400 MHz antenna through the ground and displays the reflection on a screen for immediate interpretation. GPR data was collected to evaluate the presence, depth and shape of subsurface targets (USTs, piping, buried foundations, etc.). The depth of exploration for GPR is typically limited to 5-7± feet below ground surface (bgs), depending on soil conditions.

RD techniques (RD-7000 Locator, or similar) are used to gauge the location of the buried metallic piping or conduits such as drain pipes. Radio detection involves induction of an electrical signal on metal objects (such as the ends of the piping or conduits) and tracing this signal using a hand-held detector.

#### Soil Sampling Using a Hydraulic Probe

To assess the presence of potential chemical impacts in shallow soil in the vicinity of the dry cleaner tenant space, Apex used a truck-mounted hydraulic probe (Geoprobe<sup>TM</sup> rig) and/or an electic jack



hammer with Geoprobe<sup>®</sup> rods to collect soil samples from four soil borings (B-1 and MW-1 through MW-3). Each of the borings was advanced to probe refusal, encountered at depths ranging from 4 to 18 feet bgs; copies of the boring logs are included in **Appendix C**.

Soil samples were collected continuously from ground surface to the bottom of each boring by pushing a 2-inch diameter by 5-foot long hollow-barreled sampler into/through the soil. Soil samples were collected in dedicated, disposable plastic liners contained in the sampler.

#### **Lithologic Description**

Soil samples were collected continuously from ground surface to the bottom of each boring for lithologic description and soil screening. An experienced geologist documented the subsurface conditions (soil type, photo-ionization detector [PID] measurements, the presence of staining, odors etc.). Our field observations and lithologic descriptions are summarized in the boring logs included in **Appendix C**.

#### Sample Screening/Selection

Soil samples were screened in the field for chemical odors, evidence of staining and volatile organic emissions using a PID equipped with a 10.6 eV PID lamp. The PID was calibrated using isobutylene calibration gas in accordance with the manufacturer's protocols prior to the start of fieldwork. Soil collected from various depth intervals in each boring was broken apart, placed and sealed in plastic 'ziploc' bags and after a few minutes volatile emissions were measured in the headspace using the PID. In the absence of such indications three representative soil samples were submitted for analysis. The results of the field screening are shown in Apex's boring logs, and Wisconsin DNR Soil Boring Log Information forms (Form 4400-122) in accordance with WAC NR 716.15(4)(g)(4), included in **Appendix C**.

#### Soil Sample Handling Procedures

A total of three soil samples were analyzed for volatile organic compounds (VOCs) by EPA Method 5035/8260. The samples were collected by pushing an Encore® sampler syringe into the soil to collect a 10 gram sample, the Encore® plunger was used to extrude the soil sample into clean, laboratory-supplied 40 milliliter (ml) VOA vials with methanol preservative. The VOA was immediately capped, labeled and placed in a chilled cooler for transport to the analytical laboratory. Soil samples for additional parameters were placed in clean, 4-ounce laboratory-supplied jars. Chain-of-custody protocols were maintained throughout the sample handing process.

#### **Monitoring Well Construction**

A Geoprobe rig was used to advance a borehole at each monitoring well location to document the soil conditions and to collect soil samples. A truck-mounted hollow-stem auger drill rig was then used at three locations (MW-1 through MW-3) to advance an 8-inch diameter borehole into the underlying aquifer zone; each well was installed to depths ranging from 15 to 20 feet bgs.

The monitoring wells were constructed using 2-inch diameter (schedule 40) PVC casing consisting of a 10-foot length of 0.010-inch factory slotted well screen with a blank riser. The filter pack, consisting of a sand pack, was placed around the well screen/riser extending 2-feet above the top of the screen.



The annulus of the borehole was then filled with bentonite chips (hydrated in place) to a depth of approximately 1-foot bgs, the remainder of the borehole was filled with cement. The wells were completed at ground surface using flush-mount well vaults set in cement. A magnet was placed in the void between the cover and the annular space seal in accordance with NR 716.13(14)(b). Copies of Apex's boring logs and well construction diagrams, and Wisconsin DNR Groundwater Monitoring Well Information form (Form 4400-89) and Monitoring Well Construction forms (Form 4400-113A) in accordance with WAC NR 716.15(4)(g)(2), are included in **Appendix C**.

#### **Monitoring Well Development**

Following installation, the monitoring wells were developed to remove sediment, consolidate the filter pack around the well screen and to improve hydraulic communication with the aquifer. Well development procedures consisted of the removal of approximately 2 to 6 well casing volumes of groundwater, and are documented in Wisconsin DNR Monitoring Well Development forms (Form 4400-113B) in accordance with WAC NR 716.15(4)(g)(3), included in **Appendix C**. Groundwater sampling was performed one week following well development.

#### **Groundwater Sampling**

Apex used a low-flow, peristaltic suction lift pump to purge two to three volumes of water from the well casing at a rate of ¼ gallon per minute prior to sampling. Clean, dedicated tubing was used at each well for well purging and water sampling. A multi-probe water quality meter was used to simultaneously measure pH, temperature, conductivity, dissolved oxygen and Oxidation-Reduction Potential. Once these parameters stabilized to within 10 percent on three consecutive measurements, the peristaltic pump was used to collect water samples. Groundwater parameter measurements are included in **Appendix B**.

Water samples collected for volatile organic compound (VOC) analysis were collected by filling 40-ml vials in a manner to minimize turbulence, air entrapment and overfilling. VOCs sample vials contained a hydrochloric acid preservative. The bottles were filled completely leaving a positive meniscus at the top of the vial. After capping, the vial was inverted and was tapped with a finger to confirm that air bubbles were not present. Effervesce was not observed in the vials following collection. Chain of custody documentation was maintained throughout the sample handling process. The sample vials and jars were then labeled and placed in a chilled cooler for transport to the analytical laboratory. As a quality assurance/quality control, Apex submitted one duplicate sample (from MW-1) and one trip blank for analysis.

#### **Soil-Gas Sampling Procedures**

Soil-gas samples were collected for analysis of VOCs including tetrachloroethene (PCE) and associated breakdown products from immediately below the concrete floor slab within the dry cleaner tenant space.

Apex advanced three soil-gas probes (SV-4 through SV-6) through the concrete floor slab at each location. A rotary hammer drill was used to advance a small diameter hole (5/8-inch) through the concrete slab or pavement into the underlying gravel-aggregate layer, approximately nine inches below the top of the hard surface. A 1-inch diameter hole was drilled in the same location to



approximately ½-inch below the top of the concrete floor for leak testing. The hole was then cleared of any debris prior to installing the soil gas probe. The soil gas probes consisted of a brass MIP adapter/compression coupling, covered with a silicone tube, which was inserted and seated firmly into the 5/8-inch diameter hole drilled through the hard surface. Leak testing was performed on each soil gas probe by mechanical means using the larger diameter hole as a water dam. The annulus of the 1-inch hole was filled with distilled water and monitored for fluctuations prior to and during sampling to verify that a leak had not occurred. Apex installed vapor pins in the concrete slab in 4 locations to allow for future sample collection, if warranted.

Prior to sample collection, the sub-slab gas probes were purged a minimum of three probe volumes of air from the sampling media to ensure representative samples of sub-slab soil gas and field screened for volatile organic emissions using a photoionization detector (PID) equipped with a 10.6 eV PID lamp. Soil gas samples were collected using batch-certified 6-liter Summa<sup>®</sup> canisters (evacuated stainless steel canister) with (30-minute) flow control valves with a flow rate of less than 200 milliliters per minute (mL/min). The laboratory-supplied regulator assembly was attached to the Summa® canister and a 3-foot section of 0.25-inch Teflon-lined polyethylene tubing was connected to the regulator using Swagelock® compression fittings. Leak testing was performed on each Summa® canister sample train prior to sample collection by performing a shut-in test. The shut-in test was performed by connecting the sample train tubing to a syringe and plunger. With the Summa® canister valve closed, a vacuum of approximately 20-inches mercury was applied to the sample train and maintained for 30 seconds. The pressure was observed to remain stable for the duration of the test. A photo log including photographs of the sub-slab soil gas sampling locations are included as Appendix A; soil-gas sampling details (i.e., results of field screening and leak testing; sample duration, initial and final canister pressures; and laboratory identification numbers) are recorded in the soil-gas sample logs included in Appendix B.

In areas where vapor pins were installed, the pins were capped to prevent transmission and covered with a secure stainless steel cover. The sample canisters were shipped to shipped to the analytical laboratory via Federal Express, accompanied by a completed chain-of-custody form. The samples were analyzed for VOCs by U.S. Environmental Protection Agency (EPA) Method TO-15 with a standard 5-day turnaround time.

#### **Well Surveying and Water Level Measurement**

The top of each monitoring well casing was surveyed for vertical control to an accuracy of 0.01-foot by SPACECO, Inc., a Wisconsin licensed surveyor. An electronic well sounder was used to measure to depth to groundwater from the top of the well casing to the top of shallow groundwater within an accuracy of 0.01-foot. The depth to water measurements was recorded in each well on August 14, August 17, and September 12, 2017. Stabilized water levels occurred at depths ranging from  $8\frac{1}{2}$  to 12 feet bgs, or 756.65 to 760.77 feet mean seal level (MSL). A summary of the well elevations provided by SPACECO, Inc., and the depth to groundwater and stabilized groundwater elevations are included in **Appendix D**.

#### **Hydraulic Testing**

To determine the hydraulic conductivity of the underlying aquifer Apex performed hydraulic testing in three dedicated monitoring wells (MW-1 through MW-3). A pressure transducer/data logger was



lowered below the water table and the water level was allowed to stabilize. The transducer/data logger was then connected to a Rugged Reader<sup>®</sup> using a waterproof coaxial cable. A quantity of water ('slug') was quickly removed from the well and rising head recovery rates were measured over time, until the water level recovered over the duration of the test. Due to the slow recovery, the test was performed only once in two monitoring wells (MW-1 and MW-3). A copy of the test parameters, field measurements, and head verses time data generated during the test runs are included in **Appendix D**.



# Appendix C

Boring Logs, Well Construction Diagrams & Wisconsin DNR Well and Borehole Forms





Project Name:	Bright Cleaners - Franklin	Centre	Project Number:	PECO_2016-78		
Vapor Point Installation Date:	August 31, 2016		Project Address:	7249 South 76th Street		
Sub-Slab Sample Date:	August 31, 2016		_	Franklin, Wisconsin		
		SAMPLIN	G INFORMATION			
Soil Gas Implant Purge Air:	0 Stabilized PID Reading (PPM)	3 Volume (liters)	Sample Start Time:	August 31, 2016 DATE	12:28 TIME	
Leak Test Method:	Shut-in Test Sample Train	Water Dam Soil Gas Implant	Sample End Time:	August 31, 2016 DATE	12:58 TIME	
Shut-in Test:	-20 Max. Vacuum (inches Hg)	30 Test Duration (seconds)	Initial Canister Vacuum:	-35 Inches Hg	12:28 TIME	
Leak Test Notes:	No Loss Shut-in Test	No Loss Water Dam	Final Canister Vacuum:	-15 Inches Hg	12:58 TIME	
Sample Depth:	< 1 Feet		Sample Delivery:	August 31, 2016 DATE	16:45 TIME	
	6  Volume (liters)		Delivery Method (FedEx, courier, etc.):	Delivered in person	TIME	
	Volume (liters)	Flow Controler (minutes)				
	М	ETEOROLOGICAL CO	NDITIONS FOR SAMPLING DAY	<b>Y</b>		
Ambient Temperature (°F):	64 Low	74 High	Sea Level Pressure (Inches)	30.08		
Average Wind:	North-northeast Direction	11 Velocity (mph)	Average Humidity (%):	67		
		ADDITIO	ONAL DETAILS			_
Other details for tenant space	e (e.g. recent construction/rend	ovation, cleaning activities, cl	nemical storage, slab/foundation cracks,	HVAC status etc.):		_
	Sample was collected north of	the dry cleaning plant.				
-						
Problems or inconsistancies	encountered during sampling:					
-	Not applicable					
* Include a site sketch on sep	parate sheet noting sample loca	ations (with measurements),	chemical storage areas, former operation	ons areas, etc.		
Sample Number:	SV-1		Analyses:	VOCs by EPA Sample Metho	od TO-15	
SUMMA ID Number:	4723 (60319)		Requested Turnaround Time:	1 Week TAT		
	()	-				
Regulator ID Number:	B-07		Sample Crew:	Joe Becker		



						_
Project Name:	Bright Cleaners - Franklin	Centre	Project Number:	PECO_2016-78		
Vapor Point Installation Date:	August 31, 2016		Project Address: _	7249 South 76th Street		
Sub-Slab Sample Date:	August 31, 2016		_	Franklin, Wisconsin		
		SAMPLII	NG INFORMATION			
Soil Gas Implant Purge Air:	0 Stabilized PID Reading (PPM)	3 Volume (liters)	Sample Start Time:	August 31, 2016 DATE	12:32 TIME	
Leak Test Method:	Shut-in Test Sample Train	Water Dam Soil Gas Implant	Sample End Time:	August 31, 2016 DATE	13:02 TIME	
Shut-in Test:	-18 Max. Vacuum (inches Hg)	30 Test Duration (seconds)	Initial Canister Vacuum: _	-30 Inches Hg	12:32 TIME	
Leak Test Notes:	No Loss Shut-in Test	No Loss Water Dam	Final Canister Vacuum: _	-7 1/2 Inches Hg	13:02 TIME	
Sample Depth:	< 1 Feet		Sample Delivery:	August 31, 2016 DATE	16:45 TIME	
Sample Container Details:	6 Volume (liters)	30 Flow Controler (minutes)	Delivery Method (FedEx, courier, etc.):	Delivered in person		
				,		
	M	ETEOROLOGICAL CO	ONDITIONS FOR SAMPLING DAY	Y		_
Ambient Temperature (°F):	64 Low	74 High	Sea Level Pressure (Inches)	30.08		
Average Wind:	North-northeast Direction	11 Velocity (mph)	Average Humidity (%): _	67		
		ADDIT	IONAL DETAILS			
Other details for tenant space	e (e.g. recent construction/rend	vation, cleaning activities,	chemical storage, slab/foundation cracks	, HVAC status etc.):		
	Sample was collected next to	the dry cleaning plant.				
Problems of inconsistancies	encountered during sampling:					
	Not applicable					
* Include a site sketch on sep	parate sheet noting sample loca	ations (with measurements)	), chemical storage areas, former operati	ons areas, etc.		
Sample Number:	SV-2		Analyses:	VOCs by EPA Sample Meth	nod TO-15	
SUMMA ID Number:	6054 (60339)		Requested Turnaround Time:	1 Week TAT		
Regulator ID Number:	B-03		Sample Crew:	Joe Becker		



Project Name: _	Bright Cleaners - Franklin Centre		Project Number:	PECO_2016-78	
Vapor Point Installation Date:	August 31, 2016		Project Address: 7249 South 76th Street		
Sub-Slab Sample Date:	August 31, 2016		_	Franklin, Wisconsin	
		SAMPLIN	G INFORMATION		
Soil Gas Implant Purge Air: _	0 Stabilized PID Reading (PPM)	3 Volume (liters)	Sample Start Time: _	August 31, 2016 DATE	12:34 TIME
Leak Test Method: _	Shut-in Test Sample Train	Water Dam Soil Gas Implant	Sample End Time:	August 31, 2016 DATE	13:04 TIME
Shut-in Test:	-16 Max. Vacuum (inches Hq)	30 Test Duration (seconds)	Initial Canister Vacuum: _	-32 Inches Hq	12:34 TIME
Leak Test Notes:	No Loss Shut-in Test	No Loss Water Dam	Final Canister Vacuum: _	-14 Inches Hq	13:04 TIME
Sample Depth: _	< 1 Feet		Sample Delivery:	August 31, 2016 DATE	16:45 TIME
Sample Container Details:	6 Volume (liters) Fl	30 ow Controler (minutes)	Delivery Method (FedEx, courier, etc.):	Delivered in person	
		· · ·		_	
	ME	TEOROLOGICAL CO	NDITIONS FOR SAMPLING DAY	Y	
Ambient Temperature (°F):	64 Low	74 High	Sea Level Pressure (Inches)	30.08	
Average Wind:	North-northeast Direction	11 Velocity (mph)	Average Humidity (%):	67	
		ADDITIO	ONAL DETAILS		
Other details for tenant space	(e.g. recent construction/renova		emical storage, slab/foundation cracks,	HVAC status etc.):	
<u> </u>	Sample was collected south of the	ne dry cleaning plant near t	he rear door.		
-					
Problems or inconsistancies e	encountered during sampling:				
<u>.</u>	Not applicable				
* Include a site sketch on sep	arate sheet noting sample locatio	ons (with measurements), o	chemical storage areas, former operatio	ns areas, etc.	
Sample Number:	SV-3		Analyses:	VOCs by EPA Sample Metho	od TO-15
SUMMA ID Number:	2469 (60268)		Requested Turnaround Time:	1 Week TAT	
Regulator ID Number:	B-23		Sample Crew:	Joe Becker	



Project Name:	Bright Cleaners - Franklin	Centre	Project Number: _	PECO_2017-68	
Vapor Point Installation Date:	August 11, 2017		Project Address: _	7201 South 76th Street	
Sub-Slab Sample Date:	August 14, 2017		<u>-</u>	Franklin, Wisconsin	
		SAMPLIN	IG INFORMATION		
Soil Gas Implant Purge Air: _	0.9 Stabilized PID Reading (PPM)	2 Volume (liters)	Sample Start Time: _	August 14, 2014  DATE	12:24 TIME
Leak Test Method: _	Shut-in Test Sample Train	Water Dam Soil Gas Implant	Sample End Time: _	August 14, 2014 DATE	12:54 TIME
Shut-in Test:	-17 30	30 Test Duration (seconds)	Canister Vacuum: _	-28 1/2 Initial (Inches Hq)	-7 Final (Inches Hq)
Leak Test Notes:	No Loss Shut-in Test	No Loss Water Dam	Analysis Details: s	STAT Analysis Corporation  Laboratory	Chicago, IL
Sample Depth: _	< 1 Fee	<u>t</u>	Sample Delivery: _	August 13, 2017 DATE	13:30 TIME
Sample Container Details:	6 Volume (liters)	30 Flow Controler (minutes)	Delivery Method (FedEx, courier, etc.):_	Delivered in person	
			NIDITIONS FOR CAMPI INC DA	v	
	IVI	ETEURULUGICAL CO	NDITIONS FOR SAMPLING DA	Y	
Ambient Temperature (°F):	64 Low	78 High	Barometric Pressure / Humidity _	985.54 mBar	51 %
Average Wind:	7 Velocity (mph)	South-southwest Direction	Precipitation (Inches): _	0.00 Day of Sampling	0.00 Previous 48 Hours
		ADDITI	ONAL DETAILS		
Other details for tenant space	e (e.g. recent construction/rend		nemical storage, slab/foundation cracks,	HVAC status etc.):	
<u>:</u>	Sample was collected near the	e front of the dry cleaner tena	ant space.		
_					
_					
Problems or inconsistancies e	encountered during sampling:				
_					
-					
<sup>*</sup> include a site sketch on sep	arate sheet noting sample loca	ations (with measurements),	chemical storage areas, former operation	ons areas, etc.	
Sample Number:	SV-4		Analyses: _	VOCs by EPA Sample Meth	nod TO-15
SUMMA ID Number:	60256		Requested Turnaround Time: _	1 Week TAT	
Regulator ID Number:	7248443		Sample Crew: _	Joe Becker	




Project Name:	Bright Cleaners - Franklin	Centre	Project Number: _	PECO_2017-68	
Vapor Point Installation Date:	August 11, 2017		Project Address: _	7201 South 76th Street	
Sub-Slab Sample Date:	August 14, 2017		<u>-</u>	Franklin, Wisconsin	
		SAMPLIN	IG INFORMATION		
Soil Gas Implant Purge Air:	0.1 Stabilized PID Reading (PPM)	2 Volume (liters)	Sample Start Time: _	August 14, 2014  DATE	12:35 TIME
Leak Test Method: _	Shut-in Test Sample Train	Water Dam Soil Gas Implant	Sample End Time: _	August 14, 2014 DATE	13:06 TIME
Shut-in Test:	-17 30	30 Test Duration (seconds)	Canister Vacuum: _	-27 Initial (Inches Hg)	-6 1/2 Final (Inches Hq)
Leak Test Notes: _	No Loss Shut-in Test	No Loss Water Dam	Analysis Details: _	STAT Analysis Corporation  Laboratory	Chicago, IL Location
Sample Depth: _	< 1 Fee	t	Sample Delivery: _	August 13, 2017 DATE	13:30 TIME
Sample Container Details:	6 Volume (liters)	30 Flow Controler (minutes)	Delivery Method (FedEx, courier, etc.): _	Delivered in person	
	M	ETEOROLOGICAL CO	NDITIONS FOR SAMPLING DA	Υ	
	***	2.201102001071200	2 2	•	
Ambient Temperature (°F): _	64 Low	78 High	Barometric Pressure / Humidity _	985.54 mBar	51 %
Average Wind: _	7 Velocity (mph)	South-southwest Direction	Precipitation (Inches): _	0.00 Day of Sampling	0.00 Previous 48 Hours
		ADDITI	ONAL DETAILS		
·		•	nemical storage, slab/foundation cracks	,	
-	Sample was collected flear the	e real of the or o terialit spar	ce to the west of the dry cleaning tenan	зрасе.	
- -					
Problems or inconsistancies e	encountered during sampling:				
-					
* Include a site sketch on sep	arate sheet noting sample loca	ations (with measurements),	chemical storage areas, former operation	ons areas, etc.	
Sample Number:	SV-5		Analyses: _	VOCs by EPA Sample Meth	nod TO-15
SUMMA ID Number:	60230		Requested Turnaround Time: _	1 Week TAT	
Regulator ID Number:	A0171584-1		Sample Crew: _	Joe Becker	




Project Name: _	Bright Cleaners - Franklin	Centre	Project Number: _	PECO_2017-68	
Vapor Point Installation Date:	August 11, 2017		Project Address: _	7201 South 76th Street	
Sub-Slab Sample Date:	August 14, 2017		<u>-</u>	Franklin, Wisconsin	
		SAMPLIN	IG INFORMATION		
Soil Gas Implant Purge Air: _	0.0 Stabilized PID Reading (PPM)	2 Volume (liters)	Sample Start Time: _	August 14, 2014  DATE	12:30 TIME
Leak Test Method: _	Shut-in Test Sample Train	Water Dam Soil Gas Implant	Sample End Time: _	August 14, 2014 DATE	13:01 TIME
Shut-in Test: _	-13 30	30 Test Duration (seconds)	Canister Vacuum: _	-30 Initial (Inches Hg)	-7 1/2 Final (Inches Hg)
Leak Test Notes: _	No Loss Shut-in Test	No Loss Water Dam	Analysis Details: <u>s</u>	STAT Analysis Corporation  Laboratory	Chicago, IL Location
Sample Depth: _	< 1 Fee		Sample Delivery:	August 13, 2017 DATE	13:30 TIME
Sample Container Details: _		30 Flow Controler (minutes)	Delivery Method (FedEx, courier, etc.): _	Delivered in person	
	M	ETEOROLOGICAL CO	ONDITIONS FOR SAMPLING DA	Υ	
			<u></u>	•	
Ambient Temperature (°F): _	64 Low	78 High	Barometric Pressure / Humidity _	985.54 mBar	51 %
Average Wind: _	7 Velocity (mph)	South-southwest Direction	Precipitation (Inches): _	0.00 Day of Sampling	0.00 Previous 48 Hours
		ADDITI	ONAL DETAILS		
Other details for tenant space	e (e.g. recent construction/rend	vation, cleaning activities, cl	hemical storage, slab/foundation cracks,	HVAC status etc.):	
<u>.                                    </u>	Sample was collected near the	e rear of the Pizza Hut tenan	t space to the east of the dry cleaning to	enant space.	
-					
- Problems or inconsistancies e	encountered during sampling:				
_					
* Include a site sketch on sen	arate sheet noting sample loca	ations (with measurements)	chemical storage areas, former operation	ons areas, etc.	
		(),	200 areas, former operation	, 2.0.	
Sample Number:	SV-6		Analyses: _	VOCs by EPA Sample Meth	nod TO-15
SUMMA ID Number:	60223		Requested Turnaround Time: _	1 Week TAT	
Regulator ID Number:	A01158-4		Sample Crew:	Joe Becker	

					Well I.D.	MW-1			Job Number:	PECO_201	7-68	
					Client:	Phillips Edis	on & Compar	ny	Date:	Thursday, A	August 17, 2017	
	AF	PEX	5		Project:	Franklin Ce	ntre		Sampler:	Joe Becker		
	,				Weather:	75°, Mostly	Cloudy		Time In/Out:	11:25 / 12:1	0	
					,	WELL DATA	·					
Vell Depth (f	):	19.5			Well Diamete	er (in):	2		Water Height	t (ft):	7.62	
epth to Wat	er (ft):	11.88			Screened Into	erval (ft bgs):	9-1/2 to 19-	1/2	x Multiplier		0.163	
Vater Colum	n Length (ft):	7.62			Depth to Free	e Product:	Not Encoun	tered	x Casing Vol	umes	3	
Purge Volum		14 1/2			Free Product		N/A		=Purge Volur		14	
Water I	Height Multipli	ers (gal)	1-inch :	= 0.041		= 0.162 JRGING DATA		= 0.653	1 gallon = 3.7	785 liters		
urge Metho	d:	Peristaltic P	ump		Pump Intake	Depth (ft):	19			Comments:		
Sampling Me	thod:	Peristaltic P	ump		Tubing Type:		Low Density	y Polyethylene	9			
Time	Volume Purged (liters)	Cumulative Volume Purged (liters)	DTW (btc)	Purge Rate (L/min)	рН	Temp (°C)	Cond (mS/cm)	DO (ppm)	ORP (mV)	Turbidity (NTU's)	Clarity/Color Other Remarks	
		(iiters)			+/-0.2	+/-0.5°C	+/-5%	+/-0.5	+/-20mV	+/-10%	<stabilization crite<="" td=""></stabilization>	
11:34	1	1	12.42	1/2	7.14	18.30	5.7	0.31	-59.7		Clear	
11:37	1 1/2	2 1/2	13.07	1/2	6.89	17.20	5.9	0.30	-46.7		Clear	
11:40	1 1/2	4	13.41	1/2	6.83	17.20	5.9	0.48	-40.1		Clear	
11:43	1 1/2	5 1/2	13.79	1/2	6.81	16.89	6.0	0.56	-40.6		Clear	
11:46	1 1/2	7	13.92	1/2	6.81	16.91	6.0	0.63	-41.2		Clear	
11:49	1 1/2	8 1/2	14.37	1/2	6.80	16.80	5.9	0.76	-41.3		Clear	
11:52	1 1/2	10	14.70	1/2	6.81	16.93	5.9	0.75	-18.4		Clear	
11:55	1 1/2	11 1/2	14.85	1/2	6.81	16.84	5.8	0.75	-41.1		Clear	
11:58	1 1/2	13	15.02	1/2	6.81	17.06	5.8	0.78	-42.8		Clear	
12:01	1 1/2	14 1/2	15.15	1/2	6.82	17.20	5.7	0.80	-42.2		Clear	
Namita III MO					least days 0							
namy. VC =	very cloudy,	CL - Cloudy, S	SC = slightly cl	oudy, AC = a		= clear MPLING DAT	A					
Sample ID: Sample Time		MW-1 12:05		Sampling Flo Final Depth to	w Rate:	250 mL/min 15.15		Analytical La Did Well Dev		Pace Analy No	tical	
Containers			rvative		/ Method	Field F	iltered		r Size	MS/MSD	Duplicate ID	
3 / 40 m	L Glass	Н	CI	VC	)Cs	N	0	Not Ap	pplicable		Duplicate	
						COMMENTS						



Sample ID: MW-2 Sampling Flow Rate: 250 mL/min Analytical Laboratory: Pace Analytical Sample Time: 11:20 Final Depth to Water: 12.13 Did Well Dewater? No # Containers/Type Perservative Analysis/ Method Field Filtered Filter Size MS/MSD Duplicate ID Not Applicable Not Applicable Not Applicable Not Applicable COMMENTS

Page 2 of 3



**COMMENTS** 

# Appendix D

Groundwater Elevation Measurements & Slug Test Analysis



# Groundwater Elevation Measurements Franklin Centre 7249 South 76th Street, Franklin, Wisconsin

Apex Project No.: PECO\_2017-68

Well Number	Top of Casing Elevation (ft - MSL)	Well Depth (ft)	Screened Interval (ft)	Date	Depth to Groundwater (ft)	Groundwater Elevation (ft - MSL)	Difference (ft)
				August 14, 2017	11.88	756.82	
MW-1	768.70	19.5	9.5 to 19.5	August 17, 2017	11.88	756.82	0.00
				September 12, 2017	12.05	756.65	-0.17
				August 14, 2017	11.96	756.99	
MW-2	768.95	19.5	9.5 to 19.5	August 17, 2017	11.97	756.98	-0.01
				September 12, 2017	11.97	756.98	0.00
				August 14, 2017	8.40	760.91	
MW-3	769.31	15.0	5 to 15	August 17, 2017	8.40	760.91	0.00
				September 12, 2017	8.54	760.77	-0.14

Notes: MSL - Mean Sea Level

#### Results of Hydraulic Slug Testing: MW-1

#### WELL INFORMATION

Well ID: MW-1 Tuesday, September 12, 2017 Date: Test No.: 1 Start Time: 16:00 Test Type: Rising Head Test Method: Bail down Ground Elev.: feet AMSL TOC Elev.: 768.70 feet AMSL Lithology: 3 inches asphalt; 4 inches aggregate; silty clay (CL) to a depth of 3 feet bgs; a 3 inch clayey silt (ML) lens at 3 feet bgs; silty clay (CL) with trace gravel to a depth of 15 feet bgs, where refusal was encountered.


#### INPUT PARAMETERS

Well Construction:		
Borehole Radius (r <sub>w</sub> ) =	4	inch
Casing Radius (r <sub>c</sub> ) =	1	inch
Screen Length (L <sub>e</sub> ) =	10	feet
Screen Slot Open =	0.01	inch
Filter Pack:	7-1/2 to 19-1/2 00 Silica Sand	feet bgs
Annular Fill:	Bentonite	
Depths:		
Well =	19.5	feet bgs
Stabilized Water Level (Lw)=	7.97	feet
Top of Screen =	9.5	feet bgs
Top of Aquifer =	1	feet bgs
Base of Aquifer (H)=	19.5	feet bgs
Dimensionless Parameters 14	—— A	
log(L <sub>e</sub> /r <sub>w</sub> ) = 1.5		
A = 2.5	—в	
B = 0.4	—с !	
C = 2.1	Well	
4		
2		
0		
"	1 2	3 4


#### CALCULATIONS




#### WELL DIAGRAM



#### BOUWER & RICE SLUG TEST EQUATIONS<sup>1</sup>





#### AQUIFER RESPONSE

Time (sec)	Hydraulic Head	y (ft)	y/y <sub>o</sub> (ft)
	(ft)		
0	6.78	1.20	1.00
50	7.62	0.35	0.29
100	7.65	0.32	0.27
150	7.66	0.31	0.26
200	7.67	0.30	0.25
250	7.68	0.29	0.24
300	7.69	0.29	0.24
350	7.69	0.28	0.23
400	7.70	0.27	0.23
450	7.70	0.27	0.22
500	7.71	0.26	0.22
550	7.71	0.26	0.22
600	7.72	0.25	0.21
650	7.72	0.25	0.21
700	7.73	0.24	0.20
750	7.73	0.24	0.20
800	7.73	0.24	0.20
850	7.74	0.23	0.20
900	7.74	0.23	0.19
950	7.74	0.23	0.19
1,000	7.75	0.22	0.19
1,050	7.75	0.22	0.19
1,100	7.75	0.22	0.18
1,150	7.75	0.22	0.18
1,200	7.76	0.21	0.18
1,250	7.76	0.21	0.17
1,300	7.76	0.21	0.18
1,350	7.77	0.20	0.17
1,400	7.77	0.20	0.17
1,450	7.77	0.20	0.17
1,500	7.77	0.20	0.16
1,550	7.78	0.19	0.16
1,600	7.78	0.19	0.16
1,650	7.79	0.19	0.15
1,700	7.78	0.19	0.16
1,750	7.79	0.18	0.15
1,800	7.79	0.18	0.15
1,850	7.79	0.18	0.15
1,900	7.79	0.18	0.15
1,950	7.79	0.18	0.15
2,000	7.80	0.17	0.14



<sup>&</sup>lt;sup>1</sup> Bouwer, Herman. 1989. The Bouwer and Rice Slug Test - An Update. Ground Water, Vol. 27, No. 3: 304-309.


#### Results of Hydraulic Slug Testing: MW-2

#### WELL INFORMATION

Well ID: MW-2 Tuesday, September 12, 2017 Date: Test No.: 1 Start Time: 17:00 Test Type: Rising Head Test Method: Bail down Ground Elev.: feet AMSL TOC Elev.: 768.95 feet AMSL Lithology: 3 inches asphalt; 4 inches aggregate; clayey gravelly sand (SW) to a depth of 4 feet bgs; gravelly silty clay (CL) do a depth of 10 feet bgs; glayey gravelly sand (SW) to a depth of 11 feet bgs; clayey silt (ML) with trace gravel to a depth of 15-1/2 feet; and silty clay

(CL) to a depth of 18 feet bgs, where refusal was encountered.


#### INPUT PARAMETERS



#### CALCULATIONS




#### WELL DIAGRAM



#### BOUWER & RICE SLUG TEST EQUATIONS<sup>1</sup>

Hydraulic Conductivity
$K = \frac{r_{e}^{2} ln \left(\frac{R_{e}}{r_{w}}\right)}{2L_{e}} \frac{1}{t} ln \frac{y_{0}}{y_{t}}$
Effective Radius of Influence Partially Penetrating Well $(L_w < H)$ :
$\ln\!\left(\frac{R_{\rm e}}{r_{\rm w}}\right)\!=\!\left[\frac{1.1}{\ln\!\left(\frac{L_{\rm w}}{r_{\rm w}}\right)\!+\!\frac{A+B\!\ln\!\left[\frac{\left(H-L_{\rm w}}{r_{\rm w}}\right)\!\right]}{\left(\frac{L_{\rm e}}{r_{\rm w}}\right)}\right]^{\!-1}$
Fully Penetrating Well (L <sub>w</sub> = H):
$\ln\left(\frac{R_{c}}{r_{w}}\right) = \left[\frac{1.1}{\ln\left(\frac{L_{w}}{r_{w}}\right)} + \frac{C}{\left(\frac{L_{c}}{r_{w}}\right)}\right]^{-1}$



#### AQUIFER RESPONSE

Time (sec)	Hydraulic Head	y (ft)	y/y <sub>0</sub> (ft)
	(ft)		
0	6.45	0.83	1.00
1	6.56	0.72	0.86
2	6.82	0.46	0.56
3	6.91	0.37	0.44
4	7.00	0.28	0.34
5	7.04	0.24	0.29
6	7.07	0.21	0.25
7	7.09	0.19	0.23
8	7.11	0.17	0.21
9	7.12	0.16	0.20
10	7.13	0.15	0.18
11	7.15	0.13	0.16
12	7.15	0.13	0.15
13	7.16	0.12	0.15
14	7.17	0.12	0.14
15	7.18	0.11	0.13
16	7.18	0.10	0.12
17	7.18	0.10	0.12
18	7.19	0.09	0.11
19	7.20	0.08	0.10
20	7.20	0.08	0.09
21	7.20	0.08	0.09
22	7.21	0.07	0.08
23	7.22	0.07	0.08
24	7.21	0.07	0.08
25	7.22	0.06	0.07
26	7.23	0.06	0.07
27	7.23	0.06	0.07
28	7.23	0.05	0.06
29	7.23	0.05	0.06
30	7.23	0.05	0.06
31	7.23	0.05	0.06
32	7.24	0.04	0.05
33	7.24	0.04	0.05
34	7.24	0.04	0.05
35	7.25	0.04	0.04
36	7.24	0.04	0.05
37	7.24	0.04	0.04
38	7.25	0.03	0.04
39	7.25	0.03	0.04
40	7.25	0.03	0.03

Hydraulic Conductivity									
	K =	4.68E-05	feet/second						
		1.43E-03	centimeters/second						

<sup>&</sup>lt;sup>1</sup> Bouwer, Herman. 1989. The Bouwer and Rice Slug Test - An Update. Ground Water, Vol. 27, No. 3: 304-309.

#### Results of Hydraulic Slug Testing: MW-2

#### WELL INFORMATION

Well ID: MW-2 Tuesday, September 12, 2017 Date: Test No.: 2 Start Time: 17:08 Test Type: Rising Head Test Method: Bail down Ground Elev.: feet AMSL TOC Elev.: 768.95 feet AMSL Lithology: 3 inches asphalt; 4 inches aggregate; clayey gravelly sand (SW) to a depth of 4 feet bgs; gravelly silty clay (CL) do a depth of 10 feet bgs; glayey gravelly sand (SW) to a depth of 11 feet bgs; clayey silt (ML) with trace gravel to a depth of 15-1/2 feet; and silty clay

(CL) to a depth of 18 feet bgs, where refusal was encountered.


#### INPLIT PARAMETERS

Well Construction:		
Borehole Radius (r <sub>w</sub> ) =	= 4	inch
Casing Radius (r <sub>c</sub> ) =	= 1	inch
Screen Length (L <sub>e</sub> ) =	= 10	feet
Screen Slot Open =	= 0.01	inch
Filter Pack	: 7-1/2 to 1 00 Silica S	
Annular Fill	: Bentonite	!
Depths:		
Well :	= 19.5	feet bgs
Stabilized Water Level (L <sub>w</sub> )	= 7.28	feet
Top of Screen =	= 9.5	feet bgs
Top of Aquifer =	= 1	feet bgs
Base of Aquifer (H)=	= 19.5	feet bgs
Dimensionless Parameters 14		
log(L <sub>e</sub> /r <sub>w</sub> ) = 1.5	—— А	
A = 2.5	—— в	i /
B = 0.4	——с	1 //
C = 2.1	Well	1 //
6		!
*		
2		
0	) 1	2 3 4
"		Log(Re/rw)


#### CALCULATIONS




#### WELL DIAGRAM



#### BOUWER & RICE SLUG TEST EQUATIONS<sup>1</sup>





#### AQUIFER RESPONSE

Time (sec)	Hydraulic Head	y (ft)	y/y <sub>0</sub> (ft)
0	(ft)	0.59	1.00
1	6.69 7.20	0.59	0.14
2	7.20	0.08	0.14
3	7.18	0.10	0.18
4	7.16	0.10	0.18
5	7.18	0.12	0.21
6	7.19	0.10	0.17
7	7.19	0.10	0.15
8	7.19	0.09	0.13
9	7.20	0.08	0.14
10	7.21	0.07	0.12
11	7.21	0.07	0.12
12	7.22	0.06	0.10
13	7.23	0.05	0.09
14	7.23		
	-	0.06	0.09
15	7.23	0.05	0.09
16	7.23	0.05	0.08
17	7.23	0.05	0.08
18	7.23	0.05	0.08
19	7.23	0.05	0.08
20	7.24	0.04	0.08
21	7.24	0.04	0.07
22	7.24	0.04	0.07
23	7.24	0.04	0.07
24	7.25	0.04	0.06
25	7.25	0.04	0.06
26	7.25	0.03	0.05
27	7.25	0.03	0.06
28	7.25	0.03	0.06
29	7.25	0.03	0.05
30	7.25	0.03	0.05
31	7.25	0.03	0.05
32	7.25	0.03	0.05
33	7.25	0.03	0.05
34	7.26	0.03	0.04
35	7.26	0.03	0.04
36	7.26	0.02	0.04
37	7.26	0.03	0.04
38	7.26	0.02	0.04
39	7.26	0.02	0.03
40	7.26	0.03	0.04

Hydraulic Condu	ctivity	
К =	3.62E-05	feet/second
	1.10E-03	centimeters/second

<sup>&</sup>lt;sup>1</sup> Bouwer, Herman. 1989. The Bouwer and Rice Slug Test - An Update. Ground Water, Vol. 27, No. 3: 304-309.


#### Results of Hydraulic Slug Testing: MW-2

#### WELL INFORMATION


Well ID: MW-2 Tuesday, September 12, 2017 Date: Test No.: 3 Start Time: 17:15 Test Type: Rising Head Test Method: Bail down Ground Elev.: feet AMSL TOC Elev.: 768.95 feet AMSL Lithology: 3 inches asphalt; 4 inches aggregate; clayey gravelly sand (SW) to a depth of 4 feet bgs; gravelly silty clay (CL) do a depth of 10 feet bgs; glayey gravelly sand (SW) to a depth of 11 feet bgs; clayey silt (ML) with trace gravel to a depth of 15-1/2 feet; and silty clay

(CL) to a depth of 18 feet bgs, where refusal was encountered.


#### INPUT PARAMETERS



#### CALCULATIONS




#### WELL DIAGRAM



#### BOUWER & RICE SLUG TEST EQUATIONS<sup>1</sup>

Hydraulic Conductivity
$K = \frac{r_c^2 ln\left(\frac{R_e}{r_w}\right)}{2L_e} \frac{1}{t} ln \frac{y_0}{y_t}$
Effective Radius of Influence Partially Penetrating Well (L <sub>w</sub> < H):
$ln\left(\frac{R_{c}}{r_{w}}\right) = \left[\frac{1.1}{ln\left(\frac{L_{w}}{r_{w}}\right)} + \frac{A + Bln\left[\frac{(H - L_{w})}{r_{w}}\right]}{\left(\frac{L_{c}}{r_{w}}\right)}\right]^{-1}$
$\ln\left(\frac{r_{\rm w}}{r_{\rm w}}\right) = \left[\frac{L_{\rm w}}{\ln\left(\frac{L_{\rm w}}{r_{\rm w}}\right)} + \frac{L_{\rm w}}{\left(\frac{L_{\rm w}}{r_{\rm w}}\right)}\right]$
Fully Penetrating Well (L <sub>w</sub> = H):
$\ln\left(\frac{R_{e}}{r_{w}}\right) = \left[\frac{1.1}{\ln\left(\frac{L_{w}}{r_{w}}\right)} + \frac{C}{\left(\frac{L_{e}}{r_{w}}\right)}\right]^{-1}$



#### AQUIFER RESPONSE

Time (sec)	Hydraulic Head	y (ft)	y/y <sub>o</sub> (ft)
	(ft)		
0	6.39	0.89	1.00
1	6.81	0.47	0.53
2	6.74	0.53	0.60
3	6.93	0.35	0.39
4	7.00	0.27	0.31
5	7.05	0.23	0.25
6	7.08	0.19	0.22
7	7.10	0.17	0.20
8	7.11	0.16	0.18
9	7.13	0.14	0.16
10	7.14	0.13	0.15
11	7.15	0.12	0.13
12	7.16	0.11	0.13
13	7.17	0.10	0.12
14	7.17	0.10	0.11
15	7.18	0.09	0.11
16	7.18	0.09	0.10
17	7.19	0.08	0.09
18	7.19	0.08	0.09
19	7.20	0.07	0.08
20	7.20	0.07	0.08
21	7.21	0.06	0.07
22	7.21	0.06	0.07
23	7.21	0.06	0.07
24	7.21	0.06	0.06
25	7.22	0.05	0.06
26	7.22	0.05	0.06
27	7.22	0.05	0.05
28	7.22	0.05	0.05
29	7.23	0.04	0.05
30	7.23	0.04	0.05
31	7.23	0.04	0.04
32	7.23	0.04	0.04
33	7.24	0.03	0.04
34	7.24	0.03	0.04
35	7.24	0.03	0.04
36	7.24	0.03	0.04
37	7.24	0.03	0.03
38	7.24	0.03	0.03
39	7.25	0.02	0.03
40	7.24	0.03	0.03

K =	4.74E-05	feet/second	
	1.45E-03	centimeters/second	

<sup>&</sup>lt;sup>1</sup> Bouwer, Herman. 1989. The Bouwer and Rice Slug Test - An Update. Ground Water, Vol. 27, No. 3: 304-309.

#### Results of Hydraulic Slug Testing: MW-3

#### WELL INFORMATION

Well ID: MW-3 Date: Tuesday, September 12, 2017 Test No.: 1 Start Time: 17:20 Test Type: Rising Head Test Method: Bail down Ground Elev.: feet AMSL feet AMSL TOC Elev.: 769.31 Lithology: 5 inches asphalt; 8 inches aggregate; silty clay (CL) to a depth of 8 feet bgs; clayey silt (ML) to a depth of 12 feet bgs, where refusal was encountered.


#### INPUT PARAMETERS

Well Construction:		
Borehole Radius (r <sub>w</sub> ) =	4	inch
Casing Radius (r <sub>c</sub> ) =	1	inch
Screen Length (L <sub>e</sub> ) =	10	feet
Screen Slot Open =	0.01	inch
Filter Pack:	3 to 15 00 Silica Sand	feet bgs
Annular Fill:	Bentonite	
Depths:		
Well =	15	feet bgs
Stabilized Water Level (Lw)=	6.54	feet
Top of Screen =	5	feet bgs
Top of Aquifer =	8	feet bgs
Base of Aquifer (H)=	15	feet bgs
Dimensionless Parameters $\log(\mathbb{L}_q/r_w) = 1.5$ 12 12 12 14 12 14 15 16 16 17 17 18 17 18 18 19 19 19 19 19 19 19 19 19 19 19 19 19	- Well   Log(Re,	22 3 4 (rw)


#### CALCULATIONS




#### WELL DIAGRAM




#### BOUWER & RICE SLUG TEST EQUATIONS<sup>1</sup>





#### AQUIFER RESPONSE

Time (see)	Hydraulic Head	(6)	y/y <sub>o</sub> (ft)
Time (sec)	(ft)	y (ft)	
0	6.03	0.51	1.00
50	6.29	0.25	0.49
100	6.30	0.24	0.48
150	6.30	0.24	0.47
200	6.31	0.24	0.46
250	6.31	0.23	0.45
300	6.31	0.23	0.44
350	6.31	0.23	0.45
400	6.31	0.23	0.44
450	6.32	0.23	0.44
500	6.32	0.22	0.44
550	6.32	0.22	0.44
600	6.32	0.22	0.42
650	6.32	0.22	0.42
700	6.32	0.22	0.42
750	6.32	0.22	0.43
800	6.33	0.21	0.42
850	6.33	0.21	0.42
900	6.33	0.21	0.41
950	6.33	0.21	0.41
1,000	6.33	0.21	0.40
1,050	6.33	0.21	0.41
1,100	6.33	0.21	0.41
1,150	6.33	0.21	0.41
1,200	6.34	0.20	0.40
1,250	6.34	0.21	0.40
1,300	6.34	0.20	0.40
1,350	6.34	0.20	0.39
1,400	6.34	0.20	0.40
1,450	6.34	0.20	0.39
1,500	6.34	0.20	0.39
1,550	6.34	0.20	0.39
1,600	6.34	0.20	0.38
1,650	6.34	0.20	0.38
1,700	6.35	0.20	0.38
1,750	6.35	0.20	0.38
1,800	6.35	0.20	0.38
1,850	6.35	0.19	0.38
1,900	6.35	0.19	0.37
1,950	6.35	0.19	0.37
2,000	6.35	0.19	0.37



<sup>&</sup>lt;sup>1</sup> Bouwer, Herman. 1989. The Bouwer and Rice Slug Test - An Update. Ground Water, Vol. 27, No. 3: 304-309.

# Appendix E Laboratory Reports



2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

September 09, 2016

Apex Companies, LLC 1701 East Woodfield Rd, Suite 333 Schaumburg, IL 60173

Telephone: (847) 956-8589 Fax: (847) 956-8619

Analytical Report for STAT Work Order: 16081298 Revision 0

RE: PECO-216-78, Bright Cleaners-Franklin Centre, 7249 S. 76th St., Franklin

Dear Joseph Becker:

STAT Analysis received 8 samples for the referenced project on 8/31/2016 4:45:00 PM. The analytical results are presented in the following report.

All analyses were performed in accordance with the requirements specifed in WAC DNR Chapter NR 149 (Certification Number 399099910). Analyses were performed in accordance with methods as referenced on the analytical report.

All analyses were performed within established holding time criteria, and all Quality Control criteria met EPA or laboratory specifications except when noted in the Case Narrative or Analytical Report. A listing of accredited methods/parameters can also be provided.

For sample results requiring adjustment for dilutions, the detection and reporting limits are adjusted for the corresponding dilution factor. Analytical results expressed on a dry weight basis have units of mg/Kg-dry or µg/Kg-dry on the analytical report. Corresponding reporting limits are adjusted for dry weight.

Thank you for the opportunity to serve you and I look forward to working with you in the future. If you have any questions regarding the enclosed materials, please contact me at (312) 733-0551.

Sincerely,

Craig Chawla

Project Manager

The information contained in this report and any attachments is confidential information intended only for the use of the individual or entities named above. The results of this report relate only to the samples tested. If you have received this report in error, please notify us immediately by phone. This report shall not be reproduced, except in its entirety, unless written approval has been obtained from the laboratory. This analytical report shall become property of the Customer upon payment in full. Otherwise, STAT will be under no obligation to support, defend or discuss the analytical report.



Date: September 09, 2016

**Client:** Apex Companies, LLC

**Work Order Sample Summary Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

Work Order: 16081298 Revision 0

Lab Sample ID	Client Sample ID	Tag Number	<b>Collection Date</b>	<b>Date Received</b>
16081298-001A	TW-1 @ 14'		8/31/2016 10:00:00 AM	8/31/2016
16081298-001B	TW-1 @ 14'		8/31/2016 10:00:00 AM	8/31/2016
16081298-002A	TW-2 @ 11'		8/31/2016 10:30:00 AM	8/31/2016
16081298-002B	TW-2 @ 11'		8/31/2016 10:30:00 AM	8/31/2016
16081298-003A	TW-3 @ 12'		8/31/2016 11:00:00 AM	8/31/2016
16081298-003B	TW-3 @ 12'		8/31/2016 11:00:00 AM	8/31/2016
16081298-004A	TW-1		8/31/2016 11:15:00 AM	8/31/2016
16081298-005A	TW-3		8/31/2016 12:40:00 PM	8/31/2016
16081298-006A	SV-1		8/31/2016 12:28:00 PM	8/31/2016
16081298-007A	SV-2		8/31/2016 12:32:00 PM	8/31/2016
16081298-008A	SV-3		8/31/2016 12:34:00 PM	8/31/2016

2 of 22

a para di para

Date: September 09, 2016

**CLIENT:** Apex Companies, LLC

Project: PECO-216-78, Bright Cleaners-Franklin Centre, 7249 S. 76t CASE NARRATIVE

Work Order: 16081298 Revision 0

TO-15 results that are reported in mg/m³ are calculated based on a temperature of 25°C, atmospheric pressure of 760 mm Hg, and the molecular weight of the analyte.

The TO-15 LCS analyzed 09/06/2016 had the following outside of control limits:

1,2,4-Trimethylbenzene: 133.6% (LCS) recovery (QC Limits 70-130%) 1,3-Dichlorobenzene: 131.2% (LCS) recovery (QC Limits 70-130%)

Ethylbenzene: 134.8% (LCS) recovery (QC Limits 70-130%) Naphthalene: 138.8% (LCS) recovery (QC Limits 70-130%) Total Xylenes: 132.5% (LCS) recovery (QC Limits 70-130%)

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: September 09, 2016

**ANALYTICAL RESULTS** 

**Collection Date:** 8/31/2016 10:00:00 AM

Client Sample ID: TW-1 @ 14'

**Date Printed:** September 09, 2016

**CLIENT:** Apex Companies, LLC Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

Matrix: SOIL Lab ID: 16081298-001

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds by GC/MS	SV	N5035/826	0B	Prep	Date: 8/31/2	016	Analyst: <b>PS</b>
Acetone	0.029	0.073	0.0022	JB	mg/Kg-dry	1	9/2/2016
Benzene	0.0018	0.0049	0.00019	J	mg/Kg-dry	1	9/2/2016
Bromodichloromethane	ND	0.0049	0.00039		mg/Kg-dry	1	9/2/2016
Bromoform	ND	0.0049	0.00039		mg/Kg-dry	1	9/2/2016
Bromomethane	ND	0.0097	0.00049		mg/Kg-dry	1	9/2/2016
2-Butanone	ND	0.073	0.0015		mg/Kg-dry	1	9/2/2016
Carbon disulfide	0.00019	0.049	0.00019	J	mg/Kg-dry	1	9/2/2016
Carbon tetrachloride	ND	0.0049	0.00029		mg/Kg-dry	1	9/2/2016
Chlorobenzene	ND	0.0049	0.00019		mg/Kg-dry	1	9/2/2016
Chloroethane	ND	0.0097	0.00039		mg/Kg-dry	1	9/2/2016
Chloroform	ND	0.0049	0.00019		mg/Kg-dry	1	9/2/2016
Chloromethane	ND	0.0097	0.00029		mg/Kg-dry	1	9/2/2016
Dibromochloromethane	ND	0.0049	0.00039		mg/Kg-dry	1	9/2/2016
1,1-Dichloroethane	ND	0.0049	0.00029		mg/Kg-dry	1	9/2/2016
1,2-Dichloroethane	ND	0.0049	0.00058		mg/Kg-dry	1	9/2/2016
1,1-Dichloroethene	ND	0.0049	0.00029		mg/Kg-dry	1	9/2/2016
cis-1,2-Dichloroethene	ND	0.0049	0.00029		mg/Kg-dry	1	9/2/2016
trans-1,2-Dichloroethene	ND	0.0049	0.00029		mg/Kg-dry	1	9/2/2016
1,2-Dichloropropane	ND	0.0049	0.00039		mg/Kg-dry	1	9/2/2016
cis-1,3-Dichloropropene	ND	0.0019	0.00019		mg/Kg-dry	1	9/2/2016
trans-1,3-Dichloropropene	ND	0.0019	0.00029		mg/Kg-dry	1	9/2/2016
Ethylbenzene	0.00026	0.0049	0.000097	J	mg/Kg-dry	1	9/2/2016
2-Hexanone	ND	0.019	0.00078		mg/Kg-dry	1	9/2/2016
4-Methyl-2-pentanone	ND	0.019	0.00029		mg/Kg-dry	1	9/2/2016
Methylene chloride	0.0019	0.0097	0.00078	JB	mg/Kg-dry	1	9/2/2016
Methyl tert-butyl ether	ND	0.0049	0.00019		mg/Kg-dry	1	9/2/2016
Styrene	ND	0.0049	0.00019		mg/Kg-dry	1	9/2/2016
1,1,2,2-Tetrachloroethane	ND	0.0049	0.00019		mg/Kg-dry	1	9/2/2016
Tetrachloroethene	ND	0.0049	0.00029		mg/Kg-dry	1	9/2/2016
Toluene	0.0017	0.0049	0.00019	J	mg/Kg-dry	1	9/2/2016
1,1,1-Trichloroethane	ND	0.0049	0.00019		mg/Kg-dry	1	9/2/2016
1,1,2-Trichloroethane	ND	0.0049	0.00049		mg/Kg-dry	1	9/2/2016
Trichloroethene	ND	0.0049	0.00019		mg/Kg-dry	1	9/2/2016
Vinyl chloride	ND	0.0049	0.00039		mg/Kg-dry	1	9/2/2016
Xylenes, Total	ND	0.015	0.00039		mg/Kg-dry	1	9/2/2016
Percent Moisture	D2	2974		Prep	Date: 9/1/20	16	Analyst: <b>GH</b>
Percent Moisture	13.5	0.2	0.1	*	wt%	1	9/2/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: September 09, 2016

**ANALYTICAL RESULTS** 

**Collection Date:** 8/31/2016 10:30:00 AM

DF Date Analyzed

Client Sample ID: TW-2 @ 11'

Units

MDL Qualifier

**Date Printed:** September 09, 2016

**CLIENT:** Apex Companies, LLC Work Order: 16081298 Revision 0

Analyses

PECO-216-78, Bright Cleaners-Franklin Centre, 7249

**Project:** 

Matrix: SOIL Lab ID: 16081298-002

RI.

Result

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds by GC/MS	SV	N5035/8260	В	Prep	Date: 8/31/2	016	Analyst: <b>JNM</b>
Acetone	ND	0.053	0.0016	-1	mg/Kg-dry	1	9/6/2016
Benzene	0.00044	0.0035	0.00014	J	mg/Kg-dry	1	9/6/2016
Bromodichloromethane	ND	0.0035	0.00028		mg/Kg-dry	1	9/6/2016
Bromoform	ND	0.0035	0.00028		mg/Kg-dry	1	9/6/2016
Bromomethane	ND	0.0070	0.00035		mg/Kg-dry	1	9/6/2016
2-Butanone	ND	0.053	0.0011		mg/Kg-dry	1	9/6/2016
Carbon disulfide	0.00051	0.035	0.00014	J	mg/Kg-dry	1	9/6/2016
Carbon tetrachloride	ND	0.0035	0.00021		mg/Kg-dry	1	9/6/2016
Chlorobenzene	ND	0.0035	0.00014		mg/Kg-dry	1	9/6/2016
Chloroethane	ND	0.0070	0.00028		mg/Kg-dry	1	9/6/2016
Chloroform	ND	0.0035	0.00014		mg/Kg-dry	1	9/6/2016
Chloromethane	ND	0.0070	0.00021		mg/Kg-dry	1	9/6/2016
Dibromochloromethane	ND	0.0035	0.00028		mg/Kg-dry	1	9/6/2016
1,1-Dichloroethane	ND	0.0035	0.00021		mg/Kg-dry	1	9/6/2016
1,2-Dichloroethane	ND	0.0035	0.00042		mg/Kg-dry	1	9/6/2016
1,1-Dichloroethene	ND	0.0035	0.00021		mg/Kg-dry	1	9/6/2016
cis-1,2-Dichloroethene	ND	0.0035	0.00021		mg/Kg-dry	1	9/6/2016
trans-1,2-Dichloroethene	ND	0.0035	0.00021		mg/Kg-dry	1	9/6/2016
1,2-Dichloropropane	ND	0.0035	0.00028		mg/Kg-dry	1	9/6/2016
cis-1,3-Dichloropropene	ND	0.0014	0.00014		mg/Kg-dry	1	9/6/2016
trans-1,3-Dichloropropene	ND	0.0014	0.00021		mg/Kg-dry	1	9/6/2016
Ethylbenzene	ND	0.0035	0.00007		mg/Kg-dry	1	9/6/2016
2-Hexanone	ND	0.014	0.00056		mg/Kg-dry	1	9/6/2016
4-Methyl-2-pentanone	ND	0.014	0.00021		mg/Kg-dry	1	9/6/2016
Methylene chloride	ND	0.0070	0.00056		mg/Kg-dry	1	9/6/2016
Methyl tert-butyl ether	ND	0.0035	0.00014		mg/Kg-dry	1	9/6/2016
Styrene	ND	0.0035	0.00014		mg/Kg-dry	1	9/6/2016
1,1,2,2-Tetrachloroethane	ND	0.0035	0.00014		mg/Kg-dry	1	9/6/2016
Tetrachloroethene	ND	0.0035	0.00021		mg/Kg-dry	1	9/6/2016
Toluene	0.00046	0.0035	0.00014	J	mg/Kg-dry	1	9/6/2016
1,1,1-Trichloroethane	ND	0.0035	0.00014		mg/Kg-dry	1	9/6/2016
1,1,2-Trichloroethane	ND	0.0035	0.00035		mg/Kg-dry	1	9/6/2016
Trichloroethene	ND	0.0035	0.00014		mg/Kg-dry	1	9/6/2016
Vinyl chloride	ND	0.0035	0.00028		mg/Kg-dry	1	9/6/2016
Xylenes, Total	ND	0.011	0.00028		mg/Kg-dry	1	9/6/2016
Percent Moisture	D2	2974		Prep	Date: 9/1/20	16	Analyst: <b>GH</b>
Percent Moisture	6.7	0.2	0.1	*	wt%	1	9/2/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: September 09, 2016

**ANALYTICAL RESULTS** 

**Collection Date:** 8/31/2016 11:00:00 AM

Client Sample ID: TW-3 @ 12'

**Date Printed:** September 09, 2016

**CLIENT:** Apex Companies, LLC Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

Matrix: SOIL 16081298-003 Lab ID:

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds by GC/MS	SI	W5035/826	 0B	Prep	Date: 8/31/2	2016	Analyst: <b>JNM</b>
Acetone	ND	0.058	0.0018		mg/Kg-dry	1	9/6/2016
Benzene	0.00045	0.0039	0.00015	J	mg/Kg-dry	1	9/6/2016
Bromodichloromethane	ND	0.0039	0.00031		mg/Kg-dry	1	9/6/2016
Bromoform	ND	0.0039	0.00031		mg/Kg-dry	1	9/6/2016
Bromomethane	ND	0.0077	0.00039		mg/Kg-dry	1	9/6/2016
2-Butanone	ND	0.058	0.0012		mg/Kg-dry	1	9/6/2016
Carbon disulfide	ND	0.039	0.00015		mg/Kg-dry	1	9/6/2016
Carbon tetrachloride	ND	0.0039	0.00023		mg/Kg-dry	1	9/6/2016
Chlorobenzene	ND	0.0039	0.00015		mg/Kg-dry	1	9/6/2016
Chloroethane	ND	0.0077	0.00031		mg/Kg-dry	1	9/6/2016
Chloroform	ND	0.0039	0.00015		mg/Kg-dry	1	9/6/2016
Chloromethane	ND	0.0077	0.00023		mg/Kg-dry	1	9/6/2016
Dibromochloromethane	ND	0.0039	0.00031		mg/Kg-dry	1	9/6/2016
1,1-Dichloroethane	ND	0.0039	0.00023		mg/Kg-dry	1	9/6/2016
1,2-Dichloroethane	ND	0.0039	0.00046		mg/Kg-dry	1	9/6/2016
1,1-Dichloroethene	ND	0.0039	0.00023		mg/Kg-dry	1	9/6/2016
cis-1,2-Dichloroethene	ND	0.0039	0.00023		mg/Kg-dry	1	9/6/2016
trans-1,2-Dichloroethene	ND	0.0039	0.00023		mg/Kg-dry	1	9/6/2016
1,2-Dichloropropane	ND	0.0039	0.00031		mg/Kg-dry	1	9/6/2016
cis-1,3-Dichloropropene	ND	0.0015	0.00015		mg/Kg-dry	1	9/6/2016
trans-1,3-Dichloropropene	ND	0.0015	0.00023		mg/Kg-dry	1	9/6/2016
Ethylbenzene	ND	0.0039	0.000077		mg/Kg-dry	1	9/6/2016
2-Hexanone	ND	0.015	0.00062		mg/Kg-dry	1	9/6/2016
4-Methyl-2-pentanone	ND	0.015	0.00023		mg/Kg-dry	1	9/6/2016
Methylene chloride	ND	0.0077	0.00062		mg/Kg-dry	1	9/6/2016
Methyl tert-butyl ether	ND	0.0039	0.00015		mg/Kg-dry	1	9/6/2016
Styrene	ND	0.0039	0.00015		mg/Kg-dry	1	9/6/2016
1,1,2,2-Tetrachloroethane	ND	0.0039	0.00015		mg/Kg-dry	1	9/6/2016
Tetrachloroethene	ND	0.0039	0.00023		mg/Kg-dry	1	9/6/2016
Toluene	0.00041	0.0039	0.00015	J	mg/Kg-dry	1	9/6/2016
1,1,1-Trichloroethane	ND	0.0039	0.00015		mg/Kg-dry	1	9/6/2016
1,1,2-Trichloroethane	ND	0.0039	0.00039		mg/Kg-dry	1	9/6/2016
Trichloroethene	ND	0.0039	0.00015		mg/Kg-dry	1	9/6/2016
Vinyl chloride	ND	0.0039	0.00031		mg/Kg-dry	1	9/6/2016
Xylenes, Total	ND	0.012	0.00031		mg/Kg-dry	1	9/6/2016
Percent Moisture	D2974		Prep Date: 9/1/2016			Analyst: <b>GH</b>	
Percent Moisture	11.1	0.2	0.1	*	wt%	1	9/2/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** September 09, 2016

September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

**Lab ID:** 16081298-004

**Date Printed:** 

**ANALYTICAL RESULTS** 

**Client Sample ID:** TW-1

**Collection Date:** 8/31/2016 11:15:00 AM

Matrix: AQUEOUS

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds by GC/MS	S	W8260B	(SW5030B)	Prep Date:			Analyst: RRS
Acetone	ND	0.020	0.0031		mg/L	1	9/1/2016
Benzene	ND	0.00050	0.0002		mg/L	1	9/1/2016
Bromodichloromethane	ND	0.00050	0.0002		mg/L	1	9/1/2016
Bromoform	ND	0.0010	0.0003		mg/L	1	9/1/2016
Bromomethane	ND	0.0050	0.002		mg/L	1	9/1/2016
2-Butanone	ND	0.010	0.0016		mg/L	1	9/1/2016
Carbon disulfide	ND	0.0050	0.0003		mg/L	1	9/1/2016
Carbon tetrachloride	ND	0.00050	0.001		mg/L	1	9/1/2016
Chlorobenzene	ND	0.00050	0.0002		mg/L	1	9/1/2016
Chloroethane	ND	0.0050	0.0005		mg/L	1	9/1/2016
Chloroform	ND	0.00050	0.0001		mg/L	1	9/1/2016
Chloromethane	ND	0.0050	0.0003		mg/L	1	9/1/2016
Dibromochloromethane	ND	0.00050	0.0002		mg/L	1	9/1/2016
1,1-Dichloroethane	ND	0.00050	0.0002		mg/L	1	9/1/2016
1,2-Dichloroethane	ND	0.0010	0.0002		mg/L	1	9/1/2016
1,1-Dichloroethene	ND	0.0010	0.0004		mg/L	1	9/1/2016
cis-1,2-Dichloroethene	ND	0.0010	0.0002		mg/L	1	9/1/2016
trans-1,2-Dichloroethene	ND	0.0010	0.0005		mg/L	1	9/1/2016
1,2-Dichloropropane	ND	0.0010	0.0001		mg/L	1	9/1/2016
cis-1,3-Dichloropropene	ND	0.0010	0.0002		mg/L	1	9/1/2016
trans-1,3-Dichloropropene	ND	0.0010	0.0001		mg/L	1	9/1/2016
Ethylbenzene	ND	0.00050	0.0003		mg/L	1	9/1/2016
2-Hexanone	ND	0.010	0.0002		mg/L	1	9/1/2016
4-Methyl-2-pentanone	ND	0.010	0.0007		mg/L	1	9/1/2016
Methylene chloride	ND	0.0050	0.0002		mg/L	1	9/1/2016
Methyl tert-butyl ether	ND	0.00050	0.0003		mg/L	1	9/1/2016
Styrene	ND	0.0010	0.0003		mg/L	1	9/1/2016
1,1,2,2-Tetrachloroethane	ND	0.00050	0.0001		mg/L	1	9/1/2016
Tetrachloroethene	ND	0.0010	0.0003		mg/L	1	9/1/2016
Toluene	ND	0.00050	0.0004		mg/L	1	9/1/2016
1,1,1-Trichloroethane	ND	0.0010	0.0002		mg/L	1	9/1/2016
1,1,2-Trichloroethane	ND	0.00050	0.0001		mg/L	1	9/1/2016
Trichloroethene	ND	0.0010	0.0003		mg/L	1	9/1/2016
Vinyl chloride	ND	0.0010	0.0003		mg/L	1	9/1/2016
Xylenes, Total	ND	0.0030	0.001		mg/L	1	9/1/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range



2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: September 09, 2016

**ANALYTICAL RESULTS** 

**Collection Date:** 8/31/2016 12:40:00 PM

**Date Printed:** September 09, 2016

Lab ID:

**CLIENT:** Apex Companies, LLC Work Order: 16081298 Revision 0

16081298-005

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

Matrix: AQUEOUS

Client Sample ID: TW-3

Analyses	Result	RL	MDL	Qualifier	Units	DF	<b>Date Analyzed</b>
Volatile Organic Compounds by GC/MS	SW8260B (SW5030B)		Prep Date:		Analyst: RRS		
Acetone	0.012	0.020	0.0031	J	mg/L	1	9/1/2016
Benzene	0.00024	0.00050	0.0002	J	mg/L	1	9/1/2016
Bromodichloromethane	ND	0.00050	0.0002		mg/L	1	9/1/2016
Bromoform	ND	0.0010	0.0003		mg/L	1	9/1/2016
Bromomethane	ND	0.0050	0.002		mg/L	1	9/1/2016
2-Butanone	ND	0.010	0.0016		mg/L	1	9/1/2016
Carbon disulfide	0.00034	0.0050	0.0003	J	mg/L	1	9/1/2016
Carbon tetrachloride	ND	0.00050	0.001		mg/L	1	9/1/2016
Chlorobenzene	ND	0.00050	0.0002		mg/L	1	9/1/2016
Chloroethane	ND	0.0050	0.0005		mg/L	1	9/1/2016
Chloroform	ND	0.00050	0.0001		mg/L	1	9/1/2016
Chloromethane	ND	0.0050	0.0003		mg/L	1	9/1/2016
Dibromochloromethane	ND	0.00050	0.0002		mg/L	1	9/1/2016
1,1-Dichloroethane	ND	0.00050	0.0002		mg/L	1	9/1/2016
1,2-Dichloroethane	ND	0.0010	0.0002		mg/L	1	9/1/2016
1,1-Dichloroethene	ND	0.0010	0.0004		mg/L	1	9/1/2016
cis-1,2-Dichloroethene	ND	0.0010	0.0002		mg/L	1	9/1/2016
trans-1,2-Dichloroethene	ND	0.0010	0.0005		mg/L	1	9/1/2016
1,2-Dichloropropane	ND	0.0010	0.0001		mg/L	1	9/1/2016
cis-1,3-Dichloropropene	ND	0.0010	0.0002		mg/L	1	9/1/2016
trans-1,3-Dichloropropene	ND	0.0010	0.0001		mg/L	1	9/1/2016
Ethylbenzene	ND	0.00050	0.0003		mg/L	1	9/1/2016
2-Hexanone	ND	0.010	0.0002		mg/L	1	9/1/2016
4-Methyl-2-pentanone	ND	0.010	0.0007		mg/L	1	9/1/2016
Methylene chloride	ND	0.0050	0.0002		mg/L	1	9/1/2016
Methyl tert-butyl ether	ND	0.00050	0.0003		mg/L	1	9/1/2016
Styrene	ND	0.0010	0.0003		mg/L	1	9/1/2016
1,1,2,2-Tetrachloroethane	ND	0.00050	0.0001		mg/L	1	9/1/2016
Tetrachloroethene	ND	0.0010	0.0003		mg/L	1	9/1/2016
Toluene	ND	0.00050	0.0004		mg/L	1	9/1/2016
1,1,1-Trichloroethane	ND	0.0010	0.0002		mg/L	1	9/1/2016
1,1,2-Trichloroethane	ND	0.00050	0.0001		mg/L	1	9/1/2016
Trichloroethene	ND	0.0010	0.0003		mg/L	1	9/1/2016
Vinyl chloride	ND	0.0010	0.0003		mg/L	1	9/1/2016
Xylenes, Total	ND	0.0030	0.001		mg/L	1	9/1/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** September 09, 2016

September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

**Lab ID:** 16081298-006

**Date Printed:** 

**ANALYTICAL RESULTS** 

**Client Sample ID:** SV-1

**Collection Date:** 8/31/2016 12:28:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in	Air by GC/MS TO	-15		Prep	Date: <b>9/2/2</b>	016	Analyst: <b>NLM</b>
1,1,1-Trichloroethane	ND	0.46	0.024	-	ppbv	1	9/6/2016
1,1,2,2-Tetrachloroethane	ND	0.46	0.032		ppbv	1	9/6/2016
1,1,2-Trichloroethane	ND	0.46	0.045		ppbv	1	9/6/2016
1,1-Dichloroethane	ND	0.46	0.022		ppbv	1	9/6/2016
1,1-Dichloroethene	ND	0.46	0.029		ppbv	1	9/6/2016
1,2,4-Trichlorobenzene	0.25	0.46	0.1	J	ppbv	1	9/6/2016
1,2,4-Trimethylbenzene	1.0	0.46	0.042		ppbv	1	9/6/2016
1,2-Dibromoethane	ND	0.46	0.052		ppbv	1	9/6/2016
1,2-Dichlorobenzene	0.069	0.46	0.038	J	ppbv	1	9/6/2016
1,2-Dichloroethane	ND	0.46	0.053		ppbv	1	9/6/2016
1,2-Dichloropropane	ND	0.46	0.032		ppbv	1	9/6/2016
1,3,5-Trimethylbenzene	0.28	0.46	0.032	J	ppbv	1	9/6/2016
1,3-Butadiene	ND	0.46	0.059		ppbv	1	9/6/2016
1,3-Dichlorobenzene	0.32	0.46	0.039	J	ppbv	1	9/6/2016
1,4-Dichlorobenzene	ND	0.46	0.049		ppbv	1	9/6/2016
1,4-Dioxane	ND	1.2	0.13		ppbv	1	9/6/2016
2-Butanone	2.3	1.2	0.11		ppbv	1	9/6/2016
2-Hexanone	0.76	2.3	0.13	J	ppbv	1	9/6/2016
4-Ethyltoluene	0.28	0.46	0.048	J	ppbv	1	9/6/2016
4-Methyl-2-pentanone	3.0	2.3	0.069		ppbv	1	9/6/2016
Acetone	34	4.6	0.16	*	ppbv	1	9/6/2016
Benzene	0.92	0.46	0.033		ppbv	1	9/6/2016
Benzyl chloride	ND	1.2	0.46		ppbv	1	9/6/2016
Bromodichloromethane	ND	0.46	0.032		ppbv	1	9/6/2016
Bromoform	ND	1.2	0.024		ppbv	1	9/6/2016
Bromomethane	0.14	1.2	0.054	J	ppbv	1	9/6/2016
Carbon disulfide	0.16	0.46	0.12	J	ppbv	1	9/6/2016
Carbon tetrachloride	ND	0.46	0.064		ppbv	1	9/6/2016
Chlorobenzene	ND	0.46	0.029		ppbv	1	9/6/2016
Chloroethane	ND	0.46	0.46		ppbv	1	9/6/2016
Chloroform	0.046	0.46	0.025	J	ppbv	1	9/6/2016
Chloromethane	ND	1.2	0.11		ppbv	1	9/6/2016
cis-1,2-Dichloroethene	0.44	0.46	0.034	J	ppbv	1	9/6/2016
cis-1,3-Dichloropropene	ND	0.46	0.054		ppbv	1	9/6/2016
Cyclohexane	0.71	0.46	0.098		ppbv	1	9/6/2016
Dibromochloromethane	ND	0.46	0.037		ppbv	1	9/6/2016
Dichlorodifluoromethane	0.46	0.46	0.015		ppbv	1	9/6/2016
Ethyl acetate	ND	1.2	0.092		ppbv	1	9/6/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: September 09, 2016

September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

Lab ID: 16081298-006

**Date Printed:** 

**ANALYTICAL RESULTS** 

Client Sample ID: SV-1

**Collection Date:** 8/31/2016 12:28:00 PM

Matrix: AIR

Analyses	Resul	t RL	MDL	Qualifier	r Units	DF	Date Analyzed
Volatile Organic Compounds in A	ir by GC/MS	TO-15		Pre	p Date: <b>9/2/2</b>	016	Analyst: <b>NLM</b>
Ethylbenzene	0.90	0.46	0.036		ppbv	1	9/6/2016
Freon-113	ND	0.46	0.017		ppbv	1	9/6/2016
Freon-114	ND	2.3	0.066		ppbv	1	9/6/2016
Heptane	1.3	0.46	0.045		ppbv	1	9/6/2016
Hexachlorobutadiene	0.069	0.46	0.052	J	ppbv	1	9/6/2016
Hexane	1.8	1.2	0.032		ppbv	1	9/6/2016
Isopropyl Alcohol	130	58	4.5		ppbv	25	9/7/2016
m,p-Xylene	2.0	0.92	0.068		ppbv	1	9/6/2016
Methyl tert-butyl ether	0.069	0.46	0.038	J	ppbv	1	9/6/2016
Methylene chloride	0.28	4.6	0.25	J	ppbv	1	9/6/2016
Naphthalene	0.53	0.46	0.13		ppbv	1	9/6/2016
o-Xylene	0.83	0.46	0.029		ppbv	1	9/6/2016
Propene	3.7	4.6	0.46	J	ppbv	1	9/6/2016
Styrene	0.18	0.46	0.049	J	ppbv	1	9/6/2016
Tetrachloroethene	1800	12	0.83		ppbv	25	9/7/2016
Tetrahydrofuran	2.8	1.2	0.1		ppbv	1	9/6/2016
Toluene	22	0.46	0.052		ppbv	1	9/6/2016
trans-1,2-Dichloroethene	ND	0.46	0.032		ppbv	1	9/6/2016
trans-1,3-Dichloropropene	ND	0.46	0.063		ppbv	1	9/6/2016
Trichloroethene	4.0	0.46	0.035		ppbv	1	9/6/2016
Trichlorofluoromethane	0.28	0.46	0.029	J	ppbv	1	9/6/2016
Vinyl acetate	ND	4.6	0.062		ppbv	1	9/6/2016
Vinyl chloride	ND	0.46	0.039		ppbv	1	9/6/2016
Xylenes, Total	2.9	1.4	0.096		ppbv	1	9/6/2016
Volatile Organic Compounds in A	ir by GC/MS	TO-15		Pre	p Date: <b>9/2/2</b>	016	Analyst: <b>NLM</b>
1,1,1-Trichloroethane	ND	0.0025	0.00013		mg/m³	1	9/6/2016
1,1,2,2-Tetrachloroethane	ND	0.0032	0.00022		mg/m³	1	9/6/2016
1,1,2-Trichloroethane	ND	0.0025	0.00024		mg/m³	1	9/6/2016
1,1-Dichloroethane	ND	0.0019	0.00009		mg/m³	1	9/6/2016
1,1-Dichloroethene	ND	0.0018	0.00012		mg/m³	1	9/6/2016
1,2,4-Trichlorobenzene	0.0019	0.0034	0.00076	J	mg/m³	1	9/6/2016
1,2,4-Trimethylbenzene	0.0051	0.0023	0.00021		mg/m³	1	9/6/2016
1,2-Dibromoethane	ND	0.0035	0.0004		mg/m³	1	9/6/2016
1,2-Dichlorobenzene	0.00042	0.0028	0.00023	J	mg/m³	1	9/6/2016
1,2-Dichloroethane	ND	0.0019	0.00021		mg/m³	1	9/6/2016
1,2-Dichloropropane	ND	0.0021	0.00015		mg/m³	1	9/6/2016
1,3,5-Trimethylbenzene	0.0014	0.0023	0.00016	J	mg/m³	1	9/6/2016
1,3-Butadiene	ND	0.0010	0.00013		mg/m³	1	9/6/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: September 09, 2016

September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

16081298-006 Lab ID:

**Date Printed:** 

**ANALYTICAL RESULTS** 

Client Sample ID: SV-1

**Collection Date:** 8/31/2016 12:28:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in Air by	GC/MS TO	D-15		Prep	Date: <b>9/2/2</b>	016	Analyst: <b>NLM</b>
1,3-Dichlorobenzene	0.0019	0.0028	0.00023	J	mg/m³	1	9/6/2016
1,4-Dichlorobenzene	ND	0.0028	0.00029		mg/m³	1	9/6/2016
1,4-Dioxane	ND	0.0041	0.00048		mg/m³	1	9/6/2016
2-Butanone	0.0067	0.0034	0.00031		mg/m³	1	9/6/2016
2-Hexanone	0.0031	0.0094	0.00051	J	mg/m³	1	9/6/2016
4-Ethyltoluene	0.0014	0.0023	0.00024	J	mg/m³	1	9/6/2016
4-Methyl-2-pentanone	0.012	0.0094	0.00028		mg/m³	1	9/6/2016
Acetone	0.082	0.011	0.00039	*	mg/m³	1	9/6/2016
Benzene	0.0029	0.0015	0.00011		mg/m³	1	9/6/2016
Benzyl chloride	ND	0.0060	0.0024		mg/m³	1	9/6/2016
Bromodichloromethane	ND	0.0031	0.00021		mg/m³	1	9/6/2016
Bromoform	ND	0.012	0.00025		mg/m³	1	9/6/2016
Bromomethane	0.00054	0.0045	0.00021	J	mg/m³	1	9/6/2016
Carbon disulfide	0.00050	0.0014	0.00036	J	mg/m³	1	9/6/2016
Carbon tetrachloride	ND	0.0029	0.00041		mg/m³	1	9/6/2016
Chlorobenzene	ND	0.0021	0.00013		mg/m³	1	9/6/2016
Chloroethane	ND	0.0012	0.0012		mg/m³	1	9/6/2016
Chloroform	0.00022	0.0022	0.00012	J	mg/m³	1	9/6/2016
Chloromethane	ND	0.0024	0.00024		mg/m³	1	9/6/2016
cis-1,2-Dichloroethene	0.0017	0.0018	0.00013	J	mg/m³	1	9/6/2016
cis-1,3-Dichloropropene	ND	0.0021	0.00025		mg/m³	1	9/6/2016
Cyclohexane	0.0025	0.0016	0.00034		mg/m³	1	9/6/2016
Dibromochloromethane	ND	0.0039	0.00032		mg/m³	1	9/6/2016
Dichlorodifluoromethane	0.0023	0.0022	0.000074		mg/m³	1	9/6/2016
Ethyl acetate	ND	0.0041	0.00033		mg/m³	1	9/6/2016
Ethylbenzene	0.0039	0.0020	0.00016		mg/m³	1	9/6/2016
Freon-113	ND	0.0035	0.00013		mg/m³	1	9/6/2016
Freon-114	ND	0.016	0.00046		mg/m³	1	9/6/2016
Heptane	0.0055	0.0019	0.00019		mg/m³	1	9/6/2016
Hexachlorobutadiene	0.00074	0.0049	0.00055	J	mg/m³	1	9/6/2016
Hexane	0.0064	0.0041	0.00011		mg/m³	1	9/6/2016
Isopropyl Alcohol	0.31	0.14	0.011		mg/m³	25	9/7/2016
m,p-Xylene	0.0088	0.0040	0.00029		mg/m³	1	9/6/2016
Methyl tert-butyl ether	0.00025	0.0017	0.00014	J	mg/m³	1	9/6/2016
Methylene chloride	0.00096	0.016	0.00086	J	mg/m³	1	9/6/2016
Naphthalene	0.0028	0.0024	0.00069		mg/m³	1	9/6/2016
o-Xylene	0.0036	0.0020	0.00013		mg/m³	1	9/6/2016
Propene	0.0063	0.0079	0.00079	J	mg/m³	1	9/6/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter


Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range



Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** September 09, 2016

**ANALYTICAL RESULTS** 

**Date Printed:** September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

**Lab ID:** 16081298-006

**Client Sample ID:** SV-1

**Collection Date:** 8/31/2016 12:28:00 PM

Matrix: AIR

Analyses	Resul	t RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in Ai	r by GC/MS	TO-15		Prep	Date: 9/2/2	016	Analyst: <b>NLM</b>
Styrene	0.00078	0.0020	0.00021	J	mg/m³	1	9/6/2016
Tetrachloroethene	12	0.078	0.0056		mg/m³	25	9/7/2016
Tetrahydrofuran	0.0084	0.0034	0.00031		mg/m³	1	9/6/2016
Toluene	0.081	0.0017	0.0002		mg/m³	1	9/6/2016
trans-1,2-Dichloroethene	ND	0.0018	0.00013		mg/m³	1	9/6/2016
trans-1,3-Dichloropropene	ND	0.0021	0.00028		mg/m³	1	9/6/2016
Trichloroethene	0.022	0.0025	0.00019		mg/m³	1	9/6/2016
Trichlorofluoromethane	0.0016	0.0026	0.00016	J	mg/m³	1	9/6/2016
Vinyl acetate	ND	0.016	0.00022		mg/m³	1	9/6/2016
Vinyl chloride	ND	0.0012	0.000099		mg/m³	1	9/6/2016
Xylenes, Total	0.012	0.0060	0.00042		mg/m³	1	9/6/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** September 09, 2016

September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

**Lab ID:** 16081298-007

**Date Printed:** 

**ANALYTICAL RESULTS** 

**Client Sample ID:** SV-2

**Collection Date:** 8/31/2016 12:32:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
/olatile Organic Compounds in	Air by GC/MS TO	-15		Prep	Date: <b>9/2/2</b>	016	Analyst: <b>NLM</b>
1,1,1-Trichloroethane	ND	0.37	0.019	-	ppbv	1	9/6/2016
1,1,2,2-Tetrachloroethane	ND	0.37	0.026		ppbv	1	9/6/2016
1,1,2-Trichloroethane	ND	0.37	0.036		ppbv	1	9/6/2016
1,1-Dichloroethane	ND	0.37	0.018		ppbv	1	9/6/2016
1,1-Dichloroethene	ND	0.37	0.023		ppbv	1	9/6/2016
1,2,4-Trichlorobenzene	0.13	0.37	0.082	J	ppbv	1	9/6/2016
1,2,4-Trimethylbenzene	0.80	0.37	0.034		ppbv	1	9/6/2016
1,2-Dibromoethane	ND	0.37	0.042		ppbv	1	9/6/2016
1,2-Dichlorobenzene	ND	0.37	0.031		ppbv	1	9/6/2016
1,2-Dichloroethane	ND	0.37	0.043		ppbv	1	9/6/2016
1,2-Dichloropropane	ND	0.37	0.025		ppbv	1	9/6/2016
1,3,5-Trimethylbenzene	0.19	0.37	0.026	J	ppbv	1	9/6/2016
1,3-Butadiene	ND	0.37	0.048		ppbv	1	9/6/2016
1,3-Dichlorobenzene	0.19	0.37	0.031	J	ppbv	1	9/6/2016
1,4-Dichlorobenzene	ND	0.37	0.039		ppbv	1	9/6/2016
1,4-Dioxane	0.74	0.93	0.11	J	ppbv	1	9/6/2016
2-Butanone	2.6	0.93	0.085		ppbv	1	9/6/2016
2-Hexanone	0.70	1.9	0.1	J	ppbv	1	9/6/2016
4-Ethyltoluene	0.19	0.37	0.039	J	ppbv	1	9/6/2016
4-Methyl-2-pentanone	1.5	1.9	0.056	J	ppbv	1	9/6/2016
Acetone	61	3.7	0.13	*	ppbv	1	9/6/2016
Benzene	0.45	0.37	0.027		ppbv	1	9/6/2016
Benzyl chloride	ND	0.93	0.37		ppbv	1	9/6/2016
Bromodichloromethane	ND	0.37	0.025		ppbv	1	9/6/2016
Bromoform	ND	0.93	0.02		ppbv	1	9/6/2016
Bromomethane	0.13	0.93	0.043	J	ppbv	1	9/6/2016
Carbon disulfide	ND	0.37	0.093		ppbv	1	9/6/2016
Carbon tetrachloride	ND	0.37	0.052		ppbv	1	9/6/2016
Chlorobenzene	ND	0.37	0.023		ppbv	1	9/6/2016
Chloroethane	ND	0.37	0.37		ppbv	1	9/6/2016
Chloroform	0.074	0.37	0.02	J	ppbv	1	9/6/2016
Chloromethane	ND	0.93	0.092		ppbv	1	9/6/2016
cis-1,2-Dichloroethene	4.5	0.37	0.027		ppbv	1	9/6/2016
cis-1,3-Dichloropropene	ND	0.37	0.044		ppbv	1	9/6/2016
Cyclohexane	0.37	0.37	0.079		ppbv	1	9/6/2016
Dibromochloromethane	ND	0.37	0.03		ppbv	1	9/6/2016
Dichlorodifluoromethane	0.46	0.37	0.012		ppbv	1	9/6/2016
Ethyl acetate	ND	0.93	0.074		ppbv	1	9/6/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** September 09, 2016

**ANALYTICAL RESULTS** 

**Date Printed:** September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

**Lab ID:** 16081298-007

**Client Sample ID:** SV-2

**Collection Date:** 8/31/2016 12:32:00 PM

Matrix: AIR

Analyses	Resul	t RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in	Air by GC/MS	TO-15		Prep	Date: 9/2/2	016	Analyst: <b>NLM</b>
Ethylbenzene	0.65	0.37	0.029		ppbv	1	9/6/2016
Freon-113	0.074	0.37	0.014	J	ppbv	1	9/6/2016
Freon-114	ND	1.9	0.053		ppbv	1	9/6/2016
Heptane	0.65	0.37	0.037		ppbv	1	9/6/2016
Hexachlorobutadiene	ND	0.37	0.042		ppbv	1	9/6/2016
Hexane	0.76	0.93	0.026	J	ppbv	1	9/6/2016
Isopropyl Alcohol	43	1.9	0.15		ppbv	1	9/6/2016
m,p-Xylene	1.4	0.74	0.055		ppbv	1	9/6/2016
Methyl tert-butyl ether	0.093	0.37	0.03	J	ppbv	1	9/6/2016
Methylene chloride	ND	3.7	0.2		ppbv	1	9/6/2016
Naphthalene	0.33	0.37	0.11	J	ppbv	1	9/6/2016
o-Xylene	0.56	0.37	0.024		ppbv	1	9/6/2016
Propene	2.1	3.7	0.37	J	ppbv	1	9/6/2016
Styrene	0.074	0.37	0.039	J	ppbv	1	9/6/2016
Tetrachloroethene	6500	190	13		ppbv	500	9/7/2016
Tetrahydrofuran	1.4	0.93	0.084		ppbv	1	9/6/2016
Toluene	12	0.37	0.042		ppbv	1	9/6/2016
trans-1,2-Dichloroethene	0.037	0.37	0.025	J	ppbv	1	9/6/2016
trans-1,3-Dichloropropene	ND	0.37	0.05		ppbv	1	9/6/2016
Trichloroethene	7.6	0.37	0.028		ppbv	1	9/6/2016
Trichlorofluoromethane	0.28	0.37	0.023	J	ppbv	1	9/6/2016
Vinyl acetate	ND	3.7	0.05		ppbv	1	9/6/2016
Vinyl chloride	ND	0.37	0.031		ppbv	1	9/6/2016
Xylenes, Total	1.9	1.1	0.078		ppbv	1	9/6/2016
olatile Organic Compounds in	Air by GC/MS	TO-15		Prep	Date: 9/2/2	016	Analyst: <b>NLM</b>
1,1,1-Trichloroethane	ND	0.0020	0.00011		mg/m³	1	9/6/2016
1,1,2,2-Tetrachloroethane	ND	0.0025	0.00018		mg/m³	1	9/6/2016
1,1,2-Trichloroethane	ND	0.0020	0.0002		mg/m³	1	9/6/2016
1,1-Dichloroethane	ND	0.0015	0.000073		mg/m³	1	9/6/2016
1,1-Dichloroethene	ND	0.0015	0.000093		mg/m³	1	9/6/2016
1,2,4-Trichlorobenzene	0.00096	0.0028	0.00061	J	mg/m³	1	9/6/2016
1,2,4-Trimethylbenzene	0.0039	0.0018	0.00017		mg/m³	1	9/6/2016
1,2-Dibromoethane	ND	0.0029	0.00032		mg/m³	1	9/6/2016
1,2-Dichlorobenzene	ND	0.0022	0.00019		mg/m³	1	9/6/2016
1,2-Dichloroethane	ND	0.0015	0.00017		mg/m³	1	9/6/2016
1,2-Dichloropropane	ND	0.0017	0.00012		mg/m³	1	9/6/2016
1,3,5-Trimethylbenzene	0.00091	0.0018	0.00013	J	mg/m³	1	9/6/2016
1,3-Butadiene	ND	0.00082	0.00011		mg/m³	1	9/6/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** September 09, 2016

**Date Printed:** September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

**Lab ID:** 16081298-007

**ANALYTICAL RESULTS** 

Client Sample ID: SV-2

**Collection Date:** 8/31/2016 12:32:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds i	in Air by GC/MS T	O-15		Prep	Date: <b>9/2/2</b>	016	Analyst: <b>NLM</b>
1,3-Dichlorobenzene	0.0011	0.0022	0.00019	J	mg/m³	1	9/6/2016
1,4-Dichlorobenzene	ND	0.0022	0.00024		mg/m³	1	9/6/2016
1,4-Dioxane	0.0027	0.0033	0.00039	J	mg/m³	1	9/6/2016
2-Butanone	0.0077	0.0027	0.00025		mg/m³	1	9/6/2016
2-Hexanone	0.0029	0.0076	0.00041	J	mg/m³	1	9/6/2016
4-Ethyltoluene	0.00091	0.0018	0.00019	J	mg/m³	1	9/6/2016
4-Methyl-2-pentanone	0.0061	0.0076	0.00023	J	mg/m³	1	9/6/2016
Acetone	0.14	0.0088	0.00031	*	mg/m³	1	9/6/2016
Benzene	0.0014	0.0012	0.000085		mg/m³	1	9/6/2016
Benzyl chloride	ND	0.0048	0.0019		mg/m³	1	9/6/2016
Bromodichloromethane	ND	0.0025	0.00017		mg/m³	1	9/6/2016
Bromoform	ND	0.0096	0.0002		mg/m³	1	9/6/2016
Bromomethane	0.00050	0.0036	0.00017	J	mg/m³	1	9/6/2016
Carbon disulfide	ND	0.0012	0.00029		mg/m³	1	9/6/2016
Carbon tetrachloride	ND	0.0023	0.00033		mg/m³	1	9/6/2016
Chlorobenzene	ND	0.0017	0.00011		mg/m³	1	9/6/2016
Chloroethane	ND	0.00098	0.00098		mg/m³	1	9/6/2016
Chloroform	0.00036	0.0018	0.000099	J	mg/m³	1	9/6/2016
Chloromethane	ND	0.0019	0.00019		mg/m³	1	9/6/2016
cis-1,2-Dichloroethene	0.018	0.0015	0.00011		mg/m³	1	9/6/2016
cis-1,3-Dichloropropene	ND	0.0017	0.0002		mg/m³	1	9/6/2016
Cyclohexane	0.0013	0.0012	0.00027		mg/m³	1	9/6/2016
Dibromochloromethane	ND	0.0032	0.00025		mg/m³	1	9/6/2016
Dichlorodifluoromethane	0.0023	0.0018	0.00006		mg/m³	1	9/6/2016
Ethyl acetate	ND	0.0033	0.00027		mg/m³	1	9/6/2016
Ethylbenzene	0.0028	0.0016	0.00013		mg/m³	1	9/6/2016
Freon-113	0.00057	0.0028	0.00011	J	mg/m³	1	9/6/2016
Freon-114	ND	0.013	0.00037		mg/m³	1	9/6/2016
Heptane	0.0027	0.0015	0.00015		mg/m³	1	9/6/2016
Hexachlorobutadiene	ND	0.0040	0.00045		mg/m³	1	9/6/2016
Hexane	0.0027	0.0033	0.000092	J	mg/m³	1	9/6/2016
Isopropyl Alcohol	0.11	0.0046	0.00036		mg/m³	1	9/6/2016
m,p-Xylene	0.0060	0.0032	0.00024		mg/m³	1	9/6/2016
Methyl tert-butyl ether	0.00033	0.0013	0.00011	J	mg/m³	1	9/6/2016
Methylene chloride	ND	0.013	0.00069		mg/m³	1	9/6/2016
Naphthalene	0.0018	0.0019	0.00056	J	mg/m³	1	9/6/2016
o-Xylene	0.0024	0.0016	0.0001		mg/m³	1	9/6/2016
Propene	0.0036	0.0064	0.00064	J	mg/m³	1	9/6/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter


Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range



Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** September 09, 2016

September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

**Lab ID:** 16081298-007

**Date Printed:** 

**ANALYTICAL RESULTS** 

**Client Sample ID:** SV-2

**Collection Date:** 8/31/2016 12:32:00 PM

Matrix: AIR

Analyses	Resul	t RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in A	Air by GC/MS	TO-15		Prep	Date: 9/2/2	2016	Analyst: <b>NLM</b>
Styrene	0.00032	0.0016	0.00017	J	mg/m³	1	9/6/2016
Tetrachloroethene	44	1.3	0.091		mg/m³	500	9/7/2016
Tetrahydrofuran	0.0041	0.0027	0.00025		mg/m³	1	9/6/2016
Toluene	0.046	0.0014	0.00016		mg/m³	1	9/6/2016
trans-1,2-Dichloroethene	0.00015	0.0015	0.0001	J	mg/m³	1	9/6/2016
trans-1,3-Dichloropropene	ND	0.0017	0.00023		mg/m³	1	9/6/2016
Trichloroethene	0.041	0.0020	0.00015		mg/m³	1	9/6/2016
Trichlorofluoromethane	0.0016	0.0021	0.00013	J	mg/m³	1	9/6/2016
Vinyl acetate	ND	0.013	0.00018		mg/m³	1	9/6/2016
Vinyl chloride	ND	0.00095	0.00008		mg/m³	1	9/6/2016
Xylenes, Total	0.0085	0.0048	0.00034		mg/m³	1	9/6/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

 $RL/\!MDL$  - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: September 09, 2016

**ANALYTICAL RESULTS** 

**Date Printed:** September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

Lab ID: 16081298-008 **Client Sample ID:** SV-3

**Collection Date:** 8/31/2016 12:34:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in	Air by GC/MS TO	-15		Prep	Date: <b>9/2/2</b>	016	Analyst: <b>NLM</b>
1,1,1-Trichloroethane	ND	0.51	0.027		ppbv	1	9/6/2016
1,1,2,2-Tetrachloroethane	ND	0.51	0.035		ppbv	1	9/6/2016
1,1,2-Trichloroethane	ND	0.51	0.049		ppbv	1	9/6/2016
1,1-Dichloroethane	ND	0.51	0.025		ppbv	1	9/6/2016
1,1-Dichloroethene	ND	0.51	0.032		ppbv	1	9/6/2016
1,2,4-Trichlorobenzene	0.15	0.51	0.11	J	ppbv	1	9/6/2016
1,2,4-Trimethylbenzene	1.5	0.51	0.046		ppbv	1	9/6/2016
1,2-Dibromoethane	ND	0.51	0.057		ppbv	1	9/6/2016
1,2-Dichlorobenzene	ND	0.51	0.042		ppbv	1	9/6/2016
1,2-Dichloroethane	ND	0.51	0.059		ppbv	1	9/6/2016
1,2-Dichloropropane	ND	0.51	0.035		ppbv	1	9/6/2016
1,3,5-Trimethylbenzene	0.41	0.51	0.035	J	ppbv	1	9/6/2016
1,3-Butadiene	ND	0.51	0.065		ppbv	1	9/6/2016
1,3-Dichlorobenzene	0.82	0.51	0.043		ppbv	1	9/6/2016
1,4-Dichlorobenzene	ND	0.51	0.054		ppbv	1	9/6/2016
1,4-Dioxane	0.66	1.3	0.15	J	ppbv	1	9/6/2016
2-Butanone	4.1	1.3	0.12		ppbv	1	9/6/2016
2-Hexanone	1.2	2.6	0.14	J	ppbv	1	9/6/2016
4-Ethyltoluene	0.33	0.51	0.053	J	ppbv	1	9/6/2016
4-Methyl-2-pentanone	2.3	2.6	0.077	J	ppbv	1	9/6/2016
Acetone	44	5.1	0.18	*	ppbv	1	9/6/2016
Benzene	1.1	0.51	0.037		ppbv	1	9/6/2016
Benzyl chloride	ND	1.3	0.51		ppbv	1	9/6/2016
Bromodichloromethane	ND	0.51	0.035		ppbv	1	9/6/2016
Bromoform	ND	1.3	0.027		ppbv	1	9/6/2016
Bromomethane	0.20	1.3	0.06	J	ppbv	1	9/6/2016
Carbon disulfide	0.15	0.51	0.13	J	ppbv	1	9/6/2016
Carbon tetrachloride	ND	0.51	0.071		ppbv	1	9/6/2016
Chlorobenzene	ND	0.51	0.032		ppbv	1	9/6/2016
Chloroethane	ND	0.51	0.51		ppbv	1	9/6/2016
Chloroform	0.13	0.51	0.028	J	ppbv	1	9/6/2016
Chloromethane	ND	1.3	0.13		ppbv	1	9/6/2016
cis-1,2-Dichloroethene	8.1	0.51	0.038		ppbv	1	9/6/2016
cis-1,3-Dichloropropene	ND	0.51	0.06		ppbv	1	9/6/2016
Cyclohexane	1.3	0.51	0.11		ppbv	1	9/6/2016
Dibromochloromethane	ND	0.51	0.041		ppbv	1	9/6/2016
Dichlorodifluoromethane	0.43	0.51	0.017	J	ppbv	1	9/6/2016
Ethyl acetate	ND	1.3	0.1		ppbv	1	9/6/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** September 09, 2016

September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

**Lab ID:** 16081298-008

**Date Printed:** 

**ANALYTICAL RESULTS** 

**Client Sample ID:** SV-3

**Collection Date:** 8/31/2016 12:34:00 PM

Matrix: AIR

Analyses	Resul	t RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in	Air by GC/MS	TO-15		Prep	Date: 9/2/2	2016	Analyst: <b>NLM</b>
Ethylbenzene	1.4	0.51	0.04		ppbv	1	9/6/2016
Freon-113	0.077	0.51	0.019	J	ppbv	1	9/6/2016
Freon-114	ND	2.6	0.073		ppbv	1	9/6/2016
Heptane	3.1	0.51	0.05		ppbv	1	9/6/2016
Hexachlorobutadiene	ND	0.51	0.058		ppbv	1	9/6/2016
Hexane	3.2	1.3	0.036		ppbv	1	9/6/2016
Isopropyl Alcohol	26	2.6	0.2		ppbv	1	9/6/2016
m,p-Xylene	2.7	1.0	0.075		ppbv	1	9/6/2016
Methyl tert-butyl ether	0.077	0.51	0.042	J	ppbv	1	9/6/2016
Methylene chloride	ND	5.1	0.27		ppbv	1	9/6/2016
Naphthalene	0.79	0.51	0.15		ppbv	1	9/6/2016
o-Xylene	1.1	0.51	0.033		ppbv	1	9/6/2016
Propene	3.2	5.1	0.51	J	ppbv	1	9/6/2016
Styrene	0.13	0.51	0.054	J	ppbv	1	9/6/2016
Tetrachloroethene	280	260	18		ppbv	500	9/7/2016
Tetrahydrofuran	1.9	1.3	0.12		ppbv	1	9/6/2016
Toluene	13	0.51	0.058		ppbv	1	9/6/2016
trans-1,2-Dichloroethene	ND	0.51	0.035		ppbv	1	9/6/2016
trans-1,3-Dichloropropene	ND	0.51	0.069		ppbv	1	9/6/2016
Trichloroethene	4.7	0.51	0.039		ppbv	1	9/6/2016
Trichlorofluoromethane	0.23	0.51	0.032	J	ppbv	1	9/6/2016
Vinyl acetate	ND	5.1	0.069		ppbv	1	9/6/2016
Vinyl chloride	ND	0.51	0.043		ppbv	1	9/6/2016
Xylenes, Total	3.8	1.5	0.11		ppbv	1	9/6/2016
/olatile Organic Compounds in	Air by GC/MS	TO-15		Prep	Date: 9/2/2	2016	Analyst: <b>NLM</b>
1,1,1-Trichloroethane	ND	0.0028	0.00015		mg/m³	1	9/6/2016
1,1,2,2-Tetrachloroethane	ND	0.0035	0.00024		mg/m³	1	9/6/2016
1,1,2-Trichloroethane	ND	0.0028	0.00027		mg/m³	1	9/6/2016
1,1-Dichloroethane	ND	0.0021	0.0001		mg/m³	1	9/6/2016
1,1-Dichloroethene	ND	0.0020	0.00013		mg/m³	1	9/6/2016
1,2,4-Trichlorobenzene	0.0011	0.0038	0.00084	J	mg/m³	1	9/6/2016
1,2,4-Trimethylbenzene	0.0075	0.0025	0.00023		mg/m³	1	9/6/2016
1,2-Dibromoethane	ND	0.0039	0.00044		mg/m³	1	9/6/2016
1,2-Dichlorobenzene	ND	0.0031	0.00026		mg/m³	1	9/6/2016
1,2-Dichloroethane	ND	0.0021	0.00024		mg/m³	1	9/6/2016
1,2-Dichloropropane	ND	0.0024	0.00016		mg/m³	1	9/6/2016
1,3,5-Trimethylbenzene	0.0020	0.0025	0.00017	J	mg/m³	1	9/6/2016
1,3-Butadiene	ND	0.0011	0.00014		mg/m³	1	9/6/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

 $RL/\!MDL$  - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: September 09, 2016

**Date Printed:** September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

16081298-008 Lab ID:

**ANALYTICAL RESULTS** 

**Client Sample ID:** SV-3

**Collection Date:** 8/31/2016 12:34:00 PM

Matrix: AIR

Analyses	Resul	t RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds	in Air by GC/MS	TO-15		Prep	Date: <b>9/2/</b> 2	2016	Analyst: <b>NLM</b>
1,3-Dichlorobenzene	0.0049	0.0031	0.00026		mg/m³	1	9/6/2016
1,4-Dichlorobenzene	ND	0.0031	0.00032		mg/m³	1	9/6/2016
1,4-Dioxane	0.0024	0.0046	0.00054	J	mg/m³	1	9/6/2016
2-Butanone	0.012	0.0038	0.00034		mg/m³	1	9/6/2016
2-Hexanone	0.0049	0.010	0.00057	J	mg/m³	1	9/6/2016
4-Ethyltoluene	0.0016	0.0025	0.00026	J	mg/m³	1	9/6/2016
4-Methyl-2-pentanone	0.0094	0.010	0.00031	J	mg/m³	1	9/6/2016
Acetone	0.10	0.012	0.00043	*	mg/m³	1	9/6/2016
Benzene	0.0034	0.0016	0.00012		mg/m³	1	9/6/2016
Benzyl chloride	ND	0.0066	0.0026		mg/m³	1	9/6/2016
Bromodichloromethane	ND	0.0034	0.00023		mg/m³	1	9/6/2016
Bromoform	ND	0.013	0.00028		mg/m³	1	9/6/2016
Bromomethane	0.00079	0.0050	0.00023	J	mg/m³	1	9/6/2016
Carbon disulfide	0.00048	0.0016	0.0004	J	mg/m³	1	9/6/2016
Carbon tetrachloride	ND	0.0032	0.00045		mg/m³	1	9/6/2016
Chlorobenzene	ND	0.0024	0.00015		mg/m³	1	9/6/2016
Chloroethane	ND	0.0013	0.0013		mg/m³	1	9/6/2016
Chloroform	0.00062	0.0025	0.00014	J	mg/m³	1	9/6/2016
Chloromethane	ND	0.0026	0.00026		mg/m³	1	9/6/2016
cis-1,2-Dichloroethene	0.032	0.0020	0.00015		mg/m³	1	9/6/2016
cis-1,3-Dichloropropene	ND	0.0023	0.00027		mg/m³	1	9/6/2016
Cyclohexane	0.0046	0.0018	0.00037		mg/m³	1	9/6/2016
Dibromochloromethane	ND	0.0043	0.00035		mg/m³	1	9/6/2016
Dichlorodifluoromethane	0.0021	0.0025	0.000082	J	mg/m³	1	9/6/2016
Ethyl acetate	ND	0.0046	0.00037		mg/m³	1	9/6/2016
Ethylbenzene	0.0061	0.0022	0.00017		mg/m³	1	9/6/2016
Freon-113	0.00059	0.0039	0.00015	J	mg/m³	1	9/6/2016
Freon-114	ND	0.018	0.00051		mg/m³	1	9/6/2016
Heptane	0.013	0.0021	0.00021		mg/m³	1	9/6/2016
Hexachlorobutadiene	ND	0.0054	0.00061		mg/m³	1	9/6/2016
Hexane	0.011	0.0045	0.00013		mg/m³	1	9/6/2016
Isopropyl Alcohol	0.065	0.0063	0.00049		mg/m³	1	9/6/2016
m,p-Xylene	0.012	0.0044	0.00033		mg/m³	1	9/6/2016
Methyl tert-butyl ether	0.00028	0.0018	0.00015	J	mg/m³	1	9/6/2016
Methylene chloride	ND	0.018	0.00095		mg/m³	1	9/6/2016
Naphthalene	0.0041	0.0027	0.00076		mg/m³	1	9/6/2016
o-Xylene	0.0048	0.0022	0.00014		mg/m³	1	9/6/2016
Propene	0.0055	0.0088	0.00088	J	mg/m³	1	9/6/2016
•		<del>-</del>	<del>-</del>		J		

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter


Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range



Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** September 09, 2016

September 09, 2016

**CLIENT:** Apex Companies, LLC

Work Order: 16081298 Revision 0

**Project:** PECO-216-78, Bright Cleaners-Franklin Centre, 7249

**Lab ID:** 16081298-008

**Date Printed:** 

**ANALYTICAL RESULTS** 

**Client Sample ID:** SV-3

**Collection Date:** 8/31/2016 12:34:00 PM

Matrix: AIR

Analyses	Resul	t RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in A	ir by GC/MS	TO-15		Prep	Date: <b>9/2/2</b>	2016	Analyst: <b>NLM</b>
Styrene	0.00054	0.0022	0.00023	J	mg/m³	1	9/6/2016
Tetrachloroethene	1.9	1.7	0.13		mg/m³	500	9/7/2016
Tetrahydrofuran	0.0056	0.0038	0.00034		mg/m³	1	9/6/2016
Toluene	0.047	0.0019	0.00022		mg/m³	1	9/6/2016
trans-1,2-Dichloroethene	ND	0.0020	0.00014		mg/m³	1	9/6/2016
trans-1,3-Dichloropropene	ND	0.0023	0.00032		mg/m³	1	9/6/2016
Trichloroethene	0.026	0.0027	0.00021		mg/m³	1	9/6/2016
Trichlorofluoromethane	0.0013	0.0029	0.00018	J	mg/m³	1	9/6/2016
Vinyl acetate	ND	0.018	0.00024		mg/m³	1	9/6/2016
Vinyl chloride	ND	0.0013	0.00011		mg/m³	1	9/6/2016
Xylenes, Total	0.017	0.0066	0.00046		mg/m³	1	9/6/2016

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 W. Harrison Suite 200, Chicago, Illinois 60612 Phone: (312) 733-0551 Fax: (312) 733-2386 e-mail address: STATinfo@STATAnalysis.com

am/pm Lab No.: Received on Ice: Yes X No Temperature: 4,7 °C 007 663 8 8 100 Furn Around Time (Days) Page: Additional Information: 2001/20319 89209 833 Results Needed: 2 3 Quote No.: P.O. No.: Nº: 903397 **Preservation Code:** A = None B = HNO<sub>3</sub> C = NaOH $D = H_2SO_4$  E = HCl F = 5035/EnCore G = OtherCHAIN OF CUSTODY RECORD Comments: OI - 5701 0928 16:45 Snewlla Quoex 65.6m becker Basex cos son Containers No. of J 847-756-8589 Client Tracking No .: 4 W Grab Date/Time: 6 Date/Time: 🕺 centre Date/Time: Date/Time: Date/Time: Date/Time: Comp. 3 Ŕ Matrix Franklin 12,23 10:30 22:21 15,21 11:00 e-mail: 8 Phone: Time Taken 二 元 Fax: 71-12-8 Date Taken PECO-2016-78 Bright Cleaners Apex Companies 72 49 S. 76th Client Sample Number/Description: Recta 1/WWW Becker クニしゃく j 700 Steve Relinquished by: (Signature) Relinquished by: (Signature) Relinquished by: (Signature 300 Received by: (Signature) J2-2 アンシー Received by: (Signature) Received by: (Signature) 1-1-0 ハシナ 515 Project Location: 2-15 517-1 Project Number: Project Name: Sampler(s): Report To: QC Level: Company:

หาด ใครบุรีกา

. : 9**0**0407 (

#### Sample Receipt Checklist

Client Name APEX		Date and Tim	e Received:	8/31/2016 4:45:00 PM
Work Order Number 16081298		Received by:	JDR	
Checklist completed by:  Synature  Synature  Ba	31 16 te	Reviewed by:	JOC	7/1/16
			initials	, pare
Matrix: Carrier name	e <u>Client Delivered</u>			
Shipping container/cooler in good condition?	Yes 🗸	No 🗌	Not Present	
Custody seals intact on shippping container/cooler?	Yes	No 🗌	Not Present 🗹	
Custody seals intact on sample bottles?	Yes	No 🗌	Not Present 🗹	
Chain of custody present?	Yes 🗹	No 🗌		
Chain of custody signed when relinquished and received?	Yes 🗸	No 🗌		
Chain of custody agrees with sample labels/containers?	Yes 🗸	No 🗌		
Samples in proper container/bottle?	Yes 🗹	No 🗌		
Sample containers intact?	Yes 🗸	No 🗌		
Sufficient sample volume for indicated test?	Yes 🗹	No 🗌		
All samples received within holding time?	Yes 🗹	No 🗌		,
Container or Temp Blank temperature in compliance?	Yes 🗸	No 🗌	Temperature	e 4.7 °C <b>∦</b>
Water - VOA vials have zero headspace? No VOA vials sul	bmitted	Yes 🗹	No 🗌	
Water - Samples pH checked?	Yes	No 💹	Checked by:	**************************************
Water - Samples properly preserved?	Yes 💹	No 💹	pH Adjusted?	
Any No response must be detailed in the comments section below.				
- Constrained	AND STREET AND STREET STREET STREET	more sound where comme more	the parameter and their scalables and delice at the least	
comments: To-cans recieved at an	nbent H	empera	itive.	
$S_{ij}(\hat{r}, r) = S_{ij}(\hat{r}, r)$ . The second of $S_{ij}(\hat{r}, r) = S_{ij}(\hat{r}, r)$ . The second of $S_{ij}(\hat{r}, r)$ is a second of $S_{ij}(\hat{r}, r)$ .				
ntik satio kortoos				
ugnsaber or Tomp, cenade .				
Client / Person ats have contacted:  Sample of the		Conta	cted by:	
Response:				
And the second of the second o				

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766
Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com
Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

August 25, 2017

Apex Companies, LLC 1701 East Woodfield Rd, Suite 333 Schaumburg, IL 60173 Telephone: (847) 956-8589

Fax: (847) 956-8619

Analytical Report for STAT Work Order: 17080520 Revision 0

RE: PELO-2017-68, Franklin Centre, 7201 S. 76th St., Franklin, WI

Dear Joseph Becker:

STAT Analysis received 6 samples for the referenced project on 8/15/2017 1:30:00 PM. The analytical results are presented in the following report.

All analyses were performed in accordance with the requirements specified in WI DNR Chapter NR 149 (Certification Number 399099910). Analyses were performed in accordance with methods as referenced on the analytical report.

All analyses were performed within established holding time criteria, and all Quality Control criteria met EPA or laboratory specifications except when noted in the Case Narrative or Analytical Report. A listing of accredited methods/parameters can also be provided.

For sample results requiring adjustment for dilutions, the detection and reporting limits are adjusted for the corresponding dilution factor. Analytical results expressed on a dry weight basis have units of mg/Kg-dry or  $\mu$ g/Kg-dry on the analytical report. Corresponding reporting limits are adjusted for dry weight.

Thank you for the opportunity to serve you and I look forward to working with you in the future. If you have any questions regarding the enclosed materials, please contact me at (312) 733-0551.

Sincerely,

Craig Chawla

Project Manager

The information contained in this report and any attachments is confidential information intended only for the use of the individual or entities named above. The results of this report relate only to the samples tested. If you have received this report in error, please notify us immediately by phone. The report shall not be reproduced, except in its entirety, unless written approval has been obtained from the laboratory. This analytical report shall become property of the Customer upon payment in full. Otherwise, STAT will be under no obligation to support, defend or discuss the analytical report.



**Date:** August 25, 2017

Client: Apex Companies, LLC

Project: PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fra Work Order Sample Summary

Work Order: 17080520 Revision 0

Lab Sample ID	Client Sample ID	Tag Number	<b>Collection Date</b>	<b>Date Received</b>
17080520-001A	MW-1 @ 4'		8/11/2017 8:00:00 AM	8/15/2017
17080520-001B	MW-1 @ 4'		8/11/2017 8:00:00 AM	8/15/2017
17080520-002A	MW-2 @ 6'		8/11/2017 10:40:00 AM	8/15/2017
17080520-002B	MW-2 @ 6'		8/11/2017 10:40:00 AM	8/15/2017
17080520-003A	B-1 @ 2'		8/11/2017 9:10:00 AM	8/15/2017
17080520-003B	B-1 @ 2'		8/11/2017 9:10:00 AM	8/15/2017
17080520-004A	SV-4		8/14/2017 12:24:00 PM	8/15/2017
17080520-005A	SV-5		8/14/2017 12:30:00 PM	8/15/2017
17080520-006A	SV-6		8/14/2017 12:35:00 PM	8/15/2017

**Date:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Project: PELO-2017-68, Franklin Centre, 7201 S. 76th St., Franklin, CASE NARRATIVE

Work Order: 17080520 Revision 0

STAT Analysis Corp is accredited for TO-15 analysis by Oregon Environmental Accreditation Progam (ORELAP, Accreditation Number IL300001).

TO-15 results that are reported in mg/m³ are calculated based on a temperature of 25°C, atmospheric pressure of 760 mm Hg, and the molecular weight of the analyte.

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: August 25, 2017

**ANALYTICAL RESULTS** 

**Collection Date:** 8/11/2017 8:00:00 AM

Client Sample ID: MW-1 @ 4'

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

Matrix: SOIL Lab ID: 17080520-001

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds by GC/MS	SV	V5035/8260	В	Prep	Date: 8/16/2	017	Analyst: RRS
Acetone	0.075	0.068	0.0021		mg/Kg-dry	1	8/22/2017
Benzene	0.0025	0.0045	0.00018	J	mg/Kg-dry	1	8/22/2017
Bromodichloromethane	ND	0.0045	0.00036		mg/Kg-dry	1	8/22/2017
Bromoform	ND	0.0045	0.00036		mg/Kg-dry	1	8/22/2017
Bromomethane	ND	0.0090	0.00045		mg/Kg-dry	1	8/22/2017
2-Butanone	0.011	0.068	0.0014	J	mg/Kg-dry	1	8/22/2017
Carbon disulfide	ND	0.045	0.00018		mg/Kg-dry	1	8/22/2017
Carbon tetrachloride	ND	0.0045	0.00027		mg/Kg-dry	1	8/22/2017
Chlorobenzene	ND	0.0045	0.00018		mg/Kg-dry	1	8/22/2017
Chloroethane	ND	0.0090	0.00036		mg/Kg-dry	1	8/22/2017
Chloroform	ND	0.0045	0.00018		mg/Kg-dry	1	8/22/2017
Chloromethane	ND	0.0090	0.00027		mg/Kg-dry	1	8/22/2017
Dibromochloromethane	ND	0.0045	0.00036		mg/Kg-dry	1	8/22/2017
1,1-Dichloroethane	ND	0.0045	0.00027		mg/Kg-dry	1	8/22/2017
1,2-Dichloroethane	ND	0.0045	0.00054		mg/Kg-dry	1	8/22/2017
1,1-Dichloroethene	ND	0.0045	0.00027		mg/Kg-dry	1	8/22/2017
cis-1,2-Dichloroethene	ND	0.0045	0.00027		mg/Kg-dry	1	8/22/2017
trans-1,2-Dichloroethene	ND	0.0045	0.00027		mg/Kg-dry	1	8/22/2017
1,2-Dichloropropane	ND	0.0045	0.00036		mg/Kg-dry	1	8/22/2017
cis-1,3-Dichloropropene	ND	0.0018	0.00018		mg/Kg-dry	1	8/22/2017
trans-1,3-Dichloropropene	ND	0.0018	0.00027		mg/Kg-dry	1	8/22/2017
Ethylbenzene	0.0013	0.0045	0.00009	J	mg/Kg-dry	1	8/22/2017
2-Hexanone	ND	0.018	0.00072		mg/Kg-dry	1	8/22/2017
4-Methyl-2-pentanone	ND	0.018	0.00027		mg/Kg-dry	1	8/22/2017
Methylene chloride	0.0015	0.0090	0.00072	J	mg/Kg-dry	1	8/22/2017
Methyl tert-butyl ether	ND	0.0045	0.00018		mg/Kg-dry	1	8/22/2017
Styrene	ND	0.0045	0.00018		mg/Kg-dry	1	8/22/2017
1,1,2,2-Tetrachloroethane	ND	0.0045	0.00018		mg/Kg-dry	1	8/22/2017
Tetrachloroethene	ND	0.0045	0.00027		mg/Kg-dry	1	8/22/2017
Toluene	0.0044	0.0045	0.00018	J	mg/Kg-dry	1	8/22/2017
1,1,1-Trichloroethane	ND	0.0045	0.00018		mg/Kg-dry	1	8/22/2017
1,1,2-Trichloroethane	ND	0.0045	0.00045		mg/Kg-dry	1	8/22/2017
Trichloroethene	ND	0.0045	0.00018		mg/Kg-dry	1	8/22/2017
Vinyl chloride	ND	0.0045	0.00036		mg/Kg-dry	1	8/22/2017
Xylenes, Total	0.0025	0.014	0.00036	J	mg/Kg-dry	1	8/22/2017
Percent Moisture	D2	2974		Prep	Date: 8/17/2	017	Analyst: <b>KKA</b>
Percent Moisture	15.8	0.2	0.1	*	wt%	1	8/18/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Result

RI.

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 25, 2017

MDL Qualifier

**ANALYTICAL RESULTS** 

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

**Lab ID:** 17080520-002

Analyses

Client Sample ID: MW-2 @ 6'

Units

**Collection Date:** 8/11/2017 10:40:00 AM

DF Date Analyzed

Matrix: SOIL

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds by GC/MS	SV	V5035/826	0B	Prep	Date: 8/16/2	2017	Analyst: RRS
Acetone	0.025	0.065	0.002	J	mg/Kg-dry	1	8/22/2017
Benzene	0.0021	0.0043	0.00017	J	mg/Kg-dry	1	8/22/2017
Bromodichloromethane	ND	0.0043	0.00035		mg/Kg-dry	1	8/22/2017
Bromoform	ND	0.0043	0.00035		mg/Kg-dry	1	8/22/2017
Bromomethane	ND	0.0087	0.00043		mg/Kg-dry	1	8/22/2017
2-Butanone	0.0040	0.065	0.0013	J	mg/Kg-dry	1	8/22/2017
Carbon disulfide	ND	0.043	0.00017		mg/Kg-dry	1	8/22/2017
Carbon tetrachloride	ND	0.0043	0.00026		mg/Kg-dry	1	8/22/2017
Chlorobenzene	ND	0.0043	0.00017		mg/Kg-dry	1	8/22/2017
Chloroethane	ND	0.0087	0.00035		mg/Kg-dry	1	8/22/2017
Chloroform	ND	0.0043	0.00017		mg/Kg-dry	1	8/22/2017
Chloromethane	ND	0.0087	0.00026		mg/Kg-dry	1	8/22/2017
Dibromochloromethane	ND	0.0043	0.00035		mg/Kg-dry	1	8/22/2017
1,1-Dichloroethane	ND	0.0043	0.00026		mg/Kg-dry	1	8/22/2017
1,2-Dichloroethane	ND	0.0043	0.00052		mg/Kg-dry	1	8/22/2017
1,1-Dichloroethene	ND	0.0043	0.00026		mg/Kg-dry	1	8/22/2017
cis-1,2-Dichloroethene	ND	0.0043	0.00026		mg/Kg-dry	1	8/22/2017
trans-1,2-Dichloroethene	ND	0.0043	0.00026		mg/Kg-dry	1	8/22/2017
1,2-Dichloropropane	ND	0.0043	0.00035		mg/Kg-dry	1	8/22/2017
cis-1,3-Dichloropropene	ND	0.0017	0.00017		mg/Kg-dry	1	8/22/2017
trans-1,3-Dichloropropene	ND	0.0017	0.00026		mg/Kg-dry	1	8/22/2017
Ethylbenzene	0.00088	0.0043	0.000087	J	mg/Kg-dry	1	8/22/2017
2-Hexanone	ND	0.017	0.00069		mg/Kg-dry	1	8/22/2017
4-Methyl-2-pentanone	ND	0.017	0.00026		mg/Kg-dry	1	8/22/2017
Methylene chloride	ND	0.0087	0.00069		mg/Kg-dry	1	8/22/2017
Methyl tert-butyl ether	ND	0.0043	0.00017		mg/Kg-dry	1	8/22/2017
Styrene	ND	0.0043	0.00017		mg/Kg-dry	1	8/22/2017
1,1,2,2-Tetrachloroethane	ND	0.0043	0.00017		mg/Kg-dry	1	8/22/2017
Tetrachloroethene	ND	0.0043	0.00026		mg/Kg-dry	1	8/22/2017
Toluene	0.0028	0.0043	0.00017	J	mg/Kg-dry	1	8/22/2017
1,1,1-Trichloroethane	ND	0.0043	0.00017		mg/Kg-dry	1	8/22/2017
1,1,2-Trichloroethane	ND	0.0043	0.00043		mg/Kg-dry	1	8/22/2017
Trichloroethene	ND	0.0043	0.00017		mg/Kg-dry	1	8/22/2017
Vinyl chloride	ND	0.0043	0.00035		mg/Kg-dry	1	8/22/2017
Xylenes, Total	0.0012	0.013	0.00035	J	mg/Kg-dry	1	8/22/2017
Percent Moisture	D2974		Prep	Date: 8/17/2	2017	Analyst: KKA	
Percent Moisture	16.6	0.2	0.1	*	wt%	1	8/18/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: August 25, 2017

**ANALYTICAL RESULTS** 

**Collection Date:** 8/11/2017 9:10:00 AM

Client Sample ID: B-1 @ 2'

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

Matrix: SOIL 17080520-003 Lab ID:

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds by GC/MS	SI	W5035/826	0B	Prep	Date: 8/16/2	2017	Analyst: RRS
Acetone	0.064	0.056	0.0017		mg/Kg-dry	1	8/22/2017
Benzene	0.0015	0.0037	0.00015	J	mg/Kg-dry	1	8/22/2017
Bromodichloromethane	ND	0.0037	0.0003		mg/Kg-dry	1	8/22/2017
Bromoform	ND	0.0037	0.0003		mg/Kg-dry	1	8/22/2017
Bromomethane	ND	0.0075	0.00037		mg/Kg-dry	1	8/22/2017
2-Butanone	0.0099	0.056	0.0011	J	mg/Kg-dry	1	8/22/2017
Carbon disulfide	ND	0.037	0.00015		mg/Kg-dry	1	8/22/2017
Carbon tetrachloride	ND	0.0037	0.00022		mg/Kg-dry	1	8/22/2017
Chlorobenzene	ND	0.0037	0.00015		mg/Kg-dry	1	8/22/2017
Chloroethane	ND	0.0075	0.0003		mg/Kg-dry	1	8/22/2017
Chloroform	ND	0.0037	0.00015		mg/Kg-dry	1	8/22/2017
Chloromethane	ND	0.0075	0.00022		mg/Kg-dry	1	8/22/2017
Dibromochloromethane	ND	0.0037	0.0003		mg/Kg-dry	1	8/22/2017
1,1-Dichloroethane	ND	0.0037	0.00022		mg/Kg-dry	1	8/22/2017
1,2-Dichloroethane	ND	0.0037	0.00045		mg/Kg-dry	1	8/22/2017
1,1-Dichloroethene	ND	0.0037	0.00022		mg/Kg-dry	1	8/22/2017
cis-1,2-Dichloroethene	ND	0.0037	0.00022		mg/Kg-dry	1	8/22/2017
trans-1,2-Dichloroethene	ND	0.0037	0.00022		mg/Kg-dry	1	8/22/2017
1,2-Dichloropropane	ND	0.0037	0.0003		mg/Kg-dry	1	8/22/2017
cis-1,3-Dichloropropene	ND	0.0015	0.00015		mg/Kg-dry	1	8/22/2017
trans-1,3-Dichloropropene	ND	0.0015	0.00022		mg/Kg-dry	1	8/22/2017
Ethylbenzene	0.0010	0.0037	0.000075	J	mg/Kg-dry	1	8/22/2017
2-Hexanone	ND	0.015	0.0006		mg/Kg-dry	1	8/22/2017
4-Methyl-2-pentanone	ND	0.015	0.00022		mg/Kg-dry	1	8/22/2017
Methylene chloride	ND	0.0075	0.0006		mg/Kg-dry	1	8/22/2017
Methyl tert-butyl ether	ND	0.0037	0.00015		mg/Kg-dry	1	8/22/2017
Styrene	ND	0.0037	0.00015		mg/Kg-dry	1	8/22/2017
1,1,2,2-Tetrachloroethane	ND	0.0037	0.00015		mg/Kg-dry	1	8/22/2017
Tetrachloroethene	0.00067	0.0037	0.00022	J	mg/Kg-dry	1	8/22/2017
Toluene	0.0028	0.0037	0.00015	J	mg/Kg-dry	1	8/22/2017
1,1,1-Trichloroethane	ND	0.0037	0.00015		mg/Kg-dry	1	8/22/2017
1,1,2-Trichloroethane	ND	0.0037	0.00037		mg/Kg-dry	1	8/22/2017
Trichloroethene	0.0010	0.0037	0.00015	J	mg/Kg-dry	1	8/22/2017
Vinyl chloride	ND	0.0037	0.0003		mg/Kg-dry	1	8/22/2017
Xylenes, Total	0.0014	0.011	0.0003	J	mg/Kg-dry	1	8/22/2017
Percent Moisture	D	2974		Prep	Date: 8/17/2	2017	Analyst: KKA
Percent Moisture	10.2	0.2	0.1	*	wt%	1	8/18/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

H - Holding time exceeded

6 of 20

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 25, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

**Lab ID:** 17080520-004

Client Sample ID: SV-4

**Collection Date:** 8/14/2017 12:24:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in	Air by GC/MS TO	)-15		Prep l	Date: <b>8/16/</b>	2017	Analyst: AOA
1,1,1-Trichloroethane	ND	0.81	0.039	•	ppbv	2	8/16/2017
1,1,2,2-Tetrachloroethane	ND	0.81	0.056		ppbv	2	8/16/2017
1,1,2-Trichloroethane	ND	0.81	0.1		ppbv	2	8/16/2017
1,1-Dichloroethane	ND	0.81	0.035		ppbv	2	8/16/2017
1,1-Dichloroethene	ND	0.81	0.051		ppbv	2	8/16/2017
1,2,4-Trichlorobenzene	ND	0.81	0.15		ppbv	2	8/16/2017
1,2,4-Trimethylbenzene	0.081	0.81	0.045	J	ppbv	2	8/16/2017
1,2-Dibromoethane	ND	0.81	0.089		ppbv	2	8/16/2017
1,2-Dichlorobenzene	ND	0.81	0.065		ppbv	2	8/16/2017
1,2-Dichloroethane	ND	0.81	0.094		ppbv	2	8/16/2017
1,2-Dichloropropane	ND	0.81	0.15		ppbv	2	8/16/2017
1,3,5-Trimethylbenzene	ND	0.81	0.056		ppbv	2	8/16/2017
1,3-Butadiene	ND	0.81	0.19		ppbv	2	8/16/2017
1,3-Dichlorobenzene	ND	0.81	0.061		ppbv	2	8/16/2017
1,4-Dichlorobenzene	ND	0.81	0.07		ppbv	2	8/16/2017
1,4-Dioxane	ND	2.0	0.32		ppbv	2	8/16/2017
2-Butanone	0.57	2.0	0.34	J	ppbv	2	8/16/2017
2-Hexanone	ND	4.1	0.52		ppbv	2	8/16/2017
4-Ethyltoluene	ND	0.81	0.085		ppbv	2	8/16/2017
4-Methyl-2-pentanone	ND	4.1	0.28		ppbv	2	8/16/2017
Acetone	6.6	8.1	0.75	J*	ppbv	2	8/16/2017
Benzene	0.081	0.81	0.068	J	ppbv	2	8/16/2017
Benzyl chloride	ND	2.0	0.25		ppbv	2	8/16/2017
Bromodichloromethane	ND	0.81	0.042		ppbv	2	8/16/2017
Bromoform	ND	2.0	0.04		ppbv	2	8/16/2017
Bromomethane	0.12	2.0	0.095	J	ppbv	2	8/16/2017
Carbon disulfide	ND	0.81	0.084		ppbv	2	8/16/2017
Carbon tetrachloride	ND	0.81	0.18		ppbv	2	8/16/2017
Chlorobenzene	ND	0.81	0.2		ppbv	2	8/16/2017
Chloroethane	ND	0.81	0.17		ppbv	2	8/16/2017
Chloroform	ND	0.81	0.045		ppbv	2	8/16/2017
Chloromethane	ND	2.0	0.46		ppbv	2	8/16/2017
cis-1,2-Dichloroethene	ND	0.81	0.16		ppbv	2	8/16/2017
cis-1,3-Dichloropropene	ND	0.81	0.097		ppbv	2	8/16/2017
Cyclohexane	ND	0.81	0.17		ppbv	2	8/16/2017
Dibromochloromethane	ND	0.81	0.051		ppbv	2	8/16/2017
Dichlorodifluoromethane	0.41	0.81	0.05	J	ppbv	2	8/16/2017
Ethyl acetate	ND	2.0	0.29		ppbv	2	8/16/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 25, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

**Lab ID:** 17080520-004

Client Sample ID: SV-4

**Collection Date:** 8/14/2017 12:24:00 PM

Matrix: AIR

Analyses	Resul	t RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in	Air by GC/MS	TO-15		Prep	Date: <b>8/16/</b>	2017	Analyst: AOA
Ethylbenzene	ND	0.81	0.059		ppbv	2	8/16/2017
Freon-113	0.041	0.81	0.031	J	ppbv	2	8/16/2017
Freon-114	ND	4.1	0.042		ppbv	2	8/16/2017
Heptane	ND	0.81	0.068		ppbv	2	8/16/2017
Hexachlorobutadiene	ND	0.81	0.085		ppbv	2	8/16/2017
Hexane	ND	2.0	0.14		ppbv	2	8/16/2017
Isopropyl Alcohol	20	4.1	0.31		ppbv	2	8/16/2017
m,p-Xylene	ND	1.6	0.1		ppbv	2	8/16/2017
Methyl tert-butyl ether	ND	0.81	0.046		ppbv	2	8/16/2017
Methylene chloride	1.1	8.1	0.81	J	ppbv	2	8/16/2017
Naphthalene	ND	0.81	0.23		ppbv	2	8/16/2017
o-Xylene	ND	0.81	0.052		ppbv	2	8/16/2017
Propene	0.24	8.1	0.23	J	ppbv	2	8/16/2017
Styrene	ND	0.81	0.19		ppbv	2	8/16/2017
Tetrachloroethene	350	10	0.74		ppbv	25	8/16/2017
Tetrahydrofuran	ND	2.0	0.39		ppbv	2	8/16/2017
Toluene	ND	0.81	0.092		ppbv	2	8/16/2017
trans-1,2-Dichloroethene	ND	0.81	0.056		ppbv	2	8/16/2017
trans-1,3-Dichloropropene	ND	0.81	0.81		ppbv	2	8/16/2017
Trichloroethene	2.2	0.81	0.062		ppbv	2	8/16/2017
Trichlorofluoromethane	0.24	0.81	0.051	J	ppbv	2	8/16/2017
Vinyl acetate	ND	8.1	0.33		ppbv	2	8/16/2017
Vinyl chloride	ND	0.81	0.069		ppbv	2	8/16/2017
Xylenes, Total	ND	2.4	0.15		ppbv	2	8/16/2017
olatile Organic Compounds in	Air by GC/MS	TO-15		Prep	Date: <b>8/16/</b>	2017	Analyst: AOA
1,1,1-Trichloroethane	ND	0.0044	0.00021		mg/m³	2	8/16/2017
1,1,2,2-Tetrachloroethane	ND	0.0056	0.00038		mg/m³	2	8/16/2017
1,1,2-Trichloroethane	ND	0.0044	0.00056		mg/m³	2	8/16/2017
1,1-Dichloroethane	ND	0.0033	0.00014		mg/m³	2	8/16/2017
1,1-Dichloroethene	ND	0.0032	0.0002		mg/m³	2	8/16/2017
1,2,4-Trichlorobenzene	ND	0.0060	0.0011		mg/m³	2	8/16/2017
1,2,4-Trimethylbenzene	0.00040	0.0040	0.00022	J	mg/m³	2	8/16/2017
1,2-Dibromoethane	ND	0.0063	0.00068		mg/m³	2	8/16/2017
1,2-Dichlorobenzene	ND	0.0049	0.00039		mg/m³	2	8/16/2017
1,2-Dichloroethane	ND	0.0033	0.00038		mg/m³	2	8/16/2017
1,2-Dichloropropane	ND	0.0038	0.0007		mg/m³	2	8/16/2017
1,3,5-Trimethylbenzene	ND	0.0040	0.00028		mg/m³	2	8/16/2017
1,3-Butadiene	ND	0.0018	0.00042		mg/m³	2	8/16/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 25, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

**Lab ID:** 17080520-004

Client Sample ID: SV-4

**Collection Date:** 8/14/2017 12:24:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds ir	n Air by GC/MS	ГО-15		Prep	Date: <b>8/16/</b>	2017	Analyst: AOA
1,3-Dichlorobenzene	ND	0.0049	0.00037	· ·	mg/m³	2	8/16/2017
1,4-Dichlorobenzene	ND	0.0049	0.00042		mg/m³	2	8/16/2017
1,4-Dioxane	ND	0.0073	0.0012		mg/m³	2	8/16/2017
2-Butanone	0.0017	0.0060	0.00099	J	mg/m³	2	8/16/2017
2-Hexanone	ND	0.017	0.0021		mg/m³	2	8/16/2017
4-Ethyltoluene	ND	0.0040	0.00042		mg/m³	2	8/16/2017
4-Methyl-2-pentanone	ND	0.017	0.0011		mg/m³	2	8/16/2017
Acetone	0.016	0.019	0.0018	J*	mg/m³	2	8/16/2017
Benzene	0.00026	0.0026	0.00022	J	mg/m³	2	8/16/2017
Benzyl chloride	ND	0.011	0.0013		mg/m³	2	8/16/2017
Bromodichloromethane	ND	0.0055	0.00028		mg/m³	2	8/16/2017
Bromoform	ND	0.021	0.00041		mg/m³	2	8/16/2017
Bromomethane	0.00047	0.0079	0.00037	J	mg/m³	2	8/16/2017
Carbon disulfide	ND	0.0025	0.00026		mg/m³	2	8/16/2017
Carbon tetrachloride	ND	0.0051	0.0012		mg/m³	2	8/16/2017
Chlorobenzene	ND	0.0038	0.00094		mg/m³	2	8/16/2017
Chloroethane	ND	0.0021	0.00044		mg/m³	2	8/16/2017
Chloroform	ND	0.0040	0.00022		mg/m³	2	8/16/2017
Chloromethane	ND	0.0042	0.00095		mg/m³	2	8/16/2017
cis-1,2-Dichloroethene	ND	0.0032	0.00063		mg/m³	2	8/16/2017
cis-1,3-Dichloropropene	ND	0.0037	0.00044		mg/m³	2	8/16/2017
Cyclohexane	ND	0.0028	0.0006		mg/m³	2	8/16/2017
Dibromochloromethane	ND	0.0069	0.00043		mg/m³	2	8/16/2017
Dichlorodifluoromethane	0.0020	0.0040	0.00025	J	mg/m³	2	8/16/2017
Ethyl acetate	ND	0.0073	0.001		mg/m³	2	8/16/2017
Ethylbenzene	ND	0.0035	0.00026		mg/m³	2	8/16/2017
Freon-113	0.00031	0.0062	0.00023	J	mg/m³	2	8/16/2017
Freon-114	ND	0.028	0.00029		mg/m³	2	8/16/2017
Heptane	ND	0.0033	0.00028		mg/m³	2	8/16/2017
Hexachlorobutadiene	ND	0.0087	0.0009		mg/m³	2	8/16/2017
Hexane	ND	0.0072	0.0005		mg/m³	2	8/16/2017
Isopropyl Alcohol	0.050	0.010	0.00077		mg/m³	2	8/16/2017
m,p-Xylene	ND	0.0071	0.00044		mg/m³	2	8/16/2017
Methyl tert-butyl ether	ND	0.0029	0.00017		mg/m³	2	8/16/2017
Methylene chloride	0.0040	0.028	0.0028	J	mg/m³	2	8/16/2017
Naphthalene	ND	0.0043	0.0012		mg/m³	2	8/16/2017
o-Xylene	ND	0.0035	0.00023		mg/m³	2	8/16/2017
Propene	0.00042	0.014	0.00039	J	mg/m³	2	8/16/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter


Qualifiers:

 $RL/\!MDL$  - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range



Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 25, 2017

ANALYTICAL RESULTS

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

**Lab ID:** 17080520-004

Client Sample ID: SV-4

**Collection Date:** 8/14/2017 12:24:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in A	ir by GC/MS T	O-15		Prep	Date: <b>8/16/</b>	2017	Analyst: AOA
Styrene	ND	0.0035	0.00082		mg/m³	2	8/16/2017
Tetrachloroethene	2.4	0.069	0.005		mg/m³	25	8/16/2017
Tetrahydrofuran	ND	0.0060	0.0011		mg/m³	2	8/16/2017
Toluene	ND	0.0031	0.00035		mg/m³	2	8/16/2017
trans-1,2-Dichloroethene	ND	0.0032	0.00022		mg/m³	2	8/16/2017
trans-1,3-Dichloropropene	ND	0.0037	0.0037		mg/m³	2	8/16/2017
Trichloroethene	0.012	0.0044	0.00033		mg/m³	2	8/16/2017
Trichlorofluoromethane	0.0014	0.0046	0.00029	J	mg/m³	2	8/16/2017
Vinyl acetate	ND	0.029	0.0011		mg/m³	2	8/16/2017
Vinyl chloride	ND	0.0021	0.00018		mg/m³	2	8/16/2017
Xylenes, Total	ND	0.011	0.00065		mg/m³	2	8/16/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: August 25, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

Lab ID: 17080520-005 **Client Sample ID:** SV-5

**Collection Date:** 8/14/2017 12:30:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	<b>Date Analyzed</b>
Volatile Organic Compounds in Air	by GC/MS TO	-15		Prep	Date: <b>8/16/</b>	2017	Analyst: AOA
1,1,1-Trichloroethane	0.16	0.81	0.039	J	ppbv	2	8/16/2017
1,1,2,2-Tetrachloroethane	ND	0.81	0.056		ppbv	2	8/16/2017
1,1,2-Trichloroethane	ND	0.81	0.1		ppbv	2	8/16/2017
1,1-Dichloroethane	ND	0.81	0.035		ppbv	2	8/16/2017
1,1-Dichloroethene	ND	0.81	0.051		ppbv	2	8/16/2017
1,2,4-Trichlorobenzene	ND	0.81	0.15		ppbv	2	8/16/2017
1,2,4-Trimethylbenzene	ND	0.81	0.045		ppbv	2	8/16/2017
1,2-Dibromoethane	ND	0.81	0.088		ppbv	2	8/16/2017
1,2-Dichlorobenzene	ND	0.81	0.064		ppbv	2	8/16/2017
1,2-Dichloroethane	ND	0.81	0.094		ppbv	2	8/16/2017
1,2-Dichloropropane	ND	0.81	0.15		ppbv	2	8/16/2017
1,3,5-Trimethylbenzene	ND	0.81	0.056		ppbv	2	8/16/2017
1,3-Butadiene	ND	0.81	0.19		ppbv	2	8/16/2017
1,3-Dichlorobenzene	ND	0.81	0.061		ppbv	2	8/16/2017
1,4-Dichlorobenzene	ND	0.81	0.069		ppbv	2	8/16/2017
1,4-Dioxane	ND	2.0	0.32		ppbv	2	8/16/2017
2-Butanone	ND	2.0	0.33		ppbv	2	8/16/2017
2-Hexanone	ND	4.0	0.51		ppbv	2	8/16/2017
4-Ethyltoluene	ND	0.81	0.084		ppbv	2	8/16/2017
4-Methyl-2-pentanone	ND	4.0	0.27		ppbv	2	8/16/2017
Acetone	5.8	8.1	0.74	J*	ppbv	2	8/16/2017
Benzene	0.081	0.81	0.067	J	ppbv	2	8/16/2017
Benzyl chloride	ND	2.0	0.25		ppbv	2	8/16/2017
Bromodichloromethane	ND	0.81	0.041		ppbv	2	8/16/2017
Bromoform	ND	2.0	0.039		ppbv	2	8/16/2017
Bromomethane	ND	2.0	0.095		ppbv	2	8/16/2017
Carbon disulfide	ND	0.81	0.083		ppbv	2	8/16/2017
Carbon tetrachloride	ND	0.81	0.18		ppbv	2	8/16/2017
Chlorobenzene	ND	0.81	0.2		ppbv	2	8/16/2017
Chloroethane	ND	0.81	0.16		ppbv	2	8/16/2017
Chloroform	ND	0.81	0.044		ppbv	2	8/16/2017
Chloromethane	ND	2.0	0.46		ppbv	2	8/16/2017
cis-1,2-Dichloroethene	ND	0.81	0.16		ppbv	2	8/16/2017
cis-1,3-Dichloropropene	ND	0.81	0.096		ppbv	2	8/16/2017
Cyclohexane	ND	0.81	0.17		ppbv	2	8/16/2017
Dibromochloromethane	ND	0.81	0.05		ppbv	2	8/16/2017
Dichlorodifluoromethane	0.40	0.81	0.05	J	ppbv	2	8/16/2017
Ethyl acetate	ND	2.0	0.29	-	ppbv	2	8/16/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: August 25, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

Lab ID: 17080520-005 **Client Sample ID:** SV-5

**Collection Date:** 8/14/2017 12:30:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in Air b	y GC/MS T	O-15		Prep	Date: <b>8/16/</b>	2017	Analyst: AOA
Ethylbenzene	ND	0.81	0.059		ppbv	2	8/16/2017
Freon-113	0.081	0.81	0.03	J	ppbv	2	8/16/2017
Freon-114	ND	4.0	0.042		ppbv	2	8/16/2017
Heptane	ND	0.81	0.067		ppbv	2	8/16/2017
Hexachlorobutadiene	ND	0.81	0.084		ppbv	2	8/16/2017
Hexane	ND	2.0	0.14		ppbv	2	8/16/2017
Isopropyl Alcohol	14	4.0	0.31		ppbv	2	8/16/2017
m,p-Xylene	ND	1.6	0.1		ppbv	2	8/16/2017
Methyl tert-butyl ether	ND	0.81	0.046		ppbv	2	8/16/2017
Methylene chloride	1.1	8.1	0.81	J	ppbv	2	8/16/2017
Naphthalene	ND	0.81	0.23		ppbv	2	8/16/2017
o-Xylene	ND	0.81	0.052		ppbv	2	8/16/2017
Propene	ND	8.1	0.22		ppbv	2	8/16/2017
Styrene	ND	0.81	0.19		ppbv	2	8/16/2017
Tetrachloroethene	76	0.81	0.059		ppbv	2	8/16/2017
Tetrahydrofuran	ND	2.0	0.38		ppbv	2	8/16/2017
Toluene	ND	0.81	0.091		ppbv	2	8/16/2017
trans-1,2-Dichloroethene	ND	0.81	0.056		ppbv	2	8/16/2017
trans-1,3-Dichloropropene	ND	0.81	0.81		ppbv	2	8/16/2017
Trichloroethene	4.8	0.81	0.062		ppbv	2	8/16/2017
Trichlorofluoromethane	0.32	0.81	0.051	J	ppbv	2	8/16/2017
Vinyl acetate	ND	8.1	0.32		ppbv	2	8/16/2017
Vinyl chloride	ND	0.81	0.068		ppbv	2	8/16/2017
Xylenes, Total	ND	2.4	0.15		ppbv	2	8/16/2017
Volatile Organic Compounds in Air b	y GC/MS T	O-15		Prep	Date: <b>8/16/</b>	2017	Analyst: AOA
1,1,1-Trichloroethane	0.00088	0.0044	0.00021	J	mg/m³	2	8/16/2017
1,1,2,2-Tetrachloroethane	ND	0.0056	0.00038		mg/m³	2	8/16/2017
1,1,2-Trichloroethane	ND	0.0044	0.00056		mg/m³	2	8/16/2017
1,1-Dichloroethane	ND	0.0033	0.00014		mg/m³	2	8/16/2017
1,1-Dichloroethene	ND	0.0032	0.0002		mg/m³	2	8/16/2017
1,2,4-Trichlorobenzene	ND	0.0060	0.0011		mg/m³	2	8/16/2017
1,2,4-Trimethylbenzene	ND	0.0040	0.00022		mg/m³	2	8/16/2017
1,2-Dibromoethane	ND	0.0062	0.00068		mg/m³	2	8/16/2017
1,2-Dichlorobenzene	ND	0.0049	0.00039		mg/m³	2	8/16/2017
1,2-Dichloroethane	ND	0.0033	0.00038		mg/m³	2	8/16/2017
1,2-Dichloropropane	ND	0.0037	0.00069		mg/m³	2	8/16/2017
1,3,5-Trimethylbenzene	ND	0.0040	0.00027		mg/m³	2	8/16/2017
1,3-Butadiene	ND	0.0018	0.00042		mg/m³	2	8/16/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

RL

**Date Reported:** August 25, 2017

ANALYTICAL RESULTS

**Collection Date:** 8/14/2017 12:30:00 PM

**DF** Date Analyzed

**Client Sample ID:** SV-5

Units

MDL Qualifier

**Date Printed:** August 25, 2017

**Analyses** 

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

**Lab ID:** 17080520-005 **Matrix:** AIR

Result

inaryses	Result	KL	MIDL	Quanner	Omts	DI	Date Analyzeu
olatile Organic Compounds ir	n Air by GC/MS TO	D-15		Prep	Date: <b>8/16/</b>	2017	Analyst: <b>AOA</b>
1,3-Dichlorobenzene	ND	0.0049	0.00036		mg/m³	2	8/16/2017
1,4-Dichlorobenzene	ND	0.0049	0.00042		mg/m³	2	8/16/2017
1,4-Dioxane	ND	0.0073	0.0012		mg/m³	2	8/16/2017
2-Butanone	ND	0.0060	0.00099		mg/m³	2	8/16/2017
2-Hexanone	ND	0.017	0.0021		mg/m³	2	8/16/2017
4-Ethyltoluene	ND	0.0040	0.00041		mg/m³	2	8/16/2017
4-Methyl-2-pentanone	ND	0.017	0.0011		mg/m³	2	8/16/2017
Acetone	0.014	0.019	0.0018	J*	mg/m³	2	8/16/2017
Benzene	0.00026	0.0026	0.00022	J	mg/m³	2	8/16/2017
Benzyl chloride	ND	0.010	0.0013		mg/m³	2	8/16/2017
Bromodichloromethane	ND	0.0054	0.00028		mg/m³	2	8/16/2017
Bromoform	ND	0.021	0.00041		mg/m³	2	8/16/2017
Bromomethane	ND	0.0079	0.00037		mg/m³	2	8/16/2017
Carbon disulfide	ND	0.0025	0.00026		mg/m³	2	8/16/2017
Carbon tetrachloride	ND	0.0051	0.0011		mg/m³	2	8/16/2017
Chlorobenzene	ND	0.0037	0.00093		mg/m³	2	8/16/2017
Chloroethane	ND	0.0021	0.00043		mg/m³	2	8/16/2017
Chloroform	ND	0.0039	0.00022		mg/m³	2	8/16/2017
Chloromethane	ND	0.0042	0.00095		mg/m³	2	8/16/2017
cis-1,2-Dichloroethene	ND	0.0032	0.00062		mg/m³	2	8/16/2017
cis-1,3-Dichloropropene	ND	0.0037	0.00044		mg/m³	2	8/16/2017
Cyclohexane	ND	0.0028	0.00059		mg/m³	2	8/16/2017
Dibromochloromethane	ND	0.0069	0.00043		mg/m³	2	8/16/2017
Dichlorodifluoromethane	0.0020	0.0040	0.00025	J	mg/m³	2	8/16/2017
Ethyl acetate	ND	0.0073	0.001		mg/m³	2	8/16/2017
Ethylbenzene	ND	0.0035	0.00026		mg/m³	2	8/16/2017
Freon-113	0.00062	0.0062	0.00023	J	mg/m³	2	8/16/2017
Freon-114	ND	0.028	0.00029		mg/m³	2	8/16/2017
Heptane	ND	0.0033	0.00028		mg/m³	2	8/16/2017
Hexachlorobutadiene	ND	0.0086	0.0009		mg/m³	2	8/16/2017
Hexane	ND	0.0071	0.0005		mg/m³	2	8/16/2017
Isopropyl Alcohol	0.036	0.0099	0.00077		mg/m³	2	8/16/2017
m,p-Xylene	ND	0.0070	0.00044		mg/m³	2	8/16/2017
Methyl tert-butyl ether	ND	0.0029	0.00017		mg/m³	2	8/16/2017
Methylene chloride	0.0038	0.028	0.0028	J	mg/m³	2	8/16/2017
Naphthalene	ND	0.0042	0.0012		mg/m³	2	8/16/2017
o-Xylene	ND	0.0035	0.00022		mg/m³	2	8/16/2017
Propene	ND	0.014	0.00039		mg/m³	2	8/16/2017

ND - Not Detected at the Reporting Limit

Qualifiers: J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time


\* - Non-accredited parameter

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range



Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 25, 2017

ANALYTICAL RESULTS

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

**Lab ID:** 17080520-005

**Client Sample ID:** SV-5

**Collection Date:** 8/14/2017 12:30:00 PM

Matrix: AIR

Analyses	Resul	t RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in A	Air by GC/MS	TO-15		Prep	Date: <b>8/16/</b>	2017	Analyst: AOA
Styrene	ND	0.0034	0.00081		mg/m³	2	8/16/2017
Tetrachloroethene	0.52	0.0055	0.0004		mg/m³	2	8/16/2017
Tetrahydrofuran	ND	0.0060	0.0011		mg/m³	2	8/16/2017
Toluene	ND	0.0030	0.00034		mg/m³	2	8/16/2017
trans-1,2-Dichloroethene	ND	0.0032	0.00022		mg/m³	2	8/16/2017
trans-1,3-Dichloropropene	ND	0.0037	0.0037		mg/m³	2	8/16/2017
Trichloroethene	0.026	0.0043	0.00033		mg/m³	2	8/16/2017
Trichlorofluoromethane	0.0018	0.0045	0.00029	J	mg/m³	2	8/16/2017
Vinyl acetate	ND	0.028	0.0011		mg/m³	2	8/16/2017
Vinyl chloride	ND	0.0021	0.00017		mg/m³	2	8/16/2017
Xylenes, Total	ND	0.011	0.00065		mg/m³	2	8/16/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 25, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

**Lab ID:** 17080520-006

**Client Sample ID:** SV-6

**Collection Date:** 8/14/2017 12:35:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in Air by	GC/MS TO-	-15		Prep	Date: <b>8/16/</b>	2017	Analyst: AOA
1,1,1-Trichloroethane	ND	0.37	0.018	•	ppbv	1	8/16/2017
1,1,2,2-Tetrachloroethane	ND	0.37	0.026		ppbv	1	8/16/2017
1,1,2-Trichloroethane	ND	0.37	0.048		ppbv	1	8/16/2017
1,1-Dichloroethane	ND	0.37	0.016		ppbv	1	8/16/2017
1,1-Dichloroethene	ND	0.37	0.024		ppbv	1	8/16/2017
1,2,4-Trichlorobenzene	ND	0.37	0.071		ppbv	1	8/16/2017
1,2,4-Trimethylbenzene	0.075	0.37	0.021	J	ppbv	1	8/16/2017
1,2-Dibromoethane	ND	0.37	0.041		ppbv	1	8/16/2017
1,2-Dichlorobenzene	ND	0.37	0.03		ppbv	1	8/16/2017
1,2-Dichloroethane	ND	0.37	0.043		ppbv	1	8/16/2017
1,2-Dichloropropane	ND	0.37	0.069		ppbv	1	8/16/2017
1,3,5-Trimethylbenzene	ND	0.37	0.026		ppbv	1	8/16/2017
1,3-Butadiene	ND	0.37	0.088		ppbv	1	8/16/2017
1,3-Dichlorobenzene	ND	0.37	0.028		ppbv	1	8/16/2017
1,4-Dichlorobenzene	ND	0.37	0.032		ppbv	1	8/16/2017
1,4-Dioxane	ND	0.94	0.15		ppbv	1	8/16/2017
2-Butanone	0.24	0.94	0.16	J	ppbv	1	8/16/2017
2-Hexanone	ND	1.9	0.24		ppbv	1	8/16/2017
4-Ethyltoluene	ND	0.37	0.039		ppbv	1	8/16/2017
4-Methyl-2-pentanone	ND	1.9	0.13		ppbv	1	8/16/2017
Acetone	2.2	3.7	0.34	J*	ppbv	1	8/16/2017
Benzene	0.037	0.37	0.031	J	ppbv	1	8/16/2017
Benzyl chloride	ND	0.94	0.11		ppbv	1	8/16/2017
Bromodichloromethane	ND	0.37	0.019		ppbv	1	8/16/2017
Bromoform	ND	0.94	0.018		ppbv	1	8/16/2017
Bromomethane	0.056	0.94	0.044	J	ppbv	1	8/16/2017
Carbon disulfide	ND	0.37	0.038		ppbv	1	8/16/2017
Carbon tetrachloride	ND	0.37	0.084		ppbv	1	8/16/2017
Chlorobenzene	ND	0.37	0.094		ppbv	1	8/16/2017
Chloroethane	ND	0.37	0.076		ppbv	1	8/16/2017
Chloroform	0.075	0.37	0.021	J	ppbv	1	8/16/2017
Chloromethane	ND	0.94	0.21		ppbv	1	8/16/2017
cis-1,2-Dichloroethene	ND	0.37	0.073		ppbv	1	8/16/2017
cis-1,3-Dichloropropene	ND	0.37	0.045		ppbv	1	8/16/2017
Cyclohexane	ND	0.37	0.08		ppbv	1	8/16/2017
Dibromochloromethane	ND	0.37	0.023		ppbv	1	8/16/2017
Dichlorodifluoromethane	0.45	0.37	0.023		ppbv	1	8/16/2017
Ethyl acetate	ND	0.94	0.13		ppbv	1	8/16/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

Date Reported: August 25, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

Lab ID: 17080520-006 **Client Sample ID: SV-6** 

**Collection Date:** 8/14/2017 12:35:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in A	Air by GC/MS	ГО-15		Prep	Date: <b>8/16/</b>	2017	Analyst: AOA
Ethylbenzene	ND	0.37	0.027		ppbv	1	8/16/2017
Freon-113	0.075	0.37	0.014	J	ppbv	1	8/16/2017
Freon-114	ND	1.9	0.019		ppbv	1	8/16/2017
Heptane	ND	0.37	0.031		ppbv	1	8/16/2017
Hexachlorobutadiene	ND	0.37	0.039		ppbv	1	8/16/2017
Hexane	ND	0.94	0.066		ppbv	1	8/16/2017
Isopropyl Alcohol	0.26	1.9	0.14	J	ppbv	1	8/16/2017
m,p-Xylene	0.056	0.75	0.047	J	ppbv	1	8/16/2017
Methyl tert-butyl ether	ND	0.37	0.021		ppbv	1	8/16/2017
Methylene chloride	0.56	3.7	0.37	J	ppbv	1	8/16/2017
Naphthalene	0.11	0.37	0.11	J	ppbv	1	8/16/2017
o-Xylene	0.037	0.37	0.024	J	ppbv	1	8/16/2017
Propene	0.13	3.7	0.1	J	ppbv	1	8/16/2017
Styrene	ND	0.37	0.088		ppbv	1	8/16/2017
Tetrachloroethene	3.8	0.37	0.027		ppbv	1	8/16/2017
Tetrahydrofuran	ND	0.94	0.18		ppbv	1	8/16/2017
Toluene	ND	0.37	0.042		ppbv	1	8/16/2017
trans-1,2-Dichloroethene	ND	0.37	0.026		ppbv	1	8/16/2017
trans-1,3-Dichloropropene	ND	0.37	0.37		ppbv	1	8/16/2017
Trichloroethene	ND	0.37	0.029		ppbv	1	8/16/2017
Trichlorofluoromethane	0.24	0.37	0.024	J	ppbv	1	8/16/2017
Vinyl acetate	ND	3.7	0.15		ppbv	1	8/16/2017
Vinyl chloride	ND	0.37	0.032		ppbv	1	8/16/2017
Xylenes, Total	0.094	1.1	0.069	J	ppbv	1	8/16/2017
Volatile Organic Compounds in A	ir by GC/MS	ΓΟ-15		Prep	Date: 8/16/	2017	Analyst: AOA
1,1,1-Trichloroethane	ND	0.0020	0.000098		mg/m³	1	8/16/2017
1,1,2,2-Tetrachloroethane	ND	0.0026	0.00018		mg/m³	1	8/16/2017
1,1,2-Trichloroethane	ND	0.0020	0.00026		mg/m³	1	8/16/2017
1,1-Dichloroethane	ND	0.0015	0.000066		mg/m³	1	8/16/2017
1,1-Dichloroethene	ND	0.0015	0.000094		mg/m³	1	8/16/2017
1,2,4-Trichlorobenzene	ND	0.0028	0.00053		mg/m³	1	8/16/2017
1,2,4-Trimethylbenzene	0.00037	0.0018	0.0001	J	mg/m³	1	8/16/2017
1,2-Dibromoethane	ND	0.0029	0.00031		mg/m³	1	8/16/2017
1,2-Dichlorobenzene	ND	0.0023	0.00018		mg/m³	1	8/16/2017
1,2-Dichloroethane	ND	0.0015	0.00018		mg/m³	1	8/16/2017
1,2-Dichloropropane	ND	0.0017	0.00032		mg/m³	1	8/16/2017
1,3,5-Trimethylbenzene	ND	0.0018	0.00013		mg/m³	1	8/16/2017
1,3-Butadiene	ND	0.00083	0.00019		mg/m³	1	8/16/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766

Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 25, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

**Lab ID:** 17080520-006

**Client Sample ID:** SV-6

**Collection Date:** 8/14/2017 12:35:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in	n Air by GC/MS	ΓΟ-15		Prep	Date: <b>8/16</b> /	2017	Analyst: AOA
1,3-Dichlorobenzene	ND	0.0023	0.00017	'	mg/m³	1	8/16/2017
1,4-Dichlorobenzene	ND	0.0023	0.00019		mg/m³	1	8/16/2017
1,4-Dioxane	ND	0.0034	0.00054		mg/m³	1	8/16/2017
2-Butanone	0.00072	0.0028	0.00046	J	mg/m³	1	8/16/2017
2-Hexanone	ND	0.0077	0.00097		mg/m³	1	8/16/2017
4-Ethyltoluene	ND	0.0018	0.00019		mg/m³	1	8/16/2017
4-Methyl-2-pentanone	ND	0.0077	0.00052		mg/m³	1	8/16/2017
Acetone	0.0053	0.0089	0.00082	J*	mg/m³	1	8/16/2017
Benzene	0.00012	0.0012	0.0001	J	mg/m³	1	8/16/2017
Benzyl chloride	ND	0.0048	0.00059		mg/m³	1	8/16/2017
Bromodichloromethane	ND	0.0025	0.00013		mg/m³	1	8/16/2017
Bromoform	ND	0.0097	0.00019		mg/m³	1	8/16/2017
Bromomethane	0.00022	0.0036	0.00017	J	mg/m³	1	8/16/2017
Carbon disulfide	ND	0.0012	0.00012		mg/m³	1	8/16/2017
Carbon tetrachloride	ND	0.0024	0.00053		mg/m³	1	8/16/2017
Chlorobenzene	ND	0.0017	0.00043		mg/m³	1	8/16/2017
Chloroethane	ND	0.00099	0.0002		mg/m³	1	8/16/2017
Chloroform	0.00037	0.0018	0.0001	J	mg/m³	1	8/16/2017
Chloromethane	ND	0.0019	0.00044		mg/m³	1	8/16/2017
cis-1,2-Dichloroethene	ND	0.0015	0.00029		mg/m³	1	8/16/2017
cis-1,3-Dichloropropene	ND	0.0017	0.0002		mg/m³	1	8/16/2017
Cyclohexane	ND	0.0013	0.00027		mg/m³	1	8/16/2017
Dibromochloromethane	ND	0.0032	0.0002		mg/m³	1	8/16/2017
Dichlorodifluoromethane	0.0022	0.0019	0.00011		mg/m³	1	8/16/2017
Ethyl acetate	ND	0.0034	0.00048		mg/m³	1	8/16/2017
Ethylbenzene	ND	0.0016	0.00012		mg/m³	1	8/16/2017
Freon-113	0.00057	0.0029	0.00011	J	mg/m³	1	8/16/2017
Freon-114	ND	0.013	0.00013		mg/m³	1	8/16/2017
Heptane	ND	0.0015	0.00013		mg/m³	1	8/16/2017
Hexachlorobutadiene	ND	0.0040	0.00041		mg/m³	1	8/16/2017
Hexane	ND	0.0033	0.00023		mg/m³	1	8/16/2017
Isopropyl Alcohol	0.00064	0.0046	0.00036	J	mg/m³	1	8/16/2017
m,p-Xylene	0.00024	0.0033	0.0002	J	mg/m³	1	8/16/2017
Methyl tert-butyl ether	ND	0.0014	0.000076		mg/m³	1	8/16/2017
Methylene chloride	0.0020	0.013	0.0013	J	mg/m³	1	8/16/2017
Naphthalene	0.00059	0.0020	0.00056	J	mg/m³	1	8/16/2017
o-Xylene	0.00016	0.0016	0.0001	J	mg/m³	1	8/16/2017
Propene	0.00023	0.0064	0.00018	J	mg/m³	1	8/16/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter


Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range



Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 25, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 25, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080520 Revision 0

**Project:** PELO-2017-68, Franklin Centre, 7201 S. 76th St., Fr

**Lab ID:** 17080520-006

**Client Sample ID:** SV-6

**Collection Date:** 8/14/2017 12:35:00 PM

Matrix: AIR

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds in Air	by GC/MS T	O-15		Prep	Date: <b>8/16/</b>	2017	Analyst: AOA
Styrene	ND	0.0016	0.00038		mg/m³	1	8/16/2017
Tetrachloroethene	0.026	0.0025	0.00018		mg/m³	1	8/16/2017
Tetrahydrofuran	ND	0.0028	0.00052		mg/m³	1	8/16/2017
Toluene	ND	0.0014	0.00016		mg/m³	1	8/16/2017
trans-1,2-Dichloroethene	ND	0.0015	0.0001		mg/m³	1	8/16/2017
trans-1,3-Dichloropropene	ND	0.0017	0.0017		mg/m³	1	8/16/2017
Trichloroethene	ND	0.0020	0.00015		mg/m³	1	8/16/2017
Trichlorofluoromethane	0.0014	0.0021	0.00013	J	mg/m³	1	8/16/2017
Vinyl acetate	ND	0.013	0.00053		mg/m³	1	8/16/2017
Vinyl chloride	ND	0.00096	0.000081		mg/m³	1	8/16/2017
Xylenes, Total	0.00041	0.0049	0.0003	J	mg/m³	1	8/16/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

CHAIN OF CUSTODY RECORD STAT Analysis Corporation
2242 W. Harrison Suite 200, Chicago, Illinois 60612 Phone: (312) 733-0551 Fax: (312) 733-2386
e-mail address: STATinfo@STATAnalysis.com
CHAIN OF CUSTODY RECO

e-mail address: STATinfo@STATAnalysis.com  CHAIN OF CUSTODY RECO	ATAnalysis.	сош		CH	VIN	CHAIN OF CUSTODY RECORD	rody	REC	ORD			Nº: 907377	307	37	7 Page:	Jo .	
+ Companie									ļ						Quote No.:		
- 1107	68	C	Client Tra	Fracking No.:	No.:										,		
Project Name: Konn k to	CONTRO													<del></del>	P.O. No.:		
Project Location: 7201 5, 76 th 54.	Frank	lir,	17														
Sampler(s): Toe Becker	,																
Report To: See Gental	Phone:		847	25%	2	7×2					·······				Turn Around Time (Davs)	e (Davs):	
Steve Newlin	Fax:	.,	bertie /	3	apen	Dapends. un	4,				·				1 2 3	4 5-7	710
QC Level: 1 2 3 4	e-mail:	1	Snewlin		nper	-	<del>20</del> ,								g	Ψ	
Client Sample Number/Description: Da	Date Taken	Time Taken	xirtist .qmo	dsrā	eserv.	No. of	1									/	am/pm
A. L 160 4.	0.11.12	-	-	, >		Clinaincis 17	5		+		-			+	Additional Information:		Lab No.:
יש	_	+	-	<u></u>	_	, ,	र	T	+		$\dashv$		1	$\dashv$			
	T	3 3	_	X	+	1	2	$\exists$	$\dashv$		-					8	2
1,0		9,6	<b>→</b>	X	>	-3	<u> </u>									8	
56-4	$\neg$	8-17-17- A.	-	X	4		ン									8	5
5.05	05:21	,		X	Centralism	, growth	X.									8	V
20.00	12:35	<u> </u>	7	X		-3	X				-					き 	1
									_		_			-			)
											_			$\vdash$			
														-			
			-														
							-										
					ᅦ												
Relinquished by: (Signature)	7		Date/Time:	100	41-51-8		Comments:	· · ·							Laboratory Work Order No.:	Order No.:	
Neceived by: (Signature)	Land		Date/Time:	0	1	15.70									*()	(	(
Relinquished by: (Signature)		I	Date/Time:												) 	いろくい	2
Received by: (Signature)		I	Date/Time:												Received on Ice: Yes X No	Yes 🔀	9
Relinquished by: (Signature)		I	Date/Time:			1	Preservation Code: A	ion Cod	le: A =	= None	B = HNO <sub>3</sub>	1	C = NaOH		•	1,	
Received by: (Signature)		I	Date/Time:				$D = H_2SO_4$	) <sub>4</sub> E=	E = HCl	F = 503	F = 5035/EnCore	,	G = Other		Temperature:	^}	ပွ
							Ì	1						l			

#### Sample Receipt Checklist

Client Name APEX		Date and Tim	e Received:	8/15/2017 1:30:00 PM
Work Order Number 17080520		Received by:	MGK	
Checklist completed by: Stanature Date	5/17	Reviewed by:	M K	8/15//7 Date
Matrix: Carrier name	Client Delivered			
Shipping container/cooler in good condition?	Yes 🗹	No 🗌	Not Present	
Custody seals intact on shippping container/cooler?	Yes	No 🗌	Not Present 🗹	
Custody seals intact on sample bottles?	Yes	No 🗌	Not Present 🗹	
Chain of custody present?	Yes 🗸	No 🗌		
Chain of custody signed when relinquished and received?	Yes 🗸	No 🗌		
Chain of custody agrees with sample labels/containers?	Yes 🗸	No 🗌		
Samples in proper container/bottle?	Yes 🗸	No 🗌		
Sample containers intact?	Yes 🗸	No 🗌		
Sufficient sample volume for indicated test?	Yes 🗸	No 🗌		
All samples received within holding time?	Yes 🗹	No 🗌		
Container or Temp Blank temperature in compliance?	Yes 🗸	No 🗌	Temperature	3.3 °C/
Water - VOA vials have zero headspace? No VOA vials subm	nitted	Yes 📓	No 📓	
Water - Samples pH checked?	Yes 📓	No 📓	Checked by:	
Water - Samples properly preserved?	Yes 📓	No 📓	pH Adjusted?	
				A Contraction of the Contraction
Any No response must be detailed in the comments section below.				
comments: *TO canisters were	receive	d in	ambien	t conditions
Client / Person contacted: Date contacted:		Contac	sted by:	
Response:				

2242 West Harrison St., Suite 200, Chicago, IL 60612-3766
Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com
Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

August 23, 2017

Apex Companies, LLC 1701 East Woodfield Rd, Suite 333 Schaumburg, IL 60173

Telephone: (847) 956-8589 Fax: (847) 956-8619

Analytical Report for STAT Work Order: 17080612 Revision 0

RE: PECO-2017-68, Franklin Centre, 7201 S. 76th St., Franklin, WI

Dear Joseph Becker:

STAT Analysis received 5 samples for the referenced project on 8/17/2017 4:55:00 PM. The analytical results are presented in the following report.

All analyses were performed in accordance with the requirements specified in WI DNR Chapter NR 149 (Certification Number 399099910). Analyses were performed in accordance with methods as referenced on the analytical report.

All analyses were performed within established holding time criteria, and all Quality Control criteria met EPA or laboratory specifications except when noted in the Case Narrative or Analytical Report. A listing of accredited methods/parameters can also be provided.

For sample results requiring adjustment for dilutions, the detection and reporting limits are adjusted for the corresponding dilution factor. Analytical results expressed on a dry weight basis have units of mg/Kg-dry or  $\mu$ g/Kg-dry on the analytical report. Corresponding reporting limits are adjusted for dry weight.

Thank you for the opportunity to serve you and I look forward to working with you in the future. If you have any questions regarding the enclosed materials, please contact me at (312) 733-0551.

Sincerely,

Martin Kucan

Project Manager

Martin Vynan

The information contained in this report and any attachments is confidential information intended only for the use of the individual or entities named above. The results of this report relate only to the samples tested. If you have received this report in error, please notify us immediately by phone. This report shall not be reproduced, except in its entirety, unless written approval has been obtained from the laboratory. This analytical report shall become property of the Customer upon payment in full. Otherwise, STAT will be under no obligation to support, defend or discuss the analytical report.


**Date:** August 23, 2017

Client: Apex Companies, LLC

Project: PECO-2017-68, Franklin Centre, 7201 S. 76th St., Fran Work Order Sample Summary

Work Order: 17080612 Revision 0

Lab Sample ID	Client Sample ID	Tag Number	Collection Date	Date Received
17080612-001A	MW-1		8/17/2017 12:05:00 PM	8/17/2017
17080612-002A	MW-2		8/17/2017 11:20:00 AM	8/17/2017
17080612-003A	.MW-3		8/17/2017 10:35:00 AM	8/17/2017
17080612-004A	Duplicate		8/17/2017	8/17/2017
17080612-005A	Trip Blank			8/17/2017



Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 23, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 23, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080612 Revision 0

**Project:** PECO-2017-68, Franklin Centre, 7201 S. 76th St., Fra

Lab ID: 17080612-001 Client Sample ID: MW-1

Collection Date: 8/17/2017 12:05:00 PM

Matrix: AQUEOUS

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds by GC/MS	sv	V8260B (S)	W5030B)	Prep [	Date:		Analyst: ART
Acetone	ND	0.020	0.0031		mg/L	1	8/22/2017
Benzene	ND	0.0050	0.0002		mg/L	1	8/22/2017
Bromodichloromethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
Bromoform	ND	0.0050	0.0003		mg/L	1	8/22/2017
Bromomethane	ND	0.010	0.002		mg/L	1	8/22/2017
2-Butanone	ND	0.020	0.0016		mg/L	1	8/22/2017
Carbon disulfide	ND	0.010	0.0003		mg/L	1	8/22/2017
Carbon tetrachloride	ND	0.0050	0.001		mg/L	1	8/22/2017
Chlorobenzene	ND	0.0050	0.0002		mg/L	1	8/22/2017
Chloroethane	ND	0.010	0.0005		mg/L	1	8/22/2017
Chloroform	ND	0.0050	0.0001		mg/L	1	8/22/2017
Chloromethane	ND	0.010	0.0003		mg/L	1	8/22/2017
Dibromochloromethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1-Dichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,2-Dichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1-Dichloroethene	ND	0.0050	0.0004		mg/L	1	8/22/2017
cis-1,2-Dichloroethene	ND	0.0050	0.0002		mg/L	1	8/22/2017
trans-1,2-Dichloroethene	ND	0.0050	0.0005		mg/L	1	8/22/2017
1,2-Dichloropropane	ND	0.0050	0.0001		mg/L	1	8/22/2017
cis-1,3-Dichloropropene	ND	0.0010	0.0002		mg/L	1	8/22/2017
trans-1,3-Dichloropropene	ND	0.0010	0.0001		mg/L	1	8/22/2017
Ethylbenzene	ND	0.0050	0.0003		mg/L	1	8/22/2017
2-Hexanone	ND	0.020	0.0002		mg/L	1	8/22/2017
4-Methyl-2-pentanone	ND	0.020	0.0007		mg/L	1	8/22/2017
Methylene chloride	ND	0.0050	0.0002		mg/L	1	8/22/2017
Methyl tert-butyl ether	ND	0.0050	0.0003		mg/L	1	8/22/2017
Styrene	ND	0.0050	0.0003		mg/L	1	8/22/2017
1,1,2,2-Tetrachloroethane	ND	0.0050	0.0001		mg/L	1	8/22/2017
Tetrachloroethene	ND	0.0050	0.0003		mg/L	1	8/22/2017
Toluene	ND	0.0050	0.0004		mg/L	1	8/22/2017
1,1,1-Trichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1,2-Trichloroethane	ND	0.0050	0.0001		mg/L	1	8/22/2017
Trichloroethene	ND	0.0050	0.0003		mg/L	1	8/22/2017
Vinyl chloride	ND	0.0020	0.0003		mg/L	1	8/22/2017
Xylenes, Total	ND	0.015	0.001		mg/L	1	8/22/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter


Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range



Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 23, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 23, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080612 Revision 0

**Project:** PECO-2017-68, Franklin Centre, 7201 S. 76th St., Fra

**Lab ID:** 17080612-002

Client Sample ID: MW-2

**Collection Date**: 8/17/2017 11:20:00 AM

Matrix: AQUEOUS

Analyses	Result	RI	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds by GC/MS	SV	V8260B	(SW5030B)	Prep [	Date:		Analyst: ART
Acetone	ND	0.020	0.0031		mg/L	1	8/22/2017
Benzene	ND	0.0050	0.0002		mg/L	1	8/22/2017
Bromodichloromethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
Bromoform	ND	0.0050	0.0003		mg/L	1	8/22/2017
Bromomethane	ND	0.010	0.002		mg/L	1	8/22/2017
2-Butanone	ND	0.020	0.0016		mg/L	1	8/22/2017
Carbon disulfide	ND	0.010	0.0003		mg/L	1	8/22/2017
Carbon tetrachloride	ND	0.0050	0.001		mg/L	1	8/22/2017
Chlorobenzene	ND	0.0050	0.0002		mg/L	1	8/22/2017
Chloroethane	ND	0.010	0.0005		mg/L	1	8/22/2017
Chloroform	ND	0.0050	0.0001		mg/L	1	8/22/2017
Chloromethane	ND	0.010	0.0003		mg/L	1	8/22/2017
Dibromochloromethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1-Dichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,2-Dichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1-Dichloroethene	ND	0.0050	0.0004		mg/L	1	8/22/2017
cis-1,2-Dichloroethene	ND	0.0050	0.0002		mg/L	1	8/22/2017
trans-1,2-Dichloroethene	ND	0.0050	0.0005		mg/L	1	8/22/2017
1,2-Dichloropropane	ND	0.0050	0.0001		mg/L	1	8/22/2017
cis-1,3-Dichloropropene	ND	0.0010	0.0002		mg/L	1	8/22/2017
trans-1,3-Dichloropropene	ND	0.0010	0.0001		mg/L	1	8/22/2017
Ethylbenzene	ND	0.0050	0.0003		mg/L	1	8/22/2017
2-Hexanone	ND	0.020	0.0002		mg/L	1	8/22/2017
4-Methyl-2-pentanone	ND	0.020	0.0007		mg/L	1	8/22/2017
Methylene chloride	ND	0.0050	0.0002		mg/L	1	8/22/2017
Methyl tert-butyl ether	ND	0.0050	0.0003		mg/L	1	8/22/2017
Styrene	ND	0.0050	0.0003		mg/L	1	8/22/2017
1,1,2,2-Tetrachloroethane	ND	0.0050	0.0001		mg/L	1	8/22/2017
Tetrachloroethene	ND	0.0050	0.0003		mg/L	1	8/22/2017
Toluene	ND	0.0050	0.0004		mg/L	1	8/22/2017
1,1,1-Trichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1,2-Trichloroethane	ND	0.0050	0.0001		mg/L	1	8/22/2017
Trichloroethene	ND	0.0050	0.0003		mg/L	1	8/22/2017
Vinyl chloride	ND	0.0020	0.0003		mg/L	1	8/22/2017
Xylenes, Total	ND	0.015	0.001		mg/L	1	8/22/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter


Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range



Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 23, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 23, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080612 Revision 0

**Project:** PECO-2017-68, Franklin Centre, 7201 S. 76th St., Fra

**Lab ID:** 17080612-003

Client Sample ID: MW-3

Collection Date: 8/17/2017 10:35:00 AM

Matrix: AQUEOUS

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds by GC/MS	SV	V8260B (S	W5030B)	Prep [	Date:		Analyst: ART
Acetone	ND	0.020	0.0031		mg/L	1	8/22/2017
Benzene	ND	0.0050	0.0002		mg/L	1	8/22/2017
Bromodichloromethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
Bromoform	ND	0.0050	0.0003		mg/L	1	8/22/2017
Bromomethane	ND	0.010	0.002		mg/L	1	8/22/2017
2-Butanone	ND	0.020	0.0016		mg/L	1	8/22/2017
Carbon disulfide	ND	0.010	0.0003		mg/L	1	8/22/2017
Carbon tetrachloride	ND	0.0050	0.001		mg/L	1	8/22/2017
Chlorobenzene	ND	0.0050	0.0002		mg/L	1	8/22/2017
Chloroethane	ND	0.010	0.0005		mg/L	1	8/22/2017
Chloroform	ND	0.0050	0.0001		mg/L	1	8/22/2017
Chloromethane	ND	0.010	0.0003		mg/L	1	8/22/2017
Dibromochloromethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1-Dichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,2-Dichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1-Dichloroethene	ND	0.0050	0.0004		mg/L	1	8/22/2017
cis-1,2-Dichloroethene	ND	0.0050	0.0002		mg/L	1	8/22/2017
trans-1,2-Dichloroethene	ND	0.0050	0.0005		mg/L	1	8/22/2017
1,2-Dichloropropane	ND	0.0050	0.0001		mg/L	1	8/22/2017
cis-1,3-Dichloropropene	ND	0.0010	0.0002		mg/L	1	8/22/2017
trans-1,3-Dichloropropene	ND	0.0010	0.0001		mg/L	1	8/22/2017
Ethylbenzene	ND	0.0050	0.0003		mg/L	1	8/22/2017
2-Hexanone	ND	0.020	0.0002		mg/L	1	8/22/2017
4-Methyl-2-pentanone	ND	0.020	0.0007		mg/L	1	8/22/2017
Methylene chloride	ND	0.0050	0.0002		mg/L	1	8/22/2017
Methyl tert-butyl ether	ND	0.0050	0.0003		mg/L	1	8/22/2017
Styrene	ND	0.0050	0.0003		mg/L	1	8/22/2017
1,1,2,2-Tetrachloroethane	ND	0.0050	0.0001		mg/L	1	8/22/2017
Tetrachloroethene	ND	0.0050	0.0003		mg/L	1	8/22/2017
Toluene	ND	0.0050	0.0004		mg/L	1	8/22/2017
1,1,1-Trichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1,2-Trichloroethane	ND	0.0050	0.0001		mg/L	1	8/22/2017
Trichloroethene	ND	0.0050	0.0003		mg/L	1	8/22/2017
Vinyl chloride	ND	0.0020	0.0003		mg/L	1	8/22/2017
Xylenes, Total	ND	0.015	0.001		mg/L	1	8/22/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range



Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 23, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 23, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080612 Revision 0

**Project:** PECO-2017-68, Franklin Centre, 7201 S. 76th St., Fra

Lab ID: 17080612-004 Client Sample ID: Duplicate Collection Date: 8/17/2017

Matrix: AQUEOUS

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds by GC/MS	sv	V8260B (S)	N5030B)	Prep D	Date:		Analyst: ART
Acetone	ND	0.020	0.0031		mg/L	1	8/22/2017
Benzene	ND	0.0050	0.0002		mg/L	1	8/22/2017
Bromodichloromethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
Bromoform	ND	0.0050	0.0003		mg/L	1	8/22/2017
Bromomethane	ND	0.010	0.002		mg/L	1	8/22/2017
2-Butanone	ND	0.020	0.0016		mg/L	1	8/22/2017
Carbon disulfide	ND	0.010	0.0003		mg/L	1	8/22/2017
Carbon tetrachloride	ND	0.0050	0.001		mg/L	1	8/22/2017
Chlorobenzene	ND	0.0050	0.0002		mg/L	1	8/22/2017
Chloroethane	ND	0.010	0.0005		mg/L	1	8/22/2017
Chloroform	ND	0.0050	0.0001		mg/L	1	8/22/2017
Chloromethane	ND	0.010	0.0003		mg/L	1	8/22/2017
Dibromochloromethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1-Dichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,2-Dichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1-Dichloroethene	ND	0.0050	0.0004		mg/L	1	8/22/2017
cis-1,2-Dichloroethene	ND	0.0050	0.0002		mg/L	1	8/22/2017
trans-1,2-Dichloroethene	ND	0.0050	0.0005		mg/L	1	8/22/2017
1,2-Dichloropropane	ND	0.0050	0.0001		mg/L	1	8/22/2017
cis-1,3-Dichloropropene	ND	0.0010	0.0002		mg/L	1	8/22/2017
trans-1,3-Dichloropropene	ND	0.0010	0.0001		mg/L	1	8/22/2017
Ethylbenzene	ND	0.0050	0.0003		mg/L	1	8/22/2017
2-Hexanone	ND	0.020	0.0002		mg/L	1	8/22/2017
4-Methyl-2-pentanone	ND	0.020	0.0007		mg/L	1	8/22/2017
Methylene chloride	ND	0.0050	0.0002		mg/L	1	8/22/2017
Methyl tert-butyl ether	ND	0.0050	0.0003		mg/L	1	8/22/2017
Styrene	ND	0.0050	0.0003		mg/L	1	8/22/2017
1,1,2,2-Tetrachloroethane	ND	0.0050	0.0001		mg/L	1	8/22/2017
Tetrachloroethene	ND	0.0050	0.0003		mg/L	1	8/22/2017
Toluene	ND	0.0050	0.0004		mg/L	1	8/22/2017
1,1,1-Trichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1,2-Trichloroethane	ND	0.0050	0.0001		mg/L	1	8/22/2017
Trichloroethene	ND	0.0050	0.0003		mg/L	1	8/22/2017
Vinyl chloride	ND	0.0020	0.0003		mg/L	1	8/22/2017
Xylenes, Total	ND	0.015	0.001		mg/L	1	8/22/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter


Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range



Tel: (312) 733-0551 Fax: (312) 733-2386 STATinfo@STATAnalysis.com

Accreditations: IEPA ELAP 100445; ORELAP IL300001; AIHA-LAP, LLC 101160; NVLAP LabCode 101202-0

**Date Reported:** August 23, 2017

**ANALYTICAL RESULTS** 

**Date Printed:** August 23, 2017

**CLIENT:** Apex Companies, LLC

Work Order: 17080612 Revision 0

**Project:** PECO-2017-68, Franklin Centre, 7201 S. 76th St., Fra

**Lab ID:** 17080612-005

Client Sample ID: Trip Blank

**Collection Date** 

**Matrix:** TRIP BLANK

Analyses	Result	RL	MDL	Qualifier	Units	DF	Date Analyzed
Volatile Organic Compounds by GC/MS	SW8260B (SW5030B)		Prep Date:			Analyst: ART	
Acetone	ND	0.020	0.0031	•	mg/L	1	8/22/2017
Benzene	ND	0.0050	0.0002		mg/L	1	8/22/2017
Bromodichloromethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
Bromoform	ND	0.0050	0.0003		mg/L	1	8/22/2017
Bromomethane	ND	0.010	0.002		mg/L	1	8/22/2017
2-Butanone	ND	0.020	0.0016		mg/L	1	8/22/2017
Carbon disulfide	ND	0.010	0.0003		mg/L	1	8/22/2017
Carbon tetrachloride	ND	0.0050	0.001		mg/L	1	8/22/2017
Chlorobenzene	ND	0.0050	0.0002		mg/L	1	8/22/2017
Chloroethane	ND	0.010	0.0005		mg/L	1	8/22/2017
Chloroform	ND	0.0050	0.0001		mg/L	1	8/22/2017
Chloromethane	ND	0.010	0.0003		mg/L	1	8/22/2017
Dibromochloromethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1-Dichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,2-Dichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1-Dichloroethene	ND	0.0050	0.0004		mg/L	1	8/22/2017
cis-1,2-Dichloroethene	ND	0.0050	0.0002		mg/L	1	8/22/2017
trans-1,2-Dichloroethene	ND	0.0050	0.0005		mg/L	1	8/22/2017
1,2-Dichloropropane	ND	0.0050	0.0001		mg/L	1	8/22/2017
cis-1,3-Dichloropropene	ND	0.0010	0.0002		mg/L	1	8/22/2017
trans-1,3-Dichloropropene	ND	0.0010	0.0001		mg/L	1	8/22/2017
Ethylbenzene	ND	0.0050	0.0003		mg/L	1	8/22/2017
2-Hexanone	ND	0.020	0.0002		mg/L	1	8/22/2017
4-Methyl-2-pentanone	ND	0.020	0.0007		mg/L	1	8/22/2017
Methylene chloride	ND	0.0050	0.0002		mg/L	1	8/22/2017
Methyl tert-butyl ether	ND	0.0050	0.0003		mg/L	1	8/22/2017
Styrene	ND	0.0050	0.0003		mg/L	1	8/22/2017
1,1,2,2-Tetrachloroethane	ND	0.0050	0.0001		mg/L	1	8/22/2017
Tetrachloroethene	ND	0.0050	0.0003		mg/L	1	8/22/2017
Toluene	ND	0.0050	0.0004		mg/L	1	8/22/2017
1,1,1-Trichloroethane	ND	0.0050	0.0002		mg/L	1	8/22/2017
1,1,2-Trichloroethane	ND	0.0050	0.0001		mg/L	1	8/22/2017
Trichloroethene	ND	0.0050	0.0003		mg/L	1	8/22/2017
Vinyl chloride	ND	0.0020	0.0003		mg/L	1	8/22/2017
Xylenes, Total	ND	0.015	0.001		mg/L	1	8/22/2017

ND - Not Detected at the Reporting Limit

J - Analyte detected below reporting limit

B - Analyte detected in the associated Method Blank

HT - Sample received past holding time

\* - Non-accredited parameter

Qualifiers:

RL/MDL - Reporting Limit / Method Detection Limit for the analysis

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

E - Value above quantitation range

STAT Analysis Corporation 2242 W. Harrison Suite 200, Chicago, Illinois 60612 Phone: (312) 733-0551 Fax: (312) 733-2386

AIHA, NVLAP and NELAP accredited e-mail address: STATinfo@STATAnalysis.com

am/pm Turn Around: Results Needed: Lab No.: Received on Ice: Yes X No Temperature: 4.7 °C 5000 of 31 Remarks 863939 **Preservation Code:** A = None B = HNO<sub>3</sub> <math>C = NaOHG = OtherComments: Report in MIDLY No No  $D = H_2SO_4$  E = HCI F = 5035/EnCoreCHAIN OF CUSTODY RECORD Quote No.: P.O. No.: 51em 1. 200 DCxcos.Co Lock (1/ @ 20 x107.00 Containers No. of N Ş 28 26 - 754 - 448 6.00 Client Tracking No.: Grab Date/Time: Date/Time: Date/Time: Date/Time: Date/Time: Comp Date/Time: 3 Matrix Franklin (0:34 7:05 5 Time Taken Phone: e-mail: Fax: Date Taken 10000 NOV 89-6192 へるってり Ser in 76 +2 Client Sample Number/Description: Beder ているはい 7201 S. PECO. Duo1: 6-16 cio Blan からっと Apex 5.26 Relinquished by: (Signature) 2.~\& Relinquished by: (Signature) WW.3 Relinquished by: (Signature) ز کرکج Received by: (Signature) Received by: (Signature) Received by: (Signature) Project Location: Project Number: Project Name: Sampler(s): Report To: QC Level: Company:

### Sample Receipt Checklist

Client Name APEX	Date and Time Received: 8/17/2017 4:55:00 F				
Work Order Number 17080612		Received by:	JNW		
Checklist completed by:  Signature  Date	7/17	Reviewed by:	F	8/18/17 Date	
Matrix: Carrier name	Client Delivered				
Shipping container/cooler in good condition?	Yes 🗸	No 🗌	Not Present		
Custody seals intact on shippping container/cooler?	Yes	No 🗌	Not Present 🗹		
Custody seals intact on sample bottles?	Yes	No 🗌	Not Present 🗹		
Chain of custody present?	Yes 🗸	No 🗌			
Chain of custody signed when relinquished and received?	Yes 🗸	No 🗌			
Chain of custody agrees with sample labels/containers?	Yes 🗸	No 🗌			
Samples in proper container/bottle?	Yes 🗹	No 🗌			
Sample containers intact?	Yes 🗸	No 🗌			
Sufficient sample volume for indicated test?	Yes 🗹	No 🗆			
All samples received within holding time?	Yes 🗹	No 🗌			
Container or Temp Blank temperature in compliance?	Yes 🗹	No 🗌	Temperature	4.7 °C	
Water - VOA vials have zero headspace? No VOA vials subm	itted	Yes 🗹	No 🗌		
Water - Samples pH checked?	Yes 🔳	No 📓	Checked by:		
Water - Samples properly preserved?	Yes 📓	No 📓	pH Adjusted?		
Any No response must be detailed in the comments section below.					
Comments:					
Client / Person contacted: Date contacted:		Conta	cted by:		
Response:		- The state of the			

Appendix F Specifications for RadonAway Model GP501 Mitigation Fan



# **GP Series**



# **Radon Mitigation Fan**

All RadonAway™ fans are specifically designed for radon mitigation. GP Series Fans offer a wide range of performance options that make them ideal for most sub-slab radon mitigation systems.


#### **Features**


- Quiet operation
- Water-hardened motor
- Seams sealed under negative pressure (to inhibit radon leakage)
- Mounts on duct pipe or with integral flange
- 3" diameter ducts for use with 3" or 4" pipe
- Electrical box for hard wire or plug in
- ETL Listed for indoor or outdoor use
- 4 interchangeable GP models

MODEL P/N	PAN DUCT	WATTS	MAX.	TYPICAL CFM vs. STATIC PRESSURE WC							
	P/N	DIAMETER	WALIS	PRESSURE"WC	1.0"	1.5"	2.0"	2.5"	3.0"	3.5"	4.0"
GP201	23007-1	3"	40-60	2.0	82	58	5	-	-	-	-
GP301	23006-1	3"	55-90	2.6	92	77	45	10	-	-	-
GP401	23009-1	3"	60-110	3.4	93	82	60	40	15	-	-
GP501	23005-1	3"	70-140	4.2	95	87	80	70	57	30	10









For Further Information Contact