

QAQC  
2.6.12  
dew

State of Wisconsin - Department of Natural Resources  
Substance Release Notification Report (SERTS)  
Report created on 12/09/2011

SPILL ID# 20111207NE38-1 BRRTS# 04-38-558002

04-38-558002

Incident Date & Time: 12/06/2011 13:00	Reported Date & Time: 12/07/2011 17:10	BRRTS No: 04-38-558002	Spill ID: 20111207NE38-1
DATCP Reported? No DATCP Transferred? No	NFA Letter Sent? No	ERP Transferred? No	Incident Closed? Yes : 12/08/2011

Location			
Region: NE	County: Marinette	Municipality: MARINETTE, CITY OF	
Facility/Property Name and Street Address: MARINETTE MARINE 1600 ELY ST		Description: AT THE DOCK	
Facility Type: Industrial Facility (Foundry/Factory/Plating/Manufacturing)			
Lat/Long:	PLSS:	WTM: X 707454 Y 516843	
Weather Conditions: Cloudy			

add to SDE-ALGS-2/14/2012

Responsible Parties			
Name/Address (1): MARINETTE MARINE CORP 1600 ELY ST MARINETTE, WI 54143- (715) 735-9341 x 6023 Primary	Contact: PAUL KRAUS MGR SAFETY & COMPLIANCE (715) 735-9341 x 6023 primary	Other Contact:	Spill Packet:

**Cause**

WHILE COILING A FUEL LINE THE CAP CAME OFF AND JPV FUEL RELEASED ONTO THE DOCK. IT IS ESTIMATED THAT LESS THAN 2 GALLONS RELEASED AND 1 QUART GOT INTO THE RIVER.

Cause Type: Equipment Failure

Substances						
Name	Other / Comments	Amt Released	Amt Recovered	Type	Color	Odor
Diesel	JP-5 (KEROSENE, HEAVY)	2.0 Gal	2.0 Gal	LIQUID		

Environmental Impacts / Damages			
Environmental Impacts: SURFACE WATER - Name : MENOMINEE RIVER	Resource Damages: No	Injuries: No	Evacuation: No

Cleanup Actions	
Method	Description
Absorbent (oil dry, sand, sawdust)	
Boom	

**Cleanup Action Comments**

BOOMS APPLIED, CLEANUP COMPLETE.

Contractors Hired	
Name	Description

Waste Destinations	
Location	Description

**Agencies Notified / On Scene**

State of Wisconsin - Department of Natural Resources  
 Substance Release Notification Report (SERTS)  
 Report created on 12/09/2011

SPILL ID# 20111207NE38-1 BRRTS# 04-38-558002

Agency	Notified	On Scene
COAST GUARD	X	
DHFS	X	
DIV EMERG MGT	X	
DNR	X	

**Additional Comments**

SUBMITTED VIA SERTS WEB FORM REF # 6204. 12-08-11, MOELLER SPOKE WITH PAUL KRAUS, THE SPILL WAS PROPERLY CLEANED UP USING ABSORBENT MATERIAL.

**Enforcement Action/Citation**

Enforcement Action/Citation? No

Case Activity Reports:


**Person Reporting**

Name	Representing / Address	Primary Phone	Secondary Phone
PAUL KRAUS	MARINETTE MARINE	(715) 735-9341 x 6023	

**Contractors Hired**

Name / Address	Zone Contractor Hired by DNR?
	No

**Contacts**

Role	Name	Office Phone	Date	Time
Prepared By:	Laura Szymanski	(608) 261-4939 x	12/07/2011	
Person Notified:	WARDEN DAVE OGINSKI JR		12/07/2011	
Investigated By:	USCG		12/07/2011	
Incident Commander:				
Spill Coordinator:	JASON MOELLER, NE Region 	(920) 662-5492 x	12/08/2011	

**Electronic Attachments (list)**

Name	Type
20111206NE381_RP_Doc.pdf	Portable Document Format

U.S. Department  
of Transportation

United States  
Coast Guard



Supervisor  
U.S. Coast Guard  
Marine Safety Detachment

57 N. 12th Ave

Sturgeon Bay, WI 54235  
Phone: 920-743-9448  
Fax: 920-743-9724

Witness Statement

Statement of:

PAUL KRAUS

Company/Position:

MARINETTE MARINE CO. MANAGER, SAFETY & COMPLIANCE

Address/Telephone:

1600 ELY STREET MARINETTE, WIS. 54143

Regarding:

FUEL SPILL

On (Date/Time):

12-6-2011

Statement: (Please include information such as: What happened? How did spill occur? What was spilled? How much? Into what waterway? Any sheen?)

AT APPROXIMATELY 1PM ON 12-6-2011 WE WERE REMOVING THE FUELING HOSE FROM VESSEL FORT WORTH (LCS-3) AND COILING THE HOSE ON A SKID DOCKSIDE WHEN DURING THE COILING ONE OF THE END CAPS CAME OFF AND SPILLED APPROXIMATELY 2 GALLONS OF JP-5 ON TO OUR DOCK. THE FUEL RAN INTO OUR LAUNCHWAY RAIL TROUGH WHERE < 1 QT WENT THROUGH THE TROUGH DRAIN INTO THE MENOMINEE RIVER. THE AREA WAS FULLY CONTAINED AND WE APPLIED OIL SOAK SOCKS AND PADS IMMEDIATELY AS WELL AS CLEAN OUT THE LAUNCHWAY TROUGH.

OUR CORRECTIVE ACTIONS WERE TO SECURE THE FUEL HOSE CAPS WITH CAM LOCKS ANYTIME THE FUEL HOSE IS MOVED AS WELL AS INSTALL DRAIN PLUGS IN OUR LAUNCHWAY TROUGHS TO SECURE THEM AS WELL.

The above statement is true and correct to the best of my knowledge.

Paul Kraus, MGR, SAFETY & COMPLIANCE  
Signature

12-8-2011  
date

Investigator: name and signature

date