From: Travis W. Peterson <tpeterson@kapurinc.com>

Sent: Tuesday, September 14, 2021 1:51 PM

To: Michalets, Linda M - DNR

Subject: RE: 1818 W National Avenue, 02-41-583465

CAUTION: This email originated from outside the organization.
Do not click links or open attachments unless you recognize the sender and know the content is safe.

### Linda,

Thank you for clearing up the concern with the figure Sheet 5, I have adjusted the figure accordingly. As to the "turquoise and pink lines on the north side of the property" they have no significance, it is just simply a result of the AutoCAD drawing being converted to a .pdf.

I will prepare a cross-section that shows the general redistribution of soils. Also, the excavation depths were intended to explain that the minimum depth of excavation was 2-3 feet and in general 3-4 feet though some locations were deeper as in the nearby utilities that were excavated down 7 to 8 feet. I will also address the items from your June 23<sup>rd</sup> email not covered in the recent submittal.

#### Thanks Linda



# Travis W. Peterson Associate / Economic Development Manager

**M:** 414.254.6358 | Kapur

O: 414.751.7279 7711 N Port Washington Road Milwaukee, Wisconsin 53217

From: Michalets, Linda M - DNR < Linda. Michalets@wisconsin.gov>

Sent: Friday, September 10, 2021 2:41 PM

**To:** Travis W. Peterson < tpeterson@kapurinc.com > **Subject:** 1818 W National Avenue, 02-41-583465

#### Hello Travis,

I received the revised NFA request, dated August 4, 2021; however, you did not provide responses to the specific items I requested in my June 23, 2021 email. Could you address these issues specifically, so that I can review the August 4<sup>th</sup> submittal along with this additional information. Also, provide a revised Sheet Number 5 so that the area identified in the Legend as "Minimum Area of Over-Excavation of 3-4 feet bgs or Greater" matches the hatched area on the map. The applicable area is not a solid orange color as indicated in the Legend. Also, identify the purpose of the turquoise and pink lines on the north side of the property.

As requested in my earlier email, a cross-section should be provided and would be very helpful for understanding the contamination and the soil movement that occurred at the site. For example, you

stated in the Findings and Conclusions that "the same area was excavated down a minimum 2-3 feet as a larger area of soil material onsite was deemed not suitable for construction...." Yet Sheet Number 5 indicates that a wide area around boring B-21 was over-excavated 3 to 4 feet or greater. Provide additional information about these excavation depths and the actual depths of the utilities in this area.

Let me know if you have any questions about this. Thank you, Linda

#### We are committed to service excellence.

Visit our survey at <a href="http://dnr.wi.gov/customersurvey">http://dnr.wi.gov/customersurvey</a> to evaluate how I did.

## **Linda Michalets**

she/her/hers
Hydrogeologist – Remediation and Redevelopment Program
Wisconsin Department of Natural Resources
1027 W. St. Paul Ave. \*\*New Address\*\*
Milwaukee, WI 53233
Cell Phone: 414-435-8010



linda.michalets@wisconsin.gov