

From: Sager, John E - DNR

Sent: Monday, May 15, 2023 1:19 PM

To: Gregory Prom (MP) <gprom@mnpower.com>

Subject: RE: Work Plan for the Infestation and Remediation beneath the Former Building for the Superior MGP Site (BRRTS No. 02-16-275446)

Greg,

Thank you for the work plan and the update. Based on the results of previous investigation near the building, significant contamination was found up to at least 10 feet below grade. The DNR recommends extending the borings to a depth necessary to be able to relate contamination found beneath the building to other areas of the site. If the borings are kept shallow (6 feet below grade) as proposed, this may not provide information necessary to evaluate remaining contamination at depth and additional investigation may be needed. Wis. Admin. Code § NR716.11 requires the full extent of contamination to be investigated.

Please provide me the final boring locations as installed, boring logs including PID measurements, sample depths, and field notes from the soil borings as soon as possible. Also, please submit analytical results as soon as available.

I would like to visit the site during the excavation prior to backfilling. Please let me know when a good time to do this is.

We are committed to service excellence.

Visit our survey at <http://dnr.wi.gov/customersurvey> to evaluate how I did.

John Sager

Hydrogeologist – Remediation and Redevelopment Program

Wisconsin Department of Natural Resources

1701 N. 4th St.

Superior, WI 54880

Phone: (715) 919-7239

john.sager@wisconsin.gov



dnr.wi.gov

