Lake Education And Planning Services, LLC.

# Shoreline Habitat Assessment

# Granite Lake, Barron County WDNR WBIC 2100800

Prepared by: Heather Wood, Lake Management Assistant

# **Table of Contents**

| Overview  |     |
|---|-----|
| Protocol  |     |
| Priority Ranking Parameters                               |     |
| Lake-wide Summary   |     |
| Priority Rankings by Parcel                               |     |
| High Priority Parcels                                     |     |
| Moderate Priority Parcels                                 |     |
| Low Priority Parcels                                      |     |
| No Priority Parcels                                       |     |
| Lake Management Best Practices (Healthy Lakes Initiative) |     |
| Example Parcels (Not From Granite Lake)                   |     |
| Alphabetical Index of Parcel Numbers and Owners           |     |
| Alphabetical muex of Parcel Numbers and Owners            | 107 |

# **Overview**

#### Protocol

The protocol used in this survey was developed by the Wisconsin Department of Natural Resources (WDNR) as a way to evaluate shoreline habitat. This survey is intended to provide management recommendations to individual property owners based on the evaluation of their property. This protocol involves photographing each parcel from the lake which is then matched to land use information about the riparian zone. For this survey, the riparian zone is defined as the strip of land, along the shore, from the high water level back 35 feet. The information collected includes ground cover which includes lawn, impervious surfaces, and native plants. Additional land use information includes the number of human structures in the riparian zone and various other runoff concerns. This protocol also assesses the amount of woody debris present in the lake however this is done for the entire lake instead of for each individual parcel. Woody debris provides habitat for fish, birds, and numerous other types of wildlife as well in addition to providing some protecting from bank erosion. This protocol defines woody debris as wood in no deeper than 2 feet of water that is at least 4 inches in diameter, at the widest point, and at least 5 feet long.

#### **Priority Ranking Parameters**

The priority rankings that accompany each parcel evaluation were developed by LEAPS in order to determine the needs of the each lake that the survey is conducted on with concern to the projects that could realistically be completely on each parcel. The parameters used to determine the priority were considered to be those that would have the biggest impact on rainwater runoff and habitat quality. This includes percentage of canopy cover, as well as the percentage of undisturbed vegetation and a summed percentage of ground covered by manicured lawn, impervious surfaces, and easily eroded surfaces such as exposed soil or shredded vegetation such as pine needles, loose leaves, small branches, etc. also known as duff. Additional consideration was given to the number of buildings present in the riparian zone and the presence or absence of lawns that sloped directly to the lake. For each factor that was considered, there are value ranges assigned to each parameter which determine the color to be assigned, the value ranges can be seen below in table 1. Values that fall within the red range are worth 2 points, values in the yellow range are worth 1 point, and values in the white range are not given any points. The points are then summed and the properties prioritized based on the point range for the entire lake.

#### Table 1: Value ranges for color assignments of each parameter of concern.

| Parameter  | Red range (2 points) | Yellow Range (1 Point) | White (No points) |
|--|----------------------|------------------------|-------------------|
| Percent canopy cover                                 | 0-33%                | 34-66%                 | >66%              |
| Percent shrub and<br>herbaceous (undisturbed)        | 0-33%                | 34-66%                 | >66%              |
| Percent lawn, impervious,<br>and other surfaces      | >66%                 | 34-66%                 | 0-33%             |
| Number of buildings and other human structures       | >1                   | 1                      | 0                 |
| Presence/ Absence of<br>lawn or soil sloping to lake | N/A                  | 1 (Present)            | 0 (Absent)        |
| Presence/Absence of bare soil                        | 1 (Present)          | N/A                    | 0 (Absent)        |
| Presence/Absence of sand deposits                    | N/A                  | 1 (Present)            | 0 (Absent)        |

# Lake-wide Summary

To establish priority rankings for this lake, it was important to consider the entire lake. The maximum possible score was 16 points, but the highest scoring parcel only scored 9 points. From here, four levels of concern were established: red, orange, yellow, and white. These colors correspond to the priority of concern red properties are of high concern, orange are moderate, yellow is low, and white parcels are of almost no concern. Figure 1 and Table 2 summarize the survey results for the entire lake.

| Color  | Overall Score | Priority   | Number of Parcels |
|--------|---------------|------------|-------------------|
| Red    | 7-9 Points    | High       | 11                |
| Orange | 4-6 Points    | Moderate   | 15                |
| Yellow | 2-3 Points    | Low        | 24                |
| White  | 0-1 Points    | No Concern | 42                |




Figure 1: Lakewide Shoreline Habitat Parcel Evaluations

# **Priority Rankings by Parcel**

The following pages are the summarized evaluations of each parcel. This will include the numbers used to determine the overall score as well as a photograph, and management recommendations for each parcel. Photos are intended to provide reference for individual property owners. These have been matched to the correct properties to our best knowledge. It is important to note that while ranking each parcel ONLY the 35-ft along the shoreline was considered. The photos were not used to assess properties and can be misleading for certain parameters, particularly canopy cover. For example, some parcels appear mostly shaded, but only have 15% canopy cover. This is likely because the assessment only considered 35-ft back and the canopy cover started beyond that mark. Additionally, there are other considerations such as camera angle, time of day, etc. All evaluations were done in the field to prevent any misdirection that would have been caused by using photos to assess the properties.

The management recommendations are explained, in more detail, in the section following the rankings. Generally speaking, there are very few recommendations for properties scoring under 2 points, so these have been marked with no priority ranking. The high and moderate priorities would do well with rain gardens, rock infiltrations, as well as native plantings. This is simply a general pattern, and it is important to note that there is a good amount of variation between each parcel. To account for this, there are specific management recommendations for each parcel. The recommendations for each parcel are meant to give property owners an idea of some of inexpensive small scale projects that would best suit the needs of their property. The projects suggested come primarily from the WDNR's Healthy Lakes Initiative which means most of them are eligible for grant funding through the WDNR.

# High Priority Parcels

| 18160022033181500160001816002202218220006000182200110001822001500018220029000 |             |
|---|-------------|
| 18160022022<br>18220006000<br>18220011000<br>18220015000                      | 18160022033 |
| 18220006000<br>18220011000<br>18220015000                                     | 18150016000 |
| 18220011000   18220015000   | 18160022022 |
| 18220015000   | 18220006000 |
|   | 18220011000 |
| 18220029000   | 18220015000 |
|   | 18220029000 |

Total Score: 8

# Priority: High

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 15             | 2           |
| Percent shrub and herbaceous (undisturbed)        | 5              | 2           |
| Percent lawn, impervious, and other surfaces      | 95             | 2           |
| Number of buildings and other<br>human structures | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Install a native plant buffer strip and/ or a rain garden, and plant more native trees.



Total Score: 7

# Priority: High

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 15             | 2           |
| Percent shrub and herbaceous (undisturbed)        | 15             | 2           |
| Percent lawn, impervious, and other surfaces      | 85             | 2           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Install a native plant buffer strip and/ or a rain garden, and plant more native trees.



Total Score: 7

# Priority: High

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 10             | 2           |
| Percent shrub and herbaceous (undisturbed)        | 30             | 2           |
| Percent lawn, impervious, and other surfaces      | 70             | 2           |
| Number of buildings and other<br>human structures | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Install a rock infiltration for rainwater runoff from the building, and keep the native plant buffer in place.



Total Score: 7

# Priority: High

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 30             | 2           |
| Percent shrub and herbaceous (undisturbed)        | 10             | 2           |
| Percent lawn, impervious, and other surfaces      | 90             | 2           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Install a native plant buffer strip and/ or a rain garden, and plant more native trees.



Total Score: 7

# Priority: High

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 75             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 15             | 2           |
| Percent lawn, impervious, and other surfaces      | 85             | 2           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 1              | 2           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Install a native plant buffer strip and/ or a rain garden making sure to cover the bare soil patches with native plants.



Total Score: 9

# Priority: High

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 80             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 20             | 2           |
| Percent lawn, impervious, and other surfaces      | 80             | 2           |
| Number of buildings and other<br>human structures | 4              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 1              | 2           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Install a native plant buffer strip and/ or a rain garden making sure to cover the bare soil patches with native plants.



Total Score: 7

# Priority: High

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 20             | 2           |
| Percent shrub and herbaceous (undisturbed)        | 10             | 2           |
| Percent lawn, impervious, and other surfaces      | 90             | 2           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

#### Management Recommendations:

Install a native plant buffer strip and/ or a rain garden, and add several native trees

\*No Photo Available

Total Score: 7

# Priority: High

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 90             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 20             | 2           |
| Percent lawn, impervious, and other surfaces      | 80             | 2           |
| Number of buildings and other<br>human structures | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 1              | 2           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Install a native plant buffer strip and/ or a rain garden along the shoreline



Total Score: 7

# Priority: High

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 95             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 30             | 2           |
| Percent lawn, impervious, and other surfaces      | 70             | 2           |
| Number of buildings and other human structures    | 2              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

#### Management Recommendations:

Install a native plant buffer strip and/ or a rain garden.

\*No Photo Available

Total Score: 9

# Priority: High

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 10             | 2           |
| Percent shrub and herbaceous (undisturbed)        | 5              | 2           |
| Percent lawn, impervious, and other surfaces      | 95             | 2           |
| Number of buildings and other<br>human structures | 2              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Install a native plant buffer strip and/ or a rain garden, and add several native trees to the shore area.



Total Score: 8

# Priority: High

| Parameter  | Property value | Point value |
|--|----------------|-------------|
| Percent canopy cover                                 | 5              | 2           |
| Percent shrub and herbaceous (undisturbed)           | 30             | 2           |
| Percent lawn, impervious, and other surfaces         | 70             | 2           |
| Number of buildings and other<br>human structures    | 1              | 1           |
| Presence/ Absence of lawn or soil<br>sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits               | 0              | 0           |
| Presence/ Absence of sand deposits                   | 0              | 0           |

# Management Recommendations:

Install a native plant buffer strip and/ or a rain garden, and add several native trees to the shore area.



# Moderate Priority Parcels

| 0262-0001-5000 |
|----------------|
| 0262-0001-6000 |
| 0262-0002-7000 |
| 0262-0003-0000 |
| 0262-9000-6020 |
| 0262-9001-3000 |
| 0262-9002-0000 |
| 0262-9002-2000 |
| 0262-9002-4000 |
| 0264-0000-6000 |
| 0264-0000-7000 |
| 0264-0000-8000 |
| 0264-0001-3000 |
| 0264-0220-5001 |
| 0264-0220-5022 |

Total Score: 6

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 50             | 1           |
| Percent shrub and herbaceous (undisturbed)        | 20             | 2           |
| Percent lawn, impervious, and other surfaces      | 80             | 2           |
| Number of buildings and other human structures    | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 5

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 80             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 10             | 2           |
| Percent lawn, impervious, and other surfaces      | 90             | 2           |
| Number of buildings and other<br>human structures | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 4

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 60             | 1           |
| Percent shrub and herbaceous (undisturbed)        | 50             | 1           |
| Percent lawn, impervious, and other surfaces      | 50             | 1           |
| Number of buildings and other human structures    | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 5

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 90             | 0           |
| Percent shrub and herbaceous<br>(undisturbed)     | 80             | 0           |
| Percent lawn, impervious, and other surfaces      | 20             | 0           |
| Number of buildings and other<br>human structures | 2              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 1              | 2           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Cover bare soil patches with native plants.



Total Score: 5

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 75             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 25             | 2           |
| Percent lawn, impervious, and other surfaces      | 75             | 2           |
| Number of buildings and other human structures    | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 5

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 60             | 1           |
| Percent shrub and herbaceous (undisturbed)        | 30             | 2           |
| Percent lawn, impervious, and other surfaces      | 70             | 2           |
| Number of buildings and other human structures    | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 5

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 60             | 1           |
| Percent shrub and herbaceous (undisturbed)        | 20             | 2           |
| Percent lawn, impervious, and other surfaces      | 80             | 2           |
| Number of buildings and other human structures    | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 5

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 85             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 30             | 2           |
| Percent lawn, impervious, and other surfaces      | 70             | 2           |
| Number of buildings and other human structures    | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Install a rock infiltration and divert rainwater runoff from the house to this infiltration.



Total Score: 6

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 60             | 1           |
| Percent shrub and herbaceous (undisturbed)        | 60             | 1           |
| Percent lawn, impervious, and other surfaces      | 40             | 1           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 1              | 2           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Cover bare soil patches with native plants.



Total Score: 6

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 30             | 2           |
| Percent shrub and herbaceous (undisturbed)        | 40             | 1           |
| Percent lawn, impervious, and other surfaces      | 60             | 1           |
| Number of buildings and other<br>human structures | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Expand the native plant buffer and add some more native trees to the shoreline area.



Total Score: 5

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 50             | 1           |
| Percent shrub and herbaceous (undisturbed)        | 25             | 2           |
| Percent lawn, impervious, and other surfaces      | 75             | 2           |
| Number of buildings and other human structures    | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Expand the native plant buffer.



Total Score: 4

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 20             | 2           |
| Percent shrub and herbaceous (undisturbed)        | 50             | 1           |
| Percent lawn, impervious, and other surfaces      | 50             | 1           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Expand the native plant buffer and add some more native trees to the shoreline area.



Total Score: 5

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 20             | 2           |
| Percent shrub and herbaceous (undisturbed)        | 60             | 1           |
| Percent lawn, impervious, and other surfaces      | 40             | 1           |
| Number of buildings and other<br>human structures | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

#### Management Recommendations:

Expand the native plant buffer and add some more native trees to the shoreline area.

\*No Photo Available

Total Score: 6

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 5              | 2           |
| Percent shrub and herbaceous (undisturbed)        | 30             | 2           |
| Percent lawn, impervious, and other surfaces      | 70             | 2           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Install a native plant buffer and add some more native trees to the shoreline area.



Total Score: 4

# Priority: Moderate

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 70             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 50             | 1           |
| Percent lawn, impervious, and other surfaces      | 50             | 1           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 1              | 2           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Cover the bare soil patches with native plants.



# Low Priority Parcels

| -              |
|----------------|
| 0262-0001-7000 |
| 0262-0002-0000 |
| 0262-0002-1000 |
| 0262-0002-9000 |
| 0262-0003-1000 |
| 0262-0003-2030 |
| 0262-0003-4010 |
| 0262-0003-5000 |
| 0262-9000-8000 |
| 0262-9000-9000 |
| 0262-9002-1000 |
| 0262-9002-3000 |
| 0262-9002-8001 |
| 0262-9002-8010 |
| 0262-9002-8020 |
| 0262-9002-9020 |
| 0262-9002-9045 |
| 0264-0000-5000 |
| 0264-0001-0000 |
| 0264-0110-1000 |
| 0264-0110-2000 |
| 0264-0220-5000 |
| 0264-0220-6000 |
| 0264-0221-7001 |
|                |

Total Score: 2

### Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 80             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 95             | 0           |
| Percent lawn, impervious, and other surfaces      | 5              | 0           |
| Number of buildings and other<br>human structures | 2              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

### Management Recommendations:

Monitor for and remove any invasive species.

\*No Photo Available

Total Score: 2

### Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 100            | 0           |
| Percent shrub and herbaceous (undisturbed)        | 100            | 0           |
| Percent lawn, impervious, and other surfaces      | 0              | 0           |
| Number of buildings and other<br>human structures | 2              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

### Management Recommendations:

Monitor for and remove any invasive species.

\*No Photo Available

Total Score: 3

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 50             | 1           |
| Percent shrub and herbaceous (undisturbed)        | 90             | 0           |
| Percent lawn, impervious, and other surfaces      | 10             | 0           |
| Number of buildings and other<br>human structures | 2              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Plant several trees in the shoreland area.



Total Score: 3

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 60             | 1           |
| Percent shrub and herbaceous (undisturbed)        | 60             | 1           |
| Percent lawn, impervious, and other surfaces      | 40             | 1           |
| Number of buildings and other human structures    | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Widen the native plant buffer along the shoreline.



Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 90             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 90             | 0           |
| Percent lawn, impervious, and other surfaces      | 10             | 0           |
| Number of buildings and other human structures    | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 100            | 0           |
| Percent shrub and herbaceous (undisturbed)        | 100            | 0           |
| Percent lawn, impervious, and other surfaces      | 0              | 0           |
| Number of buildings and other human structures    | 2              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 100            | 0           |
| Percent shrub and herbaceous (undisturbed)        | 100            | 0           |
| Percent lawn, impervious, and other surfaces      | 0              | 0           |
| Number of buildings and other<br>human structures | 2              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 100            | 0           |
| Percent shrub and herbaceous (undisturbed)        | 100            | 0           |
| Percent lawn, impervious, and other surfaces      | 0              | 0           |
| Number of buildings and other<br>human structures | 2              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 3

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 80             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 60             | 1           |
| Percent lawn, impervious, and other surfaces      | 40             | 1           |
| Number of buildings and other<br>human structures | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Widen the native plant buffer along the shoreline.



Total Score: 3

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 95             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 90             | 0           |
| Percent lawn, impervious, and other surfaces      | 10             | 0           |
| Number of buildings and other<br>human structures | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 1              | 2           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Cover bare soil patches with native plants.



Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 95             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 80             | 0           |
| Percent lawn, impervious, and other surfaces      | 20             | 0           |
| Number of buildings and other<br>human structures | 3              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

### Management Recommendations:

Divert rainwater runoff from the structures into a rock infiltration.



Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 100            | 0           |
| Percent shrub and herbaceous (undisturbed)        | 50             | 1           |
| Percent lawn, impervious, and other surfaces      | 50             | 1           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 95             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 50             | 1           |
| Percent lawn, impervious, and other surfaces      | 50             | 1           |
| Number of buildings and other human structures    | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 2

# Priority: Low

| Parameter  | Property value | Point value |
|--|----------------|-------------|
| Percent canopy cover                                 | 75             | 0           |
| Percent shrub and herbaceous (undisturbed)           | 70             | 0           |
| Percent lawn, impervious, and other surfaces         | 30             | 0           |
| Number of buildings and other<br>human structures    | 1              | 1           |
| Presence/ Absence of lawn or soil<br>sloping to lake | 1              | 1           |
| Presence/Absence of bare soil deposits               | 0              | 0           |
| Presence/ Absence of sand deposits                   | 0              | 0           |

### Management Recommendations:

Divert runoff from the shoreline building into a rock infiltration.



Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 95             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 95             | 0           |
| Percent lawn, impervious, and other surfaces      | 5              | 0           |
| Number of buildings and other<br>human structures | 5              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 100            | 0           |
| Percent shrub and herbaceous (undisturbed)        | 60             | 1           |
| Percent lawn, impervious, and other surfaces      | 40             | 1           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



Total Score: 3

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 90             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 90             | 0           |
| Percent lawn, impervious, and other surfaces      | 10             | 0           |
| Number of buildings and other<br>human structures | 3              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 1              | 1           |

# Management Recommendations:

Cover sand patches with native plants.



Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 95             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 95             | 0           |
| Percent lawn, impervious, and other surfaces      | 5              | 0           |
| Number of buildings and other<br>human structures | 2              | 2           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

### Management Recommendations:



Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 95             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 60             | 1           |
| Percent lawn, impervious, and other surfaces      | 40             | 1           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:



### Parcel number: 0264-0110-1000

Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 90             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 90             | 0           |
| Percent lawn, impervious, and other surfaces      | 10             | 0           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 1              | 2           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Cover bare soil patches with native plants



### Parcel number: 0264-0110-2000

Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 90             | 0           |
| Percent shrub and herbaceous (undisturbed)        | 90             | 0           |
| Percent lawn, impervious, and other surfaces      | 10             | 0           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 1              | 2           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Cover bare soil patches with native plants.



### Parcel number: 0264-0220-5000

Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 10             | 2           |
| Percent shrub and herbaceous<br>(undisturbed)     | 90             | 0           |
| Percent lawn, impervious, and other surfaces      | 10             | 0           |
| Number of buildings and other<br>human structures | 0              | 0           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Plant native trees within the riparian area



### Parcel number: 0264-0220-6000

Total Score: 2

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 50             | 1           |
| Percent shrub and herbaceous (undisturbed)        | 70             | 0           |
| Percent lawn, impervious, and other surfaces      | 30             | 0           |
| Number of buildings and other<br>human structures | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

# Management Recommendations:

Add native trees to the shoreline area.



### Parcel number: 0264-0221-7001

Total Score: 3

# Priority: Low

| Parameter   | Property value | Point value |
|---|----------------|-------------|
| Percent canopy cover                              | 30             | 2           |
| Percent shrub and herbaceous (undisturbed)        | 90             | 0           |
| Percent lawn, impervious, and other surfaces      | 10             | 0           |
| Number of buildings and other<br>human structures | 1              | 1           |
| Presence/ Absence of lawn or soil sloping to lake | 0              | 0           |
| Presence/Absence of bare soil deposits            | 0              | 0           |
| Presence/ Absence of sand deposits                | 0              | 0           |

### Management Recommendations:

Plant additional native trees in the shoreline area.

